

Superseded Drawing Note - Similar Stand Variant

A synthetic, superseded engineering note found in an uncontrolled folder. It is deliberately easy to misuse if revision and equipment applicability are ignored.

Document ID	Incident	Record type	Status
R3-CH-001	R3 carrier beam - 10/14/2024	Application test evidence	Synthetic / controlled

Document-control metadata

Field	Recorded value	Status
Title	Roughing Mill Carrier Link Retention - Stand Variant	Synthetic scenario fact
Revision	Rev D - superseded	Warning
Applies to	R2 legacy configuration; R3 applicability not established	Not established
Controlled-copy status	Uncontrolled scan; no current approval stamp	Low authority

Excerpt

The legacy note depicts a cap plate above the yoke pocket and calls it a positive link hold-down. A handwritten margin annotation says, 'same all roughers,' but the author and date of the annotation are not identified.

Required handling

- Do not apply the cap-plate requirement to R3 without a current R3 drawing or engineering confirmation.
- Treat the handwritten annotation as an unattributed claim.
- Retain the record because it may identify a design-history question, not because it proves an R3 defect.

Anonymous Handwritten Turnover Note

A synthetic low-reliability note supplied without a verified author, time, or chain of custody.

Document ID	Incident	Record type	Status
R3-CH-002	R3 carrier beam - 10/14/2024	Application test evidence	Synthetic / controlled

Transcribed note

*Thought the keeper looked out last night - told somebody near the stand.
Check before restart.*

Provenance check

Question	Finding	Status
Who wrote it?	Unknown.	Not established
When was it written?	Found after the event; no reliable creation time.	Not established
Which keeper?	No stand, component, or side identifier appears in the note.	Not established
Was the statement first-hand?	Unknown.	Not established
Does it conflict with other evidence?	The recovered R3 keeper was documented as installed after the fall; pre-event state still requires direct evidence.	Open / reconcile

Forwarded Email - Possible Crane Contact

A synthetic hearsay email with a confident subject line but no first-hand observation. It tests whether the model checks operational logs and source quality.

Document ID	Incident	Record type	Status
R3-CH-003	R3 carrier beam - 10/14/2024	Application test evidence	Synthetic / controlled

Email metadata

From	To	Sent	Subject
Outage distribution list member	R3 investigation mailbox	10/15/2024 - 8:12 AM	Crane probably bumped the carrier beam

Message body

Someone on nights said a crane may have been close to the stand during roll work. That would explain why the beam came loose. I was not in the bay and do not know which crane movement or time they meant.

Source-quality findings

Factor	Finding	Status
First-hand?	No.	Low authority
Identified original speaker?	No.	Not established
Specific time / lift / equipment?	No.	Not established
Relevant evidence comparison	The relevant-interval crane log, controller record, witnesses, and video report no crane activity at the event time.	Contradicted for event interval
Potential residual lead	Earlier roll-removal interaction can be checked against the prior-shift lift records and physical marks.	Open / bounded