

Maintenance Work Order — Completion Report

Document No: WO-001428 | Refinery Operations — Confidential Internal Document

Equipment Tag	V-122	Equipment Type	Control valve
Zone	Hydrotreater	Equipment Status	CRITICAL
Work Type	Corrective	Priority	High
Opened	08 Dec 2023	Closed	13 Dec 2023
Assigned To	Yubaraj Bista (Maintenance Technician)	Downtime	29.9 hours

1. Reported Fault

Corrective action for stem seizure on control valve V-122, hydrotreater unit. Valve was installed 02 Mar 2008 against a 10-year expected service life and is now 8 years past its rated life, consistent with the escalated corrective-maintenance frequency already logged against this asset.

2. Work Performed

Valve was isolated and removed from service. Stem and packing were inspected; seizure was confirmed at the stem-to-bonnet interface, consistent with this valve's documented failure modes (actuator failure, seat leakage, stem seizure, positioner drift). Stem was freed, packing replaced, and actuator response verified through full stroke test before return to service.

3. Downtime Impact

Total recorded downtime for this work order was 29.9 hours. Given the equipment's critical status and age well beyond expected lifespan, this asset is flagged for replacement evaluation rather than continued corrective repair.

4. Recommendation

Recommend V-122 be added to the next capital replacement cycle given it is operating 80% beyond its rated 10-year service life and has accumulated repeated stem-seizure events. Interim measure: reduce inspection interval on this valve to 90 days until replacement.

Completed by	Yubaraj Bista	Signature	
Verified by	Sunil Maharjan (Reliability Engineer)	Date	13 Dec 2023