



RELEASE NOTES

DM NVX

7.1.5259.00068

Product Description

Included Products:

- DM-NVX-350
- DM-NVX-351
- DM-NVX-352
- DM-NVX-360
- DM-NVX-363
- DM-NVX-E760
- DM-NVX-E30
- DM-NVX-D30
- DM-NVX-D80-IOAV
- DM-NVX-350C
- DM-NVX-351C
- DM-NVX-352C
- DM-NVX-360C
- DM-NVX-363C
- DM-NVX-E760C
- DM-NVX-E30C
- DM-NVX-D30C
- DM-NVX-E10
- DM-NVX-E20
- DM-NVX-E20-2G
- DM-NVX-D10
- DM-NVX-D20
- DM-NVX-D200

Item	Value
<i>File name</i>	dm-nvx-35x-enc_7.1.5259.00068_r533719.zip
<i>Products Supported</i>	DM-NVX-350, DM-NVX-351, DM-NVX-352, DM-NVX-350C, DM-NVX-351C, DM-NVX-352C
<i>Version</i>	7.1.5259.00068_r533719
<i>MD5</i>	DD7767AB04218B0BC42554A2D0FE912D
<i>SHA-256</i>	54B971DF82D792B3C1FFFEA796A564C0FE6E1CD7E0C4A4DD81695C5C034FDA88

*The MD5 and SHA-256 reference the zip file.

Item	Value
<i>File name</i>	dm-nvx-ed30-enc_7.1.5259.00068_r533719
<i>Products Supported</i>	DM-NVX-E30,DM-NVX-DE30C,DM-NVX-D30,DM-NVX-D30C
<i>Version</i>	7.1.5259.00068_r533719
<i>MD5</i>	F58D20FE00982F9B6BC099DB4AF14721
<i>SHA-256</i>	B91C127530350399EF5B1F76F58204952016E3121CAB1DD787EB540BF44A1753

*The MD5 and SHA-256 reference the zip file.

Item	Value
<i>File name</i>	dm-nvx-d80-enc_7.1.5259.00068_r533719
<i>Products Supported</i>	DM-NVX-D80-IOAV
<i>Version</i>	7.1.5259.00068_r533719
<i>MD5</i>	1865D6F6B727F719C182C75ED69D5F4B
<i>SHA-256</i>	748E27B3E140AD32C16E3ADB234CDA8A44B6F4882299655A67798F0696B60A62

*The MD5 and SHA-256 reference the zip file.

Item	Value
<i>File name</i>	dm-nvx-36x-enc_7.1.5259.00068_r533719.zip
<i>Products Supported</i>	DM-NVX-360.DM-NVX-363, DM-NVX-360C, DM-NVX-363C
<i>Version</i>	7.1.5259.00068_r533719
<i>MD5</i>	0158CEED2F46B9547895D868475268E2
<i>SHA-256</i>	E74FA0580B49EE46EE80AF7929F8456C03F066E5755AB23BD51E5172E8867055

*The MD5 and SHA-256 reference the zip file.

Item	Value
<i>File name</i>	dm-nvx-e760-enc_7.1.5259.00068_r533719.zip
<i>Products Supported</i>	DM-NVX-E760.DM-NVX-E760C
<i>Version</i>	7.1.5259.00068_r533719
<i>MD5</i>	2B1D172096E0FC369009AE17ED07AE0F
<i>SHA-256</i>	02BD7FCE00950BD2D9F42C7CE465F9DEF4FCC22A932728DAF7ECF59BAD94944E

*The MD5 and SHA-256 reference the zip file.

Item	Value
<i>File name</i>	dm-nvx-ed1020-enc_7.1.5259.00068_r533719.zip
<i>Products Supported</i>	DM-NVX-E10/20/E20-2G and DM-NVX-D10/20/200
<i>Version</i>	7.1.5259.00068_r533719
<i>MD5</i>	340617EC69B73CF81C1E958F5E2F6678
<i>SHA-256</i>	0461AA33B9F352B86A2C3A48F2300EF7186C2B2AD689B26FDF99FC114A0E6D59

*The MD5 and SHA-256 reference the zip file.

Notes and Recommendations

- **Systems using Domain-Joined Authentication will see enhanced behavior in firmware version 7.1 and newer. For more information, please see answer ID: [1001858](#)**
- **To support legacy AD devices on a restored device, one needs to turn off domain joined authentication first.**
- **When integrating New DM NVX Products with existing devices running FW version prior to 7.0, all devices must be operating on firmware version 7.0 or greater.**
- **DM-NVX-E10/20 and D10/20/200 devices may not allow firmware downgrades below 7.0.**
- **For installations requiring IPV6 support, please see answer ID [1001763](#) for more details.**
- **A small portion of NVX endpoints may have a compromised MAC address. This will not affect normal operation but may affect the ability to claim the endpoint in XIO cloud. See answer ID [1000912](#) for more details.**
- NVX will require 8-digit passwords with version 6 or greater. Updating firmware will maintain the existing password. However, restoring an endpoint will then require the new 8-digit password.
- .PUF files are no longer supported above firmware version 5.x. When downgrading from firmware version 5.x or above, please use the .zip file found within the .puf file. See online help answer ID [1000866](#) for more information.
- Starting with version 5.1, authentication will always be enabled. As a result, its best to ensure authentication is enabled prior to updating to version 5.1 or higher.
- When downgrading from a firmware version 3.1.4472.00010 or newer, port selection must be disabled for the downgrade to proceed.
- All NVX endpoints should be operating on the same Major firmware revision. For example, version 2.x.x is not compatible with 3.x.x
- If port selection is disabled, network ports on the NVX should not terminate to the same network as this may create a network loop.
- Dolby Vision displays will require that their EDID is applied to the Dolby Vision source. There are no default EDIDs for Dolby Vision.
- Image previews can support up to three images on a panel simultaneously. For more information, please see online help answer ID [1000807](#)
- The SIMPL windows symbol starting with database version 115.08.002.00, will remove secondary audio, and add a new DM NAX (AES67) audio section. Although the old symbol will have basic functionality for DM NAX (AES67), the new symbol will have to be accepted to expose all of the new features this firmware has to offer. With the exception of stream feedback (Play/Stop), the new DM NAX (AES67) joins have the same names as the legacy Secondary Audio slot. Stream feedback will require an analog equate, as there are more status options with DM-NAX (AES67). The old symbol

will remain in the database and can be exposed under the “discontinued” folder, in the SIMPL windows device library.

- DM NAX (AES67) requires PTP clock to maintain audio synchronization. Although the multicast stream can traverse subnets, the PTP clock is unable to do so without additional support from the switch. A boundary clock or other PTP forwarding mechanism may be necessary. Please consult the switch manufacture for more details on using PTP across multiple subnets.
- USB layer 2 multi device support requires a USB hub at each Host port.
- For more information on the new USB features, please refer to the product manuals.
- When installing 65 or more DM NVX devices, refer to Online Help Answer ID [1000315](#)
- Support for DM-XIO-Director has been added in version 1.3547.00018 or higher, please upgrade firmware when using the DM-XIO-Director.
- When upgrading from a firmware pre-dating version 1.3388.00031, please restore the device after the upgrade is complete. This firmware was only shipped on pre-release units.
- All DM-NVX devices and switches should be set to the same IGMP version. IGMPv2 is recommended unless IGMPv3 features are required.
- When streaming on a Control subnet of a 3 Series Control System refer to Online Help Answer ID [1000315](#)
- Crestron recommends using Google Chrome for firmware updates. When using other browsers, the firmware update may report as failed although it has actually succeeded. Check the firmware version in the status page to confirm a successful firmware update.

System Requirements and Dependencies

The following Software tool and firmware versions (or higher) are recommended:

<i>Device Database</i>	200.330.001.00
<i>SIMPL Windows</i>	4.2800.00.01
<i>DM-NVX-Director</i>	4.0.121
<i>DMF-CI-8</i>	1.3054.00066
<i>Dante Ultimo FW</i>	4.1.6.7
<i>Dante controller</i>	4.1.0.5

Upgrade Instructions

- .PUF files are no longer supported above firmware version 5.x. When downgrading from firmware version 5.x or above, please use the .zip file found within the .puf file. See online help answer ID [1000866](#) for more information.
- Firmware is installed using XiO Cloud, the device’s webpage, or Auto Update via a 3 Series Control System, or using an SFTP server. Crestron Toolbox is not used to install this firmware.

Current Version

7.1.5259.00068

Date: 2024-03-25

File name

dm-nvx-TYPE-enc_7.1.5259.00068_r533719.zip

Known Issues.

- Stream subscription may not updated if the discovery agent is turned off, then back on
- In some cases, and NVX receiver may output a green image when a source is sending Y4:2:0, and the output is set to Y:4:2:2 or RGB
- Samsung 8K display may show incomplete images when the switching between 12 bit color space.
- Removing the NTP time server URL, or disabling the feature may leave the function enabled
- Some test generator patterns may produce incorrect color from E30 and E760
- If IPV6 is disabled in a secure CIP environment, and you are using an IPV6 network, hostnames will not function for control system connections
- Restoring a configuration file will not work if the export folder is different from the import folder
- The setup button may not display the IP address for displays running at Y 4:2:0
- In some cases, refresh rates greater than 60 Hz may not allow for thumbnail image preview
- IPV6 is supported for the primary audio video stream only. NAX and USB routing requires IPV4 support
- IPV6 Secondary DNS is not displayed on the web UI status page
- When disabling DHCP, the system may not call for a reboot.
- FIPS PKCS#12 certificates with non FIPS compliant PBE algorithms fail when the device is in FIPS mode
- Connects user is unable to log into Preview Image
- Zoom aspect ratio may cause image to flicker @ 240 Hz
- Preview image may stop working when using URL Encoding format characters
- DM-NVX-35x lists scaler options that are above 120 Hz refresh rates. Setting the scaler to resolutions above 120 Hz may have unintended results. For more information, please see the product manual.
- Background image remote file path URL will not accept special characters
- NAX port number may not accept manual values. Using the up/down arrow or SIMPL/SIMPL# will allow the user to set the appropriate value
- If the DM-NVX-35x AV route set to none, it may pass audio and or video to the stream or local output.
- Multicast address form SIMPL and SIMPL # may accept invalid values, but will not pass video
- When changing endpoints from point to point mode to traditional configuration, the multicast address will need to be manually changed.
- Authentication screen may be displayed after a reboot. A refresh may be required to clear this error
- When downgrading to 4.x or below, you will not be able to create a custom EDID entry in the lower FW version. All other entries will remain operational.
- Streaming settings cannot be changed on the web interface when Statistics are enabled.
- Unable to delete Active Directory groups with "/" included in the name of the group.
- The DM-NVX requires Username/Password for 802.1x "EAP-TLS Certificate."
- DM-NVX-351 and 363 are unable to down mix some forms of Dolby Atmos (MAT 2.0) and DTSX to PCM 2ch audio.

Fixed Issues

- Security fixes:
 - Fixes a bug that allowed the user to use a console command to switch off usage of SHA-1 algorithm for webserver.
 - Fixes potential exploits in the EDID and Image Upload dialogs where users could execute commands.
 - Fixes a bug where a self-signed certificate password is exposed in the debug log file.
 - Fixes to prevent remote code execution.
 - Updated certificates.

Previous Versions

7.1.5259.00064

File name	
Item	Value
File name	dm-nvx-35x-enc_7.1.5259.00064_r515900.zip
Products Supported	DM-NVX-350, DM-NVX-351, DM-NVX-352, DM-NVX-350C, DM-NVX-351C, DM-NVX-352C
Version	7.1.5259.00064_r515900
MD5	67B451F02F880A04F543455C683B7773
SHA-256	C8C9222FA8D8BB6FB3CF0EB5B30F7A35A676F7530F091CD381486744352BA22E

*The MD5 and SHA-256 reference the internal image_7.1.5259.00064_r515900.zip

Item	Value
File name	dm-nvx-ed30-enc_7.1.5259.00064_r515900
Products Supported	DM-NVX-E30,DM-NVX-DE30C,DM-NVX-D30,DM-NVX-D30C
Version	7.1.5259.00064_r515900
MD5	2602BAD307664788D78E0335C9EE72D5
SHA-256	CF3E6EC232A15CF5C2316EE993CD7619577015AE93E6EB087FBDE658BC39CA3A

*The MD5 and SHA-256 reference the internal image_7.1.5259.00064_r515900.zip

Item	Value
File name	dm-nvx-d80-enc_7.1.5259.00059_r453766
Products Supported	DM-NVX-D80-IOAV
Version	7.1.5259.00064_r515900

<i>MD5</i>	8FDBF2EABFA308BA9CDB7A6A1EF89858
<i>SHA-256</i>	039A78F88D16245A0DF95DC62D2BC1287B8DC56FE7B7C8A5A887E96B858C8ECA

*The MD5 and SHA-256 reference the internal image_7.1.5259.00064_r515900.zip

Item	Value
<i>File name</i>	dm-nvx-36x-enc_7.1.5259.00064_r515900.zip
<i>Products Supported</i>	DM-NVX-360.DM-NVX-363, DM-NVX-360C, DM-NVX-363C
<i>Version</i>	7.1.5259.00064_r515900
<i>MD5</i>	E4266C5B981D65CC9D13B734501801C5
<i>SHA-256</i>	DB88BA5015BFD97028C33E1B6C0D99A3C14863A867683B05F23E561D622DA32

*The MD5 and SHA-256 reference the internal image_7.1.5259.00064_r515900.zip

Item	Value
<i>File name</i>	dm-nvx-e760-enc_7.1.5259.00064_r515900.zip
<i>Products Supported</i>	DM-NVX-E760.DM-NVX-E760C
<i>Version</i>	7.1.5259.00064_r515900
<i>MD5</i>	BEA46D23364EC0ACDBD02F766B8ECFEC
<i>SHA-256</i>	0A3E60357AACB0DA8841805875AF15153E5FCB76C5FBD01ACBCAA20DCE266025

*The MD5 and SHA-256 reference the internal image_7.1.5259.00064_r515900.zip

Item	Value
<i>File name</i>	dm-nvx-ed1020-enc_7.1.5259.00064_r515900.zip
<i>Products Supported</i>	DM-NVX-E10/20/E20-2G and DM-NVX-D10/20/200
<i>Version</i>	7.1.5259.00064_r515900
<i>MD5</i>	95E858F31DFA43FAAAFE86C5D360AAED
<i>SHA-256</i>	3147DE245930D21373193C4AAA3264EB2CF14E81973CEA15F1731CF0C2DB87CA

*The MD5 and SHA-256 reference the internal image_7.1.5259.00064_r515900.zip

Known Issues

- Stream subscription may not updated if the discovery agent is turned off, then back on
- In some cases, and NVX receiver may output a green image when a source is sending Y4:2:0, and the output is RGB
- Samsung 8K display may show incomplete images when the switching between 12 bit color space.
- Removing the NTP time server URL, or disabling the feature may leave the function enabled
- Some test generator patterns may produce incorrect color from E30 and E760
- If IPV6 is disabled in a secure CIP environment, and you are using an IPV6 network, hostnames will not function system connections
- Restoring a configuration file will not work if the export folder is different from the import folder
- The setup button may not display the IP address for displays running at Y 4:2:0

- In some cases, refresh rates greater than 60 Hz may not allow for thumbnail image preview
- IPV6 is supported for the primary audio video stream only. NAX and USB routing requires IPV4 support
- IPV6 Secondary DNS is not displayed on the web UI status page
- When disabling DHCP, the system may not call for a reboot.
- FIPS PKCS#12 certificates with non FIPS compliant PBE algorithms fail when the device is in FIPS mode
- Connects user is unable to log into Preview Image
- Zoom aspect ratio may cause image to flicker @ 240 Hz
- Preview image may stop working when using URL Encoding format characters
- DM-NVX-35x lists scaler options that are above 120 Hz refresh rates. Setting the scaler to resolutions above have unintended results. For more information, please see the product manual.
- Background image remote file path URL will not accept special characters
- NAX port number may not accept manual values. Using the up/down arrow or SIMPL/SIMPL# will allow the appropriate value
- If the DM-NVX-35x AV route set to none, it may pass audio and or video to the stream or local output.
- Multicast address form SIMPL and SIMPL # may accept invalid values, but will not pass video
- When changing endpoints from point to point mode to traditional configuration, the multicast address will manually changed.
- Authentication screen may be displayed after a reboot. A refresh may be required to clear this error
- When downgrading to 4.x or below, you will not be able to create a custom EDID entry in the lower FW ver entries will remain operational.
- Streaming settings cannot be changed on the web interface when Statistics are enabled.
- Unable to delete Active Directory groups with "/" included in the name of the group.
- The DM-NVX requires Username/Password for 802.1x "EAP-TLS Certificate."
- DM-NVX-351 and 363 are unable to down mix some forms of Dolby Atmos (MAT 2.0) and DTSX to PCM 2ch

Fixed Issues

- Resolved an issue with some Intel NUC PCs where multichannel audio may not pass properly
- Reduced switching time between HDMI inputs on the DM-NVX-35x
- Improved video stability for some HDMI sources
- Improved online status with the control system

7.1.5259.00059

File name

Item	Value
<i>File name</i>	dm-nvx-35x-enc_7.1.5259.00059_r504078
<i>Products Supported</i>	DM-NVX-350, DM-NVX-351, DM-NVX-352, DM-NVX-350C, DM-NVX-351C, DM-NVX-352C
<i>Version</i>	7.1.5259.00059
<i>MD5</i>	B61B5FE3C2FB1859181DFBA65A65C8E9
<i>SHA-256</i>	226C3201B7B95A25ACBB711929C868383927EF17F8F295B0529F45B6DB4876E5

*The MD5 and SHA-256 reference the internal image_7.1.5259.00059_r504078

Item	Value
<i>File name</i>	dm-nvx-ed30-enc_7.1.5259.00059_r504078
<i>Products Supported</i>	DM-NVX-E30,DM-NVX-DE30C,DM-NVX-D30,DM-NVX-D30C

<i>Version</i>	7.1.5259.00059
<i>MD5</i>	2CE6B5513B06CC3062371B267375EE54
<i>SHA-256</i>	BBBA479C33CF8BE3E127A4D9401DAC37B183E3BAA688BB7FA42967D2B72E6899

*The MD5 and SHA-256 reference the internal image_7.1.5259.00059_r504078

Item	Value
<i>File name</i>	dm-nvx-d80-enc_7.1.5259.00059_r453766
<i>Products Supported</i>	DM-NVX-D80-IOAV
<i>Version</i>	7.1.5259.00059
<i>MD5</i>	9A45F7E9BEC406F0F3E8E7D6790EDDEA
<i>SHA-256</i>	8C8A81C6CDC97B1B99B1C3A5CF75931249EBAA74F5911A51373EC45E18CBDD94

*The MD5 and SHA-256 reference the internal image_7.1.5259.00059_r504078

Item	Value
<i>File name</i>	dm-nvx-36x-enc_7.1.5259.00059_r504078
<i>Products Supported</i>	DM-NVX-360.DM-NVX-363, DM-NVX-360C, DM-NVX-363C
<i>Version</i>	7.1.5259.00059
<i>MD5</i>	31B1D7C4AD659B89B582E2B5C14C5556
<i>SHA-256</i>	DB88BA5015BFDF97028C33E1B6C0D99A3C14863A867683B05F23E561D622DA32

*The MD5 and SHA-256 reference the internal image_7.1.5259.00059_r504078

Item	Value
<i>File name</i>	dm-nvx-e760-enc_7.1.5259.00059_r504078
<i>Products Supported</i>	DM-NVX-E760.DM-NVX-E760C
<i>Version</i>	7.1.5259.00059
<i>MD5</i>	C9BC10B788AAFFBF98E7EC92A65D00C6
<i>SHA-256</i>	6E84471F97124AB3CE792A9A0CCEE193DD4BBA79131730767ED274CEBE83636C

*The MD5 and SHA-256 reference the internal image_7.1.5259.00059_r504078

Item	Value
<i>File name</i>	dm-nvx-ed1020-enc_7.1.5259.00059_r504078
<i>Products Supported</i>	DM-NVX-E10/20/E20-2G and DM-NVX-D10/20/200
<i>Version</i>	7.1.5259.00059
<i>MD5</i>	96217F9A59BC85F03267243654E4111C

*The MD5 and SHA-256 reference the internal image_7.1.5259.00059_r504078

New Features

- Interoperability updates for Software DM NVX (requires hardware to run Pixel Perfect Processing)
- Support for DM-NVX-E20-2G
- Multi-Factor authentication (for more information see answer ID [1001857](#))
- Backup and restore (for more information please see answer ID [1001859](#))

Known Issues

- Stream subscription may not updated if the discovery agent is turned off, then back on
- In some cases, and NVX receiver may output a green image when a source is sending Y4:2:0, and the output is set to Y:4:2:2 or RGB
- Samsung 8K display may show incomplete images when the switching between 12 bit color space.
- Removing the NTP time server URL, or disabling the feature may leave the function enabled
- Some test generator patterns may produce incorrect color from E30 and E760
- If IPV6 is disabled in a secure CIP environment, and you are using an IPV6 network, hostnames will not function for control system connections
- Restoring a configuration file will not work if the export folder is different from the import folder
- The setup button may not display the IP address for displays running at Y 4:2:0
- In some cases, refresh rates greater than 60 Hz may not allow for thumbnail image preview
- IPV6 is supported for the primary audio video stream only. NAX and USB routing requires IPV4 support
- IPV6 Secondary DNS is not displayed on the web UI status page
- When disabling DHCP, the system may not call for a reboot.
- FIPS PKCS#12 certificates with non FIPS compliant PBE algorithms fail when the device is in FIPS mode
- Connects user is unable to log into Preview Image
- Zoom aspect ratio may cause image to flicker @ 240 Hz
- Preview image may stop working when using URL Encoding format characters
- DM-NVX-35x lists scaler options that are above 120 Hz refresh rates. Setting the scaler to resolutions above 120 Hz may have unintended results. For more information, please see the product manual.
- Background image remote file path URL will not accept special characters
- NAX port number may not accept manual values. Using the up/down arrow or SIMPL/SIMPL# will allow the user to set the appropriate value
- If the DM-NVX-35x AV route set to none, it may pass audio and or video to the stream or local output.
- Multicast address form SIMPL and SIMPL # may accept invalid values, but will not pass video
- When changing endpoints from point to point mode to traditional configuration, the multicast address will need to be manually changed.
- Authentication screen may be displayed after a reboot. A refresh may be required to clear this error
- When downgrading to 4.x or below, you will not be able to create a custom EDID entry in the lower FW version. All other entries will remain operational.
- Streaming settings cannot be changed on the web interface when Statistics are enabled.
- Unable to delete Active Directory groups with "/" included in the name of the group.
- The DM-NVX requires Username/Password for 802.1x "EAP-TLS Certificate."

- DM-NVX-351 and 363 are unable to down mix some forms of Dolby Atmos (MAT 2.0) and DTSX to PCM 2ch audio.

Fixed Issues

- Resolved an issue where DM NAX (AES67) Clock priority was not maintained after a reboot
- Updated time zones to ensure Egypt and Fuji standard time zones function correctly
- Resolved an issue where the device may lose communication over CIP
- Improved web socket connection reliability, where the socket stopped responding after an undetermined period of time

7.1.5259.00030

Date: 2022-09-02

File name dm-nvx-x_7.1.5259.00030.zip

Item	Value
<i>File name</i>	dm-nvx-35x-enc_7.1.5259.00030_r474508
<i>Products Supported</i>	DM-NVX-350, DM-NVX-351, DM-NVX-352, DM-NVX-350C, DM-NVX-351C, DM-NVX-352C
<i>Version</i>	7.1.5259.00030
<i>MD5</i>	C1352F83AE652D35F217D9464D1F1358
<i>SHA-256</i>	FAD78DF49D445B93DA620593EC46AB4558C5FE9A64817351F3B369BEB1E776F

*The MD5 and SHA-256 reference the internal image_7.1.5259.00030_r474508

Item	Value
<i>File name</i>	dm-nvx-ed30-enc_7.1.5259.00030_r474508
<i>Products Supported</i>	DM-NVX-E30,DM-NVX-DE30C,DM-NVX-D30,DM-NVX-D30C
<i>Version</i>	7.1.5259.00030
<i>MD5</i>	F9FB85EF0E0EC744070708C38713E47D
<i>SHA-256</i>	1A7D5525A0C810914C220443421894F3A49962B2D313F4FCA76662774EB669CE

*The MD5 and SHA-256 reference the internal image_7.1.5259.00030_r474508

Item	Value
<i>File name</i>	dm-nvx-d80-enc_7.1.5259.00030_r453766
<i>Products Supported</i>	DM-NVX-D80-IOAV
<i>Version</i>	7.1.5259.00030
<i>MD5</i>	860BCFB874D5CB31C9571A12267E0D16
<i>SHA-256</i>	3B0E909403F9275151094AE1D4B4F8E6D1EF2134386A65F63049517CC527426F

*The MD5 and SHA-256 reference the internal image_7.1.5259.00030_r474508

Item	Value
<i>File name</i>	dm-nvx-36x-enc_7.1.5259.00030_r474508
<i>Products Supported</i>	DM-NVX-360.DM-NVX-363, DM-NVX-360C, DM-NVX-363C
<i>Version</i>	7.1.5259.00030
<i>MD5</i>	6C048B84F066ADB9E2F252418153E36
<i>SHA-256</i>	EF73661D7743B9CAC32BFF7978CF36FC7A258CAC8B8CB3A7679AC6B7796A2345

*The MD5 and SHA-256 reference the internal image_7.1.5259.00030_r474508

Item	Value
<i>File name</i>	dm-nvx-e760-enc_7.1.5259.00030_r474508
<i>Products Supported</i>	DM-NVX-E760.DM-NVX-E760C
<i>Version</i>	7.1.5259.00030
<i>MD5</i>	E1FAB3FC17A1D604A7DF9ED31A5A86CD
<i>SHA-256</i>	092BC0DABD1989168E465EDE0DB31E59951A63A1B7979247B8630AD333C2E934

*The MD5 and SHA-256 reference the internal image_7.1.5259.00030_r474508

Item	Value
<i>File name</i>	dm-nvx-ed1020-enc_7.1.5259.00030_r474508
<i>Products Supported</i>	DM-NVX-E10/20 and DM-NVX-D10/20/200
<i>Version</i>	7.1.5259.00030
<i>MD5</i>	860BCFB874D5CB31C9571A12267E0D16
<i>SHA-256</i>	3B0E909403F9275151094AE1D4B4F8E6D1EF2134386A65F63049517CC527426F

*The MD5 and SHA-256 reference the internal image_7.1.5259.00030_r474508

New Features

- IPV6 support for all models
- DM NAX (AES657) output gain adjustment (All models)

Known Issues.

- IPV6 is supported for the primary audio video stream only. NAX and USB routing requires IPV4 support
- DM NAX (AES657) output gain adjustment is only supported in SIMPL windows under the DM NAX TX Symbol set
- FIPS PKCS#12 certificates with non FIPS compliant PBE algorithms fail when the device is in FIPS mode
- NAX port number can only be changed using copy/paste
- Connects user is unable to log into Preview Image
- Zoom aspect ratio may cause image to flicker @ 240 Hz

- Preview image may stop working when using URL Encoding format characters
- DM-NVX-35x lists scaler options that are above 120 Hz refresh rates. Setting the scaler to resolutions above 120 Hz may have unintended results. For more information, please see the product manual.
- Background image remote file path URL will not accept special characters
- NAX port number may not accept manual values. Using the up/down arrow or SIMPL/SIMPL# will allow the user to set the appropriate value
- If the DM-NVX-35x AV route set to none, it may pass audio and or video to the stream or local output.
- Bitrate feedback in SIMPL/SIMPL# may not show the correct value
- Removing the background image remote path may throw an error message in the web UI
- Multicast address form SIMPL and SIMPL # may accept invalid values, but will not pass video
- Some Logitech cameras may have poor audio quality when routed through NVX USB extension
- When changing endpoints from point to point mode to traditional configuration, the multicast address will need to be manually changed.
- Authentication screen may be displayed after a reboot. A refresh may be required to clear this error
- When downgrading to 4.x or below, you will not be able to create a custom EDID entry in the lower FW version. All other entries will remain operational.
- Streaming settings cannot be changed on the web interface when Statistics are enabled.
- Unable to delete Active Directory groups with "/" included in the name of the group.
- The DM-NVX requires Username/Password for 802.1x "EAP-TLS Certificate."
- DM-NVX-351 and 363 are unable to down mix some forms of Dolby Atmos (MAT 2.0) and DTSX to PCM 2ch audio.

Fixed Issues

- When Vlan is enabled, ports now receive Link Local if no static or DHCP address is present
- Reduced the time it takes 802.1x to authenticate
- Resolved an issue where HDCP mode set to never still required HDCP authentication
- Improved USB traffic when using USB Pass through optical isolators
- Improved USB connectivity for some Apple computers
- Resolved an issue where the USB HID port may continue to execute keystrokes after removing the USB connection
- Improved the D30 and D200 fan control
- 120/240 hz resolution now supports the background image
- Security updates:
 - Improved password enforcement rules
 - Updated Cryptographically TLS keys
 - Fixed an issue where 802.1x trusted certificates could not be changed when port mapping was enabled
 - SFTP/SSH/WebUI sessions have additional limits regarding concurrent sessions in order to prevent potential DoS attack. (NDM-000200, WSR-000001)
 - The device can now be configured such that local password changes require a minimum number of positions in which characters are changed. (NDM-000329) This can be enabled or disabled using a new flag -CHANGE associated with the SETPasswordrule/GETPasswordrule command.

Item	Value
File name	dm-nvx-35x-enc_7.0.5057.00023_r453766.zip
Products Supported	DM-NVX-350, DM-NVX-351, DM-NVX-352, DM-NVX-350C, DM-NVX-351C, DM-NVX-352C
Version	7.0.5057.00023
MD5	CADDDFA94ABB7C01FCC9B77719CC92AB
SHA-256	643464367D5BE7DED64EE8D8F302EE986FA8E5380874A64CD0737C4497DD386D

*The MD5 and SHA-256 reference the internal image_7.0.5057.00023_r453766.zip

Item	Value
File name	dm-nvx-ed30-enc_7.0.5057.00023_r453766.zip
Products Supported	DM-NVX-E30,DM-NVX-DE30C,DM-NVX-D30,DM-NVX-D30C
Version	7.0.5057.00023
MD5	AE0BBDCBD1FC754C129C5CD3B7C8B250
SHA-256	FCA658B22C208F8E772F13A00C22EF9E65DA1AF0A5B32505DC436851B53A839F

*The MD5 and SHA-256 reference the internal image_7.0.5057.00023_r453766.zip

Item	Value
File name	dm-nvx-d80-enc_7.0.5057.00023_r453766
Products Supported	DM-NVX-D80-IOAV
Version	7.0.5057.00023
MD5	0497D231BC5BBE48B674EB7C47E99082
SHA-256	3DD01BFB2F57DA04FF8E0480DCE15216D3FC9665163BD0D87660591D85B398DB

*The MD5 and SHA-256 reference the internal image_7.0.5057.00023_r453766.zip

Item	Value
File name	dm-nvx-36x-enc_7.0.5057.00023_r453766.zip
Products Supported	DM-NVX-360.DM-NVX-363, DM-NVX-360C, DM-NVX-363C
Version	7.0.5057.00023
MD5	447B502FE15B9EA93E609FFE0484FDAB
SHA-256	E6D25F253FF5780EBF0FC26D316C61D8D40E9E3FEEAA85782FEF96EE057C7331

*The MD5 and SHA-256 reference the internal image_7.0.5057.00023_r453766.zip

Item	Value
<i>File name</i>	dm-nvx-e760-enc_7.0.5057.00023_r453766.zip
<i>Products Supported</i>	DM-NVX-E760.DM-NVX-E760C
<i>Version</i>	7.0.5057.00023
<i>MD5</i>	6FA5087D7C399953BE00120CAC459947
<i>SHA-256</i>	0411A070BEFF5648398BFCBEEBA6E219D83303F5C4A9E06843EDAC26A907F09C

*The MD5 and SHA-256 reference the internal image_7.0.5057.00023_r453766.zip

Item	Value
<i>File name</i>	dm-nvx-ed1020-enc_7.0.5057.00023_r453766.zip
<i>Products Supported</i>	DM-NVX-E10/20 and DM-NVX-D10/20/200
<i>Version</i>	7.0.5057.00023
<i>MD5</i>	8C29198BADC17353DF98943F0FE07706
<i>SHA-256</i>	8C29198BADC17353DF98943F0FE07706

*The MD5 and SHA-256 reference the internal image_7.0.5057.00023_r453766.zip

New Features

- Variable bitrate support for the following products:
 - DM-NVX-35x(c)
 - DM-NVX-36x(c)
 - DM-NVX-E760(c)
 - DM-NVX-E30/D30(c)
- 1920x1080 @120 Hz refresh rates for the following products:
 - DM-NVX-35x(c)
 - DM-NVX-36x(c)
 - DM-NVX-E30(c) and D30(c)
- 1920x1080 @ 240 Hz refresh rates for the following products:
 - DM-NVX-36x(c)
 - DM-NVX-E30(c) and D30(c)
- DM-NVX-36x-USB HID additional keystroke support for entry/exit mode
 - DM-NVX-36x only
- DM-NNVX-35x feature updates including:
 - Image freeze
 - Image preview
 - Background image
 - Stream type selection
 - Test Pattern Generator
- Support for DM-NVX-D200
 - Supports 4K60 4:2:0
 - Scaler included
 - Video wall support

Known Issues.

- DM-NVX-35x lists scaler options that are above 120 Hz refresh rates. Setting the scaler to resolutions above 120 Hz may have unintended results. For more information, please see the product manual.
- Background image remote file path URL will not accept special characters
- Background image and OSD may not work with refresh rates above 60 Hz.
- NAX port number may not accept manual values. Using the up/down arrow or SIMPL/SIMPL# will allow the user to set the appropriate value
- If the DM-NVX-35x AV route set to none, it may pass audio and or video to the stream or local output.
- Bitrate feedback in SIMPL/SIMPL# may not show the correct value
- Removing the background image remote path may throw an error message in the web UI
- Multicast address form SIMPL and SIMPL # may accept invalid values, but will not pass video
- At first boot, the DM-NVX-D30 fan will run, and a black output signal will be present until the stream is started, and stopped the first time.
- Changing the test pattern resolution may cause the image to become blue/yellow. Restart the test pattern generator to resolve the issue
- An API change was made in version 6 that modified the stream name from "stream1" to "stream01". A leading zero was incorporated to ensure uniformity across product lines.
- Some Logitech cameras may have poor audio quality when routed through NVX USB extension
- In some cases, removing and adding background images may cause a random loaded image to appear. This can be resolved by selecting a specific image after loading new images.
- Clearing the OSD while the feature is enabled, may leave the first character. Setting the feature "off" will resolve this issue.
- When changing endpoints from point to point mode to traditional configuration, the multicast address will need to be manually changed.
- Authentication screen may be displayed after a reboot. A refresh may be required to clear this error
- When downgrading to 4.x or below, you will not be able to create a custom EDID entry in the lower FW version. All other entries will remain operational.
- Streaming settings cannot be changed on the web interface when Statistics are enabled.
- Unable to delete Active Directory groups with "/" included in the name of the group.
- The DM-NVX requires Username/Password for 802.1x "EAP-TLS Certificate."
- DM-NVX-351 and 363 are unable to down mix some forms of Dolby Atmos (MAT 2.0) and DTSX to PCM 2ch audio.

Fixed Issues

- Clearing a route will now immediately set the output to black for all models.
- Resolved an issue where the endpoint may not show its link local address.
- Reduced authentication time when using Active Directory
- Improved audio lock time for all NVX models
- DM-NVX-D30 will no longer run the fan, and pass sync when no signal is present.
- Improved handling of SD card read/write cycles
- Improved reporting of CEC data through the API
- Resolved an issue where 2560x853@ 60 Hz would not pass through NVX
- LLDP information now reports properly in SIMPL/SIMPL#
- Image preview feedback data no longer prints messages to the log
- Security updates for all models

6.0.4835.00046

Date: 2021-11-02

File name	dm-nvx-x_6.0.4835.00046.zip
-----------	-----------------------------

Item	Value
File name	dm-nvx_6.0.4835.00046.zip
Products Supported	DM-NVX-350, DM-NVX-351, DM-NVX-352, DM-NVX-350C, DM-NVX-351C, DM-NVX-352C
Version	6.0.4835.00046
MD5	1297AF99C5B0177A36851C778878971A
SHA-256	EB9392984B54E48949D79E9DC52884DE5061A7FB65DADC30808D753D106B9BB3

*The MD5 and SHA-256 reference the internal image_6.0.4835.00046_r429553.zip

Item	Value
File name	dm-nvx_6.0.4835.00046.zip
Products Supported	DM-NVX-E30,DM-NVX-DE30C,DM-NVX-D30,DM-NVX-D30C
Version	6.0.4835.00046
MD5	
SHA-256	

*The MD5 and SHA-256 reference the internal image_6.0.4835.00046_r429553.zip

Item	Value
File name	dm-nvx_6.0.4835.00046.zip
Products Supported	DM-NVX-D80-IOAV
Version	6.0.4835.00046
MD5	7C2EF3AFF19A5C48D43E3CF60FB11F41
SHA-256	BBB8D7B204F0B144586C4D7AA1B93FE231FA86223F6012660BC6960604D4DFA2

*The MD5 and SHA-256 reference the internal image_6.0.4835.00046_r429553.zip

Item	Value
File name	dm-nvx_6.0.4835.00046.zip
Products Supported	DM-NVX-360.DM-NVX-363, DM-NVX-360C, DM-NVX-363C
Version	6.0.4835.00046
MD5	B1E2B44DD74311C8DA5B3436A77AB0CF
SHA-256	49A51C24BB5D48F09E6B1FA12BD5066660736368CCE0A8AFF083130BCA0629A0

*The MD5 and SHA-256 reference the internal image_6.0.4835.00046_r429553.zip

Item	Value
<i>File name</i>	dm-nvx_6.0.4835.00046.zip
<i>Products Supported</i>	DM-NVX-E760.DM-NVX-E760C
<i>Version</i>	6.0.4835.00046
<i>MD5</i>	304C364C27DDBEE0DFA65321C54661D9
<i>SHA-256</i>	1EE832AF9D6D0AF88AB3826ADB66C87C48408F29C192EE556A4E1104F5283480

*The MD5 and SHA-256 reference the internal image_6.0.4835.00046_r429553.zip

Item	Value
<i>File name</i>	dm-nvx_6.0.4835.00046.zip
<i>Products Supported</i>	DM-NVX-E10/20 and DM-NVX-D10/20
<i>Version</i>	6.0.4835.00046
<i>MD5</i>	A11229B31085FC9C5E299A7456DF23DA
<i>SHA-256</i>	621F6DB83003ED723AE41A31C906DE6F026FCB4DDA498C21E0CC5C83E8EE741F

*The MD5 and SHA-256 reference the internal image_6.0.4835.00046_r429553.zip

New Features

- Added support for the following products:
 - DM-NVX-E10
 - DM-NVX-E20
 - DM-NVX-D10
 - DM-NVX-D20

Known Issues.

- An API change was made in version 6 that modified the stream name from “stream1” to “stream01”. A leading zero was incorporated to ensure uniformity across product lines.
- Some Logitech cameras may have poor audio quality when routed through NVX USB extension
- In some cases, removing and adding background images may cause a random loaded image to appear. This can be resolved by selecting a specific image after loading new images.
- Clearing the OSD while the feature is enabled, may leave the first character. Setting the feature “off” will resolve this issue.
- When changing endpoints from point to point mode to traditional configuration, the multicast address will need to be manually changed.
- Authentication screen may be displayed after a reboot. A refresh may be required to clear this error
- When downgrading to 4.x or below, you will not be able to create a custom EDID entry in the lower FW version. All other entries will remain operational.
- When upgrading the DM-NVX-35x, if analog audio was the selected audio source, it may revert to “Audio Follows Video”. This can be resolved in the web UI, or via SIMPL programming.
- Streaming settings cannot be changed on the web interface when Statistics are enabled.
- Unable to delete Active Directory groups with “/” included in the name of the group.

- When a CA certificate is added to the web interface, the page must be manually refreshed in order to update the list.
- The DM-NVX requires Username/Password for 802.1x “EAP-TLS Certificate.”
- Crestron recommends using Google Chrome for firmware updates. When using other browsers, the firmware update may report as failed although it has actually succeeded. Check the firmware version in the status page to confirm a successful firmware update.
- DM-NVX-351 and 363 are unable to down mix some forms of Dolby Atmos (MAT 2.0) and DTSX to PCM 2ch audio.

Fixed Issues

- Improved POE power negotiation where a continual reboot may occur
- Added default NAX session name so it will no longer be blank
- Resolved an issue where DM-NVX-Director will not come online when port mapping is enabled
- Improved background image aspect ratio for products that support this feature
- The Under-scan drop down now reflects proper value (Scaler models only)
- Resolved an issue where the domain name was not being displayed properly
- NAX audio may be lost if the video Multicast address was set to 0.0.0.0
- Resolved a device response timeout error when changing device credentials
- Test pattern generator renders images properly for all resolutions (Supported models only)
- Security improvements
 - Eliminated a command injection vulnerability from the background image server path
 - Ensured SNMP updates are available when FIPS mode is enabled

6.0.4835.00027

Date: 2021-07-20

File name dm-nvx-x_6.0.4835.00027.zip

Item	Value
<i>File name</i>	dm-nvx_6.0.4835.00027.zip
<i>Products Supported</i>	DM-NVX-350, DM-NVX-351, DM-NVX-352, DM-NVX-350C, DM-NVX-351C, DM-NVX-352C
<i>Version</i>	6.0.4835.00027
<i>MD5</i>	A0A0FC45FDE409F6A9060399967FCD7E
<i>SHA-256</i>	A8D33C764B277525C3E82783B87A668FE8D81D776A27129BC0264DABC7D0E046

*The MD5 and SHA-256 reference the internal image_6.0.4835.00027_r416525.zip

Item	Value
<i>File name</i>	dm-nvx_6.0.4835.00027.zip
<i>Products Supported</i>	DM-NVX-E30,DM-NVX-DE30C,DM-NVX-D30,DM-NVX-D30C
<i>Version</i>	6.0.4835.00027
<i>MD5</i>	B82DCA34134957645E368A528D2C9F37
<i>SHA-256</i>	C3F7201E7950CE3023CB20AB54D5F84D765F8CC831645AEB619804C5AB28D5B5

*The MD5 and SHA-256 reference the internal image_6.0.4835.00027_r416525.zip

Item	Value
<i>File name</i>	dm-nvx_6.0.4835.00027.zip
<i>Products Supported</i>	DM-NVX-D80-IOAV
<i>Version</i>	6.0.4835.00027
<i>MD5</i>	FF5BBB9FA135F5BF9E60B031C5D02CCB
<i>SHA-256</i>	6212F6163EC7A26740B0D77D4B6EC2FA47FCD1A2ACEEF661216DF8E68493CA44

*The MD5 and SHA-256 reference the internal image_6.0.4835.00027_r416525.zip

Item	Value
<i>File name</i>	dm-nvx_6.0.4835.00027.zip
<i>Products Supported</i>	DM-NVX-360.DM-NVX-363, DM-NVX-360C, DM-NVX-363C
<i>Version</i>	6.0.4835.00027
<i>MD5</i>	729E33D2EA3D48FA42F0BE2A8BB6C6AF
<i>SHA-256</i>	4E5D8AACAB59A7D1EF7980BF063BAE07113C7A85F71BA1BC5FFA5A786DF6EE47

*The MD5 and SHA-256 reference the internal image_6.0.4835.00027_r416525.zip

Item	Value
<i>File name</i>	dm-nvx_6.0.4835.00027.zip
<i>Products Supported</i>	DM-NVX-E760.DM-NVX-E760C
<i>Version</i>	6.0.4835.00027
<i>MD5</i>	11E9CA436CAC89CAF67907E77697B055
<i>SHA-256</i>	0E3FCB96E585C1D49E7855770EDB0DF87EDBBE84E4660A9F16351EED8FC77D82

*The MD5 and SHA-256 reference the internal image_6.0.4835.00027_r416525.zip

New Features

- Updates for DM-NVX-36x (Encoder)/E30/E760
 - Test pattern generator
 - Image Freeze Detection
- Updates for DM-NVX-36x (Decoder)/D30/D80-IOAV
 - Background image
 - Image Freeze Detection
- Port mapping (DM-NVX-E760 updated)
- Automatic Point to point mode

Known Issues.

- An API change was made in version 6 that modified the stream name from “stream1” to “stream01”. A leading zero was incorporated to ensure uniformity across product lines.
Some Logitech cameras may have poor audio quality when routed through NVX USB extension

- In some cases, removing and adding background images may cause a random loaded image to appear. This can be resolved by selecting a specific image after loading new images.
- Background images may not appear after a power cycle.
- Test pattern generator may not render 3840x2160 @ 60 Y4:2:0 correctly for all patterns
- Underscan may not work when values are selected from the drop down. Using the incremental values will resolve this issue.
- Clearing the OSD while the feature is enabled, may leave the first character. Setting the feature “off” will resolve this issue.
- When changing endpoints from point to point mode to traditional configuration, the multicast address will need to be manually changed .
- Authentication screen may be displayed after a reboot. A refresh may be required to clear this error
- When downgrading to 4.x or below, you will not be able to create a custom EDID entry in the lower FW version. All other entries will remain operational.
- When upgrading the DM-NVX-35x, if analog audio was the selected audio source, it may revert to “Audio Follows Video”. This can be resolved in the web UI, or via SIMPL programming.
- Streaming settings cannot be changed on the web interface when Statistics are enabled.
- Unable to delete Active Directory groups with “/” included in the name of the group.
- When a CA certificate is added to the web interface, the page must be manually refreshed in order to update the list.
- The DM-NVX requires Username/Password for 802.1x “EAP-TLS Certificate.”
- Crestron recommends using Google Chrome for firmware updates. When using other browsers, the firmware update may report as failed although it has actually succeeded. Check the firmware version in the status page to confirm a successful firmware update.
- DM-NVX-351 and 363 are unable to down mix some forms of Dolby Atmos (MAT 2.0) and DTSX to PCM 2ch audio.

Fixed Issues

- Improved HBR audio stability to some AVRs such as Trinnov and Lingdorf
- Resolved an issue with dropped video or audio on some USB cameras including Huddly IQ
- Resolved an issue where the DSP source selection would reset after a power cycle, or source switch
- Security enhancements

5.2.4651.00030 (NIAP)

Date: 2022-22-2

<i>File name</i>	dm-nvx-x_6.0.4835.00046.zip
------------------	-----------------------------

Item	Value
<i>File name</i>	dm-nvx-35x-enc_5.2.4651.00030.zip
<i>Products Supported</i>	DM-NVX-350, DM-NVX-351, DM-NVX-352, DM-NVX-350C, DM-NVX-351C, DM-NVX-352C
<i>Version</i>	5.2.4651.00030
<i>MD5</i>	6A1089D53697BEE579FB272994F9E2C8
<i>SHA-256</i>	F904F72A7856AC09EA76CC14BA6881319CBB36A614490F78D03D840E723A6BB9

*The MD5 and SHA-256 reference the internal image_5.2.4651.00030_r433262.zip

Item	Value
<i>File name</i>	dm-nvx-ed30-enc_5.2.4651.00030.zip
<i>Products Supported</i>	DM-NVX-E30,DM-NVX-DE30C,DM-NVX-D30,DM-NVX-D30C
<i>Version</i>	5.2.4651.00030
<i>MD5</i>	9906617245276B4996FBB2FFC93B41E0
<i>SHA-256</i>	2B1125A3D3D9EFCDF885CB7374BF6FADE91932E4E899D0F4EDB1656824F169CE

*The MD5 and SHA-256 reference the internal image_5.2.4651.00030_r433262.zip

Item	Value
<i>File name</i>	dm-nvx-d80-enc_5.2.4651.00030.zip
<i>Products Supported</i>	DM-NVX-D80-IOAV
<i>Version</i>	5.2.4651.00030
<i>MD5</i>	46BF2F82D6544F93E6F089D52B1742A5
<i>SHA-256</i>	3E9732E38A2D37D2716BC98D211E58DC51DD72C15D9262CA35505B1763322203

*The MD5 and SHA-256 reference the internal image_5.2.4651.00030_r433262.zip

Item	Value
<i>File name</i>	dm-nvx-36x-enc_5.2.4651.00030.zip
<i>Products Supported</i>	DM-NVX-360.DM-NVX-363, DM-NVX-360C, DM-NVX-363C
<i>Version</i>	5.2.4651.00030
<i>MD5</i>	086A980428C4404EF48B5AFA02B23379
<i>SHA-256</i>	8A5ACE4AFFBB67F9F8A00D3EB039C8B49F302770A38AFD37DA3D13C4EE037971

*The MD5 and SHA-256 reference the internal image_5.2.4651.00030_r433262.zip

Item	Value
<i>File name</i>	dm-nvx-e760-enc_5.2.4651.00030.zip
<i>Products Supported</i>	DM-NVX-E760.DM-NVX-E760C
<i>Version</i>	5.2.4651.00030
<i>MD5</i>	AB8722977A49BB9E065600C3534A404B
<i>SHA-256</i>	0195ED649CDF1DA89FBFBA9A66A0FD288797F3035867B102BD6358977CACDEF7

*The MD5 and SHA-256 reference the internal image_5.2.4651.00030_r433262.zip

New Features

- Official JITC supported version for the following products:
 - **DM-NVX-350**
 - **DM-NVX-351**

- **DM-NVX-352**
- **DM-NVX-360***
- **DM-NVX-363**
- **DM-NVX-E760**
- **DM-NVX-E30**
- **DM-NVX-D30**
- **DM-NVX-D80-IOAV**
- **DM-NVX-350C**
- **DM-NVX-351C**
- **DM-NVX-352C**
- **DM-NVX-360C**
- **DM-NVX-363C**
- **DM-NVX-E760C**
- **DM-NVX-E30C**
- **DM-NVX-D30C**

Known Issues.

- A reboot is required to finalize the configuration of all 802.1x settings.
- “rsyslog ssl” will not work with nxlog server until fipsmode is disabled, and set to “tlscipher compatibility” is enabled
- Some Cisco switches using UPOE may cause the endpoint to reboot continuously. An external power adaptor may be required. See OLH [5791](#) for additional details
- Some Logitech cameras may have poor audio quality when routed through NVX USB extension
- In some cases, removing and adding background images may cause a random loaded image to appear. This can be resolved by selecting a specific image after loading new images.
- Clearing the OSD while the feature is enabled, may leave the first character. Setting the feature “off” will resolve this issue.
- When changing endpoints from point to point mode to traditional configuration, the multicast address will need to be manually changed.
- Authentication screen may be displayed after a reboot. A refresh may be required to clear this error
- When downgrading to 4.x or below, you will not be able to create a custom EDID entry in the lower FW version. All other entries will remain operational.
- When upgrading the DM-NVX-35x, if analog audio was the selected audio source, it may revert to “Audio Follows Video”. This can be resolved in the web UI, or via SIMPL programming.
- Streaming settings cannot be changed on the web interface when Statistics are enabled.
- Unable to delete Active Directory groups with “/” included in the name of the group.
- When a CA certificate is added to the web interface, the page must be manually refreshed in order to update the list.
- The DM-NVX requires Username/Password for 802.1x “EAP-TLS Certificate.”
- Crestron recommends using Google Chrome for firmware updates. When using other browsers, the firmware update may report as failed although it has actually succeeded. Check the firmware version in the status page to confirm a successful firmware update.
- DM-NVX-351 and 363 are unable to down mix some forms of Dolby Atmos (MAT 2.0) and DTSX to PCM 2ch audio.

Item	Value
File name	dm-nvx_5.2.465100018.zip
Products Supported	DM-NVX-350, DM-NVX-351, DM-NVX-352, DM-NVX-350C, DM-NVX-351C, DM-NVX-352C
Version	5.2.465100018
MD5	E864D5D96650E70E7A4BA1B87910D19F
SHA-256	FBD826B01C9E054178EA9310A7E272FDEB4739FBAC8354738C89BABDE7E115C3

*The MD5 and SHA-256 reference the internal image_5.2.4651.00018_r400406.zip.

Item	Value
File name	dm-nvx_5.2.465100018.zip
Products Supported	DM-NVX-E30,DM-NVX-DE30C,DM-NVX-D30,DM-NVX-D30C
Version	5.2.465100018
MD5	6670B6A71565701305286C9CB283F1E2
SHA-256	E383321073286A6D3E0743DAD5665D4BF9B3279EBB27BC79924D1369B4E75903

*The MD5 and SHA-256 reference the internal image_5.2.4651.00018_r400406.zip.

Item	Value
File name	dm-nvx_5.2.465100018.zip
Products Supported	DM-NVX-D80-IOAV
Version	5.2.465100018
MD5	D5D1CFD960DA66E5350587F65C2813CA
SHA-256	DB7B8DBE66475F07ACB5A50DB481CC6BE9A8348C7B7F2A2E655A1CCA090772A3

*The MD5 and SHA-256 reference the internal image_5.2.4651.00018_r400406.zip.

Item	Value
File name	dm-nvx_5.2.465100018.zip
Products Supported	DM-NVX-360.DM-NVX-363, DM-NVX-360C, DM-NVX-363C
Version	5.2.465100018
MD5	5DF30838DC33FEFCB421E5D9DB8FB32C
SHA-256	21407AACA553ECA2257B169F476731C0E4A20BD0CD501818230B96B48352E7D5

*The MD5 and SHA-256 reference the internal image_5.2.4651.00018_r400406.zip

Item	Value
File name	dm-nvx_5.2.465100018.zip
Products Supported	DM-NVX-E760.DM-NVX-E760C
Version	5.2.465100018
MD5	7E1E1EEF191E5D6CC96A5DF228961883
SHA-256	29FBC474036D7057AB82BED6BC1FC19539835C58DF3B9221B6A13EE21FE36DE0

*The MD5 and SHA-256 reference the internal image_5.2.4651.00018_r400406.zip.

Known Issues.

- Authentication screen may be displayed after a reboot. A refresh may be required to clear the error
- The DM-NVX-E760 LED Disable will not disable the LEDs for the HDBT port.
- The DM-NVX-36x LED Disable will not disable the LEDs for copper port # 3
- When downgrading to 4.x or below, you will not be able to create a custom EDID entry in the lower FW version. All other entries will remain operational.
- When upgrading to version 5.1, custom DSCP values may change to default
- Lan port # 3 on the DM-NVX-36x may take up to 2 minutes to register a change to the interface
- When upgrading the DM-NVX-35x, if analog audio was the selected audio source, it may revert to "Audio Follows Video". This can be resolved in the web UI, or via SIMPL programming.
- Stream subscriptions may be lost when downgrading from version 3.x to version 2.x.
- Streaming settings cannot be changed on the web interface when Statistics are enabled
- Unable to delete Active Directory groups with "/" included in the name of the group
- When a CA certificate is added to the web interface, the page must be manually refreshed in order to update the list
- The DM-NVX requires Username/Password for 802.1x "EAP-TLS Certificate."
- Crestron recommends using Google Chrome for firmware updates. When using other browsers, the firmware update may report as failed although it has actually succeeded. Check the firmware version in the status page to confirm a successful firmware update.
- DM-NVX-351 and 363 are unable to down mix some forms of Dolby Atmos (MAT 2.0) and DTSX to PCM 2ch audio.

Fixed Issues

- DM-NVX-D30 and D80 fan now turns off when set to "auto", if the stream is no longer present
- API updates ensure that all DM NVX endpoint names report consistently
- USB Hotkey now reports raw data in the serial join "Message_F". This ensure that the default USB data reports for all keys, up to the standard 104 key layout.
- Resolved video connectivity for Vaddio Roboshot with the E760 (HDBT)
- Web UI auto save improvements
- Security enhancements

5.1.4651.00035

Date: 2021-03-19

File name	dm-nvx-x_5.1.4651.00035.zip
-----------	-----------------------------

Item	Value
------	-------

<i>File name</i>	dm-nvx_5.1.4651.00035.zip
<i>Products Supported</i>	DM-NVX-350, DM-NVX-351, DM-NVX-352, DM-NVX-350C, DM-NVX-351C, DM-NVX-352C
<i>Version</i>	5.1.4651.00035
<i>MD5</i>	D1D5E185B4E9F4EE361209D69615B74C
<i>SHA-256</i>	7D242AF266BCFF99F1694C26CA4F34916A0BEED0E9FC563E3FB95E1DF2A0BE1E

*The MD5 and SHA-256 reference the internal image_5.1.4651.00035_r395707.zip.

Item	Value
<i>File name</i>	dm-nvx_5.1.4651.00035.zip
<i>Products Supported</i>	DM-NVX-E30,DM-NVX-DE30C,DM-NVX-D30,DM-NVX-D30C
<i>Version</i>	5.1.4651.00035
<i>MD5</i>	D991AB83A0A581346AC26BEC41F86012
<i>SHA-256</i>	487856D05F72A4DBAED21132C1621B3268709389D14049CC4C9E21C3D520C392

*The MD5 and SHA-256 reference the internal image_5.1.4651.00035_r395707.zip.

Item	Value
<i>File name</i>	dm-nvx_5.1.4651.00035.zip
<i>Products Supported</i>	DM-NVX-D80-IOAV
<i>Version</i>	5.1.4651.00035
<i>MD5</i>	1AC97DED9FD016D25F14911A736E529A
<i>SHA-256</i>	C4317582C5CEC5F4E66955CE21C40C25A8DA8C13BA1EF2F191CED43562E61471

*The MD5 and SHA-256 reference the internal image_5.1.4651.00035_r395707.zip.

Item	Value
<i>File name</i>	dm-nvx_5.1.4651.00035.zip
<i>Products Supported</i>	DM-NVX-360.DM-NVX-363, DM-NVX-360C, DM-NVX-363C
<i>Version</i>	5.1.4651.00035
<i>MD5</i>	6FBAA46312C2B162BAAD7BD19AE2E12B
<i>SHA-256</i>	F2356358FF92953740A58C67C7F687F4FC1C3EE48445D1F39336C927628BADD9

*The MD5 and SHA-256 reference the internal image_5.1.4651.00035_r395707.zip

Item	Value
<i>File name</i>	dm-nvx_5.1.4651.00035.zip
<i>Products Supported</i>	DM-NVX-E760.DM-NVX-E760C
<i>Version</i>	5.1.4651.00035

MD5	875F643FF00DD6AB252C6FA6ED665F46
SHA-256	5E922F766FA722879B5EDCA60AB7B8E3CC162F3ABE804B658E4BE38F3E97411D

*The MD5 and SHA-256 reference the internal image_5.1.4651.00035_r395707.zip.

New Features

Support for MAC Address updates (See OLH# [1000912](#) for more details)

Known Issues.

- Authentication screen may be displayed after a reboot. A refresh may be required to clear the error
- The DM-NVX-E760 LED Disable will not disable the LEDs for the HDBT port.
- The DM-NVX-36x LED Disable will not disable the LEDs for copper port # 3
- The USB-HID Message serial string does not support all keyboard functions
- When downgrading to 4.x or below, you will not be able to create a custom EDID entry in the lower FW version. All other entries will remain operational.
- When upgrading to version 5.1, custom DSCP values may change to default
- The Fan in the D30 will not shut off when stream is no longer present. This functionality will be restored in the next release.
- Lan port # 3 on the DM-NVX-36x may take up to 2 minutes to register a change to the interface
- When upgrading the DM-NVX-35x, if analog audio was the selected audio source, it may revert to "Audio Follows Video". This can be resolved in the web UI, or via SIMPL programming.
- Stream subscriptions may be lost when downgrading from version 3.x to version 2.x.
- Streaming settings cannot be changed on the web interface when Statistics are enabled
- Unable to delete Active Directory groups with "/" included in the name of the group
- When a CA certificate is added to the web interface, the page must be manually refreshed in order to update the list
- The DM-NVX requires Username/Password for 802.1x "EAP-TLS Certificate."
- Crestron recommends using Google Chrome for firmware updates. When using other browsers, the firmware update may report as failed although it has actually succeeded. Check the firmware version in the status page to confirm a successful firmware update.
- DM-NVX-351 unable to down mix some forms of Dolby Atmos and DTSX to PCM 2ch audio.

5.1.4651.00031

Date: 2021-01-18

File name	dm-nvx-x_5.1.4651.00031.zip
-----------	-----------------------------

Item	Value
File name	dm-nvx_5.1.4651.00031.zip
Products Supported	DM-NVX-350, DM-NVX-351, DM-NVX-352, DM-NVX-350C, DM-NVX-351C, DM-NVX-352C
Version	5.1.4651.00031
MD5	183CBECE8D52DA6CCA8C7AB693030B20
SHA-256	07AAC13973720ED1D70C336C94E74480C3BA3C13C4FEF293BB2FF27A2D406737

*The MD5 and SHA-256 reference the internal image_5.1.4651.00031.zip.

Item	Value
<i>File name</i>	dm-nvx_5.1.4651.00031.zip
<i>Products Supported</i>	DM-NVX-E30,DM-NVX-DE30C,DM-NVX-D30,DM-NVX-D30C
<i>Version</i>	5.1.4651.00031
<i>MD5</i>	D7CEFC58343A103CF3531BCC5DCF26BF
<i>SHA-256</i>	250F3A5009EB4C73EF8773108BD01ED48C8F638DD2EB6D82C4CBF0DEA9BFEEEE0

*The MD5 and SHA-256 reference the internal image_5.1.4651.00031_r388783.zip.

Item	Value
<i>File name</i>	dm-nvx_5.1.4651.00031.zip
<i>Products Supported</i>	DM-NVX-D80-IOAV
<i>Version</i>	5.1.4651.00031
<i>MD5</i>	A412BF4B771A01ABA0625C11021CDD34
<i>SHA-256</i>	F65F2A8AC5FCC12BD93B1B0B173392792E9C35D0F51702BF486F924FD9847ECF

*The MD5 and SHA-256 reference the internal image_5.1.4651.00031_r388783.zip.

Item	Value
<i>File name</i>	dm-nvx_5.1.4651.00031.zip
<i>Products Supported</i>	DM-NVX-360.DM-NVX-363, DM-NVX-360C, DM-NVX-363C
<i>Version</i>	5.1.4651.00031
<i>MD5</i>	D30017AB5F3F626BE54857EDA2E5E550
<i>SHA-256</i>	770E38071C6C49BBE19FFB01E7FC53DE7CADF920CB3C346AE384BDC0C1040F21

*The MD5 and SHA-256 reference the internal image_5.1.4651.00031_r388783.zip

Item	Value
<i>File name</i>	dm-nvx_5.1.4651.00031.zip
<i>Products Supported</i>	DM-NVX-E760.DM-NVX-E760C
<i>Version</i>	5.1.4651.00031
<i>MD5</i>	A7CB12096281060FD068D08FB22A51E9
<i>SHA-256</i>	4404F77C2F32F13A72C27E6438C62D564D635E2B86CE3B401E80F04032274262

*The MD5 and SHA-256 reference the internal image_5.1.4651.00031_r388783.zip.

New Features

- Support for the DM-NVX-E760(c)
- Updates for the DM-NVX-E30 and D30:
 - Dolby Vision and HDR 10 + support

- Image preview
- Updates for the DM-NVX-360(c) and 363(c)
 - USB Hot Key support
- Endpoint LED controls
- Improved web UI
- PTP Domain controls (See Online Help Answer ID [1000866](#) for more details)
- Security Updates

Known Issues.

- Authentication screen may be displayed after a reboot. A refresh may be required to clear the error
- The DM-NVX-E760 LED Disable will not disable the LEDs for the HDBT port.
- The DM-NVX-36x LED Disable will not disable the LEDs for copper port # 3
- The USB-HID Message serial string does not support all keyboard functions
- When downgrading to 4.x or below, you will not be able to create a custom EDID entry in the lower FW version. All other entries will remain operational.
- When upgrading to version 5.1, custom DSCP values may change to default
- The Fan in the D30 will not shut off when stream is no longer present. This functionality will be restored in the next release.
- Lan port # 3 on the DM-NVX-36x may take up to 2 minutes to register a change to the interface
- When upgrading the DM-NVX-35x, if analog audio was the selected audio source, it may revert to "Audio Follows Video". This can be resolved in the web UI, or via SIMPL programming.
- Stream subscriptions may be lost when downgrading from version 3.x to version 2.x.
- Streaming settings cannot be changed on the web interface when Statistics are enabled
- Unable to delete Active Directory groups with "/" included in the name of the group
- When a CA certificate is added to the web interface, the page must be manually refreshed in order to update the list
- The DM-NVX requires Username/Password for 802.1x "EAP-TLS Certificate."
- Crestron recommends using Google Chrome for firmware updates. When using other browsers, the firmware update may report as failed although it has actually succeeded. Check the firmware version in the status page to confirm a successful firmware update.
- DM-NVX-351 unable to down mix some forms of Dolby Atmos and DTSX to PCM 2ch audio.

Fixed Issues

- The fan control has been exposed for the DM-NVX-36x line of products. Please see Online Help Answer ID [1000866](#) for more details
- LLDP Joins now show all available feedback
- CEC functionality has been corrected on the 36x
- Image preview now supports all content

4.1.4472.00024

Date: 2020-10-03

File name

dm-nvx-35x_4.1.4472.00024.zip/puf

Item	Value
File name	dm-nvx_4.1.4472.00024.zip /.puf

<i>Products Supported</i>	DM-NVX-350, DM-NVX-351, DM-NVX-352, DM-NVX-350C, DM-NVX-351C, DM-NVX-352C, DM-NVX-E30, DM-NVX-DE30C, DM-NVX-D30, DM-NVX-D30C
<i>Version</i>	4.1.4472.00024
<i>MD5</i>	917C9FF07F00252F4783A893A3412A10
<i>SHA-256</i>	EF2E8223D2DA3805B236FB2C2CC96752988B2B05153BD84C064B1FAC2CF48C46

*The MD5 and SHA-256 reference the internal image_4.1.4472.00024_r381143.zip

Item	Value
<i>File name</i>	dm-nvx_4.1.4472.00024.zip
<i>Products Supported</i>	DM-NVX-D80-IOAV
<i>Version</i>	4.1.4472.00024
<i>MD5</i>	A2B251A71C64AF3B153BC28875A56022
<i>SHA-256</i>	F30ED0C961CF2262714F74807064B39F532A6E07ADF8F7D30F76AF69322C5408

*The MD5 and SHA-256 reference the internal image_4.1.4472.00024_r381143.zip

Item	Value
<i>File name</i>	dm-nvx_4.1.4472.00024.zip
<i>Products Supported</i>	DM-NVX-360.Dm-NVX-363, Dm-NVX-360C, DM-NVX-363C
<i>Version</i>	4.1.4472.00024
<i>MD5</i>	41CD1630A0A502180B6DF9883888D8BC
<i>SHA-256</i>	7D61C2C9E68A9734325A8721274FFF1C261A96786D2C54C48D9DC226BE41BE87

*The MD5 and SHA-256 reference the internal image_4.1.4472.00024_r381143.zip

Known Issues.

- When port selection is enabled, some LLDP joins may not show proper feedback
- Lan port # 3 on the DM-NVX-36x may take up to 2 minutes to register a change to the interface
- Image Preview does not support HDCP protected content as of this release
- Static DNS entries are only available for the management port
- When upgrading the DM-NVX-35x, if analog audio was the selected audio source, it may revert to "Audio Follows Video". This can be resolved in the web UI, or via SIMPL programming.
- When updating firmware from version 2.x to 3.x, the web UI progress bar may not disappear once the firmware update is complete.
- Stream subscriptions may be lost when downgrading from version 3.x to version 2.x.
- Streaming settings cannot be changed on the web interface when Statistics are enabled
- Unable to delete Active Directory groups with "/" included in the name of the group
- When a CA certificate is added to the web interface, the page must be manually refreshed in order to update the list
- The DM-NVX requires Username/Password for 802.1x "EAP-TLS Certificate."

- Crestron recommends using Google Chrome for firmware updates. When using other browsers, the firmware update may report as failed although it has actually succeeded. Check the firmware version in the status page to confirm a successful firmware update.
- DM-NVX-351 unable to down mix some forms of Dolby Atmos and DTSX to PCM 2ch audio.

Fixed Issues

- Log file was unable to be downloaded from XIO cloud
- Removing the LAN cable on the courtesy port of a Transmitter could cause video flicker in the Receiver side
- Audio and Video stream would stop after a network cable remove and reinstallation for daisy chain configurations
- Resolved an issue where the password could be printed to the downloaded error log under specific circumstances
-

4.1.4472.00021

Date: 2020-09-29

<i>File name</i>	dm-nvx-35x_4.1.4472.00021.zip/puf
------------------	-----------------------------------

Item	Value
<i>File name</i>	dm-nvx_4.1.4472.00021.zip /.puf
<i>Products Supported</i>	DM-NVX-350, DM-NVX-351, DM-NVX-352, DM-NVX-350C, DM-NVX-351C, DM-NVX-352C,DM-NVX-E30,DM-NVX-DE30C,DM-NVX-D30,DM-NVX-D30C
<i>Version</i>	4.1.4472.00021
<i>MD5</i>	043ED76F16938D0C60AFB337B80C4BDCFE ECB094
<i>SHA-256</i>	273FAB66B3FE24E5621E3922B7D207C6B3ED63EC2289D3189537E5722AD96DDE

*The MD5 and SHA-256 reference the internal image_4.1.4472.00021_r376172.zip

Item	Value
<i>File name</i>	dm-nvx_4.1.4472.00021.zip
<i>Products Supported</i>	DM-NVX-D80-IOAV
<i>Version</i>	4.1.4472.00021
<i>MD5</i>	DC5C0D26F112CCD32C7686BC9118D26D
<i>SHA-256</i>	C8EB251529FBD54500A93CE52B8FB04CBA8B4577696D21F921BE5EA827853308

*The MD5 and SHA-256 reference the internal image_4.1.4472.00021_r376172.zip

Item	Value
<i>File name</i>	dm-nvx_4.1.4472.00021.zip
<i>Products Supported</i>	DM-NVX-360.Dm-NVX-363, Dm-NVX-360C, DM-NVX-363C
<i>Version</i>	4.1.4472.00021

MD5	B9AB1E374F60CABEC155E47A35012122
SHA-256	78EC0ACB0940B948FE7CC7A6B4FE40D2C1A523D369112B70C8830BB667B5D783

*The MD5 and SHA-256 reference the internal image_4.1.4472.00021_r376172.zip

New Features

- Support for the DM-NVX-360(c) and 363(c) products with the following new features:
 - Dolby Vision
 - HDR 10 +
 - Dante (DM-NVX-363)
 - DSP Down mix (DM-NVX-363)
 - Image Preview
- Security improvements

Known Issues.

- When port selection is enabled, some LLDP joins may not show proper feedback
- Lan port # 3 on the DM-NVX-36x may take up to 2 minutes to register a change to the interface
- Image Preview does not support HDCP protected content as of this release
- Static DNS entries are only available for the management port
- When upgrading the DM-NVX-35x, if analog audio was the selected audio source, it may revert to "Audio Follows Video". This can be resolved in the web UI, or via SIMPL programming.
- When updating firmware from version 2.x to 3.x, the web UI progress bar may not disappear once the firmware update is complete.
- Stream subscriptions may be lost when downgrading from version 3.x to version 2.x.
- Streaming settings cannot be changed on the web interface when Statistics are enabled
- Unable to delete Active Directory groups with "/" included in the name of the group
- When a CA certificate is added to the web interface, the page must be manually refreshed in order to update the list
- The DM-NVX requires Username/Password for 802.1x "EAP-TLS Certificate."
- Crestron recommends using Google Chrome for firmware updates. When using other browsers, the firmware update may report as failed although it has actually succeeded. Check the firmware version in the status page to confirm a successful firmware update.
- DM-NVX-351 unable to down mix some forms of Dolby Atmos and DTSX to PCM 2ch audio.

Fixed Issues

- When NVX is used without an IGMP querier in point to point applications, the stream will no longer shut down after 4 minutes

3.1.4472.00010

Date: 2020-08-04

File name dm-nvx-35x_3.1.4472.00010.zip/puf

Item	Value
File name	dm-nvx_3.1.4472.00010.zip /.puf
Products Supported	DM-NVX-350, DM-NVX-351, DM-NVX-352, DM-NVX-350C, DM-NVX-351C, DM-NVX-352C, DM-NVX-E30, DM-NVX-DE30C, DM-NVX-D30, DM-NVX-D30C
Version	3.1.4472.00010

MD5	88863EE38E1BF83D6C20398C3396F668
SHA-256	F8CF7408E462FB28866547D6BD03879C6020DBB0B0839EE610208C420BF7AFCA

*The MD5 and SHA-256 reference the internal image_3.1.4472.00010_r367403.zip

Item	Value
File name	dm-nvx_3.1.4472.00010.zip
Products Supported	DM-NVX-D80-IOAV
Version	3.1.4472.00010
MD5	F5E9AAD3A93D50A089D294B6A57AEF3A
SHA-256	190AFACCB09BE35B11754CCF835FD556ACEA6F702050AC51BB677FA89DEDA813

*The MD5 and SHA-256 reference the internal image_3.1.4472.00010_r367403.zip

New Features

- Network port selection for the 35x product line

Known Issues

- In networks that do not contain a querier, the stream may shut down after 4 minutes.
- When port selection is enabled, some LLDP joins may not show proper feedback
- Static DNS entries are only available for the management port
- When upgrading the DM-NVX-35x, if analog audio was the selected audio source, it may revert to “Audio Follows Video”. This can be resolved in the web UI, or via SIMPL programming.
- When updating firmware from version 2.x to 3.x, the web UI progress bar may not disappear once the firmware update is complete.
- Stream subscriptions may be lost when downgrading from version 3.x to version 2.x.
- Streaming settings cannot be changed on the web interface when Statistics are enabled
- Unable to delete Active Directory groups with “/” included in the name of the group
- When a CA certificate is added to the web interface, the page must be manually refreshed in order to update the list
- The DM-NVX requires Username/Password for 802.1x “EAP-TLS Certificate.”
- Crestron recommends using Google Chrome for firmware updates. When using other browsers, the firmware update may report as failed although it has actually succeeded. Check the firmware version in the status page to confirm a successful firmware update.
- DM-NVX-351 unable to down mix some forms of Dolby Atmos and DTSX to PCM 2ch audio.

Fixed Issues

- DM NAX (AES67) Multicast address was unable to be set from SIMPL in some circumstances
- D30 Audio may not be properly selected after upgrade to 3.0

3.0.4472.00077

Date: 2020-07-07

File name dm-nvx-35x_3.0.4472.00077.zip/puf

Item	Value
<i>File name</i>	dm-nvx_3.0.4472.00077.zip /.puf
<i>Products Supported</i>	DM-NVX-350, DM-NVX-351, DM-NVX-352, DM-NVX-350C, DM-NVX-351C, DM-NVX-352C,DM-NVX-E30,DM-NVX-DE30C,DM-NVX-D30,DM-NVX-D30C
<i>Version</i>	3.0.4472.00077
<i>MD5</i>	ED1D1C1FF6D38DF9052517AC7F2FCB63
<i>SHA-256</i>	0062C793C207DDB72EADC3334D2D758ED080F55B7A63D2400914CB70097353FC

*The MD5 and SHA-256 reference the internal image_3.0.4472.00077_r364282.zip

Item	Value
<i>File name</i>	dm-nvx_3.0.4472.00077.zip
<i>Products Supported</i>	DM-NVX-D80-IOAV
<i>Version</i>	3.0.4472.00077
<i>MD5</i>	C4913AA950F6074AF0BE59DC370F672A
<i>SHA-256</i>	AD48B97436B21450C763F8AE86404047C0A0CA3FE1F476991DF53676DF7FB600

*The MD5 and SHA-256 reference the internal image_3.0.4472.00077_r364282.zip

New Features

- DM NAX (AES67)
- Image Freeze
- Adaptive Bitrate
- USB Layer 3 Encryption
- Automatic Power Control
- Switching speed improvements
- LLDP feedback in SIMPL and C#
- USB and NAX audio routing for subscribed streams

Known Issues

- When upgrading the DM-NVX-D30 to version 3.0, the audio may need to be selected to “Primary Stream Audio” via the web UI or through SIMPL programming.
- When upgrading the DM-NVX-35x, if analog audio was the selected audio source, it may revert to “Audio Follows Video”. This can be resolved in the web UI, or via SIMPL programming.
- When updating firmware from version 2.x to 3.x, the web UI progress bar may not disappear once the firmware update is complete.
- Stream subscriptions may be lost when downgrading from version 3.x to version 2.x.
- Streaming settings cannot be changed on the web interface when Statistics are enabled
- Unable to delete Active Directory groups with “/” included in the name of the group
- When a CA certificate is added to the web interface, the page must be manually refreshed in order to update the list
- The DM-NVX requires Username/Password for 802.1x “EAP-TLS Certificate.”

- Crestron recommends using Google Chrome for firmware updates. When using other browsers, the firmware update may report as failed although it has actually succeeded. Check the firmware version in the status page to confirm a successful firmware update.
- DM-NVX-351 unable to down mix some forms of Dolby Atmos and DTSX to PCM 2ch audio.
- Database version 115.06.00.00 does not contain the updated features (listed above) in SIMPL# pro. These updates will be in the next database release.

Fixed issues

- Improved interoperability for Vaddio AV Bridge
- Reduced audio pause when switching between audio formats
- Resolved an issue when the system time was set to GMT.

2.1.3900.01116 (JITC)

Date: 2020-01-29

File name dm-nvx-35x_2.1.3900.01116.puf

Item	Value
<i>File name</i>	dm-nvx-35x_2.1.3900.01116.zip / dm-nvx_2.1.3900.01116.puf
<i>Products Supported</i>	DM-NVX-350, DM-NVX-351, DM-NVX-352, DM-NVX-350C, DM-NVX-351C, DM-NVX-352C
<i>Version</i>	2.1.3900.01116
<i>MD5</i>	08B499C83EE62A2808FC522BABF1C809
<i>SHA-256</i>	5A1F80D976E7DE9954187B0F87E5A5C22DFCD1D79463A190FEC05A02E1450A01

*The MD5 and SHA-256 reference the internal image_2.1.3900.01116_r342283.zip

Item	Value
<i>File name</i>	dm-nvx_2.1.3900.01116.puf
<i>Products Supported</i>	DM-NVX-E30, DM-NVX-E30C, DM-NVX-D30, DM-NVX-D30C
<i>Version</i>	2.1.3900.01116
<i>MD5</i>	25C8B94A610FDA73DD837B8B03CC954A
<i>SHA-256</i>	AAE43B37D8E19B3A273DD2B7EC64A211E9EA82B757D6FAAB46F7D66AFABB1BE4

*The MD5 and SHA-256 reference the internal image_2.1.3900.01116_r342283.zip

New Features

- This firmware package addresses issue specific to Crestron production test. There are no user-facing changes included in this version.
- JITC certified

Known Issues

- Streaming settings cannot be changed on the web interface when Statistics are enabled
- Unable to delete Active Directory groups with "/" included in the name of the group

- When a CA certificate is added to the web interface, the page must be manually refreshed in order to update the list
- The DM-NVX requires Username/Password for 802.1x “EAP-TLS Certificate.”
- Crestron recommends using Google Chrome for firmware updates. When using other browsers, the firmware update may report as failed although it has actually succeeded. Check the firmware version in the status page to confirm a successful firmware update.
- DM-NVX-351 unable to down mix Dolby Atmos and DTSX to PCM 2ch audio.

2.1.3900.01115

Date: 2019-12-15

File name dm-nvx-35x_2.1.3900.01115.puf

Item	Value
<i>File name</i>	dm-nvx-35x_2.1.3900.01115.zip / dm-nvx_2.1.3900.01115.puf
<i>Products Supported</i>	DM-NVX-350, DM-NVX-351, DM-NVX-352, DM-NVX-350C, DM-NVX-351C, DM-NVX-352C
<i>Version</i>	2.1.3900.01115
<i>MD5</i>	F6D0058DF52222A387F5003F0D6F45B7
<i>SHA-256</i>	5CCC49B4C958F94AB03B3629861D8AE58263930E653716504B732DC63FC48CA9

*The MD5 and SHA-256 reference the internal image_2.1.3900.01115_r337114.zip

Item	Value
<i>File name</i>	dm-nvx_2.1.3900.01115.puf
<i>Products Supported</i>	DM-NVX-E30, DM-NVX-E30C, DM-NVX-D30, DM-NVX-D30C
<i>Version</i>	2.1.3900.01115
<i>MD5</i>	896B6CAE10E99B2F10D8BDC35A0405B1
<i>SHA-256</i>	63E07B9F868EF0FACC7A1839B8C141C9A78AADEE73B113DD835B47FF8BA2E7AF

*The MD5 and SHA-256 reference the internal image_2.1.3900.01115_r340057.zip

New Features

- Reduced stream switching times
- Additional security features
 - Automatically ends management sessions when user access level changes
 - Generates an audit log message when internal storage is 75% of maximum storage
 - Added support for secondary NTP time source
 - Added support for authenticated NTP time sources
 - Added support to notify the administrator of the number of successful login attempts during a specific time period
 - Enhanced web server security features including audit logging of all user actions, support for user locking, and support for banner display on login for some secure locations.

Known Issues

- Streaming settings cannot be changed on the web interface when Statistics are enabled
- Unable to delete Active Directory groups with “/” included in the name of the group
- When a CA certificate is added to the web interface, the page must be manually refreshed in order to update the list
- The DM-NVX requires Username/Password for 802.1x “EAP-TLS Certificate.”
- Crestron recommends using Google Chrome for firmware updates. When using other browsers, the firmware update may report as failed although it has actually succeeded. Check the firmware version in the status page to confirm a successful firmware update.
- DM-NVX-351 unable to down mix Dolby Atmos and DTSX to PCM 2ch audio.

Fixed Issues

- Interoperability improvements for Dell USB-C adaptors model DA-300
- Interoperability improvements for Calibre video processors
- Improvements for video signals at 1920 x 1200 @ 120 Hz resolutions
- Reduced white flashes with Direct TV receivers when changing channels, or resolutions

2.1.3900.01078

Date: 2019-6-11

File name dm-nvx-35x_2.1.3900.01078.puf

Item	Value
<i>File name</i>	dm-nvx-35x_2.1.3900.01078.zip / dm-nvx_2.1.3900.01078.puf
<i>Products Supported</i>	DM-NVX-350, DM-NVX-351, DM-NVX-352, DM-NVX-350C, DM-NVX-351C, DM-NVX-352C
<i>Version</i>	2.1.3900.01078
<i>MD5</i>	31619E22895B2F4110CE32C280673D26
<i>SHA-256</i>	F687AD64C9DDC653E5ABC27D188CF0C4026B9909B6DD53B5CAD614181A89E21B

*The MD5 and SHA-256 reference the internal image_2.1.3900.01078_r319841

Item	Value
<i>File name</i>	dm-nvx_2.1.3900.01078.puf
<i>Products Supported</i>	DM-NVX-E30, DM-NVX-E30C, DM-NVX-D30, DM-NVX-D30C
<i>Version</i>	2.1.3900.01078
<i>MD5</i>	295016D3DA06036A5FE42D931324C831
<i>SHA-256</i>	DA9CF066426F6D2F2CD5059CFC122DAE5E88840AD6C10015DED14B3484319F5D

*The MD5 and SHA-256 reference the internal image_2.1.3900.01078_r319841

New Features

- USB Layer 2 Multiple Device Support
- DM-NVX Layer 3 USB Routing Support

- Support for USB-EXT-DM devices with DM NVX USB Routing
- Fan control for the D30

Known Issues

- Streaming settings cannot be changed on the web interface when Statistics are enabled
- Unable to delete Active Directory groups with “/” included in the name of the group
- When a CA certificate is added to the web interface, the page must be manually refreshed in order to update the list
- The DM-NVX requires Username/Password for 802.1x “EAP-TLS Certificate.”
- Crestron recommends using Google Chrome for firmware updates. When using other browsers, the firmware update may report as failed although it has actually succeeded. Check the firmware version in the status page to confirm a successful firmware update.
- DM-NVX-351 unable to down mix Dolby Atmos and DTSX to PCM 2ch audio.

Fixed Issues

- Interoperability improvements for Vaddio Roboshot cameras
- Enhanced RS-232 Control response time when multiple messages are sent
- Video is lost when a Samsung Television is powered down for long periods of time
- Security improvements

2.0.3900.00056

Date: 2019-3-1

File name dm-nvx-35x_2.0.3900.01056.zip

Item	Value
File name	dm-nvx-35x_2.0.3900.00056.zip / dm_nv_x_2.0.3900.00056.puf
Products Supported	DM-NVX-350, DM-NVX-351, DM-NVX-352, DM-NVX-350C, DM-NVX-351C, DM-NVX-352C
Version	2.0.3900.00056
MD5	A88B9C602B0FF38E240455DB3BF449DB
SHA-256	342976DAB17B5981979BF5F814A82C9B071674B3C2CACA6BC879D3D88113EC5A

*The MD5 and SHA-256 reference the internal image_2.0.3900.00056_r314792

Item	Value
File name	dm_nv_x_2.0.3900.00056.puf
Products Supported	DM-NVX-E30, DM-NVX-E30C, DM-NVX-D30, DM-NVX-D30C
Version	2.0.3900.00056
MD5	E8335C7A926199D7EA93F7CFDDA6AE86
SHA-256	6B7454507E5301E96DCDD3907FB704A4C305827F9E87D40CB2DC4FFB24331950

*The MD5 and SHA-256 reference the internal image_2.0.3900.00056_r314792

Known Issues

- Streaming settings cannot be changed on the web interface when Statistics are enabled
- Unable to delete Active Directory groups with “/” included in the name of the group

- When a CA certificate is added to the web interface, the page must be manually refreshed in order to update the list
- The DM-NVX requires Username/Password for 802.1x “EAP-TLS Certificate.”
- Crestron recommends using Google Chrome for firmware updates. When using other browsers, the firmware update may report as failed although it has actually succeeded. Check the firmware version in the status page to confirm a successful firmware update.
- DM-NVX-351 unable to down mix Dolby Atmos and DTSX to PCM 2ch audio.

Fixed Issues

- DM-NVX-Director (DM-XIO-Director) enter multiple IPIDs into DM NVX device when reconfiguring devices within a domain.

2.0.3900.00049

Date: 2019-02-05

File name dm-nvx-35x_2.0.3900.01069.zip

Item	Value
<i>File name</i>	dm-nvx-35x_2.0.3900.00049.zip / dm_nvx_2.0.3900.00049.puf
<i>Products Supported</i>	DM-NVX-350, DM-NVX-351, DM-NVX-352, DM-NVX-350C, DM-NVX-351C, DM-NVX-352C
<i>Version</i>	2.0.3900.00049
<i>MD5</i>	99A5486206810D7B6260B288267A8E6E
<i>SHA-256</i>	E4BE7487885783D117AB70E56FE982508B36EECCC39F48EDE628C034A09E20CC

*The MD5 and SHA-256 reference the internal image_2.0.3900.00049_r314792

Item	Value
<i>File name</i>	dm_nvx_2.0.3900.00049.puf
<i>Products Supported</i>	DM-NVX-E30, DM-NVX-E30C, DM-NVX-D30, DM-NVX-D30C
<i>Version</i>	2.0.3900.00049
<i>MD5</i>	35C5123917E17CBBB523F3CD70EA9844
<i>SHA-256</i>	059F29AB811BD0104A046807B9DDA9241E01A699E28B5879EBF01725DE3E3B76

*The MD5 and SHA-256 reference the internal image_2.0.3900.00049_r314792

New Features

- Pixel Perfect Processing
- Lower End to End latency
- Support for New Products
- Support for VC4 Room IDs
- Initial release for the DM-NVX-352 and DM-NVX-352C with Dante/AES-67 support.

Known Issues

- Streaming settings cannot be changed on the web interface when Statistics are enabled
- Unable to delete Active Directory groups with “/” included in the name of the group
- When a CA certificate is added to the web interface, the page must be manually refreshed in order to update the list
- The DM-NVX requires Username/Password for 802.1x “EAP-TLS Certificate.”
- Crestron recommends using Google Chrome for firmware updates. When using other browsers, the firmware update may report as failed although it has actually succeeded. Check the firmware version in the status page to confirm a successful firmware update.
- DM-NVX-351 unable to down mix Dolby Atmos and DTSX to PCM 2ch audio.

Fixed Issues

- Web interface controls for blank output enabled was incorrectly feeding back it's state
- Interoperability improvements for large scale Cisco SG and catalyst series installations.
- Araknis Networks and Pakedown Network switches only operate via in DM NVX IGMP v3 mode.
- Sony displays incorrectly reports 4K24 resolutions, when a 4K60 resolution is expected.
- Improvement in the connection speed of the USB Pairing between DM NVX devices.
- Audio Delay does not function correctly from SIMPL Windows.
- Fixed multiple Security vulnerabilities.

1.0.3626.00053

Date: 2019-4-1

File name

dm-nvx-35x_1.0.3626.00053.zip

New Features

- Lower End to End latency
- Gen-locked video output for spot-on synchronization
- Cross-network video routing with ability to adjust Time to Live (TTL) – Default is five (5)
- Capability to separate Device Name from Hostname
- Ability to subscribe and unsubscribe to multiple streams at once using the XiO-Subscriptions webpage
- Ability to copy local output EDID on HDMI Input page
- Capability to save and download HDMI Output CEDID file
- DM-NVX-35xC reports chassis and slot information in web interface and SIMPL Windows
- Auto-Update capabilities on the device page
- Ability to change device mode via setup button when using a DM-NVX-35x
- Ability to change device mode, video, and audio selection via DMF-CI-8 front panel when using DM-NVX-35xC
- Network joins now available in SIMPL windows
- Added horizontal and vertical bezel compensation and blank output controls to the HDMI Output page of the web interface
- Web Page titles now include the device name and IP address
- Capability to enable Secure CIP
- Stream resolution and audio details now available on Stream page of web interface
- Support for UPOE compliant Ethernet switches

Known Issues

- Streaming settings cannot be changed on the web interface when Statistics are enabled

- Unable to delete Active Directory groups with “/” included in the name of the group
- When a CA certificate is added to the web interface, the page must be manually refreshed in order to update the list
- The DM-NVX requires Username/Password for 802.1x “EAP-TLS Certificate.”
- Crestron recommends using Google Chrome for firmware updates. When using other browsers, the firmware update may report as failed although it has actually succeeded. Check the firmware version in the status page to confirm a successful firmware update.
- DM-NVX-351 unable to down mix Dolby Atmos and DTSX to PCM 2ch audio.

Fixed Issues

- Improved HDMI output video and audio performance
- Improved de-interlacer performance for viewing interlaced content
- RS-232 TX serial strings may stop if receiving large amounts of RS-232 data
- Loss of data when controlling a Cisco SX-20 with RS-232
- Unable to pass-through Dante traffic through the DM-NVX courtesy ports
- Improved switching performance with the DM-XiO-Director
- SyncDetected_F for XiO-Subscriptions in SIMPL Windows did not update when connecting and disconnecting sources to a transmitter
- Device randomly reboots due to excessive CEC polling
- NVX does not support auto-negotiation on the SFP port. When using SFPs ensure the switch is configured not to use auto-negotiation. The NVX SFP Link and Activity LEDs will be active in this state
- Unable to view VGA source content connecting a DMPS3-300-C to a DM-NVX-35x(C)
- Panasonic Blu-Ray players and Xbox One in sleep mode trigger false sync detects
- Unable to join certain Active Directory groups
- Stopping a transmitter stream may cause the subscription list to reorder
- DM-NVX-35xC status does not update properly in DMF-CI-8 after power cycle of chassis
- Unable to open DM-NVX web UI using hostname
- DM-NVX password vulnerability detailed in OLH 5471
- DM-NVX-351 Lip-sync issues when transmitting or receiving streams
- When switching between HDR and non-HDR content LG televisions continued to output HDR, follow OLH 1000123 for solution

1.3547.00018

Date: 2017-12-07

Item	Value
<i>File name</i>	dm-nvx-350_dm-nvx-350c_dm-nvx-351_dm-nvx-351c_1.3547.00018.zip
<i>Version</i>	1.3547.00018
<i>MD5</i>	31EA47750DCF65740453A98C67747270
<i>SHA-256</i>	39E5FBE00085D8C2997CC13FA5DC41EE89E4271E2A08F037B257F7321A8220B0

*The MD5 and SHA-256 reference the internal image_1.3547.00018_r258994.zip

New Features

- Added support for the DM-XIO-Director
- When a DHCP server is not present in DHCP mode, the DM-NVX will receive a Link-Local IP address automatically

Known Issues

- Streaming settings cannot be changed on the web interface when Statistics are enabled
- Unable to delete Active Directory groups with “/” included in the name of the group
- When a CA certificate is added to the web interface, the page must be manually refreshed in order to update the list
- The DM-NVX requires Username/Password for 802.1x “EAP-TLS Certificate.” If using a certificate that does not require a username/password for EAP/TLS please contact Crestron True Blue Support.
- NVX does not support auto-negotiation on the SFP port. When using SFPs ensure the switch is configured not to use auto-negotiation. The NVX SFP Link and Activity LEDs will be active in this state.
- Crestron recommends using Google Chrome for firmware updates. When using other browsers, the firmware update may report as failed although it has actually succeeded. Check the firmware version in the status page to confirm a successful firmware update.

Fixed Issues

- Added the ability to enter the username and password for secure CIP in the web interface.
- Improved web interface stability

1.3450.00029

Date: 2017-10-29

Item	Value
<i>File name</i>	dm-nvx-350_dm-nvx-350c_dm-nvx-351_dm-nvx-351c_1.3450.00029.zip
<i>Version</i>	1.3388.00029
<i>MD5</i>	CBAC7986317B4B7C9C1C9D92D75EB1D5
<i>SHA-256</i>	B4857B41039EDA138207BEAA9F7A4F6FAC5A3FE1E9A6869E87C3AC68023043C0

Known Issues

- Unable to delete Active Directory groups with “/” included in the name of the group
- When a CA certificate is added to the web interface, the page must be manually refreshed in order to update the list
- The DM-NVX requires Username/Password for 802.1x “EAP-TLS Certificate.” If using a certificate that does not require a username/password for EAP/TLS please contact Crestron True Blue Support.
- NVX does not support auto-negotiation on the SFP port. When using SFPs ensure the switch is configured not to use auto-negotiation. The NVX SFP Link and Activity LEDs will be active in this state.
- Crestron recommends using Google Chrome for firmware updates. When using other browsers, the firmware update may report as failed although it has actually succeeded. Check the firmware version in the status page to confirm a successful firmware update.

Fixed Issues

- Addresses issue where limited number of DM-NVX transmitters are unable to subscribe to DM-NVX receivers.
- After power cycling, rebooting, or firmware upgrades the device may change from transmitter to receiver mode. NOTE: The fix will take affect when upgrading from 1.3450.00029 to a higher version of firmware. After upgrading please verify your mode of operation.

Item	Value
<i>File name</i>	dm-nvx-350_dm-nvx-350c_dm-nvx-351_dm-nvx-351c_1.3388.00051.zip
<i>Version</i>	1.3388.00051
<i>MD5</i>	4B1F91E0934782F63AF7367930032CD3
<i>SHA-256</i>	FB26220F55AFB397E2CE51D653AB7AB299DBC4E8BCBB33C3913F57CAF6B7E482

New Features

- USB connection capabilities are now available in the web interface
- IGMP version is now controllable on the web interface. IGMPv2 is the default IGMP messaging mode on the DM-NVX, however this firmware upgrade will not change existing settings. If upgrading a device from 1.3388.00051 or earlier, the IGMP Version can be changed on the network page. A device restore will set the device to IGMPv2.
 - Crestron recommends all devices and switches operate with the same IGMP version
- Help documentation is now included in the web Interface
- All video, audio, and stream routing ability is now contained on the “Routing” tab of the web interface

Known Issues

- Unable to delete Active Directory groups with “/” included in the name of the group
- When a CA certificate is added to the web interface, the page must be manually refreshed in order to update the list
- The DM-NVX requires Username/Password for 802.1x “EAP-TLS Certificate.” If using a certificate that does not require a username/password for EAP/TLS please contact Crestron True Blue Support.
- SFP LED Link and Activity information may not always properly reflect the current link status of the device and the switch

Fixed Issues

- 802.1x settings do not reset when the DM-NVX is restored
- Secondary audio stream stops and does not restart until device reboot or power cycle
- Unable to stream with a Cisco Catalyst switch without the presence of an MRouter
 - This issue is now resolved by using IGMPv2 as the default

Item	Value
<i>File name</i>	dm-nvx-350_dm-nvx-350c_dm-nvx-351_dm-nvx-351c_1.3388.00051.zip
<i>Version</i>	1.3388.00051
<i>MD5</i>	14DAA015FF1CAD38B94C723A3E7DA454
<i>SHA-256</i>	8F7CBFC07F8914DB3B3D188818CAF8B9D5470264AC22EF5264CD6499F153E470

Fixed Issues

- Subscriptions report in the incorrect order when power is lost
- Subscriptions load in the incorrect order when loading a saved .xiolist configuration file
- Available streams fail to report on the Subscriptions page with certain devices

1.3388.00049Date: 2017-6-1

Item	Value
<i>File name</i>	dm-nvx-350_dm-nvx-350c_dm-nvx-351_dm-nvx-351c_1.3388.00049.zip
<i>Version</i>	1.3388.00049
<i>MD5</i>	52E38ABAC8EA5D5C13CD8258557C0234
<i>SHA-256</i>	FB8CEF7284C9F7C4C97FA5374EA9FF402D8507B21C534A33BDC453C632400152

Fixed Issues

- Improved HDMI output switching performance when using XIO subscription based routing
- 2CH audio would not pass after hot-plugging the HDMI output multiple times

1.3388.00031Date: 2017-5-1

Item	Value
<i>File name</i>	dm-nvx-350_dm-nvx-350c_dm-nvx-351_dm-nvx-351c_1.3388.00031.zip
<i>Version</i>	1.3388.00049
<i>MD5</i>	8589321E5B1FFFC35F5A1BFA3CCFE1F0
<i>SHA-256</i>	AEE01664FB69939A229199CC0837B10CF4400BB84713569ED574D0BC10CE81BC

Initial Release

Licensing and Copyright Information

Certain Crestron products contain open source software. For specific information, please visit www.crestron.com/opensource