SANDARD OPERATING PROCEDURE Form Rev. No.01

Form No.: EHSMSM/446/4013 Form Rev. No.01 Effective date: 01.04.2009

SOP No:-	CRM/TS/SOP/CGL#2-SPM/16	Effective Date	25-2-2024	REVISION No	04
SOP DESC	WORK HANDLING IN SPM OF CGL # 2	Document No			
DEPARTMENT & SECTION	Cold Rolling Mill – CGL2 SPM	Page	1 of 5		

Step	Activity	Associated	Responsibility	Process / tools / PPEs (HOW)	Remarks /
No.	(WHAT)	Requirements/Hazards/Impacts	(WHO)		Reference
No.	(WHAT) Bringing Sending Work Roll From To Roll Shop through trailer	SAFETY: 1) Work roll may fall from the trailer 2) Trailer may hit the Shutter or Exit looper structure/	Activity to be carried out by Trailer Operator Supervision by SPM associate	wheels/fuel) PPE: Helmet, Fluorescent jacket, Safety goggles, Hand gloves, Safety Shoes, Shin guard Bringing & Sending: 1) SPM Operator informs the Trailor operator and to bring the loaded trailer: i)CGL-2 to Roll Shop ii) Roll Shop to CGL-2	checked by the driver and if any issues, immediately to be escalated to the respective SPM associate and Line Manager. Trailer should not be operated if it is faulty or if any operation malfunctioning.
		5		2. Scotch Block	

PREPARED BY	APPROVED BY
Name and Desig: S Sivanujhaa, Mgr CGL	Name and Desig:- G Sai Kumar (Head CGL)
Signature with Date	Signature with Date

Printed By -Abhishek Jha(199278) Print valid till - 17-Oct-2024

Printed on - 07-Oct-2024

SANDARD OPERATING PROCEDURE

Form No.: EHSMSM/446/4013 Form Rev. No.01 Effective date: 01.04.2009 SOP No:-CRM/TS/SOP/CGL#2-SPM/16 Effective Date 25-2-2024 REVISION No 04 SOP DESC WORK HANDLING IN SPM OF CGL # 2 **Document No DEPARTMENT & SECTION** Cold Rolling Mill - CGL2 SPM Page 2 of 5

			3. Lashir	ng tools	
	ENVIRONMENT: NA				
	QUALITY: NA				
Lifting/Placing of Work Rolls	SAFETY: 1) Slings may get teared while handling. 2) Roll may free fall due to	Activity carried out by Contract worker under the supervision of SPM associate	1) After /unload the SP. 2) SPM a activit 3) The SI activit 4) While manda engage injury. Unloading Activity 5) The un 6) Ensure 7) Check and en raise the	the Trailer is placed in the designated place for loading ading, the trailer driver to engage scotch blocks and inform PM associate. associate to communicate to the contractor to initiate the try of Roll Loading/Unloading at CGL-2. BM associate should initiate and supervise the WR handling try. be handling the slings, use of sling handling tackle is atory. In no circumstances, bare hands are to be used to re/disengage the sling as it will lead to finger entrapment of the trailer to the trailer of the trailer to the trailer of the QUALITY OF SLINGS before putting it into operation insure no visible defect. In case any defective part observed, the concern to the concerned associate/line manger to discard	damaged sling under any eircumstances. Inform line managers and get them replaced immediately before use.
				ing. t the healthiness of Crane (CT/LT/Hoist movement & Crane galarm) Proceed for the activity only when all are healthy,) ~

PREPARED BY	APPROVED BY
Name and Desig: S Sivanujhaa, Mgr CGL	Name and Desig:- G Sai Kumar (Head CGL)
Signature with Date	Signature with Date

Printed By -Abhishek Jha(199278) Print valid till - 17-Oct-2024

Printed on - 07-Oct-2024

SANDARD OPERATING PROCEDURE Form Rev. No.01

Effective Date

25-2-2024

SOP DESC WORK HANDLING IN SPM OF CGL # 2 Document No DEPARTMENT & SECTION Cold Rolling Mill – CGL2 SPM Page 3 of 5
DEPARTMENT & SECTION Cold Rolling Mill – CGL2 SPM Page 3 of 5
else raise concern to the concerned associate and line manager. 9) The activity requires 3 contractor person(One of them crane operator). 10) Unlash the Rolls from the Trailer 11) Fix the WR changing Slings(2no.) onto the work roll changing tackle with "D" shackles. 12) Place the work roll changing tackle with sling in the crane hook. 13) Bring the EOT crane over the trailer and place its tong above the Top Work Roll. 14) Place the Sling on inner slots provided on the neck of WR shaft on 2 side. Take necessary precautions so that finger does not get entangled between roll chocks/slots and sling. Use the tackles provided to engage the Slings in the right position. Refer to the figure for the procedure. 15) Very gradually lift the roll with the crane. Place two more slings on outer slots provided on the neck of Top WR shaft. 16) The other end of these two slings to be tied to inner slots provided on the neck of Bottom WR shaft on 2 sides as shown in the fig.

Printed By -Abhishek Jha(199278) Print valid till - 17-Oct-2024

CRM/TS/SOP/CGL#2-SPM/16

Form No.: EHSMSM/446/4013

Name and Desig: S Sivanujhaa, Mgr CGL Signature with Date

SOP No:-

Printed on - 07-Oct-2024

Name and Desig:- G Sai Kumar (Head CGL) Signature with Date

SOP Valid Till - 22-May-2025

Effective date: 01.04.2009

04

REVISION No

ANDARD OPERATING PROCEDURE Form Rev. No.01

Form No.: EHSMSM/440/40	715 Form Rev. No.	01		Effective dat	te: 01.04.2009
SOP No:-	CRM/TS/SOP/CGL#2-SPM/16	Effective Date	25-2-2024	REVISION No	04
SOP DESC	WORK HANDLING IN SPM OF CGL # 2	Document No			
DEPARTMENT & SECTION	Cold Rolling Mill – CGL2 SPM	Page	4 of 5		

19) Do not stand on side or below the roll within 2 metre peripheries during roll transfer with crane 20) Lift the crane carefully up to suitable height. Ensure there is no other activity being carried out in the traverse path. If so, ask the concerned agency to stop the job until the Roll handling activity is completed. Do not operate crane over area where persons are working as it might lead to severe e 21) Move the crane slowly in transverse direction towards the roll storage area. Follow the paths as shown in the figure. Any other path that has potential to hit/damage structures should not be followed without the consent of the SPM associate. 22) Bring the crane above the roll storage area. 23) Gradually bring down the crane just above the roll storage position. 24) When there is no crane swing, hold the slings on either side of the chock with the help of tackle. 25) Gradually bring down the crane and place the bottom work roll properly on the roll stand. 26) Remove the slings from the neck from bottom work roll shaft and also from the WR changing tackle. 27) Place wooden blocks above both side chocks of the bottom WR. 28) Bring down the crane further and place the top Work roll above		T	trailer
during roll transfer with crane 20) Lift the crane carefully up to suitable height. Ensure there is no other activity being carried out in the traverse path. If so, ask the concerned agency to stop the job until the Roll handling activity is completed. Do not operate crane over area where persons are working as it might lead to severe e 21) Move the crane slowly in transverse direction towards the roll storage area. Follow the paths as shown in the figure. Any other path that has potential to hit/damage structures should not be followed without the consent of the SPM associate. 22) Bring the crane above the roll storage area. 23) Gradually bring down the crane just above the roll storage position. 24) When there is no crane swing, hold the slings on either side of the chock with the help of tackle. 25) Gradually bring down the crane and place the bottom work roll properly on the roll stand. 26) Remove the slings from the neck from bottom work roll shaft and also from the WR changing tackle.			Tallel
other activity being carried out in the traverse path. If so, ask the concerned agency to stop the job until the Roll handling activity is completed. Do not operate crane over area where persons are working as it might lead to severe e 21) Move the crane slowly in transverse direction towards the roll storage area. Follow the paths as shown in the figure. Any other path that has potential to hit/damage structures should not be followed without the consent of the SPM associate. 22) Bring the crane above the roll storage area. 23) Gradually bring down the crane just above the roll storage position. 24) When there is no crane swing, hold the slings on either side of the chock with the help of tackle. 25) Gradually bring down the crane and place the bottom work roll properly on the roll stand. 26) Remove the slings from the neck from bottom work roll shaft and also from the WR changing tackle.			
storage area. Follow the paths as shown in the figure. Any other path that has potential to hit/damage structures should not be followed without the consent of the SPM associate. 22) Bring the crane above the roll storage area. 23) Gradually bring down the crane just above the roll storage position. 24) When there is no crane swing, hold the slings on either side of the chock with the help of tackle. 25) Gradually bring down the crane and place the bottom work roll properly on the roll stand. 26) Remove the slings from the neck from bottom work roll shaft and also from the WR changing tackle. 27) Place wooden blocks above both side chocks of the bottom WR.			other activity being carried out in the traverse path. If so, ask the concerned agency to stop the job until the Roll handling activity is completed. Do not operate crane over area where persons are
 23) Gradually bring down the crane just above the roll storage position. 24) When there is no crane swing, hold the slings on either side of the chock with the help of tackle. 25) Gradually bring down the crane and place the bottom work roll properly on the roll stand. 26) Remove the slings from the neck from bottom work roll shaft and also from the WR changing tackle. 27) Place wooden blocks above both side chocks of the bottom WR. 			storage area. Follow the paths as shown in the figure. Any other path that has potential to hit/damage structures should not be followed without the consent of the SPM associate.
chock with the help of tackle. 25) Gradually bring down the crane and place the bottom work roll properly on the roll stand. 26) Remove the slings from the neck from bottom work roll shaft and also from the WR changing tackle. 27) Place wooden blocks above both side chocks of the bottom WR.		·	2 1
properly on the roll stand. 26) Remove the slings from the neck from bottom work roll shaft and also from the WR changing tackle. 27) Place wooden blocks above both side chocks of the bottom WR.		180	
also from the WR changing tackle. 27) Place wooden blocks above both side chocks of the bottom WR.			
28) Bring down die crane furdier and place die job work-ton above			
PREPARED BY APPROVED BY			

PREPARED BY	APPROVED BY
Name and Desig: S Sivanujhaa, Mgr CGL	Name and Desig:- G Sai Kumar (Head CGL)
Signature with Date	Signature with Date

Printed By -Abhishek Jha(199278) Print valid till - 17-Oct-2024

Printed on - 07-Oct-2024

Form Rev. No.01

Effective Date

25-2-2024

SOP DESC WORK HANDLING IN SPM OF CGL # 2 Document No			
DEPARTMENT & SECTION Cold Rolling Mill - CGL2 SPM		Page	5 of 5
DEPARTMENT & SECTION	SPM Associates/ Shift Incharge	those wooden block 29) Remove the slings a 30) Keep the slings a 31) Remove from crarplace. 32) Step 5 to 15 to changing car whe 33) When the roll is be position of the rol 34) Ensure that the CO/S. 35) Then place the rol 36) Ensure that roll be on car 37) In Drive side, the side Roll car whe Tools: 1. WR lifting tool 2. WR lifting slings 3. Wooden blocks 4. Scotch Block	be repeated to bring the roll above D/S WR damaged sling under any circumstances. In the designated brought over the D/S WR changing car, adjust the full parallel to the car frame. Thock having WR clamping slot is placed on the olls gradually on the roll changing car frames. In the full parallel is not hit while handling and placing the roll dere is an active interlock for movement of Drive and the access gate is opened.
	PREPARED BY	5. EOT crane	APPROVED BY
Name and Desig: S Sivanujhaa	, Mgr CGL	Name and Desig:- G Sai Kum	
Signature with Date		Signature with Date	

Printed By -Abhishek Jha(199278) Print valid till - 17-Oct-2024

CRM/TS/SOP/CGL#2-SPM/16

Form No.: EHSMSM/446/4013

SOP No:-

Printed on - 07-Oct-2024

SOP Valid Till - 22-May-2025

Effective date: 01.04.2009

REVISION No 04

● ANDARD OPERATING PROCEDUE

1	Form No.: EHSMSM/446/40	10 10			Effective date	e: 01.04.2009
	SOP No:-	CRM/TS/SOP/CGL#2-SPM/16	Effective Date	25-2-2024	REVISION No	04
	SOP DESC	WORK HANDLING IN SPM OF CGL # 2	Document No			
	DEPARTMENT & SECTION	Cold Rolling Mill – CGL2 SPM	Page	6 of 5		

6. Sling handling tackles
PPEs: Ensure proper PPEs like shin guards, Helmet, safety shoes, Hand, gloves and goggles are worn
Process: 38) The SPM operator should initiate and supervise the WR handling activity. 39) The Roll Shifting activity is carried out by Contractor employees. 40) The activity requires 3 contractor person(One of them crane operator).
41) The SPM operator should unlock the WR clamp on O/S car tractor and take the tractor to home position. 42) Repeat step 5 to 15. 43) Bring the EOT crane over the roll stand or trailer and place the
Roll. 44) Repeat steps 21 to 25. Tools:
45) WR lifting tool /tackles 46) WR lifting slings. 47) Wooden blocks 48) Scotch Block 49) EOT crane PPEs:
Ensure proper PPEs like shin guards, Helmet, safety shoes, Hand, gloves and goggles are worn

PREPARED BY	APPROVED BY	1	
Name and Desig: S Sivanujhaa, Mgr CGL	Name and Desig:- G Sai Kumar (Head CGL)	JV	
Signature with Date	Signature with Date		


Printed By -Abhishek Jha(199278) Print valid till - 17-Oct-2024

Printed on - 07-Oct-2024

● ANDARD OPERATING PROCED ■ E

M	Form No.: EHSMSM/446/40	Form Rev. No.01			Effective date	e: 01.04.2009
/	SOP No:-	CRM/TS/SOP/CGL#2-SPM/16	Effective Date	25-2-2024	REVISION No	04
	SOP DESC	WORK HANDLING IN SPM OF CGL # 2	Document No			
	DEPARTMENT & SECTION	Cold Rolling Mill - CGL2 SPM	Page	7 of 5		

			1 -		
1		ENVIRONMENT: NO EFFECT			
		QUALITY:			
	Loading/Unloading WR in SPMWRC D/S	Safety: Moving Equipment, Work		Procedure:	
		under hanging load, Finger Entrapment injury	Employee	1. The Work Roll car gate is to be kept open while transferring roll in the area.	
		Zana apinene injur y		The Gate is in interlock with the movement of the Roll change car in the Drive	
				side, hence by keeping the gate open, the movement of the work roll car is	
				locked)	
	1			2. Whenever the Roll change activity is in progress, for engaging and	
	-1			disengaging the Slings from the roll. Platform on the work roll car to be utilized	
				while handing the Rolls near Work roll car. Ensure all the barricades on the platform are in place.	
			· 2 +		
		<i>‡</i>	110		



BY

ar (I

Modified Safety Platform with Handrailing


Printed Rotating AUR Sheft 9278) Print valid till - 17-0

Frinted on = 07-Oct-20

SOF Vand 1111 - 22-May-2

● ANDARD OPERATING PROCEDU●E

	Form No.: EHSMSM/446/40	Form Rev. No.01			Effective date	e: 01.04.2009	_
1	SOP No:-	CRM/TS/SOP/CGL#2-SPM/16	Effective Date	25-2-2024	REVISION No	04	
,	SOP DESC	WORK HANDLING IN SPM OF CGL # 2	Document No				-
	DEPARTMENT & SECTION	Cold Rolling Mill - CGL2 SPM	Page	8 of 5			



PREPARED BY	APPROVED BY
Name and Desig: S Sivanujhaa, Mgr CGL	Name and Desig:- G Sai Kumar (Head CGL)
Signature with Date	Signature with Date