

Mexico CSA

Database -> For Live Coding:

MEXICO lies within the NA_BW_XXXX For Ex: NA_BW_2601

Admin Levels and Descriptions:

Mexico has four Admin Levels, as indicated below:

1. Level 1: Country
2. Level 2: Estado
3. Level 3: Municipio
4. Level 4: Settlement/Colonia

→ Work Order: Latin America - FC1234-ADAS - Enhanced Geometry - WO108782...ADAS - AMER

Construction:

While coding and updating/modify ADAS if coder comes across with any construction patches these areas must be set to ADAS (Not ADAS Compliant) – ADAS Source ‘**Construction**’

Turn lanes:

Do NOT count turn lanes

→ Do not consider shoulder lane and bicycle lane for offset neither for lane count

Driving Side

Driving side indicates the side of the road the car is on

→ **MEXICO is a right-side driving country**

ADAS (ADAS Compliant)

- Use latest drive file that available:
- Both PP IMU and IMU must be used as ADAS Geometry Source Code with links that are coded ADAS (ADAS Compliant)
- IMU for Purple / Magenta GPS Trace
- PP IMU for golden GPS Trace

New geometry Addition:

- ONLY New FC12 geometry should be added as per the source (latest drive files)
- All new geometry source code should be: YYMMCL62 (Year, Month, Coding Location, 62)-62 refers to HERE TRUE drive files
- New geometry information must be entered into the ‘New Geometry Details’ sheet
- Missing geometry on FC3-5 should NOT be added. During coding, if we come across such cases, Mandatory JIRA should be raised to SDE Team

FC5 connectivity:

- Operators should not downgrade the existing position of intersecting FC5 geometry for the ADAS geometry of the main road.
- The ADAS coding should be added but the existing FC5 geometry should not be a mismatch in reality

Lane Width for Motorway/ Non-Motorway -

- Lane width for motorway and Non Motorway road 3.2 m

Divider Width -

- MEXICO Divider maximum width is 3 meters
- LEGAL DIVIDER is not coded in MEXICO.

OFFSET -

- Calculate total number of all lanes
- For bi-directional roads, calculate the total number of all lanes including center turn lanes, bus lanes, HOV lanes & dividers
- **Add an additional 2 meters for any 'big' legal or physical dividers Painted centerlines or small dividers (less than 1 meter) do not need to be considered for centerline offset**
- For Multiply-Digitised roads, only the lanes in one direction need to be counted

→ **DO NOT COUNT TURN LANES IN OFFSET**

→ **Do not consider shoulder lane and bicycle lane for offset neither for lane count**

- Add an additional 2 meters for any 'big' legal or physical dividers (for MEXICO divider over 3 meters width indicates this road should be multiply digitized)

Common Exceptions:

→ **DEG030: we expect DEG exceptions related to NUMBER OF LANE/LANE COUNT/LANE CATEGORY coding,.**

- Compare Source Codes and do not change LANE information if the actual coding has a newer date than source you are using for ADAS
- If previous value of lane count is not "0" (zero), do not change the coding if the actual source code is newer
- **ALL DEG030 non-related with LANE update (The old attribute value was 0) are considered degradation and must be resolved**

→ **DEG032: Suspicious Updates at Aligned Links and Nodes**

- NEVER align/adjust admin boundaries to the trace or imagery
- This is a high degradation for customers.
- If you did please revert the coding ASAP using the last released database as reference

NAV222:

- 1. This exception gets fired when there is existing XTDL coding on the link (lane count as per XTDL) and the lane count as per reality (drive file) differs.
- 2. Compare both XTDL and ADAS source code, If XTDL is newer do not update LANE count. do not modify XTDL coding
- 3. XTDL team will take care of legitime cases: when lane information needs to be changed and conflicts with existing XTDL coding.

- 4. Escalate the task to check XTDL coding if exception fires for ADAS coding conflicting with extended lane coding (if previous comparison between XTDL and ADAS lane count are not possible)

Motorcycle lanes: Only include the motorcycle lane on the lane count when the lane is wide enough, in this case the motorcycle lane is smaller so please keep it out of the lane count.