NO.5 WRENCH INDICATOR LIGHT ILLUMINATES/MESSAGE "Drain Water from Fuel Filter" IS INDICATED IN TFT LCD [SKYACTIV-D 2.2]

id0103g1879000

5	WRENCH INDICATOR LIGHT ILLUMINATES/MESSAGE "Drain Water from Fuel Filter" IS INDICATED IN TFT LCD	
• "Drain Water from Fuel Filter" is displayed in the TFT LCD. (with TFT LCD) • Wrench indicator light illuminates. (without TFT LCD)		
POSSIBLE CAUSE	PCM DTC is stored. Sedimentor switch malfunction Instrument cluster malfunction	

Diagnostic Procedure

STEP	INSPECTION	RES ULT S	ACTION
1	• Retrieve PCM DTCs using the M-MDS.	Yes	Go to the applicable DTC inspection. (See DTC TABLE [SKYACTIV-D 2.2].)
	(See ON-BOARD DIAGNOSTIC TEST [SKYACTIV-D 2.2].) • Are any DTCs present?	No	Go to the next step.
2	INSPECT SEDIMENTOR SWITCH	Yes	Go to the next step.
	Inspect the sedimentor switch. (See SEDIMENTOR SWITCH INSPECTION [SKYACTIV-D 2.2].) Is the sedimentor switch normal?	No	Replace the fuel filter, then go to Step 4. (See FUEL FILTER REMOVAL/INSTALLATION [SKYACTIV-D 2.2].)
3	INSPECT INSTRUMENT CLUSTER	Yes	Go to the next step.
	Inspect the instrument cluster. (See INSTRUMENT CLUSTER INSPECTION.) Is the instrument cluster normal?	No	Replace the instrument cluster, then go to the next step. (See INSTRUMENT CLUSTER REMOVAL/ INSTALLATION.)
4	 Verify the test results. If normal, return to the diagnostic index to service any additional symptoms. (See SYMPTOM DIAGNOSTIC INDEX [SKYACTIV-D 2.2].) If a malfunction remains, inspect the related Service Information and perform the repair or diagnosis. — If the vehicle is repaired, troubleshooting is completed. — If the vehicle is not repaired or additional diagnostic information is not available, replace the PCM. (See PCM REMOVAL/INSTALLATION [SKYACTIV-D 2.2].) 		