NO.22 VIBRATION CONCERNS (ENGINE) [SKYACTIV-G 2.0, SKYACTIV-G 2.5]

id0103g3802800

22	VIBRATION CONCERNS (ENGINE)	
DESCRIPTION	CRIPTION • Vibration from under bonnet or driveline.	
POSSIBLE CAUSE	Loose attaching bolts or worn parts	
FUSSIBLE CAUSE	Components malfunction such as worn parts	

Diagnostic Procedure

Diagnostic Procedure					
STEP	INSPECTION	RESULTS	ACTION		
1	VERIFY PART INSTALLATION CONDITION	Yes	Readjust installation position or retighten the suspect		
	Inspect the following components for loose		parts.		
	attaching bolts or worn parts:		Repair or replace the malfunctioning part according to		
	Cooling fan		the inspection results for other parts.		
	Condenser fan	No	Inspect the following systems:		
	Engine mounts		• Wheels		
	Exhaust system		Transmission and mounts		
	Abnormal combustion		Driveline		
	Is there any malfunction?		Suspension		
	,		If there is any malfunction:		
			Repair or replace the malfunctioning part		
			according to the inspection results.		
			If there is no malfunction:		
			Go to the next step.		
			Misfire		
			If there is any malfunction:		
			Inspect the parts related to the ignition system,		
			intake air system, and control system, repair or		
			replace the malfunctioning part.		
			If there is no malfunction:		
			Go to the next step.		
2	Verify the test results.				
_	If normal, return to the diagnostic index to service any additional symptoms.				
	(See SYMPTOM DIAGNOSTIC INDEX [SKYACTIV-G 2.0, SKYACTIV-G 2.5].)				
	• If a malfunction remains, inspect the related Service Information and perform the repair or diagnosis.				
	— If the vehicle is repaired, troubleshooting is completed.				
	 If the vehicle is not repaired or additional diagnostic information is not available, replace the PCM. 				
	(See PCM REMOVAL/INSTALLATION [SKYACTIV-G 2.0, SKYACTIV-G 2.5].)				
	(SEE FOW REWOVAL/INSTALLATION [SKTACTIV-G 2.0, SKTACTIV-G 2.3].)				