NO.25 FUEL ODOR (IN ENGINE COMPARTMENT) [SKYACTIV-D 2.2]

id0103g1899200

25	FUEL ODOR (IN ENGINE COMPARTMENT)	
DESCRIPTION	ON • Fuel odor from inside/outside of cabin or engine compartment.	
POSSIBLE CAUSE	PCM DTC is stored.	
POSSIBLE CAUSE	Fuel system malfunction (leak in supply system)	

Diagnostic Procedure

STEP	INSPECTION	RES ULT S	ACTION	
1	• Retrieve PCM DTCs using the M-MDS. (See ON-BOARD DIAGNOSTIC TEST [SKYACTIV-D 2.2].) • Are any DTCs present?	Yes	Go to the applicable DTC inspection. (See DTC TABLE [SKYACTIV-D 2.2].)	
		No	Go to the next step.	
2	INSPECT FOR FUEL LEAKAGE FROM FUEL	Yes	Go to the next step.	
	Visually inspect the following: Fuel leakage from the fuel tank, fuel pump, hose, pipe, fuel injector, supply pump, common rail Cracking and damage in fuel hose and pipe Clamp installation condition for each hose and pipe Fuel pipe securing condition due to deterioration such as rubber of clamp Are all items normal?	No	Repair or replace the malfunctioning part according to the inspection results, then go to the next step.	
3	 Verify the test results. If normal, return to the diagnostic index to service any additional symptoms. (See SYMPTOM DIAGNOSTIC INDEX [SKYACTIV-D 2.2].) If a malfunction remains, inspect the related Service Information and perform the repair or diagnosis. — If the vehicle is repaired, troubleshooting is completed. — If the vehicle is not repaired or additional diagnostic information is not available, replace the PCM. (See PCM REMOVAL/INSTALLATION [SKYACTIV-D 2.2].) 			