## DTC U0401:00 [DYNAMIC STABILITY CONTROL (DSC)]

id0402b2887900

DTC U0401	:00 Abnormal message from PCM		
DETECTION CONDITION	• Correct data cannot be received from PCM		
FAIL-SAFE FUNCTION	<ul> <li>* Illuminates the TCS/DSC indicator light*1 and master warning light*1*2.</li> <li>• Tire pressure monitoring system warning light illuminates after flashes. (Not illuminated/flashed depending on malfunction content.)</li> <li>* Inhibits the TCS*3, DSC*3, roll over mitigation (ROM)*3, vehicle roll prevention function*3*4, hill launch assist (HLA)*3, TPMS*3, smart city brake support (SCBS)*2*3, and secondary collision reduction (SCR)*3 controls.</li> <li>*1: Not illuminated depending on malfunction content.</li> <li>*2: Vehicles with smart city brake support (SCBS)</li> <li>*3: Enabled depending on malfunction content.</li> <li>*4: ATX only</li> </ul>		
POSSIBLE CAUSE	PCM malfunction		
SYSTEM WIRING DIAGRAM			

Diagnostic procedure

STEP	INSPECTION		ACTION
1	INSPECT FOR PCM MALFUNCTION	Yes	Go to applicable DTC inspection.
	Switch the ignition to off.		(See DTC TABLE [SKYACTIV-G 2.0, SKYACTIV-G
	• Using the M-MDS, perform the DTC inspection for the		2.5].)
	PCM.		(See DTC TABLE [SKYACTIV-D 2.2].)
	(See ON-BOARD DIAGNOSTIC TEST [SKYACTIV-G 2.0, SKYACTIV-G 2.5].)	No	Go to the next step.
	(See ON-BOARD DIAGNOSTIC TEST [SKYACTIV-D 2.2].)		
	Are any DTCs detected?		
2	VERIFY THAT THE SAME DTC IS NOT PRESENT	Yes	Repeat the inspection from Step 1.
	Clear the DTCs from the memory.		If the malfunction recurs, replace the PCM, then go to
	(See ON-BOARD DIAGNOSIS [DYNAMIC STABILITY		the next step.
	CONTROL (DSC)].)		(See PCM REMOVAL/INSTALLATION [SKYACTIV-
	Are the same DTCs present?		G 2.0, SKYACTIV-G 2.5].)
			(See PCM REMOVAL/INSTALLATION [SKYACTIV-
			D 2.2].)
		No	Go to the next step.
3	VERIFY THAT NO OTHER DTCS ARE PRESENT	Yes	Go to the applicable DTC inspection.
	Are any other DTCs output?		(See ON-BOARD DIAGNOSIS [DYNAMIC
			STABILITY CONTROL (DSC)].)
		No	DTC troubleshooting completed.