DTC U3000:41 [SKYACTIV-G 2.0, SKYACTIV-G 2.5]

id0102h4851600

DTC U3000:41	PCM processor error	
	PCM internal EEPROM malfunction.	
	Diagnostic support note	
DETECTION	This is a continuous monitor (other).	
CONDITION	The check engine light does not illuminate.	
	FREEZE FRAME DATA (Mode 2)/Snapshot data is not available.	
	• DTC is not stored in the PCM memory.	
FAIL-SAFE	Not applicable	
FUNCTION		
POSSIBLE	• PCM internal maltunction	
CAUSE		
SYSTEM		
WIRING	VIRING Not applicable	
DIAGRAM		

Diagnostic Procedure

Diagnostic Procedure				
STEP	INSPECTION		ACTION	
1	VERIFY RELATED SERVICE INFORMATION	Yes	Perform repair or diagnosis according to the available	
	AVAILABILITY		Service Information.	
	Verify related Service Information availability.		If the vehicle is not repaired, go to the next step.	
	Is any related Service Information available?	No	Go to the next step.	
2	VERIFY DTC TROUBLESHOOTING	Yes	Replace the PCM, then go to the next step.	
	COMPLETED		(See PCM REMOVAL/INSTALLATION [SKYACTIV-G 2.0,	
	Clear the DTC from the PCM memory using the		SKYACTIV-G 2.5].)	
	M-MDS.	No	Go to the next step.	
	(See AFTER REPAIR PROCEDURE			
	[SKYACTIV-G 2.0, SKYACTIV-G 2.5].)			
	Perform the KOEO self test.			
	(See KOEO/KOER SELF TEST [SKYACTIV-G			
	2.0, SKYACTIV-G 2.5].)			
	Is the same DTC present?			
3	VERIFY AFTER REPAIR PROCEDURE	Yes	Go to the applicable DTC inspection.	
	Perform the "AFTER REPAIR PROCEDURE".		(See DTC TABLE [SKYACTIV-G 2.0, SKYACTIV-G 2.5].)	
	(See AFTER REPAIR PROCEDURE	No	DTC troubleshooting completed.	
	[SKYACTIV-G 2.0, SKYACTIV-G 2.5].)			
	Are any DTCs present?			