NO.16 HIGH OIL CONSUMPTION/LEAKAGE [SKYACTIV-G 2.0, SKYACTIV-G 2.5]

id0103g3802200

16	HIGH OIL CONSUMPTION/LEAKAGE
DESCRIPTION	Oil consumption is excessive.
	Improper dipstick
	Improper engine oil viscosity
POSSIBLE CAUSE	Oil leakage
	PCV valve malfunction
	Engine internal parts malfunction

Diagnostic Procedure

Diagnostic Procedure					
STEP	INSPECTION	RESULTS	ACTION		
1	INSPECT ENGINE OIL AND RELATED PARTS	Yes	Service if necessary.		
	Inspect the following:		Repeat this step.		
	Proper dipstick	No	Go to the next step.		
	Proper engine oil viscosity				
	Engine oil level				
	Is there any malfunction?				
2	VISUALLY INSPECT FOR ENGINE OIL	Yes	Repair or replace the malfunctioning part according to		
	LEAKAGE		the inspection results.		
	Inspect for engine oil leakage outside of the engine.	No	Go to the next step.		
	Is there any leakage?				
3	INSPECT IF MALFUNCTION CAUSE IS PCV	Yes	Replace the PCV valve.		
	VALVE OR ENGINE INTERNAL PART		(See POSITIVE CRANKCASE VENTILATION (PCV)		
	Inspect the PCV valve.		VALVE REMOVAL/INSTALLATION [SKYACTIV-G 2.0,		
	(See POSITIVE CRANKCASE VENTILATION		SKYACTIV-G 2.5].)		
	(PCV) VALVE INSPECTION [SKYACTIV-G	No	Inspect the internal engine parts such as valves, valve		
	2.0, SKYACTIV-G 2.5].)		guides, valve stem seals, cylinder head drain passage,		
	Is there any malfunction?		and piston rings.		
			Repair or replace the malfunctioning part according to		
			the inspection results, then install the removed parts.		
4	Verify the test results.				
	If normal, return to the diagnostic index to service any additional symptoms.				
	(See SYMPTOM DIAGNOSTIC INDEX [SKYACTIV-G 2.0, SKYACTIV-G 2.5].) • If a malfunction remains, inspect the related Service Information and perform the repair or diagnosis.				
	 If the vehicle is repaired, troubleshooting is completed. 				
	— If the vehicle is not repaired or additional diagnostic information is not available, replace the PCM.				
	(See PCM REMOVAL/INSTALLATION [SKYACTIV-G 2.0, SKYACTIV-G 2.5].)				