DTC P1886:00

DTC P1886:00	Configuration data not recorded	
DETECTION CONDITION	4WD CM detects vehicle type information data error	
FAIL-SAFE	Control disabled.	
FUNCTION	4WD warning light: Illuminated	
POSSIBLE	PCM malfunction	
CAUSE	Wrong 4WD CM is installed	

Diagnostic procedure

Diagnostic procedure				
STEP	INSPECTION		ACTION	
1	INSPECT FOR PCM MALFUNCTION Switch the ignition to off. Using the M-MDS, perform the DTC inspection for the PCM.	Yes	Go to applicable DTC inspection. (See DTC TABLE [SKYACTIV-G 2.0, SKYACTIV-G 2.5].) (See DTC TABLE [SKYACTIV-D 2.2].)	
	(See ON-BOARD DIAGNOSTIC TEST [SKYACTIV-G 2.0, SKYACTIV-G 2.5].) (See ON-BOARD DIAGNOSTIC TEST [SKYACTIV-D 2.2].) • Are any DTCs detected?	No	Go to the next step.	
2	• Is correct 4WD CM installed?	Yes	Replace the 4WD CM. (See 4WD CONTROL MODULE REMOVAL/ INSTALLATION.)	
		No	Go to the next step.	
3	COUPLING COMPONENT CALIBRATION DATA WRITING Write the coupling component calibration data. (See COUPLING COMPONENT CALIBRATION DATA WRITING.) Clear the DTCs from the memory. (See ELECTRONIC 4WD CONTROL SYSTEM ON-BOARD DIAGNOSIS.) Is the same DTC present?		Go to the next step.	
4	VERIFY THAT THE SAME DTC IS NOT PRESENT	Yes	Repeat the inspection from Step 1.	
	Clear the DTCs from the memory. (See ELECTRONIC 4WD CONTROL SYSTEM ON-BOARD DIAGNOSIS.) Is the same DTC present?	No	Go to the next step.	
5	• Are any other DTCs output?	Yes	Go to the applicable DTC inspection. (See ELECTRONIC 4WD CONTROL SYSTEM ON-BOARD DIAGNOSIS.)	
		No	DTC troubleshooting completed.	