
8. Level 3 Repair (VIETMOBILE.VN)


8-1. Components Layout

<PBA TOP SIDE>




8. Level 3 Repair (VIETMOBILE.VN)


<PBA BOTTOM SIDE>




(VIETMOBILE.VN)

WWW.AliFixit.COM






WWW.AliFixit.COM



Soldering iron


8. Level 3 Repair

8-3. Flow chart of Troubleshooting.




8960 & Spectrum Analyzer

8-4-1. Power On




WWW.ALISALER.COM


8-4-2. Initial




8-4-3. No Service




8-4-4. SIM Part




8-4-5. T-Flash Part




8-4-6-1. Cable Charging Part (Normal)




8-4-6-2. OTG




8-4-7-1. ACC Sensor




8-4-7-2. Proximity sensor




8-4-7-3. Flip cover detect




8-4-7-4. Fingerprint Sensor




8-4-8. Microphone Part - Main MIC




8-4-9. Speaker Part



8-4-10. Receiver Part




8-4-11. BT/WIFI




WWW.ALISALER.COM


8-4-12. GPS




8-4-13. FM radio part




8-4-14. Display




8-4-15. DUAL CAMERA




8-4-16. VT CAMERA




8-4-17. Motor




8-4-18.GSM 850/900, WCDMA B5/8, LTE B5/8/12/13/17/20/28 PRx




8-4-19. GSM DCS/PCS, WCDMA B1/2/4, LTE B1/2/3/4/66 PRx




8-4-20. LTE B7/38/40/41 PRx




8-4-21. GSM 850/900, WCDMA B5/8, LTE B5/8/12/13/17/20/28 DRx




8-4-22. GSM DCS/PCS, WCDMA B1/2/4, LTE B1/2/3/4/66 DRx




8-4-23. LTE B7/38/40 DRx




8-4-24. GSM 850/900, WCDMA B5/8, LTE B5/8/12/13/17/20/28 TX



8-4-25. GSM DCS/PCS, WCDMA B1/2/4, LTE B1/2/3/4/66 Tx



8-4-26. LTE B7/38/40 Tx



8-5. Service Schematics

- AP Top view

