

⚠ SEVERITY: CRITICAL — Update Available — Action Required

About This Notice (Revision 1.0)

This is a notification of a critical security vulnerability that affects select Frontline products. A software patch is available. Action is required to update the affected products.

Advisory Summary

Advisory ID	TDY-PSG-2026-001
Revision	1.0
Issue Date	June 24, 2026
Severity	Critical (CVSS v3.1 Base Score: 9.8)
Vulnerability Type	Remote Code Execution (RCE)
Attack Vector	Network — Ethernet-connected devices only; USB-only operation is not affected
Authentication Required	None
Patch Available	Yes
Customer Action Required	Yes — Update affected products immediately or apply interim mitigations based on your risk profile (see below)
Affected Products	Frontline X240 / X240i • Frontline X500 / X500e

Vulnerability Description

Teledyne LeCroy has identified two critical vulnerabilities in the Wireless Protocol Software Suite (WPS) affecting the Frontline product line. These vulnerabilities may permit an unauthenticated remote attacker to execute arbitrary code on a device connected to an Ethernet network.

Products operated exclusively via USB connection are not affected by these vulnerabilities.

Teledyne LeCroy is not aware of any active exploitation of these vulnerabilities at the time of publication. This advisory is issued proactively so that customers can take timely protective action.

Affected Software Versions

All previously released versions of WPS are affected. Specifically:

- WPS 4.70 Alpha — Build 25.9.37086.38119 or lower
- WPS 4.61 Alpha — Build 25.9.37086.37673 or lower
- WPS 4.60 GA — Build 25.9.37086.37567 or lower

Software Update Instructions

We recommend immediately updating the WPS software and the product system firmware to WPS 4.70 Beta or higher.

1. Download WPS 4.70 Beta software (or newer version) to your computer. You can find the software at: <https://go.teledynelecroy.com/wps-software>
2. Install WPS 4.70 Beta software on your computer and launch the software.
3. Connect each of the affected Frontline systems to the computer with the new software.
 - a. A dialog will appear prompting a firmware upgrade.
 - b. Click Upgrade Firmware to install the latest firmware on your device.
4. Please remember to repeat the process of updating the firmware for each of the Frontline systems affected.

Interim Mitigations

If you cannot update the software immediately, Teledyne LeCroy recommends that customers assess their specific deployment environment and risk tolerance and implement one or more of the following mitigations accordingly. These mitigations reduce exposure but **do not eliminate the underlying vulnerability**. They should remain in place until the patch is applied.

Customers should make their own determination as to which measures are appropriate given the sensitivity of their application, the security posture of the networks to which Frontline products are connected, and their operational requirements.

Risk Tier	Suggested Mitigation Actions
HIGHEST Air-gap / most sensitive	• Disconnect affected Frontline systems from all Ethernet networks immediately. • Operate exclusively via USB until the patch is released and applied. • Power off units when not actively in use.
ELEVATED Internal network, limited exposure	• Isolate affected systems to a dedicated, firewalled network segment with no external internet access. • Restrict inbound and outbound Ethernet traffic to known, required hosts only. • Monitor network traffic to and from affected devices for anomalous activity. • Operate via USB where operationally feasible.

MANAGED Well-controlled, monitored environment	• Ensure affected systems are behind a properly configured firewall and are not directly internet-accessible. • Apply principle of least privilege to network access for affected devices. • Enable logging and alerting on network connections to affected systems. • Document current network topology and review with your security team.
ALL	<i>Contact Teledyne LeCroy support if you need assistance evaluating the appropriate mitigation for your environment. See the Contact section below.</i>

Contact and Support

For questions about this advisory or assistance evaluating mitigations for your environment:

- Email: psgsupport@teledyne.com
- Reference subject line: Security Advisory TDY-PSG-2026-001 — [Your Company Name]

To report a security vulnerability in a Teledyne LeCroy product, email psgsupport@teledyne.com with the subject line “Security Vulnerability Report.” Teledyne LeCroy is committed to responsible disclosure and to working collaboratively with customers and security researchers.