ROBERTSON - CARUSO CORPORATION

TECHNICAL TIPS - AUGUST 1996

Problem: Whenever the max2.sys driver is in the config.sys, the system locks during boot.

Solution: load max2A.sys file 4330 bytes

when you type this file it should not have any readable ascii text.

There are two max2.sys files:

- 1) One of the files can be identified as follows: when you type this file at 4330 bytes, it lists maxpeed ss8 series 2 MOS driver v 5.03.
- 2) the other driver at 4330 bytes has no readable ascii text.

Download max2a.zip and replace any exsisting maxpeed 5.03 driver with max2a.sys.

- MAX 512E: 1985

Information: a user reported that PC-MOS 5.01 Booster II was able to successfully partition and format a 2.0 gig IDE drive. The actual drive size was 2.5 gig. IF the disk partition exceeded 2.0 gig, PC-MOS format command generated the following error:

"divide by zero"

WITH MSDOS FDISK

This information has not been verifed but based on the report it appears PC-MOS can format a logical disk partion up to 2.0 gig. The user had LBA mode enabled.

##

DRIVE O & C: YI DLG-P 198A

AMI BIOS AMI AH74-070396, 7-15-1995

Pentium 100 users where \$386.sys caused system to lock during boot.

problem: MOS locked during booT and found 639k ram. This occured whenever the PC-MOS memory manager \$386.sys was loaded into the config.sys

solution:

DRIVE 15 D: X PL 6-P 1989

Disable PC/IDE Bus Mastering on AMI AH74- 070396 \leftarrow \vdash \cdot \checkmark Dook for this feature in PCI/PNP setup. BIOS date 7-15-95 copywrite date 1996. Once the bus mastering was disabled MOS booted and 640k was found in the first meg.

###

Problem: files saved with a -s attribute

When updat501.sys is not present, files "MAY BE" saved with a -s attribute. This attribute creates a secured file(S) that DOS cannot read.

Solution:

Some users have successfully removed the -s with the copy command.

copy /-c

This proceedure does not work in all cases.

If users have PC-MOS security installed, they will need to signon first (SIGNON AS USER WITH HIGHEST SECURITY LEVEL) in order to removed the -s attribute.

###

These tips have been provided by Robertson-Caruso Technical Support. Some of the tips have not been verifed by support but are passed along as REASONALBE tips to trouble shoot various problems. In all cases make a good back up of your system diskettes and configuration files:

config.sys
autoexec.bat
\$\$user.sys (if present)
startup batch files