

Project (If Applicable)		TRA Ref. No.	DOUS-TRA-001		
Location / Worksite					
Sub Location / Area					
Equipment Spread (Optional)					
Task / Activity	PRE AND / OR POST DIVE CHECKS				
Approver					
Responsible Person					
Date TRA Created					
Reference Supporting Documents & Task Plan					
S3RA:			Hot Work Checklist:		
Task Plan:			Work at Height Checklist:		
Lift Plan:			Confined Space Work Checklist:		
PTW:			Electrical Equipment Checklist:		
COSHH / SDS:			Electrical Isolation Checklist:		
Rescue Plan:			Machinery Isolation Checklist:		
Work Equipment Assessment:			Pressure Systems Checklist:		
Other:			Other:		
Reason for TRA (Tick where Applicable)					
Identification of New Task	Annual Review	Review following Incident	Management of Change Record	Other, Please Specify	
☐	☐	☐	☐	☐	
Other (Details):					
TRA Participants					
Name	Position		Signature		
NOTE: STANDARD PPE OF SAFETY FOOTWEAR, SAFETY HELMET, COVERALLS, GLASSES AND GLOVES MUST BE WORN. ANY ADDITIONAL PPE REQUIRED SHALL BE CAPTURED IN THE MITIGATING CONTROLS SECTION OF THE TRA TEMPLATE BELOW.					

Task Risk Assessment Form

DEEPOCEAN

No.	Task /Activity	Hazard and Consequence		Initial Risk			Mitigating Controls	Residual Risk		
	Sequential Steps	Hazard	Consequence	Probability	Consequence Severity	Risk Rating	Measures to Reduce Risk to ALARP	Probability	Consequence Severity	Risk Rating
1	Review TRA and TBT	Miscommunication	Personnel Injury / Environmental Pollution	1	2	M	Situational awareness and proper use of PPE. Hard hats, impact gloves, cotton gloves, latex gloves, steel toed boots, safety glasses, side shields and face shield	1	1	L
2	Prior to any task being undertaken ensure that all personnel are aware of the hazards involved.	Electrical shock, possible slips trips and falls. Pinch points poor body position. Hydraulic discharge and spills.	Personnel Injury / Environmental Pollution	2	3	M	All personnel must be aware of their surrounds and weather conditions. Use proper Manual Handling techniques, i.e., Always use proper body positioning, lift with legs, and obtain second personnel when loads are over 40lbs. Read all SDS on chemicals used, use PPE that is specified in SDS and be aware of where all spill kits are located.	2	2	L
3	Energize IPDS for TMS	High voltage, electrical shock	Personnel Injury / Environmental Pollution / Damage to Equipment	2	4	S	Good Comms, no personnel on TMS, ground straps connected if TMS is separated.	2	2	L
4	Testing of TMS cameras, electric actuators, and lights	High voltage, electrical shock, moving actuators.	Personnel Injury / Environmental Pollution / Damage to Equipment	2	2	M	Good Comms, no personnel on TMS, ground straps connected if TMS is separated.	1	1	L
5	Test TMS latch and tether in/out function. No more than 5 inches.	High voltage, electrical shock, moving actuators.	Personnel Injury / Environmental Pollution / Damage to Equipment	2	4	S	Good Comms, no personnel on TMS, ground straps connected if TMS is separated.	2	2	L
6	Energize IPA for ROV	High voltage, electrical shock	Personnel Injury / Environmental Pollution / Damage to Equipment	2	4	S	Good Comms, no personnel working on ROV, ground straps connected	2	2	L
7	Testing of ROV cameras, electric actuators, and lights.	High voltage, electrical shock, moving actuators.	Personnel Injury / Environmental Pollution / Damage to Equipment	2	2	M	Good Comms, no personnel working on ROV, ground straps connected	1	1	L

Doc ID : DO-HSE-FRM-138
 Doc Name : Task Risk Assessment Form
 Parent Doc ID : DO-HSE-PRO-074 Risk Assessment Procedure

Rev : A
 Date : 29/07/2021
 Page : 2 of 3

8.	Energize HPU for ROV	Burst hose projecting material or fluid, unanticipated movement of hydraulic components (thrusters/manipulators). HPU motor overheating, and fluid leak from hydraulic circuit.	Personnel Injury / Environmental Pollution / Damage to Equipment	3	4	S	Good comms, all personnel wearing proper PPE, oil absorbent pads on hand, remove nonessential personnel, barricades, deck personnel to keep safe distance, announce HPU energizing prior to start-up. Good comms. Keep an eye on motor temperature	2	2	L
9.	Enable control and function check thrusters. Leave Min Pressure of 500 PSI	Appendages or foreign objects in propeller path, or tools in path being projected, burst hose projecting material or fluid. Fluid leak from hydraulic circuit	Personnel Injury / Environmental Pollution / Damage to Equipment	3	4	S	Good comms, all personnel wearing proper PPE, oil absorbent pads on hand, remove nonessential personnel, barricades, deck personnel to keep safe distance. Deck personnel to visually verify all thrusters clear of tools and foreign objects. The pilot will announce HPU energizing prior to start-up.	2	2	L
10.	Pilot is to Disable thruster control	Continued thruster rotation, Accidental operation thrusters while continuing with other checks.	Personnel Injury / Environmental Pollution / Damage to Equipment	2	2	M	De-select flight on GUI and confirm with technician on deck that thrusters are not rotating.	1	1	L
11.	Enable and function check Manipulators	Impacting, crushing, or pinning of personnel, burst hose causing fluid to leak from hydraulic circuit. Impact of Manipulators to ROV frame, deck, or railing.	Personnel Injury / Environmental Pollution / Damage to Equipment	4	4	S	Good comms, personnel always clear of Manipulators during testing. Erect barricades, remove nonessential personnel, ensure manipulator activity is announced prior to moving. Oil absorbent pads on hand. Pilot must inform operator if manipulators is not clear of any deck objects.	2	2	M
12.	De-energize HPU for ROV	Fluid leak from hydraulic circuit.	Environmental Pollution / Damage to Equipment	2	3	M	Good comms, spill kits available	1	1	L

TRA Approval	Name	Position	Signature	Date
By signing, the Approver confirms that the TRA has been reviewed and considers the task acceptable to proceed with residual risk meeting the acceptance criteria of DO Risk Matrix.				

*Reference DO-HSE-FRM-140 for DeepOcean Risk Assessment Matrix (RAM) and Guidewords