515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 1 OF 89

ESTIMATED MHR: ALL

STAGE: ALL

RUN DATE: 10/6/2023

RUN TIME : 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

STATUS: ALL JSN RANGE SELECTED: ALL

ORIG-STAGE: ALL PERIOD: ALL

ATA NO: ALL DISPOSITION CODE: ALL ZONE: ALL AREA: ALL

DEFECT TYPE: ALL

ORIGINATING CUST REF NO:

TRADE: ALL CUST ENDORSE: ALL

CTRL CODE :					TYPE CODE:	ORIGINATOR: ALL			
	ZONE	STG						STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL0017	500	NRR	AE	2800	TA28000201	PERFORM A/C DE-FUELLING FOR MAINTENANCE	L001	COMP	09/20/2023
	WNG								0.0
								-	0.0
XJL0025	500	NRR	AE	2800	TA28000201	PERFORM A/C FUEL SUMP DRAIN FOR FUEL TANK MAINTENANCE	L002	COMP	09/24/2023
	F/T								0.0
								-	0.0
XJL0033	100	NRP	AE	07	777-BM-CONTROL-	TOWING A/C FOR MAINTENANCE/OPERATIONAL NEEDS	L003	WIP	09/20/2023
	FUS				CARD-01				0.0
						1C 1 PERFORM AIRPLANE TOWING FROM OUTSIDE 3 BAY TO BAY9.			5.0
								-	5.0
XJL0041	100	NRP	AE	0711	777-900002-01-1-01	JACK THE AIRPLANE FOR MAINTENANCE	L004	WIP	09/20/2023
	FUS					REF TO XMN TASK CARD: TA07000101-BOE			0.0
						1C 1 REMOVE BODY FAIRING 191SL &192SR			0.0
						1C 2 AIR MOD SIMULATION PREPARATION			0.0
						1C 3 LIFT THE AIRCRAFT WITH JACK			0.0
						1C 4 LOWER THE AIRCRAFT OFF OF THE JACK			0.0
						2C 5 REINSTALL THE BODYFAIRING191SL&192SR			0.0
						2C 6 AIR MODE SIMULATION RESTORATION			0.0
						2C 7 PERFORM WOW LOAD SENSOR CALIBRATION			0.0
								-	0.1
XJL0058	200	NRR	AI	2500	777-53-904-00-01	CABIN G1 GALLERY R112 TOASTER MACHINE TRACK FOUND DAMAGE	L005	OPEN	09/20/2023
7.02000	CAB			2000	65 65 65 65	OF BITTER OF BEECK TO THE TOTAL TOTAL BUILDING	2003	OFLIN	4.0
								_	
V II 0000	000	NDD	43.7	0500	777 50 004 00 04				4.0
XJL0066	200 CAB	NRR	AV	2500	777-53-904-00-01	CABIN VCC V01 COMPARTMENT INNER DOOR CLOSE SWITCH BOX FOUND DAMAGE	L006	WIP	10/04/2023
	OAD							_	0.0
									0.0
XJL0074	200	NRP	SS	25	777-25-050-08-CX-R- 01	PEY SEAT CONSOLE PTV ARM OPERATION FOUND TIGHTEN AT 30D E F G 31A C 32H K TOTAL:8EA	L007	COMP	10/04/2023
	CAB				• .				8.0
								-	8.0

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: RUN DATE: 10/6/2023

2 OF 89

RUN TIME : 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

> ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL0082	200	NRR	Al	2541	777-53-904-00-01	CABIN ZONE B LAV B TOILET SEAT COVER BUMPER	R FUNCTION DISAPPEARED	L008	COMP	10/02/2023
	CAB									4.0
									-	4.0
XJL0090	200	NRR	ΑI	2541	777-53-904-00-01	CABIN ZONE A LAV A TOILET SEAT COVER BUMPER	R FUNCTION DISAPPEARED	L009	COMP	10/02/2023
	CAB									4.0
									-	4.0
XJL0108	200	NRR	ΑI	2541	777-53-904-00-01	CABIN ZONE A LAV A FAUCET FOUND DAMAGE		L010	WIP	09/28/2023
	CAB									4.0
									-	4.0
XJL0116	200	NRR	ΑI	2531	777-53-904-00-01	CABIN ZONE A G1 GALLERY PLACARD FOUND CHIF	PPED	L011	WIP	09/29/2023
	CAB									3.0
									-	3.0
XJL0124	200	NRR	ΑI	2500	777-53-908-00-01	CABIN FB2 STOWAGE COMPARTMENT S1CA TOP D	OOR SNUBBER FOUND WEAK	L012	COMP	09/28/2023
	CAB									1.0
									-	1.0
XJL0132	200	NRR	Al	2500	777-53-908-00-01	CABIN FB2 STOWAGE COMPARTMENT S2CA TOP D	OOR SNUBBER FOUND WEAK	L013	COMP	09/28/2023
	CAB									1.0
									-	1.0
XJL0140	200	NRR	Al	2531	777-53-908-00-01	CABIN ZONE B GALLERY G2 PLACARD FOUND CHIF	PPED	L014	OPEN	09/20/2023
	CAB									4.0
									-	4.0
XJL0157	200	NRR	Al	2531	777-53-908-00-01	CABIN ZONE B GALLERY G3 PLACARD FOUND CHIF	PPED	L015	OPEN	09/20/2023
	CAB									4.0
									-	4.0
XJL0165	200	NRR	SS	2525	777-C252440-04-02-	EY PAX SEAT BACKREST TABLE FND TIGHT AT :40H	H J K 41H J K 42H J K 43H J K 44H J K 45H J K 46H J K TTL:21EA	L016	WIP	09/25/2023
	CAB				01					4.0
									-	4.0

0PPC DISTRIBUTION:

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

ORIGINATOR: ALL

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

3 OF 89 PAGE:

RUN TIME :

RUN DATE: 10/6/2023

14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

TYPE CODE:

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL ALL

TRADE: ALL DEFECT TYPE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE:

DEFECT DESCRIPTION JSN	STATUS	UPDATED DATE
DEFECT DESCRIPTION JSN		
52. 20. 5200 1101	STATUS	EST Mhr
RACK FOUND WORN 4 EA L017	COMP	09/28/2023
		4.0
	-	4.0
K L018	OPEN	09/20/2023
		12.0
	-	12.0
MISSING L019	COMP	10/02/2023
		1.0
	-	1.0
E F G 41D E F G 42D E F G 43D E F G 44D E F G 45D E F L020	WIP	09/25/2023
		6.0
	-	6.0
T FOUND DIRTY L021	COMP	10/03/2023
		8.0
	-	8.0
L022	WIP	09/29/2023
		4.0
	-	4.0
ET FOUND TORN. L023	WIP	10/04/2023
		8.0
	-	8.0
FOUND TORN. L024	WIP	10/04/2023
		16.0
	-	16.0
KLOOSE L025	WIP	09/29/2023
		5.0
	-	5.0
	EF G 41D EF G 42D EF G 43D EF G 44D EF G 45D EF L020 ET FOUND DIRTY L022 ET FOUND TORN. L023	K LO18 OPEN OMISSING LO19 COMP EF G 41D EF G 42D EF G 43D EF G 44D EF G 45D EF LO20 WIP ET FOUND DIRTY LO21 COMP LO22 WIP FOUND TORN. LO23 WIP FOUND TORN. LO24 WIP

0PPC DISTRIBUTION:

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

4 OF 89 PAGE: RUN TIME :

RUN DATE: 10/6/2023

14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

TYPE CODE:

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ATA NO: ALL ORIGINATING CUST REF NO: ZONE: ALL DISPOSITION CODE: ALL ALL

ORIGINATOR: ALL

TRADE: ALL DEFECT TYPE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE:

CIRL CODE:					TYPE CODE:	URIGINATUR: ALL				
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
KJL0264	100	NRR	Al	2580	777-53-822-00-01	FWD CARGO COMPARTMENT BILGE AREA IN:	SULATION BLANKET CLAMPS FOUND MISSING.	L026	COMP	10/03/2023
	LWR									1.0
									-	1.0
KJL0272	100	NRR	Al	2580	777-53-862-00-01	AFT CARGO COMPARTMENT BILGE AREA INS	ULATION BLANKET FOUND TORN.	L027	COMP	09/30/2023
	LWR									8.0
									-	8.0
(JL0280	100	NRR	Al	2580	777-53-862-00-01	AFT CARGO COMPARTMENT BILGE AREA INS	ULATION BLANKET FOUND DIRTY.	L028	COMP	09/30/2023
	LWR									16.0
									-	16.0
(JL0298	100	NRR	Al	2580	777-53-862-00-01	AFT CARGO COMPARTMENT BILGE AREA INS	ULATION BLANKET CLAMPS FOUND MISSING.	L029	WIP	10/03/2023
	LWR									1.0
									-	1.0
JL0306	100	NRR	Al	2580	777-53-854-00-01	AFT CARGO COMPARTMENT SIDEWALL AREA	INSULATION BLANKET FOUND TORN.	L030	WIP	10/03/2023
	LWR									16.0
									-	16.0
JL0314	200	NRR	Al	5600	777-53-904-00-01	CABIN A ZONE L2 WINDOW DUST COVER FOL	IND SCRATCHED	L031	COMP	10/02/2023
	CAB									4.0
									-	4.0
JL0322	100	NRR	Al	5300	777-53-874-00-01	BULK CARGO COMPARTMENT FLOOR PANEL	SCREWS FOUND WORN.	L032	WIP	10/03/2023
	LWR									1.0
									-	1.0
(JL0330	100	NRR	Al	2580	777-53-874-00-01	BULK CARGO COMPARTMENT BILGE AREA IN	SULATION BLANKET FOUND BROKEN	L033	COMP	09/30/2023
	LWR							2000		5.0
									-	5.0
JL0348	200	NRR	SS	2525	777-C252440-04-02-	EY PAX SEAT BACKREST TABLE FND TIGHT A	T : 59H J K 60H J K 61H J K 62H J K 63H J K 64H J K 65H J K 66H J K 67H J	L034	WIP	09/25/2023
	CAB				01	K 68H J K 69H J K 70H J K 71H J K TTL:39EA		2004	****	8.0
									-	8.0
										8.0

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE :

5 OF 89

RUN DATE: 10/6/2023

RUN TIME : 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

OTTLE GODE .	ZONE	STG			111 2 0052.	ordon vitore.			STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL0355	200 CAB	NRR	SS	2525	777-C252440-04-02- 01	EY PAX SEAT BACKREST TABLE FND TIGH TTL:20EA	F AT : 39A C 40A B C 41A B C 42A B C 43A B C 44A B C 45A B C 46A B C	L035	WIP	09/25/2023
	CAB									4.0
									-	4.0
XJL0363	100	NRR	Al	2580	777-53-874-00-01	BULK CARGO COMPARTMENT SIDEWALL A	REA INSULATION BLANKET FOUND BROKEN	L036	WIP	10/03/2023
	LWR									4.0
									-	4.0
XJL0371	100	NRR	Al	2580	777-53-874-00-01	BULK CARGO COMPARTMENT BILGE AREA	INSULATION BLANKET FOUND DIRTY	L037	COMP	09/30/2023
	LWR									5.0
									-	5.0
XJL0389	200	NRR	Al	2541	777-53-904-00-01	CABIN ZONE B LAV D FAUCET FOUND MAL	FUNCTION	L038	WIP	09/28/2023
	CAB									4.0
									-	4.0
XJL0397	200	NRR	Al	5600	777-53-904-00-01	CABIN A ZONE R1 WINDOW DUST COVER F	OUND SCRATCHED	L039	COMP	10/02/2023
	CAB									4.0
									-	4.0
XJL0405	100	NRR	Al	2552	777-53-818-00-01	FWD CGO COMP'T CEILING PNL FIREPROC	F TAPE FOUND AGED.	L040	OPEN	09/20/2023
	LWR									1.0
									-	1.0
XJL0413	100	NRR	Al	2552	777-53-818-00-01	FWD CGO COMP'T S/W PNL FIREPROOF TA	PE FOUND AGED.	L041	OPEN	09/20/2023
	LWR									1.0
									-	1.0
XJL0421	200	NRR	Al	2531	777-53-908-00-01	CABIN ZONE B GALLERY G2 COMPARTMEN	IT 210 DOOR LATCH DAMAGE	L042	COMP	09/28/2023
	CAB							20.2		3.0
									-	3.0
XJL0439	100	NRR	Al	2552	777-53-854-00-01	AFT CGO COMP'T CEILING PNL FIREPROOI	TAPE FOUND AGED.	L043	WIP	10/05/2023
3_2.30	LWR		- **					L043	4 4 11	1.0
									-	
										1.0

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 6 OF 89

RUN DATE: 10/6/2023

RUN TIME : 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CIRL CODE:					TYPE CODE:	ORIGINATOR: ALL			
	ZONE	STG						STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL0447	100	NRR	Al	2552	777-53-854-00-01	AFT CGO COMP'T S/W PNL FIREPROOF TAPE FOUND AGED.	L044	WIP	10/05/2023
	LWR								1.0
								-	1.0
XJL0454	100	NRR	Al	2552	777-53-822-00-01	FWD CGO COMPARTMENT FLOOR PNL SCREWS FOUND WORN.	L045	COMP	10/03/2023
	LWR								1.0
								-	1.0
XJL0462	200	NRR	Al	2531	777-53-908-00-01	CABIN ZONE B GALLERY G3 OVEN 3 4 5 DOOR EXTERNAL PLACARD FOUND CHIPPED	1.040	OPEN	
AJL0402	CAB	INIXIX	Ai	2001	777-33-900-00-01	CADIN ZONE D GALLERT G3 OVEN 3 4 3 DOOR EXTERNAL PLACARD FOUND CHIFFED	L046	OPEN	09/20/2023
								_	3.0
									3.0
XJL0470	200	NRR	Al	2524	777-53-912-00-01	CABIN L/R 3 DOOR O/B FWD CLOSETS TOP SEAL FOUND DAMAGE	L047	OPEN	09/20/2023
	CAB								6.0
								-	6.0
XJL0488	100	LOG	Al	25		AS PER CX B-KPV OPEN TL ENTRIES TL3517: EQUIP COOLING FAN R(STATUS)	L048	OPEN	09/20/2023
	LWR								0.0
						1C 1 PLS MAKE LOG BOOK ENTRY.			0.2
						2C 2 REMOVE THE ELECTRICAL CONNECTOR OF THE EQUIPMENT COOLING FAN 2C 3 REMOVE THE EQUIPMENT COOLING FAN			0.5
						2C 3 REMOVE THE EQUIPMENT COOLING FAN 2C 4 CONNECT THE ELECTRICAL CONNECTOR OF THE EQUIPMENT COOLING FAN			2.0 0.5
						2C 5 INSTALL THE EQUIPMENT COOLING FAN			2.0
						3C 6 CARRY OUT THE EQUIPMENT COOLING FAN INSTALLATION TEST			1.0
								-	6.2
XJL0496	100	NRR	Al	2552	777-53-818-00-01	FWD CGO COMP'T CEILING PNL SCREWS FOUND WORN.	L049	OPEN	09/20/2023
	LWR						2043	OI LIV	1.0
								_	
V II 0504	100	NDD		0550	777 50 040 00 04	EWD COO COMPARTMENT ON THE COREMO FOLIND WORK			1.0
XJL0504	100 LWR	NRR	Al	2552	777-53-818-00-01	FWD CGO COMPARTMENT S/W PNL SCREWS FOUND WORN.	L050	OPEN	09/20/2023
	LVVIX							_	1.0
									1.0
XJL0512	200	NRR	Al	2524	777-53-912-00-01	CABIN R 3 DOOR O/B FWD CLOSETS FWD SEAL RETAINER FOUND DETACHED	L051	COMP	10/02/2023
	CAB								6.0
								-	6.0

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

7 OF 89 PAGE:

RUN TIME :

RUN DATE: 10/6/2023

14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL

PERIOD: ALL

ESTIMATED MHR: ALL DISPOSITION CODE: ALL

ORIGINATING CUST REF NO: ALL

TRADE: ALL

ATA NO: ALL ZONE: ALL CUST ENDORSE: ALL

STAGE: ALL

DEFECT TYPE : ALL AREA: ALL TYPE CODE: ORIGINATOR: ALL

	CODE	

TINE CODE .	ZONE	STG			TIFE CODE.	ONGINATOR: ALL			STATUS	UPDATED DATE
JOB NO	AREA	316	TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
(JL0520	200	NRR	Al	2524	777-53-912-00-01	CABIN L3 DOOR O/B FWD CLOSETS FWD SEAL RET.		L052	COMP	10/02/2023
	CAB									6.0
									-	6.0
JL0538	100	NRR	Al	2552	777-53-854-00-01	AFT CGO COMP'T CEILING PNL SCREWS FOUND WO	DRN.	L053	OPEN	09/20/2023
	LWR									1.0
									-	1.0
JL0546	100	NRR	Al	2552	777-53-854-00-01	AFT CGO COMPARTMENT S/W PNL SCREWS FOUNI	D WORN.	L054	OPEN	09/20/2023
	LWR									1.0
									-	1.0
JL0553	100	NRR	Al	2552	777-53-862-00-01	AFT CGO COMPARTMENT FLOOR PNL SCREWS FO	UND WORN.	L055	WIP	10/03/2023
	LWR									1.0
									-	1.0
JL0561	200	NRR	SS	2525	777-C252440-04-02-	EY PAX SEAT BACKREST TABLE FND TIGHT AT :59A	B C 60A B C 61A B C 62A B C 63A B C 64A B C 65A B C 66A B C 67A	L056	WIP	09/25/2023
	CAB				01	B C 68A B C 69A B C 70A B C 71A B C 72A C TTL:41EA				8.0
									-	8.0
JL0579	200	NRR	SS	2525	777-C252440-04-02-		D E F G 61D E F G 62D E F G 63D E F G 64D E F G 65D E F G 66D E F	L057	WIP	09/25/2023
	CAB				01	G 67D E F G 68D E F G 69D E G 70D E G 71D E G 72D	E G TTL: 48EA			9.0
									-	9.0
IL0587	400	NRP	CL	7100	777-900001-01-1-01	#1 ENG BOTH FAN COWLS DIRTY.		L058	COMP	10/03/2023
	ENG									4.0
									-	4.0
JL0595	400	NRP	CL	7100	777-900001-01-1-01	#2 ENG BOTH FAN COWLS DIRTY.		L059	COMP	10/03/2023
	ENG									4.0
									-	4.0
JL0603	400	NRP	CL	4900	777-900001-01-1-01	APU CAVITY DIRTY.		L060	COMP	10/03/2023
	ENG									6.0
									-	6.0

0PPC DISTRIBUTION:

REFERENCE NO: BMS571R1-2

ORIGINATING CUST REF NO: ALL

515653

REQUESTED BY:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: RUN DATE: 10/6/2023

8 OF 89

RUN TIME : 14:22

FINOSECT. AS COSTONIEN. CA ACTIFE. ITT AVENEUN. D-NFV CHECKTIFE.	PROJECT: XJ	CUSTOMER: CX	A/C TYPE: 777	A/C REGN: B-KPV	CHECK TYPE: 2C
--	-------------	--------------	---------------	-----------------	----------------

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

> ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CIRL CODE:					TYPE CODE:	URIGINATUR :	ALL			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL0611	400	NRP	CL	7100	777-900001-01-1-01	#1 ENG GEARBOX AREA DIRTY		L061	COMP	10/03/2023
	ENG									6.0
									-	6.0
XJL0629	400	NRP	CL	7100	777-900001-01-1-01	#2 ENG GEARBOX AREA DIRTY		L062	COMP	10/03/2023
	ENG									6.0
									-	6.0
XJL0637	400	NRP	CL	7800	777-900001-01-1-01	#1 ENG BOTH TR COWL DIRTY.		L063	COMP	10/03/2023
	ENG									6.0
									-	6.0
XJL0645	400	NRP	CL	7800	777-900001-01-1-01	#2 ENG BOTH TR COWL DIRTY.		L064	COMP	10/03/2023
	ENG									6.0
									-	6.0
XJL0652	400	NRP	CL	5400	777-900001-01-1-01	#2 PYLON AFT CAVITY DIRTY		L065	COMP	10/03/2023
	ENG									4.0
									-	4.0
XJL0660	400	NRP	CL	5400	777-900001-01-1-01	#1 PYLON AFT CAVITY DIRTY		L066	COMP	10/03/2023
	ENG									4.0
									-	4.0
XJL0678	400	NRP	PT	7100	777-900001-01-1-01	#2 ENG NOSE COWL INLET ACOUSTIC	SURFACE PAINT IN POOR CONDITION.	L067	OPEN	09/20/2023
	ENG									8.0
									-	8.0
XJL0686	400	NRP	PT	7100	777-900001-01-1-01	#1 ENG NOSE COWL INLET ACOUSTIC	SURFACE PAINT IN POOR CONDITION.	L068	OPEN	09/20/2023
	ENG							2000	0. 2	8.0
									-	8.0
XJL0694	400	NRP	PT	7800	777-900001-01-1-01	#2 ENG BOTH TR COWL EXTERNAL DU	JCT AFT ACOUSTIC SURFACE PAINT IN POOR CONDITION.	L069	OPEN	09/20/2023
	ENG							5009	OI LIV	8.0
									-	
										8.0

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 9 OF 89

RUN DATE: 10/6/2023

RUN TIME: 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CIRL CODE :					TYPE CODE:	ORIGINATOR: ALL				
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFE	ECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL0702	400	NRP	PT	7800	777-900001-01-1-01	#1 ENG BOTH TR COWL EXTERNAL DUCT AFT ACOUSTIC SURFACE P	AINT IN POOR CONDITION.	L070	OPEN	09/20/2023
	ENG									8.0
									-	8.0
XJL0710	400	NRP	PT	7100	777-900001-01-1-01	#2 ENG RH FAN COWL INNER LOWER SURFACE PAINT IN POOR CONI	DITION.	L071	OPEN	09/20/2023
	ENG									8.0
									-	8.0
XJL0728	400	NRP	SM	7100	777-900001-01-1-01	#2 ENG NOSE COWL LIP SKIN MULTIPLE FND CORROSION.		L072	WIP	09/24/2023
	ENG									0.0
						1C 1 REMOVE THE LIP SKIN CORROSION				60.0
						1C 2 PTOTECT THE REWORK AREA				4.0
						1C 3 NDT THICKNESS CHK				180.0
						1C 4 NDT CRACK CHK				20.0
									-	264.0
XJL0736	400	NRP	SM	7100	777-900001-01-1-01	#1 ENG NOSE COWL LIP SKIN MULTIPLE FND CORROSION.		L073	WIP	09/23/2023
	ENG									0.0
						1C 1 REMOVE THE LIP SKIN CORROSION				40.0
						1C 2 PTOTECT THE REWORK AREA				4.0
						1C 3 NDT THICKNESS CHK				130.0
						1C 4 NDT CRACK CHK				20.0
									-	194.0
XJL0744	400	NRP	SM	5400	777-900001-01-1-01	#2 PYLON ACC PNL 12EA ANCHOR NUTS FND BROKEN.		L074	COMP	10/02/2023
	ENG									6.0
									-	6.0
XJL0751	400	NRP	SM	5400	777-900001-01-1-01	#1 PYLON ACC PNL 13EA ANCHOR NUTS FND BROKEN.		L075	COMP	10/02/2023
	ENG									6.0
									-	6.0
XJL0769	400	NRP	AE	5400	777-900001-01-1-01	#2 PYLON ACC PNL 12EA SCREWS HEAD FND WORN.		L076	WIP	09/28/2023
	ENG							20.0	****	2.0
									-	
										2.0

0PPC DISTRIBUTION:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

10 OF 89 PAGE: RUN DATE: 10/6/2023

RUN TIME : 14:22

REFERENCE NO: PROJECT: XJ

REQUESTED BY:

CUSTOMER: CX

A/C TYPE: 777

A/C REGN: B-KPV

CHECK TYPE: 2C

ESTIMATED MHR: ALL

JSN RANGE SELECTED: ALL ORIGINATING CUST REF NO: ALL

STATUS: ALL

ORIG-STAGE: ALL ATA NO: ALL

PERIOD: ALL ZONE: ALL

DISPOSITION CODE: ALL

DEFECT TYPE : ALL

CTRL CODE:

515653

BMS571R1-2

TRADE: ALL TYPE CODE:

CUST ENDORSE: ALL ORIGINATOR: ALL

AREA: ALL

STAGE: ALL

LIDDATED DATE

0747110

	ZONE	STG					STA	ATUS UPDATED	DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION	JSN STA	ATUS EST Mhr	
XJL0777	200	NRR	Al	25	777-53-920-00-01	M/D L LAV I/B AFT BABY BASSINET TABLE MIRROR BUMPER MISSING	L077 CO	MP 09/26/2023	
	CAB								1.0
									1.0
XJL0785	400	NRP	AE	5400	777-900001-01-1-01	#1 PYLON ACC PNL 13EA SCREWS HEAD FND WORN.	L078 WII	09/28/2023	
	ENG							:	2.0
									2.0
XJL0793	200	NRR	Al	25	777-53-920-00-01	M/D L LAV I/B AFT BIG MIRROR FOUND CRACKED	L079 OP	EN 09/20/2023	
	CAB							4	4.0
									4.0
XJL0801	200	LOG	AV	23		"AS PER CX B-KPV DEFERRAL REPORT ITEM ADD A090: ES0 10 1- EENABLED SYSTEM, HARDWARE,	L080 CO	MP 10/02/2023	
	CAB					IPAD,ACCOMPLISHMENT OF A/C ETECHLOG PROLONGED PARKING PROCEDURES, CABIN ETECHLOG IPAD DEACTIVATEDADD RAISED FOR DEACTIVATION OF CABIN ETECHLOG IPAD AS PER ELPM CHAPTER		(0.0
						2-2.1.4.2,ACTIONED IN ACCORDANCE WITH OTHER ELPM CHAPTER 2-2.1.4.2.(PLS REF TO ATTACHED "CX DEF REPORT" FOR THE REQUIRED ACTION ITEM)	FERRAL		
						1C 1 PLS MAKE LOG BOOK ENTRY		0.2	2
									0.2
XJL0819	200	NRR	Al	25	777-53-920-00-01	M/D L LAV FLOOR PAN FOUND CRACKED	L081 OP	EN 09/20/2023	
	CAB							4	4.0
									4.0
XJL0827	400	NRP	GW	5400	777-900001-01-1-01	#1 PYLON ACC PNL 8EA SCREWS SEIZED.	L082 CO	MP 10/02/2023	
	ENG							{	8.0
									8.0
XJL0835	400	NRP	GW	5400	777-900001-01-1-01	#2 PYLON ACC PNL 9EA SCREWS SEIZED.	L083 CO	MP 10/02/2023	
	ENG							•	9.0
									9.0
XJL0843	200	NRR	Al	25	777-53-916-00-01	G4R GALLEY FAUCET FOUND WATER LEAKING	L084 WII	09/25/2023	
	CAB								0.0
						1C 1 REPLACE GALLEY FAUCET 1C 2 C/O GALLEY FAUCET WATER LEAK CHECK		3.0 0.5	
						10 L 0/0 OALLET MODEL WATER LEAR OFFLOR			
									ა.ⴢ

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 11 OF 89

RUN DATE: 10/6/2023

RUN TIME : 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL

ALL PERIOD: ALL ESTIMATED MHR: ALL
ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

ATA NO: ALL

TRL CODE :					TYPE CODE:	ORIGINATOR: ALL			
	ZONE	STG						STATUS	UPDATED DAT
OB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
.0850	200	LOG	SS	25		AS PER CX B-KPV DEFERRAL REPORT ITEM ADD A091: 251 6 08 SEAT BELT PROBLEM. REF CMADD CM503. SEATS	L085	OPEN	09/20/2023
	CAB					11A,12A,16A,17A,18A,19A,20A,21A,22A,23A,24A,25A,25G,26A,26K AIRBAG SEAT BELT INFLATOR REPLACED AND NEW INFLATOR EXPIRY DATE: 0621 / MAF DATE: A0711, LESS THAN 2 YEARS LIFE BUT OVER 100 DAY. (CONTINUE TO SWS ITEM 1)			0.0
						1C 1 AS PER CMADD 503 INSTRUCTION NEW INFLATOR EXPIRY DATE LESS THAN 2 YEARS LIFE BUT OVER 100 DAYS, RAISED ADD. ACTIONED IAW CMM 25-02-05 REV SEP 2020. (PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS)			0.0
						1C 2 PLS MAKE LOG BOOK ENTRY			0.2
								-	
	000	NDD		0.5	777 50 040 00 04				0.2
0868	200 CAB	NRR	Al	25	777-53-916-00-01	M/D H LAV FAUCET FOUND WATER LEAKING	L086	WIP	09/28/2023
	CAB								0.0
						1C 1 REPLACE LAV FAUCET			4.0
						1C 2 C/O LAV FAUCET WATER LEAK CHECK			0.5
								-	4.5
	400	LOG	AV	71		AS PER CX B-KPV DEFERRAL REPORT ITEM ADD A095: OB2 9 ITEM NOT FOUND IN FAULT TREE (REFER TO REMARK),	L087	OPEN	09/20/2023
	ENG					ENGINE 1 ENG #1 IDG FILTER BLOCKED INDICATION ON MFD. AMM 12-22-07-200-802 IDG OIL FILTER CONDITION CHECK FOLLOWED. IDG DPI RED BUTTON INSPECTED FOUND NOT EXTENDED. FILTER REMOVED AND INSPECTED NIL DEBRIS. FILTER REPLACED IAW 24-11-01-000-801-001. (CONTINUE TO SWS ITEM 1)			0.0
						1C 1 FAULT STILL REMAINS DURING EGR IDLE. DEFECT DEFERRED. ADD RAISED AS PER AMM 12-22-07-200-802 FOR INSPECTION EVERY 7 DAYS 4 TIMES FOR DPI EXTENSION. ACTIONED IN ACCORDANCE WITH AMM 12-22-07-200-802			0.0
						REV 05 MAY 2023. (PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS) 1C 2 PLS MAKE LOG BOOK ENTRY.			0.2
								-	0.2
0884	100	LOG	ΑE	53		AS PER B-KPV A/C EXTERNAL DEFECT/REPAIR LIST ITEM FUS 3 : RH FX SKIN TOTAL 29EA HEAT DAMAGE AT	L088	OPEN	09/20/2023
	FUS					FASTENERS DUE LIGHTNING STRIKE LOC FROM STN 200 TO 2200 AND STR S36R TO S45R.			0.0
						1C 1 PLS MAKE LOG BOOK ENTRY			0.2
								-	0
1892	200	NRR	CL	2524	777-53-920-00-01	CAB ALL CURTAINS FOUND DIRTY			
0092	CAB	INICIC	CL	2524	777-55-920-00-01	CAB ALL CURTAINS FOUND DIRTY	L089	WIP	09/22/2023
	CAB								0.0
						1C 1 REMOVE ALL CABIN CURTAIN			2.0
						1C 2 CLEAN THE CURTAIN			10.0
						1C 3 INSTALL CAB ALL CURTAIN			6.0
								-	18.

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 12 OF 89

RUN TIME:

RUN DATE: 10/6/2023

14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL

PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO:

ALL

TRADE: ALL

CUST ENDORSE: ALL

ZONE: ALL AREA: ALL

DISPOSITION CODE: ALL

STAGE: ALL

CTRL CODE:

DEFECT TYPE : ALL

TYPE CODE:

ORIGINATOR: ALL

ATA NO: ALL

	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL0900	200 CAB	NRR	CL	2527	777-53-904-00-01	COCKPIT ALL CARPETS FOUND WORN		L090	COMP	10/06/2023
	CAD					1C 1 REMOVE COCKPIT FLOOR CARP	- -			0.0
						1C 1 REMOVE COCKPIT FLOOR CARP 1C 2 FABICATE COCKPIT FLOOR CARP				2.0 0.0
						1C 3 INSTALL COCKPIT FLOOR CARPE				6.0
									-	8.0
XJL0918	200	NRR	ΑI	25	777-53-904-00-01	#1 AND #2 DOOR GALLEY AREA FLOOR MAT THE	RESHOLD FOUND AGED	L091	WIP	10/05/2023
	CAB									8.0
									-	8.0
XJL0926	200	NRR	ΑI	25	777-53-904-00-01	#4 AND #5 DOOR GALLEY AREA FLOOR MAT THE	RESHOLD FOUND AGED	L092	COMP	10/03/2023
	CAB									8.0
									-	8.0
XJL0934	200	NRR	ΑI	25	777-53-920-00-01	M/D L AND M LAV WASTE COMPT DOOR INSIDE 2	PEA SCREWS MISSING.	L093	COMP	09/28/2023
	CAB									1.0
									-	1.0
XJL0942	200	NRR	ΑI	25	777-53-912-00-01	M/D G LAV TOILET SHROUD AFT CLOURSE PANE	EL LOWER AREA CRACKED	L094	COMP	10/02/2023
	CAB									2.0
									-	2.0
XJL0959	200	NRR	ΑI	25	777-53-912-00-01	M/D G LAV UPPER CLOSE OUT SEAL FOUNS DET	ACHED	L095	COMP	10/02/2023
	CAB									1.0
									-	1.0
XJL0967	200	LOG	ΑI	25		AS PER CX B-KPV DEFERRAL REPORT ITEM ADD	A097: PBE EXPIRED. QTY 1 EXPIRED AT LOCATION FWD FACE OF	L096	COMP	09/28/2023
	CAB					AFT BULKHEAD ABOVE 2 ND OBSERVER SEAT. (REQUIRED ACTION ITEMS)	PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE			0.0
						1C 1 PLS MAKE LOG BOOK ENTRY.				0.2
									-	0.2
XJL0975	200	LOG	ΑI	35			A098: OFCR PORTABLE BREATHING EQUIPMENTS FOUND EXPIRED.	L097	COMP	09/30/2023
	CAB					REQUIRED ACTION ITEMS)	(PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE			0.0
						1C 1 PLS MAKE LOG BOOK ENTRY.				0.2
									-	0.2

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 13 OF 89 RUN DATE: 10/6/2023

10/0/202

RUN TIME : 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE :					TYPE CODE:	ORIGINATOR: ALL			
	ZONE	STG						STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL0983	200	LOG	Al	35		AS PER CX B-KPV DEFERRAL REPORT ITEM ADD A099: OFAR PORTABLE BREATHING EQUIPMENTS FOUND EXPIRED. REPLACEMENT DEFERRED FOR TWO PBE AT OFAR STATION. (PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR	L098	COMP	09/28/2023
	CAB					THE REQUIRED ACTION ITEMS)			0.0
						1C 1 PLS MAKE LOG BOOK ENTRY			0.2
								_	0.2
XJL0991	200	NRR	Al	2524	777-C252420-01-04- 02	CABIN FB2 SEAT RETRACTABLE ARMREST FOUND STIFF TO OPERATE FROM 11D TO 20D TTL 10EA	L099	OPEN	09/20/2023
	CAB				02				27.5
								-	27.5
XJL1007	200	NRR	SS	2527	777-53-912-00-01	M/D ALL AISLE AREA FLOOR CARPETS FOUND WORN	L100	WIP	09/22/2023
	CAB								0.0
						1C 1 REMOVE M/D ALL AISLE AREA FLOOR CARPETS FLOOR CARPETS.			44.0
						1C 2 REMOVE SEAT TRACK COVER 1C 3 FABRICATE M/D ALL AISLE AREA FLOOR CARPETS FLOOR CARPETS.			2.0 0.0
						1C 4 INSTALL M/D ALL AISLE AREA FLOOR CARPETS FLOOR CARPETS.			88.0
						2C 5 INSTALL SEAT TRACK COVER			2.0
								-	136.0
XJL1015	200	NRR	Al	25	777-53-912-00-01	G LAV FWD O/B SIDE CLOSE OUT SEAL FOUND MISSING	L101	COMP	09/26/2023
	CAB						2.0.	00	2.0
								-	2.0
XJL1023	200	NRR	Al	2524	777-C252420-01-04-	CABIN FB2 SEAT RETRACTABLE ARMREST FOUND STIFF TO OPERATE FROM 21D TO 26D TTL 5EA	L102	OPEN	09/20/2023
7021020	CAB	MINIX	711	2024	02	ONDITY BE GETT THE TOTALE AND THE TOTAL OF EACH ENTER THOM ETD TO 200 THE GET	L102	OPEN	27.5
								_	
V II 4004	222	NDD		0504	777 0050400 04 04				27.5
XJL1031	200 CAB	NRR	Al	2524	777-C252420-01-04- 02	CABIN FB2 SEAT RETRACTABLE ARMREST FOUND STIFF TO OPERATE FROM 11G TO 16G TTL 5EA	L103	WIP	10/04/2023
	OND							_	16.5
									16.5
XJL1049	200	NRR	Al	25	777-53-916-00-01	G4 GALLEY L/H FWD EMERGENCY EQUIPMENT RACK HANDLE CRACKED	L104	COMP	09/28/2023
	CAB								1.0
								-	1.0
XJL1056	200	NRR	Al	2524	777-C252420-01-04-	CABIN FB2 SEAT RETRACTABLE ARMREST FOUND STIFF TO OPERATE FROM 16G TO 26G TTL 10EA	L105	WIP	10/06/2023
	CAB				02				44.0
								-	44.0

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 14 OF 89

ESTIMATED MHR: ALL

RUN DATE: 10/6/2023

RUN TIME : 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL

ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CIRL CODE :					TYPE CODE:	ORIGINATOR: ALL				
	ZONE	STG							STATUS	UPDATED DATI
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFE	ECT DESCRIPTION	JSN	STATUS	EST Mhr
(JL1064	200	NRR	Al	25	777-53-916-00-01	G4 GALLEY L/H FWD VERTICAL BUMPER LOWER AREA ATTACH SCRI	EWS MISSING	L106	COMP	09/28/2023
	CAB									1.0
									-	1.0
JL1072	200	LOG	Al	35		AS PER CX B-KPV DEFERRAL REPORT ITEM ADD A100: CABIN PORTA	ABLE BREATHING EQUIPMENTS FOUND	L107	COMP	09/28/2023
	CAB					EXPIRED. SIX HAVE BEEN REPLACED TO SATISFY MEL REQUIREMEN				0.0
						DEFERRED TO HKG STATION. (PLS REF TO ATTACHED "CX DEFERRA 1C 1 PLS MAKE LOG BOOK ENTRY.	REPORT FOR THE REQUIRED ACTION ITEMS)			0.2
									-	0.2
JL1080	200	NRR	Al	25	777-53-920-00-01	M/D M LAV DOOR FRAME O/B EDGE SEAL FOUND DETACHED		L108	COMP	10/02/2023
	CAB									1.0
									-	1.0
JL1098	200	LOG	AV	23		AS PER CX B-KPV DEFERRAL REPORT ITEM ADD A101: 23 COMMUNIO	CATIONS ON CHK FOLIND WHE P ANTENNA (LWP)	L109	WIP	09/30/2023
121000	CAB	LOO	, , ,	20		SURFACE COATING MATERIAL MISSING AND ERODEDTO ADD DUE	TIME, VHF-R SYSTEM IS CONSIDERED INOP.	L109	VVIP	0.0
5.12						VHF-L OPERATES NORMAL. ACTIONED IN ACCORDANCE WITH OTHER MEL 23-12-01 REV MAY23 (PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS)			0.0	
						1C 1 PLS MAKE LOG BOOK ENTRY.	EWIO)			0.2
						2C 2 REPLACE R SYSTEM (UNDER AFT CGO) VHF ANTENN	NA A			4.0
						2C 3 PERFORM INSTALLATION TEST OF VHF ANTENNA				1.0
						2C 4 C/0 R VHF ANTENNA (UNDER AFT CGO) PAINT/MARK	PROCEDURE			2.0
									-	7.2
JL1106	200	NRR	Al	25	777-53-920-00-01	M/D DOOR O/H PANEL ATTACH LANYARDS TOTAL 11EA BROKEN		L110	WIP	10/02/2023
	CAB									1.0
									-	1.0
JL1114	200	NRR	Al	2524	777-C252420-01-04-	CABIN FB2 SEAT RETRACTABLE ARMREST FOUND STIFF TO OPERAT	TE FROM 11A TO 22A TTL 12EA	L111	OPEN	09/20/2023
	CAB				01					44.0
									-	44.0
JL1122	200	NRR	Al	25	777-53-920-00-01	M/D M LAV FLOOR PAN I/B EDGE RETAINER FOUND LOOSEN		L112	COMP	10/02/2023
	CAB									1.0
									-	1.0
L1130	200	NRR	Al	2524	777-C252420-01-04-	CABIN FB2 SEAT RETRACTABLE ARMREST FOUND STIFF TO OPERAT	TE FROM 22A TO 26A TTL 12EA	L113	OPEN	09/20/2023
	CAB	14141	,	LULT	01	5. S		LII3	OFEN	22.0
									_	
										22.0

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 15 OF 89 RUN DATE: 10/6/2023

RUN TIME : 14:22

PROJECT: XJ

515653

BMS571R1-2

CUSTOMER: CX

A/C TYPE: 777

A/C REGN: B-KPV

CHECK TYPE: 2C

ESTIMATED MHR: ALL

JSN RANGE SELECTED: ALL ORIGINATING CUST REF NO: ALL

STATUS: ALL

ATA NO: ALL ZONE: ALL

PERIOD: ALL

AREA: ALL

DISPOSITION CODE: ALL

DEFECT TYPE: ALL

CTRL CODE:

TRADE: ALL TYPE CODE:

CUST ENDORSE: ALL ORIGINATOR: ALL

ORIG-STAGE: ALL

STAGE: ALL

		U

	ZONE	STG			2 0052.			STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL1148	200	NRR	Al	2524	777-C252420-01-04-	CABIN FB2 SEAT RETRACTABLE ARMREST FOUND STIFF TO OPERATE FROM 11K TO 12K TTL 2EA	L114	WIP	10/04/2023
	CAB				01				11.0
								-	11.0
XJL1155	200	NRR	Al	25	777-53-920-00-01	M/D G6 GALLEY #7 COFFEE MAKER FOUND WATER LEAKING	L115	WIP	09/26/2023
	CAB								0.0
						1C 1 REPLACE COFFEE MAKER			1.0
						1C 2 C/O COFFEE MAKER FUNCTIONAL TEST			0.5
								-	1.5
XJL1163	200	NRR	Al	2524	777-C252420-01-04-	CABIN FB2 SEAT RETRACTABLE ARMREST FOUND STIFF TO OPERATE FROM 12K TO 26K TTL 14EA	L116	WIP	10/06/2023
	CAB				01				38.5
								-	38.5
XJL1171	200	NRR	Al	2524	777-C252420-01-05-	CABIN FB2 SEAT BACK SHELL NOMEX TRIM FOUND DETACHED AT COLUMN D 15EA	L117	WIP	09/26/2023
	CAB				02				22.5
								-	22.5
XJL1189	200	NRR	Al	2524	777-C252420-01-05-	CABIN FB2 SEAT BACK SHELL NOMEX TRIM FOUND DETACHED AT COLUMN G 13EA	L118	WIP	09/26/2023
	CAB				02				19.5
								-	19.5
XJL1197	200	NRR	Al	2524	777-C252420-01-05-	CABIN FB2 SEAT BACK SHELL NOMEX TRIM FOUND DETACHED AT COLUMN A 14EA	L119	WIP	09/26/2023
	CAB				01				21.0
								-	21.0
XJL1205	200	NRR	Al	2524	777-C252420-01-05-	CABIN FB2 SEAT BACK SHELL NOMEX TRIM FOUND DETACHED AT COLUMN K 11EA	L120	WIP	09/26/2023
	CAB				01				16.5
								-	16.5
XJL1213	200	NRR	Al	25	777-53-912-00-01	M/D #3 TO #4 DOOR L/H PARTITION BABY BASSINET SCREWS FOUND LOOSEN	L121	COMP	10/02/2023
	CAB								1.0
								-	1.0

REQUESTED BY:

REFERENCE NO:

DEFECT TYPE: ALL

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 16 OF 89 RUN DATE: 10/6/2023

RUN TIME: 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL

PERIOD: ALL

ESTIMATED MHR: ALL DISPOSITION CODE: ALL

ORIGINATING CUST REF NO:

ALL

TRADE: ALL

ATA NO: ALL ZONE: ALL CUST ENDORSE: ALL AREA: ALL

STAGE: ALL

CTRL CODE:

TYPE CODE: ORIGINATOR: ALL

CIRL CODE:					TYPE CODE:	ORIGINATOR: ALL			
	ZONE	STG						STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL1221	200	NRR	Al	25	777-53-912-00-01	M/D #3 TO #4 DOOR L/H PARTITION BABY BASSINET LOWER BUMPER FOUND MISSING	L122	COMP	09/25/2023
	CAB								1.0
								-	1.0
XJL1239	400	LOG	AE	71		AS PER CX B-KPV DEFERRAL REPORT ITEM PADD P023: HTP T13 WORK ORDER (WO) / WORK CARD REF W/O	L123	COMP	09/22/2023
	ENG					9571955/10 RAISE PADD TO PERFORM AN EDTO VERIFICATION FLT DUE TO FUEL & OIL SYSTEM DISTURBED ON BOTH ENGINES. PERFORM AN EDTO VERIFICATION FLIGHT DUE TO FUEL & OIL SYSTEM DISTURBED ON BOTH ENGINES.(CONTINUE TO SWS ITEM 1)			0.0
						1C 1 ACTIONED IN ACCORDANCE WITH OTHER EEPM 3-1 REV AUG 2022. (PLS REF TO ATTACHED "CX DEFERRAL			0.0
						REPORT" FOR THE REQUIRED ACTION ITEMS) 1C 2 PLS MAKE LOG BOOK ENTRY			0.2
								-	0.2
XJL1247	200	NRR	Al	25	777-53-912-00-01	M/D #3 TO #4 DOOR R/H PARTITION 1EA MAGAZINE RACK FOUND BROKEN	L124	COMP	10/02/2023
	CAB								1.0
								-	1.0
XJL1254	200	NRR	Al	25	777-53-912-00-01	M/D #3 TO #4 DOOR CTR PARTITION 1EA MAGAZINE RACK FOUND BROKEN	L125	COMP	10/02/2023
	CAB								1.0
								-	1.0
XJL1262	200	NRR	Al	25	777-53-916-00-01	G4L GLY LOWER COMPT AFT TIE DOWN COVER FOUND DETACHED	L126	COMP	10/03/2023
	CAB								1.0
								-	1.0
XJL1270	200	NRR	Al	25	777-53-916-00-01	G4L GLY L4-11.L4-12 COMPT CTR PARTITION 2EA TURN BUTTON FOUND STIFF	L127	COMP	10/02/2023
	CAB								1.0
								-	1.0
XJL1288	200	NRR	Al	25	777-53-916-00-01	G4L GLY 421 COMPT LOWER EDGE TURN BUTTON FOUND STIFF	L128	COMP	10/02/2023
	CAB								1.0
								-	1.0
XJL1296	200	NRR	Al	25	777-53-916-00-01	G4R GLY R4-12 ICE DRAWER TRAY FOUND LOOSEN	L129	COMP	10/02/2023
	CAB								2.0
								-	2.0

DISTRIBUTION: 0PPC REQUESTED BY: 515653

ALL

BMS571R1-2

REFERENCE NO:

ORIGINATING CUST REF NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 17 OF 89 RUN DATE: 10/6/2023

RUN TIME :

14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

STATUS: ALL PERIOD: ALL JSN RANGE SELECTED: ALL ORIG-STAGE: ALL ESTIMATED MHR: ALL

> ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE TYPE CODE ODICINATOD.

CTRL CODE :					TYPE CODE:	ORIGINATOR :	ALL			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL1304	200	NRR	Al	25	777-53-916-00-01	G4R GLY R4-31.R4-21 COMPT DOOR	TURN BUTTON FOUND MALFUNCTION	L130	COMP	10/02/2023
	CAB									2.0
									-	2.0
XJL1312	200	NRR	ΑI	25	777-53-916-00-01	G4R GLY FWD EQUIPMENT RACK HA	NDLE FOUND CRACKED	L131	OPEN	09/20/2023
	CAB									1.0
									-	1.0
XJL1320	200	NRR	ΑI	25	777-53-916-00-01	G4R GLY AFT O/B EDGE SEAL LOOSE	EN	L132	COMP	10/02/2023
	CAB									2.0
									-	2.0
XJL1338	400	LOG	AV	29			RT ITEM PADD P024: REFER_TL REFER TO TL ITEM REF TL3501, BOTH ENG	L133	OPEN	09/20/2023
	ENG					CX EDTO POLICY. ACTIONED IN ACCO	NSTALLATION. PADD RAISED TO CALL OUT EDTO VERIFICATION FLIGHT AS PER DRDANCE WITH OTHER AEO-29704 REV 00. (PLS REF TO ATTACHED "CX			0.0
						DEFERRAL REPORT" FOR THE REQUI				0.2
									-	0.2

REQUESTED BY:

REFERENCE NO:

DEFECT TYPE: ALL

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 18 OF 89

RUN DATE: 10/6/2023

RUN TIME: 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL

PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO:

ALL

ATA NO: ALL CUST ENDORSE: ALL ZONE: ALL AREA: ALL

DISPOSITION CODE: ALL STAGE: ALL

CTRL CODE:

TRADE: ALL TYPE CODE:

ORIGINATOR: ALL

STATUS

LIPDATED DATE

	ZONE	STG						STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL1346	400	LOG	SS	72		AS PER CX B-KPV DEFERRAL REPORT ITEM SADD S087: ***THIS TASK TO C/OUT REPAIR AS TERMINATIVE	L134	WIP	09/23/2023
	ENG					ACTION***#2 ENGINE FAN BLADES #1, #14 AND #17 HAVE CONCAVE SURFACE COATING LOSS AND BLADES #14 AND #17 HAVE METAL TIP CAP EXPOSED. #2 ENGINE FAN BLADES #1 #14 AND #17 INSPECTED WITHIN AMM 72-21-02 LIMITS.(CONTINUE TO SWS ITEM 1)			0.0
						1C 1 NIL DISBOND ON METAL TIP CAPS OF BLADES #14 AND #17 TO SADD FOR COATING REPAIR OR REPEAT INSPECTION WITHIN 150 CYCLES IAW AMM 72-21-02 REV JAN 20. (PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS)			0.0
						1C 2 PLS MAKE LOG BOOK ENTRY			0.2
						2C 3 REMOVE THE FAN ROTOR SPINNER ASSY			4.0
						2C 4 REMOVE THE SUBJECT FAN BLADES			6.0
						2C 5 DO AN INSPECTION TO THE REMOVAL FAN BLADES			2.0
						2C 6 INSTALL REMOVAL THE SUBJECT FAN BLADES			8.0
						3C 7 INSTALL REMOVAL FAN ROTOR SPINNER ASSY			6.0
						3C 8 PERFORM LPT VIBRATION SURVEY			2.0
						4C 9 PERFORM FAN BLADE TIP CLEARANCE INSPECTION			16.0
						5C 10 REMOVE LOOSE OR DAMAGED BLACK POLYURETHANE FILM FROM THE VISUAL TIP CAP METAL AREAS OF NO.14 AND NO.17 FAN BLADES			6.0
						5C 11 DO AN INSPECTION TO THE VISUAL TIP CAP METAL AREAS OF NO.14 AND NO.17 FAN BLADES TO CHECK FOR THE TIP CAP DISBOND			0.5
						5C 12 CLEAN AND DO THE REPAIR TO VISUAL TIP CAP METAL AREAS OF NO.14 AND NO.17 FAN BLADES			10.0
						5C 13 DO AN INSPECTION TO TO VISUAL TIP CAP METAL REPAIR AREAS OF NO.14 AND NO.17 FAN BLADES			0.5
						6C 14 CUT AWAY THE LOOSE OR TORN POLYURETHANE COATING AND ACCEPT THE CONDITION OF ALL THE SUBJECT FAN BLADES THAT THE DAMAGE AREAS(NOT INCLUDING VISUAL TIP CAP METAL AREAS)EXCEED THE REPAIR LIMIT			4.0
								-	65.2
XJL1353	200	NRR	Al	2524	777-C252420-01-05- 01	CABIN FB2 SEAT SHELL RETRACTABLE TABLE FOUND STIFF TO OPERATE AT COLUMN A	L135	COMP	10/04/2023
	CAB				U I				35.0
								-	35.0
XJL1361	200	NRR	Al	2524	777-C252420-01-05-	CABIN FB2 SEAT SHELL RETRACTABLE TABLE FOUND STIFF TO OPERATE AT COLUMN K	L136	COMP	10/04/2023
	CAB				01				32.5
								-	32.5
XJL1379	200	NRR	Al	2524	777-C252420-01-05- 01	CABIN FB2 SEAT SHELL RETRACTABLE TABLE FOUND STIFF TO OPERATE AT COLUMN D	L137	COMP	10/04/2023
	CAB				O I				32.5
								-	32.5

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

DEFECT TYPE: ALL

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 19 OF 89

RUN DATE: 10/6/2023

72.8

0.0

22.7

RUN TIME : 14:22

CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: PROJECT: XJ 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

CUST ENDORSE: ALL

OTDL 00DE TVDE 00DE ODIOINIATOD

TRADE: ALL

CTRL CODE:					TYPE CODE:	ORIGINATOR	: ALL			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL1387	200	NRR	Al	2524	777-C252420-01-05- 01	CABIN FB2 SEAT SHELL RETRACT.	ABLE TABLE FOUND STIFF TO OPERATE AT COLUMN G	L138	WIP	10/01/2023
	CAB				01					32.5
									-	32.5
XJL1395	200	LOG	SS	25			ORT ITEM SADD S110: HTP T13 WORK ORDER (WO) / WORK CARD REF W/O 9571960	L139	OPEN	09/20/2023
	CAB					RAISE SADD FOR FIRST OFFICER S	SEAT TO PERFORM AEO-27666 PART-2 AND AEO-27669 PART 2 NO LATER THAN			0.0

6FC'S AFTER OCTOBER 7, 2022 UNTIL DECEMBER 31, 2024. THE 6 FLIGHT CYCLES WILL BE FERRY FLIGHTS WITH NO	0.0
PASSENGERS ONBOARD. AFTER EMBODIMENT OF THE MODICATION AS PER (CONTINUE TO SWS ITEM 1)	
1C 1 AEO-27666 PART 2 AND AEO-27669 PART 2. CLEAR SADD RAISED AGAINST THIS AEO PART 1. XFRD TO SADD AS	0.0
PER INSTRUCTIONS IN AEO- 29541 REV 00 ACTIONED IN ACCORDANCE WITH AMM 25-11-01 REV 05 MAY 2023.(PLS	
REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS)	
1C 2 PLS MAKE LOG BOOK ENTRY	0.2

								-	0.2
XJL1403	200	NRR	Al	2524	777-C252420-01-05-	CABIN FB2 SEAT SHELL PTV ARM HARD TO OPERATE AT 19D-26D 24A 22A 16A 12A 11A 12G 11K 18G 21G 22G 24G 25G	L140	COMP	10/02/2023
	CAB				01	26G 17K 18K 19K 21K 22K 23K			70.0

								72.8
XJL1411	200	LOG	Al	25	AS PER CX B-KPV DEFERRAL REPORT ITEM SADD S112: HTP T13(WO)REPLACEMENT OF EMERGENCY ESCAPE	L141	OPEN	09/20/2023
	CAB				SLIDE/ RAFT - R2. R2 SLIDE/RAFT DETAILS: W/O: 9571786/1 P/N: 62771-128 S/N: 2039 ACTIONED IAW AMM 25-66-01 REV			0.0

05 MAY 2023. XRFD TO SADD DUE TO NIL SPARES. ACTIONED IAW AMM 25-66-01 REV 05 MAY 2023. (PLS REF TO

ATTACHED "CX DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS)

	0 0.	TO ELECTION TO THE REGULES AGAINST TEMO,	
1C	1	PLS MAKE LOG BOOK ENTRY.	0.2
2C	2	REPLACE DOOR SLIDE RAFT	8.0
2C	3	C/O INSPECTION PER IPI REQUIREMENT	0.5

AREA: ALL

STAGE: ALL

								8.7	
XJL1429	200	LOG	Al	25	AS PER CX B-KPV DEFERRAL REPORT ITEM SADD S113: HTP T13 WORK ORDER (WO) / WORK CARD REF W/O 9571787	L142	OPEN	09/20/2023	
	CAB				REPLACEMENT OF OFF-WING EMERGENCY ESCAPE SLIDE ASSEMBLY. XFRD TO SADD DUE TO NIL SPARES.			0.0	

I L	L/ (OLIVILIA	TOF OFF WING EMERGENOT EGON E GEIDE NOGEMBET. AFRID TO GROD DOE TO THE OF NICE.	0.0							
ACT	ACTIONED IAW AMM 25-65-01 REV 05 MAY 2023.(PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE									
REC	QUIRED AC	TION ITEMS)								
1C	1	PLS MAKE LOG BOOK ENTRY.	0.2							
2C	2	DISCONNECT OFF WING SLIDE RAFT ELECTRICAL CONNECTOR	0.5							
20.	3	REMOVE OFF WIND ESCAPE SLIDE PACK	10.0							

20	3	NEWOVE OF T WIND ESCAPE SLIDE PACK	10.0
2C	4	INSTALL NEW OFF WIND ESCAPE SLIDE PACK	10.0
2C	5	CONNECT OFF WING ESCAPE SLIDE PACK ELECTRICAL CONNECTOR	1.0
3C	6	C/O OFF WING ESCAPE SLIDE LIGHTS TEST	1.0

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 20 OF 89

ESTIMATED MHR: ALL

RUN DATE: 10/6/2023

RUN TIME: 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL

ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

JIKL CODE .					TIPE CODE.	ORIGINATOR	R. ALL			
	ZONE	STG							STATUS	UPDATED DAT
IOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
L1437	200	LOG	ΑI	25		AS PER CX B-KPV DEFERRAL RE	PORT ITEM SADD S114: HTP T13 REF W/O: 9571788/1 REPLACEMENT OF OFF-WING	L143	OPEN	09/20/2023
	CAB						EMBLY. XFRD TO SADD DUE TO NIL SPARES. ACTIONED IAW AMM 25-65-01 REV 05 AFT DETAILS: P/N: 5A3109-1 S/N: ST0958(PLS REF TO ATTACHED "CX DEFERRAL TION ITEMS)			0.0
						1C 1 PLS MAKE LOG BO	,			0.2
						2C 2 DISCONNECT OF	F WING SLIDE RAFT ELECTRICAL CONNECTOR			0.5
						2C 3 REMOVE OFF WIN	ND ESCAPE SLIDE PACK			10.0
						2C 4 INSTALL NEW OF	F WIND ESCAPE SLIDE PACK			10.0
						2C 5 CONNECT OFF W	ING ESCAPE SLIDE PACK ELECTRICAL CONNECTOR			1.0
						3C 6 C/O OFF WING ES	SCAPE SLIDE LIGHTS TEST			1.0
									-	22.7
L1445	200 CAB	LOG	Al	25			PORT ITEM SADD S115:HTP T13 (WO) REF W/O: 9571790 /1 REPLACEMENT OF T - L4. XFRD TO SADD DUE TO NIL SPARES ACTIONED IAW AMM 25-66-01 REV 05	L144	OPEN	09/20/2023
	CAB						04-339 S/N M8187 (PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE			0.0
						1C 1 PLS MAKE LOG B	OOK ENTRY.			0.2
						2C 2 REPLACE DOOR S	SLIDE RAFT			8.0
						2C 3 C/O INSPECTION	PER IPI REQUIREMENT			0.5
									-	8.7
L1452	200 CAB	LOG	Al	25		AS PER CX B-KPV DEFERRAL REI	PORT ITEM SADD S116: HTP T13 (WO) REF W/O: 9571791 /1REPLACEMENT OF T - L5	L145	OPEN	09/20/2023
	CAB						RES. ACTIONED IAW AMM 25-66-01 REV 05 MAY 2023. L5 SLIDE RAFT DETAILS: P/N: ATTACHED "CX DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS)			0.0
						1C 1 PLS MAKE LOG BO	,			0.2
						2C 2 REPLACE DOOR S	SLIDE RAFT			8.0
						2C 3 C/O INSPECTION	PER IPI REQUIREMENT			0.5
									-	8.7
L1460	200	LOG	Al	25			PORT ITEM SADD S117: REF W/O: 9571792 /1 REPLACEMENT OF EMERGENCY FRD TO SADD DUETO NIL SPARE. ACTIONED IAW AMM	L146	OPEN	09/20/2023
	CAB					25-66-01 REV 05 MAY 2023 R5 SLIE	DE/RAFT DETAILS: P/N: 65344-428 S/N: 0274(PLS REF TO ATTACHED "CX DEFERRAL			0.0
						REPORT" FOR THE REQUIRED AC 1C 1 PLS MAKE LOG BO	,			0.2
						2C 2 REPLACE DOOR S				8.0
							PER IPI REQUIREMENT			0.5
									-	8.7

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

AREA: ALL

21 OF 89 PAGE:

RUN TIME :

STAGE: ALL

RUN DATE: 10/6/2023 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

ESTIMATED MHR: ALL JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL

ORIGINATING CUST REF NO: ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL

CTDL CODE.	TYPE CODE:	
CIRI CODE		

CTRL CODE :	ZONE	CTC			TYPE CODE:		ORIGINATOR:	ALL			STATUS	UPDATED DATE
JOB NO	AREA	SIG	TD	ATA	ORIG CUST REF NO.	CTRL SH NO			DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL1478	200 CAB	LOG	AI	25		EMERGENCY E	SCAPESLIDE/RAFT - L2. X RAFT DETAILS: P/N:62771-	(FRD TO SADD -127 S/N: M8984 NTRY. RAFT	S: HTP T13 (WO) REF W/O: 9571794 /1 REPLACEMENT OF DUE TO NIL SPARE. ACTIONED IAW AMM 25-66-01 REV 05 MAY (PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE	L147	OPEN	09/20/2023 0.0 0.2 8.0 0.5
XJL1486	200 CAB	LOG	AI	25		9571795 REPLA	ACEMENT OF EMERGENC' AMM 25-66-01 REV 05 MA	Y ESCAPE SLID AY 2023.(PLS RE NTRY RAFT	D: HTP T13 WORK ORDER (WO) / WORK CARD REF W/O: E/RAFT -R4. R4 SLIDE RAFT DETAILS: P/N: 63604-324 S/N: 0034 F TO ATTACHED "CX DEFERRAL REPORT" FOR THE	L148	OPEN .	8.7 09/20/2023 0.0 0.2 8.0 0.5
XJL1494	200 CAB	NRR	SS	25	777-53-904-00-01	CABIN F/C SEA 1C 1 1C 2 1C 3 2C 4	AT PARTIITON AISLE TEDL REMOVE F/C SEAT PARTI F/C SEAT PARTITION SIE REINSTALL F/C SEAT PARTI REPAIR F/C SEAT PARTI	TITION SIDE BU DE BUMPER 1D ARTITION SIDE I	2D TEDLAR REPLACE	L149	WIP	09/23/2023 0.0 1.0 22.0 1.0 2.0
XJL1502	200 CAB	LOG	AV	33		REMARK) CRE\ OFAR BACK-UF	WATTENDANT RESTS (OF PLIGHTING POWER PACK FAMM 33-29-10 REV 05 MA	FCR,OFAR) CAN S-TO BE PERFO NY 2023.(PLS RE	D: OB2 9 ITEM NOT FOUND IN FAULT TREE (REFER TO IT BE USED. AMS 33-115-00 FUNCTIONALLY CHK OFCR & / OR DRMED NO LATER THAN NEXT REVENUE FLIGHT. TO SADD IF TO ATTACHED "CX DEFERRAL REPORT" FOR THE	L150	OPEN .	09/20/2023 0.0 0.2
XJL1510	200 CAB	NRR	AI	2524	777-C252420-01-05- 01	CABIN FB2 SEA	AT SHELL O/B SIDE GAP C	COVER PANEL F	OUND DISCOLOUR AT COLUMN A	L151	COMP	0.2 09/30/2023 14.0
XJL1528	200 CAB	NRR	Al	2524	777-C252420-01-05- 01	CABIN FB2 SE	AT SHELL O/B SIDE GAP C	COVER PANEL F	OUND DISCOLOUR AT COLUMN K	L152	COMP -	10/02/2023 13.0 13.0

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 22 OF 89 RUN DATE: 10/6/2023

RUN TIME : 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL ALL DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE : TYPE CODE: ORIGINATOR ·

TRL CODE :					TYPE CODE:		ORIGINATOR: ALL		STATUS	UPDATED DAT
JOB NO	ZONE AREA	SIG	TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
L1536	200	LOG	AV	52		AS PER CX B	(PV DEFERRAL REPORT ITEM SADD S121: OB2 9 ITEM NOT FOUND IN FAULT TREE (REFER TO	L153	WIP	10/03/2023
	CAB					,	ER CX WO/TASK 9571808/1 OVER WING DOOR EPAS BATTERY NEED TO REPLACE.(PLS REF TO (DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS)			0.0
						1C 1	PLS MAKE LOG BOOK ENTRY.			0.2
						2C 2	REPLACE THE NO.3 LEFT OVER WING DOOR BACKUP BATTERY			1.0
						2C 3	PERFORM EPAS BATTERY OPERATION TEST			0.5
									-	1.7
L1544	200	LOG	AV	52			(PV DEFERRAL REPORT ITEM SADD S122: OB2 9 ITEM NOT FOUND IN FAULT TREE (REFER TO ER CX WO/TASK 9571809/1 NO.3 OVER WING DOOR BACKUP BATTERY NEED TO REPLACE.(PLS REF TO	L154	WIP	10/03/2023
	CAB					,	CEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS)			0.0
						1C 1	PLS MAKE LOG BOOK ENTRY.			0.2
						2C 2	REPLACE THE NO.3 LEFT OVER WING DOOR BACKUP BATTERY			1.0
						2C 3	PERFORM EPAS BATTERY OPERATION TEST			0.5
									-	1.7
	200	LOG	AV	52		AS PER CX B-KPV DEFERRAL REPORT ITEM SADD S123: OB2 9 ITEM NOT FOUND IN FAULT TREE (REFER TO REMARK) AS PER CX WO/TASK 9571810/1 NO.3 RIGHT OVER WING EPAS BATTERY NEED TO REPLACE. (PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS)	L155	WIP	10/03/2023	
	CAB								0.0	
						1C 1	PLS MAKE LOG BOOK ENTRY			0.2
						2C 2	REPLACE THE NO.3 RIGHT OVER WING DOOR BACKUP BATTERY			1.0
						2C 3	PERFORM EPAS BATTERY OPERATION TEST			0.5
									-	1.7
IL1569	200	NRR	SS	25	777-53-904-00-01	CABIN F/C SE	AT BACK SHELL AISLE S/W FOUND SCEATCHED AT 1K 2K 1D 2D 1A 2A(TOTAL 6 EA)	L156	WIP	09/23/2023
	CAB									0.0
						1C 1	REMOVE F/C SEAT PARTITION AISLE BUMPER 1K 2K 1D 2D 2A 1A			2.0
						1C 2	REMOVE F/C SEAT PARTITION AISLE LIGHT 1K 2K 1D 2D 2A 1A			2.0
						1C 3	F/C SEAT PARTITION AISLE BUMPER 1K 2K 1D 2D 2A 1A TEDLAR REPLACE			60.0
						1C 4	REINSTALL F/C SEAT PARTITION AISLE BUMPER 1K 2K 1D 2D 2A 1A			2.0
						2C 5	REINSTALL F/C SEAT PARTITION AISLE LIGHT 1K 2K 1D 2D 2A 1A		-	2.0
										68.0
L1577	200	LOG	AV	52			(PV DEFERRAL REPORT ITEM SADD S124: OB2 9 ITEM NOT FOUND IN FAULT TREE (REFER TO	L157	WIP	10/03/2023
	CAB					,	ER CX WO/TASK 9571811/1 NO.3 RIGHT OVERWING DOOR BACKUP BATTERY NEED TO REPLACE.(PLS HED "CX DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS)			0.0
						1C 1	PLS MAKE LOG BOOK ENTRY.			0.2
						2C 2	REPLACE THE NO.3 RIGHT OVER WING DOOR BACKUP BATTERY			1.0
						2C 3				0.5
									-	1.7

515653

REQUESTED BY:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

PAGE: 23 OF 89

RUN DATE: 10/6/2023

0.0

REFERENCE NO: BMS571R1-2 (By JSN) RUN TIME: 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

TRL CODE .					TIPE CODE.		ORIGINATOR: ALL			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH	NO DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
JL1585	100 LWR	LOG	Al	38			(B-KPV DEFERRAL REPORT ITEM SADD S126: HTP T13 (WO) REF W/O: 9571955/10 BOTTLE WATER UPLIFT . POTABLE WATER SYSTEM-DISINFECTANT TO BE PERFORMED IN HKG. DON'T USE POTABLE WATER FOR	L158	OPEN	09/20/2023
	LVVIX						E. TOILET FLUSH REMAINS SERVICEABLE. BOTTLE WATER UPLIFT REQUIRED. POTABLE WATER FECTANT TO BE PERFORMED IN HKG. (CONTINUE TO SWS ITEM 1)			0.0
						1C 1	DON'T USE POTABLE WATER FOR BEVERAGE. TOILET FLUSH REMAIN SERVICEABLE. ACTIONED IAW AMM 38-10-00-600-801 REV 05 MAY 2023 (PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE REQUIRED ACTION			0.0
							ITEMS)			
						1C 2	PLS MAKE LOG BOOK ENTRY			0.2
									-	0.2
JL1593	200	NRR	SS	25	777-53-904-00-01		SEAT MEAL SIDE DOOR TEDLAR FOUND SCRATCHED AT K1 .1D .(M3)AFT .(M1)AFT. 1A. (M2)AFT (TOTAL 6	L159	WIP	09/23/2023
	CAB					EA)				0.0
						1C 1	REMOVE F/C SEAT COMPT DOOR 1K 1D (M3)AFT (M1)AFT (M1)AFT 1A			2.0
						1C 2	REMOVE F/C SEAT COMPT DOOR LIGHT 1D			0.5
						1C 3	F/C SEAT COMPT DOOR 1K 1D (M3)AFT (M1)AFT (M2)AFT 1A TEDLAR REPLACE			60.0
						1C 4	REINSTALL F/C SEAT COMPT DOOR 1K 1D (M3)ADT (M1)AFR (M2)AFT 1A TOTAL 6 WA			2.0
						2C 5	REINSTALL F/C SEAT COMPT DOOR LIGHT 1D			0.5
						20 0			-	65.0
JL1601	400	LOG	AE	71		AS PER C	(B-KPV DEFERRAL REPORT ITEM SADD S127: HTP T13 (WO) , ENGINE 1 REF W/O 9571955 /16 ENG #1 IDG	L160	WIP	09/23/2023
	ENG		3 AL			PRESERV	D ON WING. REMOVE IDG FOR SHOP VISIT WITHIN MAXIMUM OF 25 FLIGHT HOURS. SADD RAISED.			
							IAW AMM 24-11-01 REV 05 MAY 2023.(PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE			0.0
							ACTION ITEMS)			
						1C 1	PLS MAKE LOG BOOK ENTRY.			0.2
						2C 2	DISCONNECT NO.1 ENG IDG ELECTRICAL CONNECTOR.			2.0
						2C 3	REPLACE NO.1 ENG IDG.			16.0
						2C 4	RECONNECT NO.1 ENG IDG ELECTRICAL CONNECTOR.			4.0
						2C 5	C/O IPI FOR IDG OIL SVC.			2.0
						3C 6	C/O OPERATIONAL TEST FOR RH IDG.			1.0
						3C 7	C/O OPERATIONAL TEST FOR RH IDG.			1.0
						3C 8	CARRY OUT IPI PROCEDURE OF NO.1 ENG IDG FEEDER CABLE INSTALLATION			0.5
						3C 9	C/O PART-POWER LEAK CHECK			1.0
									-	27.7
JL1619	200 CAB	NRR	SS	25	777-53-904-00-01	CABIN F/0	SEAT PARTITION POST TEDLAR FOUND TORN AT (M1)FWD/ AFT ,(M3)FWD/AFT TOTAL 4 EA	L161	COMP	10/05/2023
	CAB									0.0
									-	

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 24 OF 89

RUN DATE: 10/6/2023 RUN TIME :

14:22

13.0

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

BMS571R1-2

515653

STATUS: ALL

ORIG-STAGE: ALL

PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL

ATA NO: ALL

ZONE: ALL AREA: ALL

DISPOSITION CODE: ALL

DEFECT TYPE: ALL

TRADE: ALL

CUST ENDORSE: ALL

STAGE: ALL

CTRL CODE:

TYPE CODE: ORIGINATOR: ALL

	ZONE	STG			2 0022.		0.11011111101111		STATUS	UPDATED DATE
JOB NO	AREA	010	TD	ATA	ORIG CUST REF NO.	CTRL SH N	O DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL1627	200	NRR	SS	25	777-53-904-00-01	CABIN F/C S	EAT MEAL TABLE PNL TEDLAR FOUND SCRATCHED AT 2A 2D 1D 2K 1K(TOP SIDE)2A 1A 2D 2K	L162	WIP	09/26/2023
	CAB					1K(BOTTOM	SIDE) TOTAL 10 EA			40.0
									-	40.0
XJL1635	200	NRR	SS	2500	777-53-904-00-01	CABIN F/C S	AET FWD LITERATURE SHROUD SURFACE TEDLAR FOUND SCRATCHED AT 2A 1D 2D 1K 2K TOTAL 5EA	L163	WIP	09/23/2023
	CAB									0.0
						1C 1	REMOVE F/C SEAT LITERATURE SHRPUD 1K 2K 1D 2D 2A			1.0
						1C 2	F/C SEAT MAGAZINE COVER 1K 2K 2A 1D 2D TEDLAR REPLACE			50.0
						1C 3	REINSTALL F/C SEAT LITERATURE SHROUD 1K 2K 2A 1D 2D			1.0
									-	52.0
XJL1643 200	200	NRR	SS	2500	777-53-920-00-01	CAB-G8 GLY	L/H AND R/H S8-01 COMPT DR TEDLAR FND DENT.	L164	COMP	10/03/2023
	CAB									0.0
						1C 1	REMOVE G8 GLY LOWER DOOR S8-01.			0.5
						1C 2	G8 GLY LOWER DOOR S8-01 TEDLAR REPLACE			16.0
						1C 3	REINSTALL G8 GLY LOWER DOOR S8-01.			0.5
									-	17.0
KJL1650	200	NRR	SS	2500	777-53-904-00-01	CAB #1 DOC	R S1 STOWAGE FWD B/HEAD TEDLAR FOUND SCRATCHED	L165	WIP	09/23/2023
	CAB									0.0
						1C 1	REMOVE S1 STOWAGE FWD B/HEAD BUMPER			0.5
						1C 2	REMOVE S1 STOWAGE FWD B/HAED LIGHT			0.5
						1C 3	REINSTALL S1 STOWAGE FWD B/HAED BUMPER			0.5
						1C 4	REINSTALL S1 STOWAGE FWD B/HAED LIGHT			0.5
						2C 5	S1 STOWAGE FWD B/HAED TEDLAR REPLACE			11.0
									-	40.0

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 25 OF 89 RUN DATE: 10/6/2023

RUN TIME :

STAGE: ALL

14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL JSN RANGE SELECTED: ALL ESTIMATED MHR: ALL

ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL ORIGINATING CUST REF NO: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL

CTRL CODE :					TYPE CODE:			ORIGINATOR: ALL			
	ZONE	STG								STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTR	SH NO	D DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL1668	400	LOG	AE	71				3-KPV DEFERRAL REPORT ITEM SADD S128: HTP T13 WORK ORDER (WO) / WORK CARD, ENGINE 2 REF	L166	WIP	09/25/2023
	ENG					HOU	RS. SAD	5/ 16 ENG #2 IDG PRESERVED ON WING. REMOVE IDG FOR SHOP VISIT WITHIN MAXIMUM OF 25. FLIGHT D RAISED. ACTIONED IAW AMM 24-11-01 REV 05 MAY 23(PLS REF TO ATTACHED "CX DEFERRAL REPORT"			0.0
						1C	1	QUIRED ACTION ITEMS) PLS MAKE LOG BOOK ENTRY.			0.2
						2C	2	DISCONNECT NO.2 ENG IDG ELECTRICAL CONNECTOR.			2.0
						2C	3	REPLACE NO.2 ENG IDG.			16.0
						2C	4	RECONNECT NO.2 ENG IDG ELECTRICAL CONNECTOR.			4.0
						2C	5	C/O IPI FOR IDG OIL SVC.			2.0
						3C	6	C/O OPERATIONAL TEST FOR RH IDG.			1.0
						3C	7	C/O OPERATIONAL TEST FOR RH IDG.			1.0
						3C	8	CARRY OUT IPI PROCEDURE OF NO.2 ENG IDG FEEDER CABLE INSTALLATION			0.5
						3C	9	C/O PART-POWER LEAK CHECK			1.0
											27.7
XJL1676	200	NRR	SS	2500	777-53-904-00-01	CAE	-G1C GL	Y C-102 C-103 COMPT DR TEDLAR FND DENT	L167	COMP	10/04/2023
	CAB										0.0
						1C	1	REMOVE G1C GLY C-102 C103 COMPT DOOR			0.5
						1C	2	G1C GLY C-102 C-103 COMP DOOR TEDLAR REPLACE			12.0
						1C	3	REINSTALL G1C GLY C-102 C-103 COMPT DOOR			1.0
										•	13.5
XJL1684	400	LOG	ΑE	71		AS I	PER CX E	3-KPV DEFERRAL REPORT ITEM SADD S129:HTP T13 WORK ORDER (WO) / WORK CARD, ENGINE 1 REF	L168	WIP	09/23/2023
	ENG							/ 16 ENG# 1 BUG PRESERVED ON WING. REMOVE FOR SHOP VISIT WITHIN MAXIMUM 25 HRS. SADD			0.0
								IONED IAW AMM 24-25-01 REV 01 MAY 23. (PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE CTION ITEMS)			0.0
						1C	UIRED A 1	PLS MAKE LOG BOOK ENTRY.			0.2
						2C	2	DISCONNECT THE NO.1 ENG BUG ELECTRICAL CONNECTOR.			2.0
						2C	3	REPLACE NO.1 ENG BUG.			12.0
						2C	4	RECONNECT NO.1 ENG BUG THE ELECTRICAL CONNECTOR.			3.0
						2C	5	C/O IPI FOR NO.1 ENG BUG OIL SVC.			2.0
						3C	6	C/O NO.1 ENG PART-POWER LEAK CHECK.			1.0
						3C	7	DO THE NO.1 BUG INSTALLATION TEST.			1.0
						3C	8	TRANSFER TERMINAL BLOCK ADAPTER FROM OLD TO NEW BACKUP GENERATOR			2.0
						3C	9	C/O IPI PROCEDURE FOR NO.1 BACKUP GENERATOR PHASE LEADS			0.5
										-	23.7

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 26 OF 89

RUN TIME :

RUN DATE: 10/6/2023

14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

TRL CODE :					TYPE CODE:			ORIGINATOR: ALL			
	ZONE	STG								STATUS	UPDATED DA
OB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTR	L SH N	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
1692	400	LOG	AE	71		AS F	PER CX E	-KPV DEFERRAL REPORT ITEM SADD S130: HTP T13 WORK ORDER (WO) / WORK CARD, ENGINE 2 REF	L169	WIP	09/25/2023
	ENG					RAIS	SED ACT	/ 16 ENG# 2 BUG PRESERVED ON WING. REMOVE FOR SHOP VISIT WITHIN MAXIMUM 25 HRS. SADD DNED IAW AMM 24-25-01 REV 05 MAY 2023.(PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE CTION ITEMS)			0.0
						1C	1	PLS MAKE LOG BOOK ENTRY.			0.2
						2C	2	DISCONNECT THE NO.2 ENG BUG ELECTRICAL CONNECTOR.			2.0
						2C	3	REPLACE NO.2 ENG BUG.			16.0
						2C	4	RECONNECT NO.2 ENG BUG THE ELECTRICAL CONNECTOR.			3.0
						2C	5	C/O IPI FOR NO.2 ENG BUG OIL SVC.			2.0
						3C	6	C/O NO.2 ENG PART-POWER LEAK CHECK.			1.0
						3C	7	DO THE NO.2 BUG INSTALLATION TEST.			1.0
						3C	8	TRANSFER TERMINAL BLOCK ADAPTER FROM OLD TO NEW BACKUP GENERATOR			2.0
						3C	9	C/O IPI PROCEDURE FOR NO.2 BACKUP GENERATOR PHASE LEADS			0.5
										-	27.7
L1700 200 CAB		NRR	SS	2500	777-53-904-00-01	CAE	8 #1 DOC	R G1L GALLEY AFT B/HEAD TEDLAR FOUN DENT	L170	COMP	10/04/2023
					1C	1	REMOVE G1L GLY AFT B/HEAD PNL			0.0 0.5	
						1C	2	REBOND G1L GLY AFT B/HEAD PNL TEDLAR REPLACE			11.0
						1C	3	REINSTALL G1L GLY AFT B/HEAD PNL			0.5
										-	12.0
.1718	200	NRR	SS	25	777-53-904-00-01	CAE	BIN F/C S	EAT CLOSET COMPT DOOR TEDLAR FOUND SCEATCHED AT M3	L171	WIP	09/23/2023
	CAB										0.0
						1C	1	REMOVE F/C SEAT CLOSET COMPT DOOR			1.0
						1C	2	F/C SEAT CLOSET COMPT DOOR (M3)TEDLAR REPLACE			11.0
						1C	3	REINSTALL F/C SEAT CLOSET COMPT DOOR			1.0
										-	13.
1726	200	LOG	SS	25		AS F	PER CX E	-KPV DEFERRAL REPORT ITEM SADD S131: HTP T13(WO) REF W/O 9571960 TO PERFORM AEO-27666	L172	OPEN	09/20/2023
	CAB					WILL	BE FER	27669 PART 1 NO LATER THAN 6 FC AFT OCTOBER 7 2022 UNTIL DECEMBER 31, 2024.6 FLIGHT CYCLES RY FLIGHTS WITH NO PASSENGERS ONBOARD. AFT EMBODIMENT OF MODIFICATION AS PER AEO-27666			0.0
						PAR 1C	T Q,& AE 1	D-27669 PART 1, CLEAR SADD RAISED AGAINST THIS AEO PART 1.(CONTINUE TO SWS ITEM 1) SADD RAISED AS PER INSTRUCTIONS IN AEO 29541 REV 00. ACTIONED IAW OTHER AEO-29541 REV REV 00.(PLS			0.0
						1C	2	REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS) PLS MAKE LOG BOOK ENTRY.			0.2
							_			-	
											0.2

REFERENCE NO: BMS571R1-2

ORIGINATING CUST REF NO:

515653

ALL

REQUESTED BY:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 27 OF 89

RUN DATE: 10/6/2023

RUN TIME : 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE:					TYPE CODE:		ORIGINATOR:	ALL				
	ZONE	STG									STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO			DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL1734	100 LWR	LOG	AI	26		REMARK) WO NO : CARTRIDGES FOR REV 05 MAY 2023.(1C 1 PL	: 9571803/1 C/O REPLA R BOTTLE 2A SERIAL N (PLS REF TO ATTACHE LS MAKE LOG BOOK EI	CEMENT OF C O: 1610BA PAR ED "CX DEFERF NTRY.	33: OB2 9 ITEM NOT FOUND IN FAULT TREE (REFER TO CGO COMPARTMENT FIRE EXTINGUISHING BOTTLES SQUIB RT NO : 473876-3 AS PER AMS LIST ACTIONED IAW AMM 26-23-01 RAL REPORT" FOR THE REQUIRED ACTION ITEMS)	L173	WIP	09/28/2023 0.0 0.2
							EMOVE THE FIRE BOT		IECTOR OF FIRE BOTTLE SQUIB			1.0 0.5
									TOR OF FIRE BOTTLE SQUIB			0.5
							ISTALL THE FIRE BOTT		TOR OF FIRE BOTTLE SQUIB			1.0
									HING SQUIBS OPERATIONAL TEST			1.0
									TWEEN THE FIRE EXTINGUISHING BOTTLE AND THE BONDING BRACKET			1.0
									HING PRESSURE SWITCH OPERATIONAL TEST			1.0
									PRESSURE SWITCH - OPERATIONAL TEST			1.0
											-	7.2
XJL1742	100	LOG	Al	26					34: OB2 9 ITEM NOT FOUND IN FAULT TREE (REFER TO	L174	OPEN	09/20/2023
	LWR					CARTRIDGE FOR 2	2D SERIAL NO : 1544BA	A PART NO: 473	CARGO COMPARTMENT FIRE EXTINGUISHER BOTTLES SQUIB 3876-3 AS PER AMS LIST ACTIONED IAW AMM 26-23-01 REV 05 PORT" FOR THE REQUIRED ACTION ITEMS)			0.0
						`	LS MAKE LOG BOOK EI		TOTAL TEXT TEXT TEXT TOTAL TEMPS			0.2
						2C 2 RE	EMOVE THE FIRE BOT	TLE SQUIB				1.0
						2C 3 DI	SCONNECT THE ELEC	TRICAL CONN	IECTOR OF FIRE BOTTLE SQUIB			0.5
						2C 4 CC	ONNECT THE ELECTRI	ICAL CONNECT	TOR OF FIRE BOTTLE SQUIB			0.5
						2C 5 IN	ISTALL THE FIRE BOTT	TLE SQUIB				1.0
						3C 6 CA	ARRY OUT CARGO FIR	RE EXTINGUISH	HING SQUIBS OPERATIONAL TEST			1.0
						4C 7 D0	O A CHECK OF THE RE	SISTANCE BET	TWEEN THE FIRE EXTINGUISHING BOTTLE AND THE BONDING BRACKET			1.0
						4C 8 CA	ARRY OUT CARGO FIR	RE EXTINGUISH	HING PRESSURE SWITCH OPERATIONAL TEST			1.0
											-	6.2
XJL1759	500 F/T	NRM	AE	5708	AEO-28656-01	LHW FUEL TANK A	ACCESS DOORS 532AE	B 544DB GASK	ET FOUND WORN	L175	COMP	10/03/2023
	171										-	1.0
XJL1767	200	NRR	SS	2500	777-53-904-00-01	CABIN PARTITION	I L/R LOWER SURFACE	E TEDLAR FOU	ID SCRATHED	L176	COMP	1.0 10/05/2023
7.02.1.0.	CAB			2000	65 65 . 65 6 .	0,12,11,11,11,11,11,11,11,11,11,11,11,11,	,,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,,		5 0010	LITO	COMP	8.0
											-	8.0
XJL1775	600	NRM	AE	5700	AEO-28656-02	RHW FUEL TANK	ACCESS DOORS632AE	3 644DB GASKE	ET FOUND WORN	L177	COMP	10/03/2023
	F/T											1.0
											-	1.0

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 28 OF 89 RUN DATE: 10/6/2023

ESTIMATED MHR: ALL

10/6/2023

RUN TIME : 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL

ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

STRL CODE:					TYPE CODE:		ORIGINATOR: ALL				
	ZONE	STG								STATUS	UPDATED DAT
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH N	0	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL1783	200	NRR	SS	2500	777-53-908-00-01	CABIN #2 DO	OOR G3 GLY R/H AISLE S/W FOUND SCRATCH	IED	L178	WIP	09/24/2023
	CAB										0.0
						1C 1	REMOVE G3 GLY RHS AISLE LIGHT				0.5
						1C 2	REMOVE G3 GLY RHS AISLE PNL				1.0
						1C 3	G3 GLY RHS AISLE TEDLAR REPLACE				11.0
						1C 4	REINSTALL G3 GLY RHS AISLE PNL				1.0
						2C 5	REINSTALL G3 GLY RHS AISLE LIGHT				0.5
										-	14.0
KJL1791	200	NRR	Al	2531	777-53-908-00-01	CABIN G2 G	ALLERY COMPARTMENT 203 LOWER GUIDE I	BUMPER FOUND DAMAGE	L179	OPEN	09/20/2023
	CAB										5.0
										-	5.0
(JL1809	200	NRR	SS	2500	777-53-908-00-01	CABIN #2 DO	OOR G2R GLY L/H AISLE S/W FOUND SCRATO	HED	L180	WIP	09/23/2023
	CAB										0.0
						1C 1	REMOVE G2R GLY LHS AISLE PNL				0.5
						1C 2	REMOVE G2RGLY LHS AISLE LIGHT				0.5
						1C 3	G2RGLY LHS AISLE TEDLAR REPLACE				11.0
						1C 4	REINSTALL G2R GLY LHS AISLE PNL				0.5
						2C 5	REINSTALL G2R GLY LHS AISLE LIGHT				0.5
										-	13.0
(JL1817	200	NRR	SS	2500	777-53-920-00-01	CAB-G7 GLY	G702 COMPT DR TEDLAR FND DENT.		L181	COMP	10/03/2023
	CAB										0.0
						1C 1	REMOVE G7 GLY 702 COMPT DOOR				0.5
						1C 2	G7 GLY 702 COMPT DOOR TEDLAR REPL	ACE			6.0
						1C 3	REINSTALL G7GLY 702 COMPT DOOR				0.5
										-	7.0
											7.0

DISTRIBUTION: 0PPC REQUESTED BY: 515653 TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 29 OF 89

RUN TIME :

RUN DATE: 10/6/2023

14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

STATUS: ALL

ORIG-STAGE: ALL

PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO:

REFERENCE NO: BMS571R1-2

ALL

ATA NO: ALL

ZONE: ALL

DISPOSITION CODE: ALL

DEFECT TYPE: ALL

TRADE: ALL

CUST ENDORSE: ALL

AREA: ALL STAGE: ALL

OTDL CODE	T) (DE 00DE	ODIONIATOR	
CTRL CODE :	TYPE CODE:	ORIGINATOR :	ALL

TINE CODE .	ZONE	STG			TIFE CODE.	ONGINATO	M. ALL		STATUS	UPDATED DATE
JOB NO	AREA	010	TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
(JL1825	100 LWR	LOG	Al	26		9571798/1 C/O REPLACE OF CGC PART :446347-1 FWD CGO LOCA 26-23-05 REV 05 MAY 2023.(PLS 1C 1 PLS MAKE LOG 2C 2 REMOVE THE FI 2C 3 DISCONNECT E 2C 4 CONNECT ELEC 2C 5 INSTALL THE FI	LOW VALVE LECTRICAL PLUG OF THE FLOW VALVE ITRICAL PLUG OF THE FLOW VALVE	L182	WIP	09/20/2023 0.0 0.2 2.0 0.5 0.5 2.0 1.0
									-	6.2
KJL1833	200 CAB	NRR	AI	2531	777-53-908-00-01	CABIN G3 GALLERY 301 RH LOV	VER MATEL TRIM FOUND MISSING	L183	COMP	10/02/2023
									-	5.0
JL1841	100 FUS	NRR	AE	5300	777-53-800-00-09	FUSELAGE LOWER HALF TOTAL	. 15 EA DRAIN VALVE AGED	L184	OPEN	09/20/2023
									-	2.0
JL1858	100 LWR	LOG	Al	26		REPLACE OF CARGO FIRE EXTII 446347-1 FWD CGO LOCATION-A REV 05 MAY 2023. (PLS REF TO . 1C 1 PLS MAKE LOG 2C 2 REMOVE THE FI 2C 3 DISCONNECT E 2C 4 CONNECT ELEC 2C 5 INSTALL THE FL	LOW VALVE LECTRICAL PLUG OF THE FLOW VALVE ITRICAL PLUG OF THE FLOW VALVE	L185	WIP	09/22/2023 0.0 0.2 2.0 0.5 0.5 2.0 1.0
JL1866	600 WNG	LOG	AE	27		AS PER CX WO 9571807/1 RH WI	EPORT ITEM SADD S138:OB2 9 ITEM NOT FOUND IN FAULT TREE (REFER TO REMARK) NG SPOILER AUXILIARY RETRACT DEVICE (SARD) PYROTECHNIC CARTRIDGE NEED ACHED "CX DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS) BOOK ENTRY.	L186	COMP -	6.2 09/23/2023 0.0 0.2

515653

REQUESTED BY:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

PAGE: 30 OF 89

STAGE: ALL

RUN DATE: 10/6/2023

0.2

REFERENCE NO: BMS571R1-2 (By JSN) RUN TIME : 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL

TYPE CODE CTDL CODE ODICINIATOD .

CTRL CODE:					TYPE CODE:		ORIGINATOR: ALL			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL1874	200	NRR	SS	2500	777-53-908-00-01	CAB #2 DOOR	S1R UPPER B/HEAD TEDLAR FOUND SCRATCHED	L187	WIP	09/26/2023
	CAB									10.0
									-	10.0
XJL1882	500	LOG	ΑE	27		AS PER CX B-	(PV DEFERRAL REPORT ITEM SADD S139: 275 022 02 FLAP/SLAT CONTROL 2 (STATUS) EARLY IN	L188	WIP	09/22/2023
	WNG					LATCHED. MEL	STATUS MESSAGE PHASE OF FLIGHT: CRUISE FIM 27-82 TASK 806 FOLLOWED, CONFIRM THE MSG IS APPLIED DUE TIME. MAINT PROCEDURE CARRIED OUT IAW AMM27-00-00 REV SEP23. (PLS REF TO			0.0
						1C 1	DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS) PLS MAKE LOG BOOK ENTRY.			0.2
						2C 2	PERFORM T/S AS			2.0
						2C 3	C/O WIRING CHECK SLAT PRIMARY CONTROL VALVE V27003 RESISTANCE CHECK			2.0
						3C 4	DISCONNECT THE ELECTRICAL CONNECTORS			0.5
						3C 5	REMOVE THE LEFT WHEEL WELL SLAT PRIMARY CONTROL VALVE V27003			6.0
						3C 6	INSTALL THE LEFT WHEEL WELL SLAT PRIMARY CONTROL VALVE V27003			8.0
						3C 7	CONNECT THE ELECTRICAL CONNECTORS FOR THE SLAT PRIMARY CONTROL VALVE			1.0
						4C 8	CARRY OUT BONDING TEST BETWEEN THE VALVE ASSEMBLY AND STRUCTURE			1.0
						4C 9	CARRY OUT SLAT PRIMARY CONTROL VALVE TEST			2.0
									-	22.7
XJL1890	100 FUS	NRR	AV	3100	777-53-832-00-01	PLEASE DISCO	DNNECT AND CONNECT THE LOWER BODY ANTI-COLLISION LIGHT CONNECTIONS FOR ACCESS	L189	WIP	09/25/2023
	103									0.0
						1C 1	DISCONNECT CONNECTOR OF LOWER ANTI-COLLISION LIGHT			1.0
						1C 2	RECONNECT CONNECTOR OF LOWER ANTI-COLLISION LIGHT			1.0
						1C 3	PERFORM TEST OF LOWER ANTI-COLLISION LIGHT			0.5
									-	2.5
XJL1908	200	NRR	SS	25	777-53-912-00-01	CABIN FB2 SE	AT PARTITION SIDE CONSOLE AREA TEDLAR BUBBLE AT 11G 26K 26D 11K 18K TOTAL 5 EA	L190	WIP	09/23/2023
	CAB									0.0
						1C 1	REMOVE FB2 SEAT PARTITION SIDE CONSOLE AREA BUMPER 11G 26G 26D 11K 18K TOTAL 5 EA			2.0
						1C 2	FB2 SEAT PARTITION SIDE CONSOLE AREA BUMPER 11G 11K 26K 26D 11K 18K TEDLAR REPLACE			50.0
						1C 3	REINSTALL FB2 SEAT PARTITION SIDE CONSOLE AREA BUMPER 11G 26G 26D 11K 18K			2.0
									-	54.0
XJL1916	200	LOG	AV	33			(PV DEFERRAL REPORT ITEM SADD S140:353 101 -1 PORTABLE OXYGEN DISPENSING UNITS	L191	OPEN	09/20/2023
	CAB					R3, L4, R4, L5&	KS) REF Z242 PORTABLE OXY CYLINDER 9EA AT LOCATIONS R1, L2, L3(2EA), R5 FND EXPIRED. TO SADD DUE TO SPARE N/S, EXPIRED POB&MASK 9EA WERE REMOVED. ADD BACK P23. ACTIONED IAW OTHER MEL 35-31-01 REV MAR23. (PLS REF TO ATT "CX DEFERRAL REPORT" FOR			0.0
						THE REQUIRED) ACTION ITEMS)			
						1C 1	PLS MAKE LOG BOOK ENTRY.			0.2
									-	0.2

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 31 OF 89 RUN DATE: 10/6/2023

. 10/0/202

RUN TIME : 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE:

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL

ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL
ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

2C

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

THE OODE.	ZONE	STG			111 2 0052.	ONORWI ON. ALL		STATUS	UPDATED DAT
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
KJL1924	200 CAB	NRR	SS	2500	777-53-904-00-01	CAB-CLOSET S2CR-01 COMPT DR TEDLAR FND DENT.	L192	WIP	09/23/2023
	CAB					40 4 PENOVE OLOGET OCCUPATIONS			0.0
						1C 1 REMOVE CLOSET S2CR -01COMPT DOOR 1C 2 CLOSET S2CR-01 COMPT DOOR TEDLAR REPLACE			0.5
						1C 2 CLOSET S2CR-01 COMPT DOOR TEDLAR REPLACE 1C 3 REINSTALL CLOSET S2CR-01 COMPT DOOR			6.0 0.5
						TO 3 REINSTALL CLOSET SZCR-UT COWIFT DOOR		-	
L1932	100	NRP	AV	3831	777-53-545-01-01	PLEASE DISCONNECT AND CONNECT THE FUS LOWER FWD DRAIN MAST CONNECTIONS FOR ACCESS	L193	WIP	7.0 09/27/2023
	FUS								0.0
						1C 1 DISCONNECT THE ELECTRICAL SPLICE CONNECTIONS TO THE DRAIN MAST			0.0
						1C 2 DISCONNECT THE DRAIN HOSE FROM THE DRAIN MAST			0.5
						1C 3 DISCONNECT THE THE GROUND CONNECTION AND BONDING JUMPER TO STRUCTURE			0.5
						1C 4 CONNECT THE THE GROUND CONNECTION AND BONDING JUMPER TO STRUCTURE			0.5
						2C 5 CONNECT THE DRAIN HOSE FROM THE DRAIN MAST			0.5
						2C 6 CONNECT THE ELECTRICAL SPLICE CONNECTIONS TO THE DRAIN MAST			2.0
						2C 7 CHECK THAT THE RESISTANCE BETWEEN THE BONDING JUMPER TERMINAL AND THE STRUCTURE DOES NOT EXCEED 1. MILLIOHMS			0.5
						2C 8 APPLY THE SEALANT TO BONDING JUMPER TERMINAL			0.5
						3C 9 MAKE SURE THAT THE WATER FLOWS FROM THE FORWARD DRAIN MAST WITHOUT LEAKAGE			0.5
						3C 10 DO DRAIN MAST AND GRAY WATER DRAIN LINE HEATERS OPERATIONAL TEST			0.5
								-	6.0
L1940	100 LWR	NRR	Al	5234	777-52-190-00-01	FWD CGO DOOR ROTARY ACTUATOR FOUND NOISY	L194	WIP	09/29/2023
	LVVK					1C 1 REMOVE FWD CARGO ROTARY ACTUATORS			0.0 6.0
									6.0
						1C 2 INSTALL FWD CARGO ROTARY ACTUATORS 1C 3 DO THE LIFT MECHANISM ADJUSTMENT			10.0
						1C 4 CARRY OUT FWD CARGO ROTARY ACTUATORS INSTALLATION TEST			2.0
						TO 4 CANNI OUT I WE CANGO NOTANT ACTUATORS INSTALLATION ILST		-	24.0
.1957	200	LOG	AV	26		AS PER CX B-KPV NOTICE TO FLIGHT AND GROUND CREW NTC001:THIS AIRCRAFT IS INSTALLED WITH 2 CREW	L195	COMP	09/26/2023
1007	CAB	200	, .,	20		OXYGEN CYLINDERS. (AEO-26231: OXYGEN - CREW OXYGEN SYSTEM - INSTALLATION OF ADDITIONAL CREW	L195	COIVIE	
	OAD					OXYGEN CYLINDER HAS BEEN EMBODIED.			0.2
								-	0.2
.1965	200	LOG	AV	11		AS PER CX B-KPV NOTICE TO FLIGHT AND GROUND CREW NTC002: AEO-27365 INCORPORATED THE GOGO 2KU	L196	COMP	09/26/2023
	CAB					CONNECTIVITY RADOME STC HKCAD STC-2018-11 (FAA STC ST04240CH) ON THIS AIRCRAFT.			0.2
								-	0.2

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: RUN TIME : 32 OF 89

RUN DATE: 10/6/2023 14:22

0.2

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE :	TYPE CODE:	ORIGINATOR :	ALL

	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL1973	200	NRR	PT	5121	777-53-908-00-01	M/D 1-5# DOOR FUSELAGE EDGE FND PAI	NT CHIPPED TTL:10EA	L197	COMP	09/28/2023
	CAB									30.0
									-	30.0
XJL1981	200	NRR	PT	2500	777-53-904-00-01	M/D B/C SEAT UPPER AROUND BUMPER S	SURFACE FND PAINT CHIPPED TTL:9EA	L198	WIP	10/05/2023
	CAB									54.0
									-	54.0
KJL1999	200	LOG	AV	12			GROUND CREW NTC003:AEO-27365 INCORPORATED THE GOGO 2KU	L199	COMP	09/26/2023
	CAB					CONNECTIVITY CABIN STC HKCAD STC-20	18-12 (FAA STC ST04241CH) ON THIS AIRCRAFT.			0.2
									-	0.2
XJL2005	200	NRR	PT	5121	777-53-908-00-01	M/D 1-5# DOOR FRAME EDGE FND PAINT (CHIPPED TTL:10EA	L200	COMP	09/28/2023
	CAB									20.0
									-	20.0
XJL2013	200	NRR	PT	2525	777-53-908-00-01	C/A SEAT SURFACE FND CHIPPED AT: 1#E	OOOR5#DOOR TTL: 16EA	L201	OPEN	09/20/2023
	CAB									8.0
									-	8.0
KJL2021	200	NRR	PT	2500	777-53-904-00-01	M/D L/R 1 DOOR HINGE COVER FND PAINT	CHIP TTL:2EA	L202	COMP	09/28/2023
	CAB									4.0
									-	4.0
(JL2039	200	NRR	PT	5121	777-53-908-00-01	M/D ENTER DOORS FITTING FND FND PAIL	NT CHIP TTL:10EA	L203	WIP	10/02/2023
	CAB									10.0
									-	10.0
KJL2047	200	LOG	Al	56			GROUND CREW NTC004: L1 WINDSHIELD HAS SCARTCH ON INNER PANE	L204	COMP	10/02/2023
	CAB					VISION IS NOT IMPAIRED.	2 INCHES IN LENGTH & LESS THAN 0.001 INCH IN DEPTH. WITHIN LIMITS /			0.2
									-	0.2
(JL2054	200	LOG	AE	25			GROUND CREW NTC006: BOTH ENGINE OIL TYPE HAS BEEN CHANGED	L205	COMP	09/22/2023
	CAB					FROM MOBIL JET II TO ETO2197 POST THE	ACCOMPLISHMENT OF AEO-25935.			0.2
									-	

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 33 OF 89

RUN DATE: 10/6/2023

RUN TIME: 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

IRL CODE.					TIPE CODE.	ORIGINATOR	ALL		STATUS	UPDATED DATE				
JOB NO	ZONE AREA	STG	TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr				
JL2062	500	LOG	AE	28	URIG CUST REF NO.									
JL2062	500 F/T	LOG	AE	28			HT AND GROUND CREW NTC007: MAIN FUEL TANK WATER SCAVENGE SYSTEM VENGE SYSTEM HAVE BEEN MODIFIED PER AEO-19540 ISSUED AGAINST BOEING	L206	COMP	09/22/2023				
									-	0.2				
L2070	200	LOG	Al	56			T AND GROUND CREW NTC008: R2 WINDOW DELAMINATED LWR FWD CORNER 3"	L207	COMP	10/02/2023				
	CAB					X 0.5" VISION NOT IMPAIRED.				0.2				
									-	0.2				
L2088		ΑI	56			HT AND GROUND CREW NTC009: L2 WINDOW DELAMINATED ALL FWD EDGE	L208	COMP	10/02/2023					
	CAB					APPROX 0.5" WIDE VISION NOT IMPA	AIRED.			0.2				
									-	0.2				
L2096	200	LOG	ΑI	25		AS PER CX B-KPV NOTICE TO FLIGI	HT AND GROUND CREW NTC010: THIS AIRCRAFT IS FITTED WITH THE ETECHLOG	L209	COMP	09/28/2023				
	CAB		AML/CDML WILL REMAIN ONBOARD	AS THE MASTER MAINTENANCE RECORD. THE IPAD EFB DEVICE IS STORED IN THE AML/CDML. THE PAPER AML/CDML WILL REMAIN ONBOARD AS A BACKUP ONLY. COMPLY 365 IS INSTALLED IN BOTH FLIGHT DECK IPAD AND CABIN IPAD WITH OPERATIONAL MANUALS.			0.2							
									-	0.2				
L2104	200	LOG AI 25	G AI 25	AI 25	Al			HT AND GROUND CREW NTC011: ACTIVE NTC/NTCC ENTRIES HAVE BEEN	L210	COMP	09/22/2023			
	CAB										HLOG WHICH IS NOW THE PRIMARY MEANS TO CONSULT NTC/NTCC ON THIS ML/CDML SHALL BE USED DURING PAPER FALLBACK ONLY. (REF : AEO-28695)			0.2
							,		-	0.2				
L2112	200	LOG	AV	25		AS PER CX B-KPV NOTICE TO FLIGI	HT AND GROUND CREW NTC012: SB777-22A0046/AEO-29595 AFCS S/W	L211	WIP	09/26/2023				
	CAB						IS AIRCRAFT. THIS SB CANCELS FCOM OMB CAT-136 ERRONEOUS AFDS RFERENCE OCCURS. THIS NTC IS VALID UNTIL 1 MONTH AFTER ALL AIRCRAFTS			0.2				
									-	0.2				
L2120	200	LOG	AV	31			HT AND GROUND CREW NTC013: AEO-29174/SB 777-31A0342 EMBODIED ON THIS	L212	COMP	09/26/2023				
	CAB					AIRCRAFT, REFER TO FON "AIMS-2 COMPLETED.	BLOCK POINT V17C INTRODUCTION". THIS NTC IS VALID UNTIL FLEET UPGRADE			0.2				
									-	0.2				
_2138	200	LOG	AV	23		AS PER CX B-KPV NOTICE TO FLIGI	HT AND GROUND CREW NTC014: THE AIRCRAFT/ENGINES HAVE BEEN EQUIPPED	L213	OPEN	09/20/2023				
	CAB					WITH NEW FADEC SOFTWARE P/N 7	(30A-GECA08- 06 (A.0.8.6) REF SB 777-73-0037/AEO-29704.			0.2				
									-	0.2				

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 34 OF 89

ESTIMATED MHR: ALL

RUN DATE: 10/6/2023

RUN TIME: 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL

ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

				TIPE CODE.	ORIGINATOR.	ALL			
ZONE	STG							STATUS	UPDATED DAT
AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
(JL2146 200 CAB	LOG	Al	25		ETECHLOG AS THE MASTER MAINTENAN PAPER AML/CDML WILL REMAIN ONBOAR	ICE RECORD. THE IPAD EFB DEVICE IS STORED IN THE AML/CDML. THE RD AS A BACKUP ONLY. COMPLY 365 IS INSTALLED IN BOTH FLIGHT DECK	L214	COMP	09/28/2023
								-	0.2
200 CAB	LOG	Al	28		MIGRATED FROM PAPER TO E-TECHLOG	WHICH IS NOW THE PRIMARY MEANS TO CONSULT NTC/NTCC ON THIS	L215	COMP	09/28/2023
					AIRCRAFT TAIL. PAPER COPIES IN AML/C	DML SHALL BE USED DURING PAPER FALLBACK ONLY. (REF : AEO-28695)		-	
000	1.00	A) /	00		AO DED OV D VOVADOTIOS TO SUOUT AN	ID ODGUND ODGU NITOOGO WILENWI ELOONNEGTIVITY IOOUE DEDOR TED			0.2
	LOG	AV	23				L216	COMP	09/26/2023
07.12									0.2
								-	0.2
200	NRR	ΑI	2500	777-53-908-00-01	CABIN G3 GALLERY COMPARTMENT 311	BOTTOM BUMPERS FOUND CRACKED	L217	WIP	10/03/2023
CAB									3.0
								-	3.0
600	NRR	GW	5700	777-57-980-02-01	RHW #7 FIXED FAIRING 676BB SCREW (2	PEA) FOUND SEIZED	L218	COMP	09/26/2023
WNG									2.0
								-	2.0
600	NRR	GW	5700	777-57-984-02-01	RHW #8FIXED FAIRING 677DREW (3EA) F	FOUND SEIZED	L219	COMP	09/26/2023
WNG									3.0
								-	3.0
600	NRR	SM	5700	777-57-984-02-01	RHW #8FIXED FAIRING 677DR (3EA) AND	HOR NUT FOUND WORN	L220	COMP	10/02/2023
WNG									1.5
								-	1.5
600	NRR	SM	5700	777-57-980-02-01	RHW #7 FIXED FAIRING 676BB ANCHOR	NUT (2EA) FOUND WORN	L221	COMP	10/02/2023
WNG									1.0
								-	1.0
	200 CAB 200 CAB 200 CAB 200 CAB 600 WNG 600 WNG 600	200 LOG CAB	AREA TD 200 LOG AI CAB 200 LOG AI CAB 200 LOG AV CAB 200 NRR AI CAB 600 NRR GW WNG 600 NRR SM WNG 600 NRR SM	AREA TD ATA 200 LOG AI 25 200 LOG AI 28 200 LOG AV 23 CAB AV 23 CAB AV 23 CAB AV 5700 WNG AREA AI 5700	ZONE AREA STG TD ATA ORIG CUST REF NO. 200 CAB LOG AI 25 200 CAB LOG AI 28 200 CAB LOG AV 23 200 CAB NRR AI 2500 7777-53-908-00-01 600 NRR GW 5700 7777-57-980-02-01 WNG SM 5700 7777-57-984-02-01 600 NRR SM 5700 7777-57-984-02-01 WNG SM 5700 7777-57-980-02-01	ZONE STG AREA TD ATA ORIG CUST REF NO. CTRL SH NO 200 LOG AI 25 AS PER CX B-KPV NOTICE TO FLIGHT AN ETECHLOG AS THE MASTER MAINTENAN PAPER AMIL/CDML WILL REMAIN ONBOAF IPAD AND CABIN IPAD WITH OPERATION. 200 LOG AI 28 AS PER CX B-KPV NOTICE TO FLIGHT AN MIGRATED FROM PAPER TO E-TECHLOG AIRCRAFT TAIL. PAPER COPIES IN AMIL/CDM. 200 LOG AV 23 AS PER CX B-KPV NOTICE TO FLIGHT AN BY PAX, REFER TO GOSO SYSTEM HEAL CCM/SP TABLET. GREEN BAR NOICATES ECTIVITY ISSUE WITH SPECIFIC DETAIL VECABIN LOG ENTRY. 200 NRR AI 2500 777-53-908-00-01 CABIN G3 GALLERY COMPARTMENT 311 ECABIN LOG ENTRY. 200 NRR GW 5700 777-57-980-02-01 RHW #7 FIXED FAIRING 676BB SCREW (3 MAY) FIXED FAIRING 677DR (3EA) FIXED FAIRING 677DR (3EA) AND WING 600 NRR SM 5700 777-57-984-02-01 RHW #8FIXED FAIRING 677DR (3EA) AND WING 600 NRR SM 5700 777-57-980-02-01 RHW #7 FIXED FAIRING 676BB ANCHOR	ZONE STG ATA ORIG CUST REF NO. CTRL SH NO DEFECT DESCRIPTION 200 LOG AJ 25 AS PER CX B-KPV NOTICE TO FLIGHT AND GROUND CREW NTCC001: THIS ARCRAFT IS RITTED WITH THE ETCHLOG AS THE MASTER MAINTENANCE RECORD. THE IPAD EFB DEVICE IS STORED IN THE AML/COMUL THE PAPER AML/COMUL PLAND AND CABIN IPAD WITH OPERATIONAL MANUALS. 200 LOG AJ 28 AS PER CX B-KPV NOTICE TO FLIGHT AND GROUND CREW NTCC0022/ACTIVE NTCNTCC ENTRIES HAVE BEEN MIGRATED FROM PAPER TO E-TECHLOG WHICH IS NOW THE PRIMARY MEANS TO CONSULT NTCNTCC ON THIS ARCRAFT TAIL. PAPER COPIES IN AML/COMUL SHOWN TO COS01: WHEN WI-FI CONNECTIVITY ISSUE REPOR TED BY PAX. REFER TO GOOG SYSTEM HEALTH APP ON A BE ONLINE AND NO RESET REQUIRED. REPORT THE CONNECTIVITY ISSUE WITH SPECIFIC DETAIL VIA THE GOGO SYSTEM HEALTH APP AND FLIGHT JOURNAL DO NOT RA ISE ECABIN LOG ENTRY. 200 NRR AJ 2500 777-53-908-00-01 CABIN GS GALLERY COMPARTMENT 311 BOTTOM BUMPERS FOUND CRACKED 600 NRR GW 5700 777-57-984-02-01 RHW #8FIXED FAIRING 6768B SCREW (2EA) FOUND SEIZED 600 NRR SM 5700 777-57-984-02-01 RHW #8FIXED FAIRING 677DREW (3EA) FOUND SEIZED 600 NRR SM 5700 777-57-984-02-01 RHW #8FIXED FAIRING 677DREW (3EA) FOUND WORN	ZONE STG TD ATA ORIG CUST REF NO. CTRL SH NO DEFECT DESCRIPTION JSN CAB LOG AU 25 TO ATA ORIG CUST REF NO. CTRL SH NO DEFECT DESCRIPTION L214 CAB LOG AU 25 TO ATA AS PER CX B APP NOTICE TO FLIGHT AND GROUND CREW INTOCODY: THIS AIRCRAFT IS FITTED WITH THE PETCH LOG AS THE MASTER MAINTENANCE RECORD. THE IPAD EPRD DEVICE IS STORED IN THE AMLODAL THE PAPER AND CARBIN PARAL CORNILL THE PAPER AMLODAL THE PAPER AND CARBIN PAPER TO CHESH AND CREW INTOCODY. COMPLY 365 IS NSTALLED IN BOTH FLIGHT DECK IPAD AND CABIN IPAD WITH OPERATIONAL MANUALS. L215 200 LOG AU 28 TO ATA AS PER CX BAPP NOTICE TO FLIGHT AND GROUND CREW INTOCODY. WHEN WITH CONSULT INTOCITIC TO THIS AIRCRAFT TAIL. PAPER COPIES IN AMLICOME. SHALL BE USED DURING PAPER FACILIZACION Y. (REF - AE-0-26896) L216 CAB LOG AV 23 TO ATA CABBRET TO GOOD SYSTEM HEALTH APP ON S L216 CAB NRR A 2500 777-53-908-00-01 CABIN GS GABLERY COMPARTIMENT 311 BOTTOM BLIMPERS FOUND CREACED L217 600 NRR GW 5700 777-57-984-02-01 RHW #F FIXED FAIRING 678BB SCREW (ZEA) FOUND SEIZED L219 <	STATUS STATUS AREA TO ATA ORIG CUST REF NO. CTRL SH NO DEFECT DESCRIPTION JSN STATUS

REQUESTED BY:

REFERENCE NO:

DEFECT TYPE: ALL

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 35 OF 89

RUN TIME:

RUN DATE: 10/6/2023

14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL

ORIG-STAGE: ALL

CUST ENDORSE: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL

515653

BMS571R1-2

ALL

ATA NO: ALL ZONE: ALL

DISPOSITION CODE: ALL

STAGE: ALL

CTRL CODE:

TRADE : ALL TYPE CODE:

ORIGINATOR: ALL

AREA: ALL

PERIOD: ALL

JIKL CODE .					TYPE CODE.		ORIGINATOR . ALL		STATUS	UPDATED DATE
100.110		STG			ODIO OLIOT DEE NO	0.751 01110	DESCRIPTION OF THE PROPERTY OF	1011		
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO		JSN	STATUS	EST Mhr
KJL2229	500 WNG	NRR	AE	2780	777-57-806-01-01	MANUAL RETF	RACT L/E SLAT FOR T/R MAINTENANCE(WITHOUT ELEC POWER)	L222	WIP	09/24/2023
						1C 1	REMOVE SLAT ELECTRICAL MOTOR			0.0 0.0
						1C 1	DISCONNECT L/E SLAT ELEC PLUG			0.0
						1C 3	MANUAL RETRACT L/E SLAT			0.0
						1C 4	EXTENDED L/E SLAT			0.0
						2C 5	REINSTALL L/E SLAT MOTOR			0.0
						2C 6	RECONNECT SLAT MOTOR ELEC PLUG			0.0
						2C 7	C/O L/E SLAT SYSTEM TEST			0.0
									-	0.1
JL2237	600	NRR	CL	5711	777-57-984-02-01	RHW (#5~8)FL	AP TRACK AND FAIRING INTERNAL FOUND DIRTY	L223	COMP	09/28/2023
	WNG									18.0
									-	18.0
JL2245	200	NRR	PT	2500	777-53-904-00-01	COCKPIT OBS	ERVER SEAT HANDRAIL SURFACE AND SIDE STOWAGE FOUND PAINT PEEL OFF	L224	WIP	10/03/2023
	CAB									4.0
									-	4.0
JL2252	500	NRR	CL	57	777-57-892-01-01	LHW (#1~4)FL	AP TRACK AND FAIRING INTERNAL FOUND DIRTY	L225	COMP	09/28/2023
	WNG									18.0
									-	18.0
JL2260	200	NRR	Al	25	777-53-916-00-01	G4.G5 GALLEY	Y PLACARD FOUND TORN	L226	COMP	10/02/2023
	CAB									2.0
									-	2.0
JL2278	200	NRR	Al	25	777-53-920-00-01	G6.G7 GALLEY	Y PLACARD FOUND TORN	L227	COMP	10/02/2023
	CAB									2.0
									-	2.0
JL2286	500	NRR	CL	5700	777-57-868-01-01	LHW SPOILER	LOWER SURFACE &T/E CAVITY FOUND DIRTY	L228	COMP	09/28/2023
	WNG									20.0
									-	20.0

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 36 OF 89

RUN DATE: 10/6/2023

1.0

RUN TIME: 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CIRL CODE :	ZONE	CTC			TYPE CODE:	ORIGINATOR:	ALL		STATUS	UPDATED DATE
JOB NO	AREA	SIG	TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL2294	200	NRR	AV	2331	777-23-010-00-01	PERFORMED ALL TEST FOUND L C	TR LATTICE ABOVE ROW 64 SDM 5-2 DOES NOT RESPOND	L229	WIP	09/27/2023
	CAB									2.0
									-	2.0
XJL2302	200	NRR	Al	25	777-53-916-00-01	G5 GALLEY OVEN2.OVEN4.OVEN5 L	OWER AREA BUMPER CRACKED	L230	COMP	10/03/2023
	CAB									6.0
									-	6.0
KJL2310	600	NRR	CL	5700	777-57-960-02-01	RHW SPOILER LOWER SURFACE &	T/E CAVITY FOUND DIRTY	L231	COMP	09/28/2023
	WNG									20.0
									-	20.0
	200	NRR	Al	25	777-53-916-00-01	G5 GLY 505 COMPT TURN RETAINE	R FOUND MALFUNCTION	L232	COMP	09/28/2023
	CAB									1.0
									-	1.0
(JL2336	200	NRR	Al	25	777-53-916-00-01	G5 GALLEY AFT BABY BASSINET SO	PREWS LOOSEN	L233	COMP	10/02/2023
	CAB									1.0
									-	1.0
XJL2344	500	NRR	CL	2781	777-57-504-01-01	LHW L/E SLAT T/E WEDGE & FRONT	SPAR FOUND DIRTY	L234	COMP	09/28/2023
	WNG									20.0
									-	20.0
KJL2351	100	PNT	PT	51	777-11-000-09-CXNA -01	STRIP THE RESIDUAL COATING AF	TER FUS STRIPPING	L235	OPEN	09/21/2023
	FUS				-01					160.0
									-	160.0
KJL2369	200	NRR	AV	3326	777-C330000-01-03- 01	PERFORM CSCP ALL TEST FOUND	DOME LIGHTS INOP AT LAV D,L,K,	L236	OPEN	09/21/2023
	CAB									3.0
									-	3.0
XJL2377	200 CAB	NRR	Al	25	777-53-920-00-01	R5 FWD CLOSET S5R-11.S5R-12 INS	IDE COMPT 2EA BUMPER MISSING	L237	COMP	09/28/2023
	CAB									1.0
									-	

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE:

RUN TIME :

37 OF 89

RUN DATE: 10/6/2023 14:22

1.0

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

STATUS: ALL

ORIG-STAGE: ALL

PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL

ATA NO: ALL

ZONE: ALL

DISPOSITION CODE: ALL

DEFECT TYPE: ALL CTRL CODE:

REQUESTED BY:

REFERENCE NO:

515653

BMS571R1-2

TRADE: ALL TYPE CODE:

CUST ENDORSE: ALL ORIGINATOR: ALL

AREA: ALL STAGE: ALL

	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL2385	600	NRR	CL	2781	777-57-538-02-01	RHW L/E SLAT T/E WEDGE & FRONT SPAR	FOUND DIRTY	L238	COMP	09/28/2023
	WNG									20.0
									-	20.0
XJL2393	200	NRR	ΑI	25	777-53-920-00-01	G6 GLY OVEN1.OVEN2.OVEN3 LOWER BUN	IPER FOUND CRACKED	L239	COMP	10/03/2023
	CAB									6.0
									-	6.0
XJL2401	200	NRR	AV	3326	777-C330000-01-03-	PERFORM CSCP ALL TEST FOUND ROW 46	LAVATORY SIGN INOP	L240	WIP	10/03/2023
	CAB				01					1.0
									-	1.0
XJL2419	200	NRR	SS	25	777-C252000-01-07-	FB2 SEAT STRUCTURE VELCRO TAPE FOU	ND LOOSEN AT:11G H 12G H 16G H -26G H TOTAL:26EA	L241	COMP	10/04/2023
	CAB				R-01					10.5
									-	10.5
XJL2427	200	NRR	SS	25	777-C252000-01-07-	FB2 SEAT STRUCTURE VELCRO TAPE FOU	ND LOOSEN AT:11A D 12A D 15A -26A 16D-26D TOTAL:27EA	L242	COMP	10/04/2023
	CAB				R-01					10.5
									-	10.5
XJL2435	200	NRR	SS	25	777-C252430-01-06-	PEY PAX SEAT BACK REST FOUND DISALIC	SNMENT AT30DEFG 31DEFG 32DEFG 33DEFG 34DEFG TOTAL:20EA	L243	COMP	10/04/2023
	CAB				01					10.0
									-	10.0
XJL2443	200	NRR	SS	25	777-C252430-01-01-	PEY PAX SEAT STRUCTURE VELCRO TAPE	FOUND LOOSEN AT:30DEFG-34DEFG 32HK-34HK 31AC -34AC TOTAL:34EA	L244	COMP	10/04/2023
	CAB				01					17.0
									-	17.0
XJL2450	200	NRR	SS	25	777-C252430-01-04-		FOWAGE SHROUD VELCRO TAPE FOUND LOOSEN AT:30DEFG-34DEFG	L245	COMP	10/04/2023
	CAB				01	31AC-34AC 32HK-34HK TOTAL34EA				13.5
									-	13.5
XJL2468	200	NRR	AV	3326	777-C330000-01-03-	PERFORM CSCP ALL TEST FOUND OFAR B	UNK 4 AREA LIGHT INOP	L246	WIP	09/26/2023
	CAB				01					1.0
									-	

REQUESTED BY:

REFERENCE NO:

DEFECT TYPE: ALL

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 38 OF 89 RUN DATE: 10/6/2023

RUN TIME : 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL PERIOD: ALL

ZONE: ALL

AREA: ALL

ESTIMATED MHR: ALL DISPOSITION CODE: ALL

ORIGINATING CUST REF NO:

ALL

TRADE: ALL CUST ENDORSE: ALL

ATA NO: ALL

STAGE: ALL

CTRL CODE:

TYPE CODE: ORIGINATOR: ALL

	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL2476	200	NRR	Al	25	777-53-920-00-01	G6.G7 GALLEY WORK DECK EDGE SEALANT F	OUND AGED	L247	COMP	10/04/2023
	CAB									4.0
									-	4.0
XJL2484	200	NRR	SS	25	777-C252430-01-04-		ND DISALIGNMENT AT:30DEFG-34DEFG 32HK-34HK 31AC -34AC	L248	COMP	10/04/2023
	CAB				01	TOTAL34EA				13.5
									-	13.5
XJL2492	200	NRR	SS	25	777-C252430-01-04-		RATION FOUND JAM AT:30D E F G-34D E F G 32H K -34H K 31A C -34A C	L249	WIP	09/28/2023
	CAB				01	TOTAL:34EA				13.5
									-	13.5
XJL2500	200	NRR	ΑI	25	777-53-916-00-01	G4.G5 GALLEY WORK DECK EDGE SEALANT F	OUND AGED	L250	COMP	10/04/2023
	CAB									4.0
									-	4.0
XJL2518	500	NRR	CL	57	777-57-856-01-01	LHW ALL REMOVED ACCESS PANEL INNER SU	JRFACE FOUND DIRTY	L251	COMP	09/28/2023
	WNG									0.0
									-	0.0
XJL2526	200	NRR	ΑI	25	777-53-916-00-01	G4L.G4R GALLEY WORK DECK EDGE SEALAN	T FOUND AGED.	L252	COMP	10/04/2023
	CAB									4.0
									-	4.0
XJL2534	200	NRR	AV	3324	777-C330000-01-03- 01	PERFORM CSCP ALL TEST FOUND ROW 11&6	0 CTR NO SMOKING SIGN INOP	L253	WIP	10/03/2023
	CAB				UT					2.0
									-	2.0
XJL2542	600	NRR	CL	57	777-57-948-02-01	RHW ALL REMOVED ACCESS PANEL INNER S	URFACE FOUND DIRTY	L254	COMP	09/28/2023
	WNG									0.0
									-	0.0
XJL2559	200	NRR	ΑI	25	777-53-920-00-01	G6 GALLEY 606.607 COMPT SHORT TURN BUT	TON FOUND MALFUNCTION	L255	COMP	09/25/2023
	CAB									2.0
									-	2.0

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 39 OF 89

RUN DATE: 10/6/2023

2.0

RUN TIME : 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL

ATA NO: ALL

PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL

ZONE: ALL AREA: ALL

DISPOSITION CODE: ALL

STAGE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL CTRL CODE:

TYPE CODE: ORIGINATOR: ALL

	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL2567	200	NRR	Al	25	777-53-920-00-01	G6 GALLEY 603.605.607 LOWER COMPT UPPER	F GUIDE 3EA BUMPER CRACKED	L256	COMP	10/02/2023
	CAB									6.0
									-	6.0
XJL2575	200	NRR	AV	3321	777-C330000-01-01-		ITS INOP AT LAV 4F-1L(LAV H) ,ABOVE DR 2L STOWAGE S2L,ABOVE	L257	OPEN	09/21/2023
	CAB				01	DR 2 RIGHT , ROW 2 LEFT ABOVE BIN				4.0
									-	4.0
XJL2583	200	NRR	Al	25	777-53-920-00-01	G7 GALLEY 706.707 COMPT TURN RETAINER AF	T INDICATOR BUMPER FOUND MISSING	L258	COMP	09/28/2023
	CAB									1.0
									-	1.0
XJL2591	200	NRR	Al	25	777-53-920-00-01	G7 GALLEY 708 WASTE COMPT DOOR AFT SIDE	UPPER AREA 1EA BUMPER CRACKED	L259	COMP	10/02/2023
	CAB									2.0
									-	2.0
XJL2609	200	NRR	Al	25	777-53-920-00-01	G7 GALLEY 714.715.726 COMPT SMALL TURN BU	TTON FOUND STIFF	L260	COMP	10/02/2023
	CAB									1.0
									-	1.0
XJL2617	200	NRR	Al	25	777-53-920-00-01	G7 GALLEY 702 COMPT SHORT TURN BUTTON F	OUND MALFUNCTION	L261	COMP	09/25/2023
	CAB									1.0
									-	1.0
XJL2625	200	NRR	Al	25	777-53-920-00-01	G7 GALLEY 701.705.707 LOWER COMPT UPPER	F GUIDE 3EA BUMPER CRACKED	L262	COMP	10/02/2023
	CAB									6.0
									-	6.0
XJL2633	200	NRR	AV	4420	777-24-001-00-01	PERFORM IFE TEST FOUND 66D,70E MONITORS	TOUCHSCREEN DOES NOT RESPOND	L263	WIP	10/01/2023
	CAB									4.0
									-	4.0
XJL2641	200	NRR	AV	4420	777-24-001-00-01	PERFORM IFE TEST FOUND 23A MONITOR TOUG	CHSCREEN DOES NOT RESPOND	L264	WIP	09/27/2023
	CAB							L20 1	****	2.0
									-	

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 40 OF 89

STAGE: ALL

RUN DATE: 10/6/2023

RUN TIME: 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL

CTRL CODE :					TYPE CODE:	ORIGINATOR:	ALL			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL2658	200	NRR	AV	2525	777-24-001-00-01	PERFORM BC SEAT ELECTRICAL OF	PERATION TEST FOUND 24A SEAT INOP	L265	OPEN	09/21/2023
	CAB									2.0
									-	2.0
XJL2666	200	NRR	AV	2525	777-24-001-00-01	PERFORM BC SEAT OPERATION TES	ST FOUND 23G,20K,21G TTL LIGHT INOP	L266	OPEN	09/21/2023
	CAB									3.0
									-	3.0
XJL2674	200	NRP	SS	25	777-25-060-01-CX-01	C/A SEAT STRUCTURE VELCRO TAP	PE END LOOSEN TTI :16EA	L267	OPEN	09/21/2023
	CAB							LZUI	OI LIV	6.0
									-	
V II 0000	000	NDD	00	0.5	777 0050440 04 04					6.0
XJL2682	200 CAB	NRR	SS	25	777-C252410-01-01- 01	FIRST CLASS SEAT STRUCTURE VE	LCRO TAPE FND LOOSEN AT:1A D K-2A D K TTL:6EA	L268	WIP	10/05/2023
	O/ID								_	4.0
										4.0
XJL2690	100	NRP	GW	5346	777-900002-01-1-01	FUS-LH BODY FAIRING 195AL 3EA S	CREWS SEIZED.	L269	COMP	09/27/2023
	FUS									3.0
									-	3.0
XJL2708	200	NRR	SS	25	777-C252440-04-03-	E ZONE EY PAX SEAT BACKREST RE	ECLINE OPERATION FND TIGHTEN AT:39AC-45ABC TTL:20EA	L270	COMP	10/05/2023
	CAB				01					4.0
									-	4.0
XJL2716	200	NRR	SS	25	777-C252000-01-07-	CAB B ZONE B/C SEAT BACK COVER	R FOUND TORN TTL:13EA	L271	WIP	10/05/2023
	CAB				R-01					6.5
									-	6.5
XJL2724	200	NRR	SS	25	777-C252000-01-07-	CAB B ZONE B/C SEAT LEGREST CO	AVED FOLIND NOT MATCH TTI -1EA	1.070	00140	
AJLZ1Z4	CAB	MIXIX	33	25	R-01	OAD D ZONE BIO SEAT LEGILLOT CO	VERTICAL NOT WATCH TIE. IEA	L272	COMP	10/04/2023
									_	0.5
										0.5
XJL2732	200	NRR	SS	25	777-C252000-01-07- R-01	CAB B ZONE B/C SEAT HEADREST S	TRUCTURE FOUND CRACKED TTL:6EA	L273	WIP	10/02/2023
	CAB									3.0
									-	3.0

REQUESTED BY:

REFERENCE NO:

DEFECT TYPE: ALL

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

41 OF 89 PAGE: RUN DATE: 10/6/2023

RUN TIME :

14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL

AREA: ALL

ESTIMATED MHR: ALL DISPOSITION CODE: ALL

ORIGINATING CUST REF NO: ALL

TRADE: ALL

ATA NO: ALL ZONE: ALL CUST ENDORSE: ALL

STAGE: ALL

CTRL CODE:

ΤY

TYPE CODE:	ORIGINATOR:	ALL

THE OODE .	ZONE	STG			TITE GODE.	Ortion viron			STATUS	UPDATED DATI
JOB NO	AREA	010	TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
IL2740	200	NRR	SS	25	777-C252000-01-08-	CAB C ZONE PEY SEAT BOTTOM C	OVER FOUND NOT MATCH TTL:4EA	L274	COMP	10/04/2023
	CAB				R-01					2.0
									-	2.0
L2757	200	NRR	SS	25	777-C252440-04-03-	E ZONE EY PAX SEAT BACKREST	RECLINE OPERATION FND TIGHTEN AT:39DEFG-46DEFG TTL:32EA	L275	COMP	10/05/2023
	CAB				01					6.0
									-	6.0
_2765	200	NRR	SS	25	777-C252440-04-03-	E ZONE EY PAX SEAT BACKREST	RECLINE OPERATION FND TIGHTEN AT:40HJK-46HJK TTL:21EA	L276	COMP	10/05/2023
	CAB				01					6.0
									-	6.0
L2773	200	NRR	SS	25	777-C252000-01-08-	CAB C ZONE PEY SEAT HEADRES	T STRUCTURE SCREW FOUND LOOSE TTL:12EA	L277	COMP	10/03/2023
CA	CAB				R-01					2.0
									-	2.0
L2781	200	NRR	SS	25	777-C252440-04-03-	D ZONE EY PAX SEAT BACKREST	RECLINE OPERATION FND TIGHTEN AT:59ABC-72AC TTL: 41	L278	COMP	10/05/2023
	CAB				01			8.0		
									-	8.0
_2799	200	NRR	SS	25	777-C252440-04-03-	D ZONE EY PAX SEAT BACKREST	RECLINE OPERATION FND TIGHTEN AT:60DEFG-72DEG TTL:48EA	L279	COMP	10/05/2023
	CAB				01					9.0
									-	9.0
L2807	200	NRR	SS	25	777-C252440-04-03-	D ZONE EY PAX SEAT BACKREST	RECLINE OPERATION FND TIGHTEN AT:59HJK-71HJK TTL:39EA	L280	COMP	10/05/2023
	CAB				01					8.0
									-	8.0
_2815	200	NRR	SS	25	777-C252440-04-02-	EY F/R SEAT IN ARM TABLE FND T	IGHTEN AT:39A.C D.E.F.G H.J.K.59A.B.C.H.J.K.60D.E.F.G TTL:19EA	L281	WIP	09/25/2023
CA	CAB				01					6.0
									-	6.0

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

A/C REGN: B-KPV

PAGE: 42 OF 89

RUN DATE: 10/6/2023 RUN TIME: 14:22

PROJECT: XJ

REQUESTED BY:

REFERENCE NO:

CUSTOMER: CX A/C TYPE: 777

> STATUS: ALL ORIG-STAGE: ALL

PERIOD: ALL

CHECK TYPE:

ESTIMATED MHR: ALL

JSN RANGE SELECTED: ALL ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

ATA NO: ALL

ZONE: ALL

DISPOSITION CODE: ALL

STAGE: ALL

2C

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL

CTRL CODE:

TYPE CODE: ORIGINATOR: ALL

STATUS LIPDATED DATE

	ZONE	STG						STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
(JL2823	100	NRM	AV	2431	AEO-27438-01	DISCONNECT AND RECONNECT MAIN BATTERY AND APU BATTERY FOR POWER PANEL REWORK	L282	WIP	09/22/2023
	LWR								0.0
						1C 1 RECONNECT CONNECTOR OF MAIN BATTERY			1.0
						1C 2 RECONNECT CONNECTOR OF APU BATTERY			1.0
						1C 3 PERFORM MAIN BATTERY RECONNECTION TEST			1.0
						1C 4 DISCONNECT CONNECTOR OF APU BATTERY			1.0
						2C 5 PERFORM APU BATTERY RECONNECTION TEST			1.0
						2C 6 DISCONNECT CONNECTOR OF MAIN BATTERY			1.0
								-	6.0
JL2831	200	NRR	SS	2500	777-53-908-00-01	CABIN #2 DOOR G2 GLY R/H AISLE S/W FOUND SCRATCHED	L283	WIP	09/24/2023
	CAB								0.0
						1C 1 REMOVE G2 GLY RHS AISLE LIGHT			0.5
						1C 2 REMOVE G2 GLY RHS AISLE PNL			1.0
						1C 3 G2 GLY RHS AISLE TEDLAR REPLACE			11.0
						1C 4 REINSTALL G3 2 GLY RHS AISLE PNL			1.0
						2C 5 REINSTALL G2 GLY RHS AISLE LIGHT			0.5
								-	14.0
JL2849	100	NRR	PT	2500	777-53-854-00-01	AFT CGO BILGE AREA RIVETS PAINT FOUND PEEL OFF	L284	OPEN	09/22/2023
	LWR								4.0
								-	4.0
JL2856	100	NRR	PT	5121	777-53-854-00-01	AFT CGO DOOR ARM SUPPORT FND PAINT CHIP	L285	OPEN	09/22/2023
	LWR								2.0
								-	2.0
JL2864	100	NRR	PT	5121	777-53-818-00-01	FWD CGO DOOR ARM SUPPORT FND PAINT CHIP	L286	OPEN	09/22/2023
	LWR								2.0
								-	2.0
JL2872	100	NRR	PT	5121	777-53-818-00-01	FWD CGO DOOR DEPRESSOR SEAL FOUND PAINT CHIPPED.	L287	WIP	09/27/2023
	LWR								6.0
								-	
									6.0

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 43 OF 89

RUN DATE: 10/6/2023

RUN TIME : 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO:

ALL

ATA NO: ALL

ZONE: ALL

DISPOSITION CODE: ALL

DEFECT TYPE : ALL	TRADE: ALL	CUST ENDORSE: ALL	AREA: ALL	STAGE: ALL	
CTRL CODE:	TYPE CODE:	ORIGINATOR: ALL			FATUR LIBRATED DATE

	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL2880	100	NRR	PT	5121	777-53-854-00-01	AFT CGO COMP'T BALL MAT AF	REA RED LOCK FOUND PAINT PEELED.TTL30EA	L288	WIP	09/27/2023
	LWR									15.0
									-	15.0
XJL2898	100	NRR	PT	5121	777-53-870-00-01	BULK CGO DOOR SILL AND BLA	ACK LINE FOUND PAINT PEELED.	L289	COMP	09/28/2023
	LWR									5.0
									-	5.0
XJL2906	100	NRR	PT	5121	777-53-870-00-01	BULK CGO CTR FLOOR PANEL	FOUND PAINT PEELED.	L290	COMP	09/28/2023
	LWR									8.0
									-	8.0
XJL2914	100	NRR	PT	5121	777-53-854-00-01	FWD AND AFT CGO DOOR LOW	VER SILL FITTING BLACK MARKING FOUND PAINT PEELED	L291	OPEN	09/22/2023
	LWR									5.0
									-	5.0
XJL2922	100	NRR	PT	5121	777-53-818-00-01	FWD CGO COMP'T BALL MAT A	AREA RED LOCK FOUND RED PAINT PEELED.TTL:30EA	L292	WIP	09/27/2023
	LWR									15.0
									-	15.0
XJL2930	100	NRR	PT	5121	777-53-818-00-01	FWD CGO COMP'T BALL MAT PA	PANEL FOUND PAINT PEELED.TTL5EA.	L293	COMP	09/28/2023
	LWR									15.0
									-	15.0
XJL2948	100	NRR	PT	5121	777-53-854-00-01	AFT CGO BALL MAT PNL FOUNI	ID PAINT PEEL.TTL:5EA	L294	COMP	09/28/2023
	LWR									5.0
									-	5.0
XJL2955	100	NRR	PT	5121	777-53-854-00-01	AFT CGO DOOR DEPRESSOR S	SEAL FOUND PAINT CHIPPED.	L295	WIP	09/27/2023
	LWR									6.0
									-	6.0

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 44 OF 89

RUN TIME :

STATUS

RUN DATE: 10/6/2023 14:22

UPDATED DATE

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL

PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO:

ALL

ATA NO: ALL

ZONE: ALL

DISPOSITION CODE: ALL

DEFECT TYPE: ALL

TRADE: ALL

CUST ENDORSE: ALL

AREA: ALL STAGE: ALL

CTRL CODE:

		TYPE CODE:	ORIGINATOR:	ALL
ZONE	STG			

JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	D DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL2963	200 CAB	NRR	SM	2520	777-53-907-00-01	FWD ZONE C	FCR LH &RH CREW SEAT PAN FOUND DAMAGED	L296	WIP	09/30/2023
						1C 1				0.0
						1C 1	PLS REMOVE L/R SEAT REMOVE L/R SEAT L/R SIDE ARM			2.0 8.0
						1C 2	SEAT PAN& DOUBLER REPLACE			48.0
						1C 3	REINSTALL L/L SEAT L/R SIDE ARM			8.0
						2C 5	REINSTALL LI'R SEAT			1.0
						20 0	NEIGONEE EN GEN		-	67.0
KJL2971	600	NRR	SS	5700	777-57-972-02-01	DHW #6 FIYE	D FAIRING FOUND EROSION	L297	WIP	09/24/2023
(JLZ37 1	WNG	INIXIX	00	3700	777-372-02-01	KIIW #01 IXL	DI AIKING I COND ERCOION	L297	WIP	
	WIVO									0.0
						1C 1	DO AN INSPECTION TO FIND THE DAMAGE DIMENSION			1.0
						1C 2	CONFIRM DAMAGE WITHIN SRM ADL			2.0
						1C 3	MAKE A PERMANENT SEAL TO PERMITTED DAMAGE			3.0
						1C 4	APPLY ONE LAYER OF BMS10-60 ENAMEL		_	0.0
/ II 0000 000 ND									6.0	
	NRR	SS	5700	777-57-982-02-01	RHW #7 FIXE	D FAIRING FWD CUTOUT FOUND EROSION	L298	WIP	09/24/2023	
	WNG									0.0
						1C 1	DO AN INSPECTION TO FIND THE DAMAGE DIMENSION			1.0
						1C 2	CONFIRM DAMAGE WITHIN SRM ADL			2.0
						1C 3	MAKE A PERMANENT SEAL TO PERMITTED DAMAGE			3.0
						1C 4	APPLY ONE LAYER OF BMS10-60 ENAMEL			0.0
									-	6.0
KJL2997	600	NRR	SS	5700	777-57-982-02-01	RHW #8 FIXE	D FAIRING FWD CUTOUT FOUND EROSION	L299	WIP	09/24/2023
	WNG									0.0
						1C 1	DO AN INSPECTION TO FIND THE DAMAGE DIMENSION			1.0
						1C 2	CONFIRM DAMAGE WITHIN SRM ADL			2.0
						1C 3	MAKE A PERMANENT SEAL TO PERMITTED DAMAGE			3.0
						1C 4	APPLY ONE LAYER OF BMS10-60 ENAMEL			0.0
									-	6.0
KJL3003	600	NRR	AE	2708	777-57-954-02-01	RHW FLAPER	RON LIP DOORS I/B SEAL FOUND TORN	L300	COMP	09/28/2023
	WNG									2.0
									-	2.0

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 45 OF 89 RUN DATE: 10/6/2023

RUN TIME : 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

> ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

JIKL CODE .					TIPE CODE.	URIGINATUR . ALL				
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
JL3011	600	NRR	ΑE	2708	777-57-954-02-01	RHW FLAPERON O/B LOWERLOWER SEAL FO	UND TORN	L301	COMP	09/28/2023
	WNG									6.0
									-	6.0
JL3029	600	NRR	AE	2750	777-57-952-02-01	RHW I/B MAIN FLAP I/B EDGE SEAL FOUND TO	RN	L302	OPEN	09/22/2023
	WNG									1.0
									-	1.0
XJL3037 600	600	NRR	AE	2750	777-57-860-01-01	LHW I/B MAIN FLAP I/B EDGE SEAL FOUND TO	RN	L303	OPEN	09/22/2023
	WNG					2 ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		2000	OI LIV	1.0
									-	
II 0045	000	NDD	۸.	0700	777 57 000 04 04		No Topy			1.0
JL3045	600 WNG	NRR	AE	2708	777-57-862-01-01	LHW FLAPERON I/B UPPER LOWER SEAL FOL	ND TORN	L304	COMP	09/28/2023
VVIVC	WITO								_	6.0
										6.0
JL3052	500	NRR	AE	2700	777-57-880-01-01	LHW FLAPERON I/B HINGE AFTER FAIRING SE	AL FOUND TORN	L305	COMP	09/28/2023
	WNG									2.0
									-	2.0
JL3060	500	NRR	SS	57	777-57-900-02-01	WING LE ACCESS PNLS 611 CB GB FOUND EX	TERNAL SURFACE PAINT IRREGULARITY	L306	WIP	09/27/2023
	WNG									0.0
						1C 1 APPLY THE RESIN COATING T	O IRREGULAR AREA			3.0
						1C 2 SAND THE RESIN COATING TO	MAKE SURFACE SMOOTHER			3.0
						1C 3 APPLY THE SURFACE PAINT				0.0
									-	6.0
JL3078	100	NRR	Al	2500	777-53-862-00-01	AFT CGO R/H BALL MAT AREA PDU ROLLER F	OUND WORN.TOTAL 5 PAIRS	L307	COMP	10/03/2023
	LWR									5.0
									-	5.0
JL3086	100	NRR	Al	2500	777-53-862-00-01	AFT CGO R/H AFT BALL MAT AREA R/H AFT PI	DU SENSOR FOUND WORN. TOTAL 1EA.	L308	COMP	10/03/2023
	LWR									2.0
									-	2.0
										2.0

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 46 OF 89 RUN DATE: 10/6/2023

RUN TIME :

14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

STATUS: ALL

ORIG-STAGE: ALL

PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL

ATA NO: ALL

ZONE: ALL

DISPOSITION CODE: ALL

DEFECT TYPE : ALL

515653

BMS571R1-2

TRADE: ALL

CUST ENDORSE: ALL

AREA: ALL

STAGE: ALL

CTRL CODE :	TYPE CODE:	ORIGINATOR:	ALL

				TIPE CODE.	ORIGINATOR. P				
	STG								UPDATED DATE
AREA			ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
100	NRR	Al	2500	777-53-862-00-01	AFT CGO R/H AFT BALL MAT AREA R/H FV	D STOP AXLE PIN FOUND BROKEN. TOTAL 1EA.	L309	COMP	10/03/2023
LWK									2.0
								-	2.0
800	NRP	CL	52	777-52-531-01-01	M/D ALL DOOR STOP FITTING AREA FOUN	D DIRTY.	L310	COMP	09/28/2023
CAB									10.0
								-	10.0
800	NRP	CL	52	777-52-531-01-01	M/D ALL DOOR CUTOUT STOP FITTING AF	EA FOUND DIRTY.	L311	COMP	09/28/2023
CAB									10.0
								-	10.0
200	NRR	PT	2500	777-53-916-00-01	M/D R5 DOOR BUSTLE PNL FND PAINT CH	P	L312	COMP	09/28/2023
CAB									4.0
								-	4.0
200	NRR	PT	2500	777-53-908-00-01	CABIN S2CL S2CR CLOSET UPPER EDGE	FND PAINT CHIPPED	L313	COMP	10/05/2023
CAB									10.0
								-	10.0
200	NRR	PT	2500	777-53-916-00-01	M/D R4-01 R4-02 R4-03 R4-04 GALLEY DOC	R INTERIOR SURFACE FND PAINT CHIPPED	L314	COMP	10/03/2023
CAB									8.0
								-	8.0
200	NRR	PT	2500	777-53-904-00-01	M/D C-103 R-103 R-123 GALLEY DOOR INT	ERIOR SURFACE FND PAINT CHIPPED	L315	COMP	10/03/2023
CAB									6.0
								-	6.0
200	NRR	PT	2500	777-53-908-00-01	M/D G201 G202 GALLEY DOOR INTERIOR	SURFACE FND PAINT CHIPPED	L316	COMP	10/03/2023
CAB									4.0
								-	4.0
200	NRR	PT	2500	777-53-908-00-01	M/D R2-01 R2-02 R2-03GALLEY DOOR INTE	RIOR SURFACE FND PAINT CHIPPED	L317	COMP	10/03/2023
CAB									6.0
								-	6.0
	200 CAB 200 CA	100 NRR LWR NRP CAB NRP CAB NRR	AREA TD 100 NRR AI 800 NRP CL CAB NRR PT CAB NRR PT	AREA TD ATA 100 LWR NRR NRP AI 2500 800 CAB NRP CL 52 800 CAB NRR PT 2500 200 CAB NRR PT 2500	AREA TD ATA ORIG CUST REF NO. 100 NRR NRR AI 2500 777-53-862-00-01 800 NRP CL 52 777-52-531-01-01 800 NRP CL 52 777-52-531-01-01 200 NRR PT 2500 777-53-916-00-01 200 NRR PT 2500 777-53-908-00-01 200 NRR PT 2500 777-53-916-00-01 200 NRR PT 2500 777-53-904-00-01 200 NRR PT 2500 777-53-904-00-01 200 NRR PT 2500 777-53-908-00-01	AREA TD ATA ORIG CUST REF NO. CTRL SH NO 100 NRR AI 2500 7777-53-862-00-01 AFT CGO RIH AFT BALL MAT AREA RIH FW. 800 NRP CL 52 777-52-531-01-01 M/D ALL DOOR STOP FITTING AREA FOUN 800 NRP CL 52 777-52-531-01-01 M/D ALL DOOR CUTOUT STOP FITTING AREA FOUN 200 NRR PT 2500 7777-53-916-00-01 M/D R5 DOOR BUSTLE PNL FND PAINT CH CAB NRR PT 2500 777-53-908-00-01 CABIN S2CL S2CR CLOSET UPPER EDGE F 200 NRR PT 2500 777-53-916-00-01 M/D R4-01 R4-02 R4-03 R4-04 GALLEY DOOR INTE 200 NRR PT 2500 777-53-904-00-01 M/D C-103 R-103 R-123 GALLEY DOOR INTE 200 NRR PT 2500 777-53-908-00-01 M/D G201 G202 GALLEY DOOR INTERIOR S 200 NRR PT 2500 777-53-908-00-01 M/D R2-01 R2-02 R2-03GALLEY DOOR INTERIOR S	AREA TD ATA ORIG CUST REF NO. CTRL SH NO DEFECT DESCRIPTION 100 NRR AI 2500 777-53-862-00-01 AFT CGO RH AFT BALL MAT AREA RH FWD STOP AXLE PIN FOUND BROKEN. TOTAL 1EA 800 NRP CL 52 777-52-531-01-01 MID ALL DOOR STOP FITTING AREA FOUND DIRTY. 800 NRP CL 52 777-52-531-01-01 MID ALL DOOR CUTOUT STOP FITTING AREA FOUND DIRTY. 200 NRR PT 2500 777-53-916-00-01 MID R5 DOOR BUSTLE PNL FND PAINT CHIP 200 NRR PT 2500 777-53-916-00-01 MID R5 DOOR BUSTLE PNL FND PAINT CHIP 200 NRR PT 2500 777-53-908-00-01 MID R4-01 R4-02 R4-03 R4-04 GALLEY DOOR INTERIOR SURFACE FND PAINT CHIPPED 200 NRR PT 2500 777-53-908-00-01 MID C-103 R-103 R-123 GALLEY DOOR INTERIOR SURFACE FND PAINT CHIPPED 200 NRR PT 2500 777-53-908-00-01 MID G-201 R-202 G-203 GALLEY DOOR INTERIOR SURFACE FND PAINT CHIPPED 200 NRR PT 2500 777-53-908-00-01 MID G-201 R-202 G-203 GALLEY DOOR INTE	AREA TO	AREA TD ATA ORIG CUST REF NO. CTRL SH NO DEFECT DESCRIPTION JSN STATUS 100 NRR JULIA 2500 777-52-962-00-01 AFT COOR IN AFT BALL MAT AREA RIFF FUOL TO DRIVE PINT DUND BROKEN. TOTAL IEA. 1300 COMP 800 NRP JULIA 520 777-52-531-01-01 MD ALL DOOR STOP FITTING AREA FOUND DIRTY. 1311 COMP 800 NRP JULIA 520 777-52-531-01-01 MD ALL DOOR CUTOUT STOP FITTING AREA FOUND DIRTY. 1311 COMP 200 NRR JULIA 520 777-53-916-00-01 MD RES DOOR BUSTLE PINE FID PAINT CHIPPED 1312 COMP 200 NRR JULIA 520 777-53-916-00-01 MD RES DOOR BUSTLE PINE FID PAINT CHIPPED 131 COMP 200 NRR JULIA 520 777-53-916-00-01 MD RES DOOR BUSTLE PINE FID PAINT CHIPPED 131 COMP 200 NRR JULIA 520 777-53-916-00-01 MD RES DOOR BUSTLE PINE FID PAINT CHIPPED 131 COMP 200 NRR JULIA 520 777-53-916-00-01 MD RES DOOR BUSTLE PINE FID PAINT CHIPPED 131

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 47 OF 89

RUN DATE: 10/6/2023

RUN TIME: 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL

PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO:

ALL

ATA NO: ALL

ZONE: ALL

DISPOSITION CODE: ALL

DEFECT TYPE : ALL

TRADE: ALL

CUST ENDORSE: ALL

AREA: ALL STAGE: ALL

CTRL CODE :	TYPE CODE:	ORIGINATOR: ALL	

CIRL CODE:					TYPE CODE:	URIGINATUR :	ALL		0747110	
	ZONE	STG							STATUS	UPDATED DAT
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
JL3185	200	NRR	PT	2500	777-53-908-00-01	M/D G2 G4 GALLEY CEILING SURFACE	E FOUND PAINT CHIP	L318	WIP	10/05/2023
	CAB									16.0
									-	16.0
JL3193	200	NRR	PT	2500	777-53-916-00-01	CABIN S1L S1R CLOSET UPPER EDGE	FND PAINT CHIPPED	L319	COMP	10/05/2023
	CAB									10.0
									-	10.0
JL3201	100	NRR	PT	5121	777-53-920-00-01	M/D G702 703 706 707 606 607 GALLE	OOOR FOUND PAINT PEEL TTL:6EA	L320	COMP	10/03/2023
	CAB									12.0
									-	12.0
JL3219	200	NRR	PT	2500	777-53-908-00-01	CABIN S2CL-11 S2CR-11CLOSET INTE	RIOR SURFACE FND PAINT CHIPPED	L321	WIP	09/30/2023
	CAB									4.0
									-	4.0
JL3227	200	NRR	Al	2524	777-53-908-00-01	CAB-FB2 SEAT BACK SHELL BOTTLE	CONSOLE HORIZONTAL TRIM FOUND CRACKED AT 21G.	L322	COMP	09/30/2023
	CAB									1.0
									-	1.0
JL3235	200	NRR	Al	2524	777-53-908-00-01	CABIN FB2 SEAT OTTOMAN FOOT RE	ST PLASTIC COVER GAP SEAL FOUND MISSING AT 11A 16A 21A 11K 16K	L323	COMP	10/02/2023
	CAB							2020		15.0
									-	15.0
JL3243	200	NRR	SS	2524	777-53-908-00-01	CABIN FB2 SEAT SHELL BLACK FABR	IC FOUND WORN AT 21D 20D 18D 26D 19G 16K	L324	COMP	10/04/2023
0202.0	CAB				00 000 00 0.		0.00.00.00.00.00.00.00.00.00.00.00.00.0	L324	COME	0.0
						1C 1 REMOVAL SEAT BLAC	K FABRIC COVER			3.0
						1C 2 REPLACE SEAT BLAC	K FABRIC			30.0
						1C 3 PLS INSTALL BLACK F	ABRIC COVER			3.0
									-	36.0
JL3250	200	NRR	PT	2500	777-53-908-00-01	M/D D LAV WASTE BIN MARKING FND	PAINT CHIP	L325	WIP	09/29/2023
	CAB									1.0
									-	1.0
										1.0

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 48 OF 89

RUN DATE: 10/6/2023

RUN TIME : 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL

PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO:

ALL

ATA NO: ALL

ZONE: ALL AREA: ALL

DISPOSITION CODE: ALL

DEFECT TYPE: ALL

TRADE: ALL

CUST ENDORSE: ALL

STAGE: ALL

CTRL CODE :	TYPE CODE:	ORIGINATOR:	ALL		
ZONE STG				STATUS	UPDATED DATE

JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL S	SH NC	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL3268	200	NRR	Al	2524	777-53-908-00-01	CABIN	FB2 SI	EAT OTTOMAN AROUND NOMEX TRIM FOUND DAMAGE AT 26D 22G 19K 21K.	L326	COMP	09/30/2023
	CAB										10.0
											10.0
XJL3276	200	NRR	SS	2524	777-53-908-00-01			T BACK SHELL BOTTLE CONSOLE RED FABRIC TRIM FOUND DETACH 19D 11K 17K 12K 25A 18A 16K 22K	L327	COMP	10/04/2023
	CAB) 17G ′	2G 18G 21G 26G			0.0
							1	REMOVAL SEAT RED NOMEX COVER REINSTALL SEAT RED NOMEX			7.5 45.0
							3	PLS INSTALL RED NOMEX COVER			45.0 7.5
											60.0
XJL3284	200	NRR	Al	2524	777-53-908-00-01	CABIN	FB2 SI	EAT OTTOMAN FOOT REST CUSHION LEATHER FOUND WORN AT 12G	L328	COMP	09/30/2023
	CAB										3.0
											3.0
XJL3292	200	NRR	Al	2524	777-53-908-00-01	CAB-FI	B2 SEA	T BACK SHELL BOTTLE CONSOLE PLASTIC TRIM FOUND DETACHED AT 26K.	L329	COMP	10/02/2023
	CAB										0.5
											0.5
XJL3300	200	NRR	Al	2541	777-53-904-00-01	CABIN	ZONE	A LAV A FLOOR PAN EDGE TRIM FOUND DAMAGE	L330	COMP	10/02/2023
	CAB										2.0
											2.0
XJL3318	200	NRR	PT	2500	777-53-870-00-01	BULK (CGO S/	W PNLS SURFACE FND PAINT CHIPPED TTL:6EA	L331	COMP	09/28/2023
	LWR										18.0
											18.0
XJL3326	200	NRR	SS	2525	777-C252000-01-09-	EY PA	X SEAT	POCKET COVER FND DIRTY AT: 40H 65K 69H 67C 59C TTL: 5EA	L332	WIP	10/03/2023
	CAB				R-04						4.0
											4.0
XJL3334	200	NRR	SS	2525	777-C252000-01-09-	EY PA	X SEAT	POCKET COVER BUTTON FND LOOSEN AT: 41F 45E 59H 63K 71D 71A TTL: 6EA	L333	WIP	10/05/2023
	CAB				R-04						1.0
											1.0

0PPC DISTRIBUTION:

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

49 OF 89 PAGE: RUN DATE: 10/6/2023

RUN TIME : 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

> ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE : ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

				TYPE CODE:	ORIGINATOR:				
	STG								UPDATED DATE
									EST Mhr
	NRR	SS	25	777-C252000-01-06- R-02	CAB A ZONE SEAT OTTOMANS CUSHION	N FOUND TORN TTL:6EA	L334	WIP	10/03/2023
CAB									3.0
								-	3.0
	NRR	SS	25	777-C252000-01-09- R-04	CAB F ZONE EY SEAT ALL HEADREST T	TL 128EA FOUND DIRTY	L335	WIP	10/05/2023
CAB									8.0
								-	8.0
200	NRR	SS	25	777-C252000-01-09-	CAB E ZONE EY SEAT ALL HEADREST T	TL73EA FOUND DIRTY	L336	WIP	10/05/2023
CAB				R-04					4.0
								-	4.0
200	NRR	SS	25	777-C252000-01-09-	CAB F ZONE EY SEAT BOTTOM DRESS (COVER FOUND NOT MATCH TTL:28EA	L337	COMP	10/03/2023
CAB				R-04					14.0
								-	14.0
200	NRR	SS	25	777-C252000-01-09-	CAB E ZONE EY SEAT BOTTOM DRESS (COVER FOUND NOT MATCH TTL:13EA	L338	WIP	10/03/2023
CAB				R-04					6.5
								-	6.5
200	NRR	SS	2525	777-C252440-04-02-	EY PAX SEAT BACKREST TABLE FND DI	RTY AT:40H 41K 45H 62D 69D 60B 71B TTL:7EA	L339	COMP	10/04/2023
CAB				01					4.0
								-	4.0
600	NRR	GW	5700	777-57-948-02-01	RHW T/E ACCESS PANEL 652LB (3EA) So	CREW FOUND SEIZED	L340	COMP	09/26/2023
WNG									3.0
								-	3.0
600	NRR	SM	5700	777-57-948-02-01	RHW T/E ACCESS PANEL 652LB (3EA) AI	NCHOR NUT	I 341	COMP	10/02/2023
WNG					, ,		20	00	1.5
								-	1.5
500	NRR	GW	5700	777-12-008-00-01	LHW L/E ACCESS PANEL 511FB (1FFA 5	11GB(1EA) 511KB(2EA) 511PB(10EA) SCREW FOUND SEIZED	1342	COMP	09/26/2023
WNG			00			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	LU4Z	OOME	14.0
								-	14.0
	200 CAB 200 CAB 200 CAB 200 CAB 200 CAB 200 CAB 600 WNG 600 WNG 500	200 NRR CAB NRR WNG NRR WNG NRR	AREA TD 200 NRR SS CAB NRR SW WNG NRR SM	AREA TD ATA 200 CAB NRR SS 25 200 CAB NRR SS 2525 CAB NRR GW 5700 600 WNG NRR SM 5700 500 NRR GW 5700	AREA TD ATA ORIG CUST REF NO. 200 NRR SS 25 7777-C252000-01-06- R-02 200 NRR SS 25 7777-C252000-01-09- R-04 600 NRR SS 2525 7777-C252440-04-02- 01 600 NRR SM 5700 7777-57-948-02-01 WNG 500 NRR GW 5700 7777-12-008-00-01	AREA TD ATA ORIG CUST REF NO. CTRL SH NO 200 NRR SS 25 777-C252000-01-06-R-02 CAB A ZONE SEAT OTTOMANS CUSHION CAB 200 NRR SS 25 7777-C252000-01-09-R-04 CAB F ZONE EY SEAT ALL HEADREST TOMANS CUSHION CAB 200 NRR SS 25 7777-C252000-01-09-R-04 CAB E ZONE EY SEAT ALL HEADREST TOMANS CUSHION CAB 200 NRR SS 25 7777-C252000-01-09-R-04 CAB E ZONE EY SEAT BOTTOM DRESS OF CAB 200 NRR SS 25 7777-C252000-01-09-R-04 CAB E ZONE EY SEAT BOTTOM DRESS OF CAB 200 NRR SS 2525 7777-C252000-01-09-R-04 EY PAX SEAT BACKREST TABLE FND DITE 200 NRR SS 2525 7777-C252440-04-02-DT EY PAX SEAT BACKREST TABLE FND DITE 600 NRR GW 5700 777-57-948-02-01 RHW T/E ACCESS PANEL 652LB (3EA) ALL HEADREST TOWARD AND ADDRESS OF CAB 500 NRR GW 5700 777-12-008-00-01 LHW LIE ACCESS PANEL 511FB (1EEA 5	AREA TD ATA ORIG CUST REF NO. CTRL SH NO DEFECT DESCRIPTION 200 CAB NRR SS 25 777-C252000-01-06- R-02 CAB A ZONE SEAT OTTOMANS CUSHION FOUND TORN TILGEA 200 CAB NRR SS 25 777-C252000-01-09- R-04 CAB F ZONE EY SEAT ALL HEADREST TIL 128EA FOUND DIRTY 200 CAB NRR SS 25 777-C252000-01-09- R-04 CAB E ZONE EY SEAT ALL HEADREST TIL 128EA FOUND DIRTY 200 CAB NRR SS 25 777-C252000-01-09- R-04 CAB E ZONE EY SEAT BOTTOM DRESS COVER FOUND NOT MATCH TIL 128EA 200 CAB NRR SS 25 777-C252000-01-09- R-04 CAB E ZONE EY SEAT BOTTOM DRESS COVER FOUND NOT MATCH TIL 13EA 200 CAB NRR SS 25 777-C252040-01-09- R-04 EY PAX SEAT BACKREST TABLE FND DIRTY AT-40H 41K 45H 62D 69D 60B 71B TIL 7EA 200 CAB NRR SS 5700 777-57-948-02-01 R-HW TIE ACCESS PANEL 652LB (3EA) SCREW FOUND SEIZED 600 WNG NRR SM 6700 777-57-948-02-01 R-HW TIE ACCESS PANEL 652LB (3EA) ANCHOR NUT 500 NRR S700 777-12-008-00-01 LIHW LI	AREA TD ATA ORIG CUST REF NO. CTRL SH NO DEFECT DESCRIPTION JSN 200 CAB NRR SS 25 777-C252000-01-06- R-Q4 CAB A ZONE SEAT OTTOMANS CUSHION FOUND TORN TITLEEA 1334 200 CAB NRR SS 25 777-C252000-01-09- R-Q4 CAB F ZONE EY SEAT ALL HEADREST TITL 128EA FOUND DIRTY 1336 200 CAB NRR SS 25 777-C252000-01-09- R-Q4 CAB E ZONE EY SEAT ALL HEADREST TITL 73EA FOUND DIRTY 1336 200 	AREA TD ATA ORIG CUST REF NO. CTRL SH NO DEFECT DESCRIPTION JSN STATUS 200 CAB NRR SS 25 777-C252000-01-08- R-02 CABA ZONE SEAT OLITOMANS CUSHION FOUND TORN ITILEEA 1334 WIP 200 CAB NRR SS 25 777-C252000-01-09- R-04 CAB F ZONE EY SEAT ALL HEADREST ITIL 128EA FOUND DIRTY 1336 WIP 200 CAB NRR SS 25 777-C252000-01-09- R-04 CAB E ZONE EY SEAT ALL HEADREST ITIL 128EA FOUND DIRTY 1336 WIP 200 CAB NRR SS 25 777-C252000-01-09- R-04 CAB E ZONE EY SEAT BOTTOM DRESS COVER FOUND NOT MATCH ITIL-128EA 1338 WIP 200 CAB NRR SS 25 777-C252000-01-09- R-04 CAB E ZONE EY SEAT BOTTOM DRESS COVER FOUND NOT MATCH ITIL-128EA 1338 WIP 200 CAB NRR SS 252 777-C252000-01-09- R-04 EY PAX SEAT BACKREST TABLE FND DIRTY AT-40H 41K 49H 620 680 688 71B TIL/EA 1340 COMP 600 CAB NRR SW 5700 777-57-948-02-01 RHW TIE ACCESS PANEL 652LB (3EA) SCREW FOUND SEIZED 1

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 50 OF 89

RUN DATE: 10/6/2023

RUN TIME : 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL

PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO:

ALL

ATA NO: ALL

ZONE: ALL

DISPOSITION CODE: ALL

DEFECT TYPE: ALL CTRL CODE:

TRADE: ALL TYPE CODE:

CUST ENDORSE: ALL ORIGINATOR: ALL

AREA: ALL

STAGE: ALL

STATUS	UPDATED DATE

	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL3433	500	NRR	SM	5700	777-12-008-00-01	LHW L/E ACCESS PANEL 511FB	(1EEA 511GB(1EA) 511KB(2EA) 511PB(10EA) ANCHOR NUT FOUND WORN	L343	COMP	10/02/2023
	WNG									7.0
										7.0
XJL3441	500	NRR	AE	5700	777-12-008-00-01	LHW L/E ACCESS PANEL 511FB	GB CB SCREW FOUND WORN	L344	OPEN	09/22/2023
	WNG									1.0
										1.0
XJL3458	200	NRR	AV	2525	777-24-001-00-01	PERFORM BC SEAT ELECTRICA	AL OPERATION TEST FOUND 23D SEAT INOP	L345	WIP	10/01/2023
	CAB							20.0		3.0
										3.0
XJL3466	600	NRR	AE	5700	777-12-008-00-04	RHW L/E ACCESS PANEL 621 AC	CB BB GB MB WB ZB QB RB AFB SCREWS FOUND WORN	L346	OPEN	09/22/2023
7,020 100	WNG	14141	,,_	0,00	777 12 000 00 01	NIW EL NOOLOGI MALE 021 MC	SO DO SO NO VO ZO QUI NO VI DI SONE MONTO	L340	OPEN	1.0
V II 2474	500	NRR	ΑE	5700	777-57-856-01-01	LUM TIE ACCECC DANEL FEOLID	LOD LD CODEWO FOLIND WORK			1.0
XJL3474	WNG	NKK	AE	5700	777-57-856-01-01	LHW T/E ACCESS PANEL 552HB	CB LB SCREWS FOUND WORN	L347	OPEN	09/22/2023
										1.0
										1.0
XJL3482	500 WNG	NRR	AE	5700	777-57-856-01-01	PERFORM LHW T/E REAR SPAR	R CIC AFTER CLEANING	L348	WIP	10/05/2023
	WING									4.0
									•	4.0
XJL3490	500	NRR	AE	5700	777-57-948-02-01	PERFORM RHW T/E REAR SPAR	R CIC AFTER CLEANING	L349	WIP	10/05/2023
	WNG									4.0
										4.0

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 51 OF 89

RUN DATE: 10/6/2023

10/0/2020

RUN TIME : 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE : TYPE CODE: ORIGINATOR : ALL

STAL CODE.					TIFE CODE.			ONGINATOR. ALL		OTATUO	LIDDATED DAT
	ZONE	STG								STATUS	UPDATED DAT
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRI	L SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
KJL3508	200	NRP	AV	3351	777-33-115-00-02			ALL EMERGENCY LIGHT POWER SUPPLY ELECTRICAL CONNECTORS DURING AIRCRAFT POWER OFF	L350	WIP	09/23/2023
	CAB					PERI	IOD TO PR	EVENT BATTERY FAILURE.			0.0
						1C	1	LOWER DOWN ALL OVERDOOR PANELS.			2.0
						1C	2	REMOVE OFAR LH AFT MIRROR PANEL ASSY AND A PANEL IN THE RIGHT WALL OF THE AFT CLOSET .			1.0
						1C	3	REMOVE OFCR ENTRY MODULE A SUPPORT PANEL UNDER THE SECOND STEP AND ANOTHER SUPPORT PANEL ABOVE SEAT 2D			1.0
						1C	4	DISCONNECT ALL OVERDOOR EMERGENCY LIGHT POWER SUPPLY UNIT ELECTRICAL CONNECTORS.			5.0
						2C	5	RECONNECT ALL EMERGENCY LIGHT POWER SUPPLY UNIT ELECTRICAL CONNECTORS			5.0
						2C	6	DISCONNECT OFAR EMERGENCY LIGHT POWER SUPPLY ELECTRICAL CONNECTORS			1.0
						2C	7	DISCONNECT OFCR EMERGENCY LIGHT POWER SUPPLY ELECTRICAL CONNECTORS			1.0
						2C	8	RECONNECT OFAR EMERGENCY LIGHT POWER SUPPLY ELECTRICAL CONNECTORS			1.0
						3C	9	REINSTALL OFAR LH AFT MIRROR PANEL ASSY AND A PANEL IN THE RIGHT WALL OF THE AFT CLOSET			1.0
						3C	10	RECONNECT OFCR EMERGENCY LIGHT POWER SUPPLY ELECTRICAL CONNECTORS			1.0
						3C	11	REINSTALL OFCR ENTRY MODULE A SUPPORT PANEL UNDER THE SECOND STEP AND ANOTHER SUPPORT PANEL ABOVE SEAT 2D			1.0
						3C	12	REINSTALL ALL OVERDOOR PANELS.			2.0
						4C	13	CARRY OUT EMERGENCY LIGHT POWER SUPPLY UNIT INSTALLATION TEST			3.0
										-	25.0
JL3516	200	NRR	ΑI	25	777-53-920-00-01	OFA	R FWD CL	OET LOWER DRAWER UPPER EDGE TRIM FOUND DISBOND	L351	COMP	10/02/2023
	CAB										3.0
										-	3.0
JL3524	200	NRP	SS	25	777-25-060-01-CX-01	C/A	SEAT PAN	VELCRO TAPE COVER FOUND BROKEN AT L1AFT	L352	WIP	10/04/2023
	CAB								LUUZ	VVII	2.0
										_	2.0
											2.0
JL3532	200	NRP	SS	25	777-25-060-01-CX-01	C/A	SEAT COV	/ER FOUND DIRTY AT R1 R2FWD L2AFT L4 R5I/B L5I/B O/B TTL7EA	L353	OPEN	09/23/2023
	CAB										3.0
										-	3.0
JL3540	200	NRP	SS	25	777-25-060-01-CX-01	C/A	SEATION	VER BACKRES SCREW NUT SPRING FOUND MISSING L1FWD	L354	WIP	10/05/2023
0200.0	CAB				20 000 01 07(01	Ont	OD (1 LOV	TELEVISION LES GOVERNO LA VIII O L'ANNO L'OURING EN VID	L334	VVII	
										-	1.0
0557	400	NDE		0500	777 50 000 00 04						1.0
JL3557	100	NRR	Al	2500	777-53-822-00-01	FWD	CGO LH	STA540 SIDE GUIDE RAIL JOINT PLATE FND BROKEN. TTL2EA	L355	OPEN	09/23/2023
	LWR										2.0
										-	2.0

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: RUN DATE: 10/6/2023

52 OF 89

RUN TIME : 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

> ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

TRADE: ALL DEFECT TYPE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

CIRL CODE :					TYPE CODE:	ORIGINATOR: ALL				
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL3565	100	NRR	Al	2500	777-53-822-00-01	FWD CGO HANDLING SYSTEM PDU ROLLER FN	ID WORN AT 6R 7R 17R & 20R.	L356	OPEN	09/23/2023
	LWR									4.0
										4.0
XJL3573	100	NRR	Al	2500	777-53-822-00-01	FWD CGO THE LAST CENTER GUIDE RED LEAF	FND STIFF.	L357	WIP	10/03/2023
	LWR									0.5
										0.5
XJL3581	100	NRR	Al	2500	777-53-812-00-01	MEC INSULATION BLANKET FOUND BROKEN		L358	COMP	10/03/2023
	LWR							2000		6.0
										6.0
XJL3599	300	NRP	AE	5535	777-55-806-00-01	EMPREMOVE VERTICAL FIN L/E PANEL 321E FO	DR ACCESS	L359	WIP	0.0
7.020000	EMP	1414	,,_	0000	777 00 000 00 01	LIVITALINOVE VERTICALITATE IN THE TANKE OF THE	N/NOCCO.	L339	VVIP	0.0
						1C 1 REMOVE VERTICAL FIN 321E AG	CCESS EVIDIVIC EOD VCCESS			2.0
							DMMUNICATION ANTENNA FEEDLINE CONNECTION ATTACH BOLT			0.5
						1C 3 REINSTALL THE L/E FRG 321E	DIVINIONICATION ANTENNAT ELDLINE CONNECTION ATTACT BOLT			4.0
							ION ANTENNA FEED LINES CONNECTOR			1.0
							TWEEN HF ANTENNA AND THE STRUCTURE			0.5
						2C 6 CARRY OUT HF SYSTEM TEST	TWEENTH /WILLWW//WO THE OTTOOTORE			0.5
						20 0 Outline Colemn 1201				
XJL3607	200	NRR	Al	25	777-53-920-00-01	L5.L4.R4 DOOR BUSTLE EDGE TRIM FOUND TO	DN		00115	8.5
AJL3007	CAB	INIXIX	AI	25	777-55-920-00-01	L3.L4.R4 DOOR BUSTLE EDGE TRIM FOUND TO	riv.	L360	COMP	10/02/2023
										6.0
										6.0
XJL3615	100 LWR	NRR	SM	5300	777-53-874-00-01	BULK CGO FLOOR PANEL ANCHOR NUT FOUNI	D DAMAGED.TOTAL 4EA	L361	COMP	10/03/2023
	LVVIX									4.0
										4.0
XJL3623	100	NRR	Al	2500	777-53-854-00-01	AFT CGO SIDEWALL FOUND WORN		L362	OPEN	09/23/2023
	LWR									4.0
										4.0
XJL3631	200	NRR	Al	56	777-53-904-00-01	M/D R1 DOOR WINDOW INSIDE FOUND DIRTY		L363	COMP	09/25/2023
	CAB									5.0
										5.0
										3.0

ORIGINATING CUST REF NO:

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 53 OF 89

RUN DATE: 10/6/2023

1.0

RUN TIME : 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

> ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

515653

BMS571R1-2

ALL

DEI LOT TIT					TIVIDE : ALI	COOT ENDONOE: NEE	AUCEAL ACE	OTAGE: ALL		
CTRL CODE :					TYPE CODE:	ORIGINATOR: ALL			CTATUC	LIDDATED DATE
100 110	ZONE	STG			ODIO OLIOT DEE NO	OTPL CLING	DEFECT DECORPTION	1011	STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL3649	200 CAB	NRR	Al	56	777-53-904-00-01	M/D L1 DOOR WINDOW INSIDE FOUND DIRTY		L364	COMP	09/25/2023
	CAB									5.0
										5.0
XJL3656	200	NRR	Al	56	777-53-908-00-01	M/D L2 DOOR WINDOW INSIDE FOUND DIRTY		L365	COMP	09/25/2023
	CAB									5.0
										5.0
XJL3664	200	NRR	Al	56	777-53-908-00-01	M/D R2 DOOR WINDOW INSIDE FOUND DIRTY		L366	COMP	09/25/2023
	CAB							2000	00	5.0
KJL3672	700	NRP	CL	22	777-900002-01-1-01	NOSE LANDING GEAR W/W AREA FND DIRTY.		1007	\4/15	5.0
NJL3072	LDG	INIXE	CL	32	777-900002-01-1-01	NOSE LANDING GEAR W/W AREA FIND DIKTY.		L367	WIP	09/24/2023
						1C 1 CLEAN THE AREA.				0.0 12.0
						1C 2 APPLY CIC.				6.0
										18.0
XJL3680	700	NRP	CL	32	777-900002-01-1-01	RH MLG W/W AREA FND DIRTY		L368	WIP	09/24/2023
	LDG									0.0
						1C 1 CLEAN THE AREA .				24.0
						1C 2 APPLY CIC.				10.0
										34.0
XJL3698	700	NRP	CL	32	777-900002-01-1-01	LH MLG W/W AREA FND DIRTY.		L369	WIP	09/24/2023
	LDG									0.0
						1C 1 CLEAN THE AREA.				24.0
						1C 2 APPLY CIC.				10.0
										34.0
(JL3706	200	NRR	SS	25	777-25-040-03-CX-01 -01	FB2 SEAT AIRBAG INFLATABLE FND EXPIRY DATE AT TTL:14EA	:15A 26D 25D 24D 23D 22D 21D 20D 19D 18D 17D 16D 12D	I1D L370	WIP	10/01/2023
	CAB				•					21.0
										21.0
KJL3714	200	NRR	SS	25	777-C252440-04-02-	EY PAX SEAT COAT HOOK FND LOOSEN AT:63E		L371	WIP	10/05/2023
	CAB				01					1.0
										1.0

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 54 OF 89

RUN DATE: 10/6/2023

RUN TIME : 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

STATUS: ALL

ORIG-STAGE: ALL

PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO:

ALL

ATA NO: ALL

ZONE: ALL ΔΡΕΔ · ΔΙΙ

DISPOSITION CODE: ALL

515653

BMS571R1-2

STAGE: ALL

DEFECT TYPE: ALL	TRADE: ALL	CUST ENDORSE: ALL	AREA: ALL
CTRL CODE :	TYPE CODE:	ORIGINATOR: ALL	

JIRL CODE :					TYPE CODE:	URIGINATUR: ALL				
	ZONE	STG							STATUS	UPDATED DAT
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
JL3722	200	NRR	SS	25	777-C252440-04-02- 01	EY PAX SEAT COAT HOOK FND MISSING AT:59	Н	L372	WIP	10/06/2023
	CAB				01					1.0
									-	1.0
JL3730	200	NRR	SS	25	777-C252440-04-02- 01		PRING FND LOOSEN AT:61A 62A 64A.B 66A 67A 68A 69A 71A 65J 62F 63D	L373	WIP	10/05/2023
	CAB				O I	64G 65E 65F 66F 67G 69E.G 71E.G 59A 60A.B TT	L:Z4EA			8.0
									-	8.0
JL3748	200	NRR	SS	25	777-C252440-04-02-		PRING FND LOOSEN AT:42K 44J 45H 39F 40D 41D 41G 42D.E.F 43F 44D	L374	WIP	10/05/2023
	CAB				01	42B 43A TTL:14EA				4.0
									-	4.0
JL3755	200	NRR	SS	25	777-C252410-01-01-	F/C SEAT RECLINE CABLE FOUND LOOSEN AT	1D	L375	OPEN	09/23/2023
	CAB				01					1.0
									-	1.0
JL3763	200	NRP	SS	25	777-25-060-01-CX-01	C/A SEAT PAN SPRING FOUND LOOSEN AT L50	D/B	L376	WIP	10/05/2023
	CAB									1.0
									-	1.0
JL3771	200	NRR	SS	25	777-25-040-03-CX-01	FB2 SEAT AIRBAG INFLATOR FND EXPIRY DAT	E AT:11G 12G 16G 17G 18G 19G 20G 21G 22G 23G 24G 26G TTL:12EA	L377	WIP	10/01/2023
	CAB				-01					18.0
									-	18.0
JL3789	200	NRR	SS	25	777-25-040-03-CX-01	FB2 SEAT AIRBAG INFLATOR FND EXPIRY DAT	E AT:11K 12K 16K 17K 18K 19K 20K 21K 22K 23K 24K 25K TTL:12EA	L378	WIP	10/01/2023
	CAB				-01					18.0
									-	18.0
JL3797	500	NRR	GW	5700	777-57-856-01-01	LHW T/E ACCESS PANEL 552BB(3EA) CB(3EA) I	B(3EA) SCREW FOUND SEIZED	L379	COMP	09/26/2023
	WNG									9.0
									-	9.0
JL3805	500	NRR	SM	5700	777-57-856-01-01	LHW T/E ACCESS PANEL 552BB(3EA) CB(3EA) I	B(3EA) ANCHOR NUT FOUND WORN	L380	COMP	10/02/2023
	WNG									6.0
									-	6.0

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 55 OF 89 RUN DATE: 10/6/2023

RUN TIME: 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

					TYPE CODE:	URIGINATUR: ALI				
	ZONE	STG							STATUS	UPDATED DATE
IOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
JL3813	200	NRR	SS	25	777-C252410-01-01- 01	F/C SEAT RECLINE CABLE FOUND LOOSEN	AT 1D	L381	WIP	10/05/2023
	CAB				O1					2.0
									-	2.0
JL3821	200	NRR	Al	2531	777-53-904-00-01	CABIN ZONE A G1 GALLERY OVEN1&3 WATE	R HOSE FOUND LEAK	L382	WIP	10/05/2023
	CAB									3.0
									-	3.0
JL3839	200	NRR	Al	2533	777-C250009-01-01- R-01	GALLEY 1L CHILLER TEMPERATURE OUT OF	LIMIT	L383	WIP	09/29/2023
	CAB				K-01					0.0
									-	0.0
JL3847	200	NRR	Al	2531	777-53-904-00-01	CABIN ZONE A G5 GALLERY OVEN 2 WATER	HOSE FOUND LEAK	L384	COMP	10/03/2023
	CAB									3.0
									-	3.0
JL3854	200	NRR	ΑI	2533	777-C250009-01-01-	GALLEY 4R CHILLER MALFUNCTION		L385	OPEN	09/24/2023
	CAB				R-01					0.0
									-	0.0
JL3862	200	NRR	Al	2531	777-53-904-00-01	CABIN ZONE A G7 GALLERY OVEN 2&3; GAL	ERY G6 OVEN 1&4 WATER HOSE FOUND LEAK	L386	OPEN	09/24/2023
	CAB									3.0
									-	3.0
JL3870	200	NRR	Al	2531	777-53-908-00-01	CABIN G3 GALLERY OVEN LOWER BUMPER	FOUND DAMAGE	L387	WIP	10/03/2023
	CAB									5.0
									-	5.0
JL3888	200	NRR	Al	2500	777-53-900-00-01	COCKPIT LH RAIN COAT CLOSET INSIDE CA	TCH FOUND DAMAGE	L388	COMP	10/02/2023
	CAB									1.0
									-	1.0
JL3896	200	NRR	AV	3327	777-C330000-01-02- 01	GALLEY 2&3 LOWER CEILING PANEL L/H AFT	AREA LIGHT MALFUNCTION	L389	WIP	10/03/2023
	CAB				UI					2.0
									-	2.0

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 56 OF 89 RUN DATE: 10/6/2023

RUN TIME: 14:22

7.0

PROJECT: XJ

515653

BMS571R1-2

CUSTOMER: CX

A/C TYPE: 777

A/C REGN: B-KPV

CHECK TYPE: 2C

ESTIMATED MHR: ALL

JSN RANGE SELECTED : ALL
ORIGINATING CUST REF NO: ALL

LL STATUS: ALL

ALL ORIG-STAGE : ALL ATA NO : ALL PERIOD: ALL ZONE: ALL AREA: ALL

DISPOSITION CODE: ALL

STAGE: ALL

DEFECT TYPE: ALL

CTRL CODE:

ALL TRADE : ALL

ALL CUST ENDORSE : ALL

TYPE CODE: ORIGINATOR: ALL

	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL3904	200	NRR	AV	3327	777-C330000-01-02-	GALLEY 4&5 LOWER CEILING PANEL R/H FWD AREA	IGHT MALFUNCTION	L390	OPEN	09/24/2023
	CAB				01					2.0
									-	2.0
XJL3912	500	NRR	GW	5700	777-12-008-00-03	LHW L/E ACCESS PANEL 521ZB(2EA) UB(2EA) TB(2EA) QB(3EA) MB(1EA) FB(1EA) SCREWS FOUND SEIZED	L391	COMP	09/28/2023
	WNG									11.0
									-	11.0
XJL3920	500	NRR	SM	5700	777-12-008-00-03	LHW L/E ACCESS PANEL 521ZB(2EA) UB(2EA) TB(2EA	QB(3EA) MB(1EA) FB(1EA) ANCHOR NUT FOUND WORN	L392	COMP	10/02/2023
	WNG					. , , , ,		2002		6.0
									-	6.0
XJL3938	200	NRP	AV	2532	777-C250008-01-01-	G6 OVEN 2 CONTROL PANEL ON/OFF BUTTOM MALF	INCITON	L393	WIP	10/02/2023
7.020000	CAB	1414	,	2002	01	SO SVENZ SONTINGET AND SONT BOTTOM WINDER	3,011011	L393	VVIE	1.5
									-	
V II 2046	500	NRR	GW	5708	777 57 964 04 04	LUMETE ACCECC DANIELECAL DIGETA CODEINO FOLINI	0.051750			1.5
XJL3946	WNG	INFXFX	GW	5706	777-57-864-01-01	LHW T/E ACCESS PANEL561LB(2EEA SCREWS FOUN	J SEIZEU	L394	COMP	09/26/2023
									_	2.0
										2.0
XJL3953	500 WNG	NRR	SM	5708	777-57-864-01-01	LHW T/E ACCESS PANEL561LB(2EA) ANCHOR NUT FO	JUND WORN	L395	COMP	10/02/2023
	WING								_	1.0
										1.0
XJL3961	100	NRR	CL	2500	777-53-818-00-01	FWD CARGO CEILING PANEL SURFACE FND DIRTY		L396	WIP	10/02/2023
	LWR									7.0
									-	7.0
XJL3979	100	NRR	CL	2500	777-53-818-00-01	FWD CARGO SIDEWALL PANEL SURFACE FND DIRTY		L397	WIP	10/02/2023
	LWR									7.0
									-	7.0
XJL3987	100	NRR	CL	2500	777-53-854-00-01	AFT CARGO CEILING PANEL SURFACE FND DIRTY		L398	COMP	10/05/2023
	LWR									7.0
									-	

0PPC DISTRIBUTION:

REFERENCE NO: BMS571R1-2

ORIGINATING CUST REF NO: ALL

515653

REQUESTED BY:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

57 OF 89 PAGE:

RUN DATE: 10/6/2023

RUN TIME : 14:22

	PROJECT: XJ	CUSTOMER: CX	A/C TYPE: 777	A/C REGN: B-KPV	CHECK TYPE :	2C
--	-------------	--------------	---------------	-----------------	--------------	----

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

> ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

CIRL CODE :					TYPE CODE:	ORIGINATOR: ALL				
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL3995	100	NRR	CL	2500	777-53-854-00-01	AFT CARGO SIDEWALL PANEL SURFACE FND	DIRTY	L399	WIP	10/02/2023
	LWR									7.0
									-	7.0
XJL4001	100	NRR	CL	2500	777-53-870-00-01	BULK CARGO COMP CEILING AND SIDEWALL F	ANEL FND DIRTY	L400	WIP	10/05/2023
	LWR									5.0
									-	5.0
XJL4019	100	NRR	CL	2500	777-53-862-00-01	AFT CARGO AND BULK CGO FLOOR PANEL FN	D DIRTY	L401	OPEN	09/24/2023
	LWR									10.0
									-	10.0
XJL4027	100	NRR	CL	2500	777-53-862-00-01	AFT CARGO ROLLER TRAY FND DIRTY		L402	COMP	10/05/2023
	LWR									16.0
									-	16.0
XJL4035	100	NRR	CL	2500	777-53-822-00-01	FWD CARGO FLOOR PANEL SURFACE FND DII	RTY	L403	OPEN	09/24/2023
	LWR									7.0
									-	7.0
XJL4043	100	NRR	CL	2500	777-53-822-00-01	FWD CARGO ROLLER TRAY FND DIRTY		L404	WIP	09/28/2023
	LWR									16.0
									-	16.0
XJL4050	200	NRR	Al	2541	777-53-908-00-01	CABIN LAV A C D F TOILET SHROUD ANTICOLL	ISION PLATE FOUND MISSING	L405	WIP	10/03/2023
	CAB									4.0
									-	4.0
XJL4068	200	NRR	Al	2541	777-53-908-00-01	CABIN LAV M L H TOILET SHROUD ANTICOLLIS	ION PLATE FOUND MISSING	L406	COMP	10/03/2023
	CAB									3.0
									-	3.0
XJL4076	200	NRR	Al	2541	777-53-908-00-01	CABIN LAV M TOILET SHROUD SEAT COVER D	AMPER COVER FOUND CRACKED	L407	COMP	10/02/2023
	CAB							2.01	30	3.0
									-	3.0
										3.0

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 58 OF 89 RUN DATE: 10/6/2023

RUN TIME :

14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL ALL DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE :					TYPE CODE:			ORIGINATOR:	A	ALL			
	ZONE	STG										STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL	SH NO			DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL4084	500	NRR	SS	5700	777-20-251-10-01	LHW	L/E ACCI	ESS PANEL511AB EXTE	ERNA	NAL SURFACE FOUND DELAMINATION	L408	WIP	09/25/2023
	WNG												0.0
						1C	1	DO AN INSPECTION T	TO FI	FIND THE DAMAGE DIMENSION			1.0
						1C	2	DO THE REPAIR TO D					20.0
						1C	3	DO THE POST REPAIR	IR INS	NSPECTION			1.0
						1C	4	APPLY RESIN AND SM	OOM8	OTH OUT			2.0
						2C	5	APPLY CONDUCTIVE	E COA	DATING			0.5
						2C	6	MEASURE THE RESIS	ISTIVI	VITY OF CONDUCTIVE COATING			0.5
						2C	7	RESTORE SURFACE	FINIS	NISH			0.5
						2C	8	FILL IN THE SDR FOR	RM				0.0
												-	25.5
XJL4092	500	NRR	SS	5700	777-20-251-10-01	RHW	L/E ACC	ESS PANEL611GB EXTE	TERNA	NAL SURFACE FOUND DELAMINATION	L409	WIP	09/25/2023
	WNG												0.0
						1C	1	DO AN INSPECTION T	TO FI	FIND THE DAMAGE DIMENSION			1.0
						1C	2	DO THE REPAIR TO D					20.0
						1C	3	DO THE POST REPAIR					1.0
						1C	4	APPLY RESIN AND SM					2.0
						2C	5	APPLY CONDUCTIVE					0.5
						2C	6			VITY OF CONDUCTIVE COATING			0.5
						2C	7	RESTORE SURFACE					0.5
						2C	8	FILL IN THE SDR FOR	RM				0.0
												-	25.5
XJL4100	500	NRR	SS	5700	777-20-251-10-01	RHW	L/E ACC	ESS PANEL611KB EXTE	ERNA	NAL SURFACE FOUND DELAMINATION	L410	WIP	09/25/2023
	WNG												0.0
						1C	1	DO AN INSPECTION T	TO FI	FIND THE DAMAGE DIMENSION			1.0
						1C	2	DO THE REPAIR TO D	DAMA	MAGED AREA			20.0
						1C	3	DO THE POST REPAIR	IR INS	NSPECTION			1.0
						1C	4	APPLY RESIN AND SM	SMOO	OTH OUT			2.0
						2C	5	APPLY CONDUCTIVE	E COA	DATING			0.5
						2C	6	MEASURE THE RESIS	ISTIVI	VITY OF CONDUCTIVE COATING			0.5
						2C	7	RESTORE SURFACE	FINIS	NISH			0.5
						2C	8	FILL IN THE SDR FOR	RM				0.0
												-	25.5

0PPC DISTRIBUTION:

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

59 OF 89 PAGE: RUN DATE: 10/6/2023

RUN TIME : 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

> ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

TRADE: ALL DEFECT TYPE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

CIRL CODE:					TYPE CODE:	URIGINATUR: AL	L			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL4118	200	NRR	AV	2525	777-24-001-00-01	PC POWER TEST FOUND 31E PC OULET RE	DLIGHT	L411	OPEN	09/24/2023
	CAB									2.0
									-	2.0
XJL4126	300	NRP	AV	2361	777-55-806-00-01	VERTICAL FIN FWD #1 STATIC DISCHARGER	R BROKEN.	L412	OPEN	09/24/2023
	EMP									2.0
									-	2.0
XJL4134	200	NRM	Al	2560	AEO-29097-01	CABIN PASSENGER LIFE VEST FOUND EXP	RED DAY LESS THAN 4.5 MONTHS 154EA	L413	WIP	09/28/2023
	CAB									7.5
									-	7.5
XJL4142	200	NRM	Al	2560	AEO-29097-01	CABIN SPARE LIFE VEST FOUND EXPIRED I	DAY LESS THAN 4.5 MONTHS 3EA IN 70AC	L414	WIP	09/26/2023
	CAB									1.0
									-	1.0
XJL4159	200	NRM	Al	2560	AEO-29097-01	CABIN SPARE LIFE VEST FOUND EXPIRED I	DAY LESS THAN 4.5 MONTHS 1EA IN 70HK	L415	WIP	09/28/2023
	CAB									1.0
									-	1.0
XJL4167	200	NRM	Al	2560	AEO-29097-01	CABIN SPARE INFANT LIFE VEST FOUND EX	PIRED DAY LESS THAN 4.5 MONTHS 11EA IN 70AC	L416	WIP	09/28/2023
	CAB									1.0
									-	1.0
XJL4175	600	NRR	AV	2361	777-57-958-02-01	RH WING TIP 1 EA STATIC DISCHARGER BR	OKEN.	L417	OPEN	09/24/2023
	WNG							2417	OI LIV	2.0
									-	2.0
XJL4183	300	NRR	AV	2361	777-55-830-01-01	LEFT STAB TIP 1EA STATIC DISCHARGER B	ROKEN	L418	OPEN	09/24/2023
7621100	EMP	14141	,	2001	777 00 000 01 01		NO.E.I.	L410	OPEN	2.0
									-	
V II 4404	200	NRR	۸۱/	2264	777 55 950 02 04	DIOLIT CTAD TID 4EA CTATIO DIOCUADOED	PROVEN			2.0
XJL4191	300 EMP	INKK	AV	2361	777-55-850-02-01	RIGHT STAB. TIP 1EA STATIC DISCHARGER	DROKEN.	L419	OPEN	09/24/2023
									-	2.0
										2.0

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

ALL

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 60 OF 89 RUN DATE: 10/6/2023

RUN TIME :

14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL

ORIG-STAGE: ALL PERIOD: ALL

ZONE: ALL

AREA: ALL

ATA NO: ALL

CUST ENDORSE: ALL

DISPOSITION CODE: ALL STAGE: ALL

ESTIMATED MHR: ALL

DEFECT TYPE: ALL

ORIGINATING CUST REF NO:

TYPE CODE ODICINATOR

CTDL CODE

TRADE: ALL

CTRL CODE :					TYPE CODE:	ORIGINATOR:	ALL			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL4209	100	NRP	ΑE	0711	777-900002-01-1-01	FUS-PERFORM THE A/C SPECIAL JA		L420	COMP	10/05/2023
	FUS					REF TO XMN TASK CARD: TA0700010	11-BOE			0.0
									-	0.0
XJL4217	200	NRR	AV	2525	777-25-040-03-CX-01	FB2 BC SEAT COMPLIANCE CHECK	OF EMA FOUND 56EA EMA EXPIRY DATE OUT OF LIMIT	L421	OPEN	09/24/2023
	CAB				-01					112.0
									-	112.0
XJL4225	500	NRR	ΑE	5700	777-57-848-01-01	LHW WING TIP L/E FAIRING SEALAN	T FOLIND MISSING	L422	COMP	09/28/2023
7.02.220	WNG			0.00	0. 0.0 0. 0.	ETW WING THE E/ET/MINITO DE MES MY	TO SOLD MISSING	L422	COMP	1.0
									-	
V II 4000	200	NIDM	A. I.	0500	AEO 20572 04	CARIN PRE INCIRE CEAR AT ROOM	FOUL OWED SIDE WALL DAVIEL ASPESSO FROM STAIRS ASPESSOR FOUND EXPIDED			1.0
XJL4233	200 CAB	NRM	Al	2560	AEO-29573-01	CABIN PBE INSIDE OFAR AT DOOR S	5 ON LOWER SIDE WALL PANEL ACROSS FROM STAIRCASE FOUND EXPIRED	L423	COMP	09/30/2023
	O/ LD								_	1.0
										1.0
XJL4241	200 CAB	NRR	Al	2531	777-53-908-00-01	CABIN G2R GALLERY COMPARTMEN	NT R2-12 ICE DRAWER TRACK FOUND DAMAGE	L424	WIP	09/29/2023
	CAB									5.0
									-	5.0
XJL4258	600	NRR	AE	28	777-28-021-10-05	RHW FUEL TANK ACCESS PNLS FOL	UND DIRTY	L425	COMP	09/26/2023
	WNG									8.0
									-	8.0
XJL4266	500	NRR	ΑE	28	777-28-021-10-04	LHW FUEL TANK ACCESS PNLS FOL	JND DIRTY	L426	COMP	09/26/2023
	WNG									8.0
									-	8.0
XJL4274	100	NRR	AE	2152	777-53-830-00-02	FUS-RH PACK HEAT EXCHANGER FO	OUND CRACKED.	L427	WIP	10/03/2023
	FUS									0.0
						1C 1 REMOVE THE DUAL	HEAT EXCHANGER.			10.0
							AL HEAT EXCHANGER.			12.0
							YPASS CHECK VALVE.			2.0
							EXCHANGER INSTALLATION TEST. YPASS CHECK VALVE.			1.0 1.0
						20 0 REMOVE THE FAN B	TRADO CHECK VALVE.		_	1.0
										26.0

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

AREA: ALL

PAGE: 61 OF 89 RUN DATE: 10/6/2023

2C

STAGE: ALL

RUN TIME : 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE:

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE : ALL TRADE : ALL CUST ENDORSE : ALL

CTRL CODE : ORIGINATOR : ALL

CTRL CODE	: ZONE	STC			TYPE CODE:	ORIGINATOR: ALL		STATUS	UPDATED DATE
JOB NO	AREA	316	TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL4282	100	NRR	AE	2152	777-53-830-00-02	FUS-RH PACK DIFFUSER HOUSING FOUND DE LAMINATION.	L428	WIP	10/03/2023
	FUS								0.0
						1C 1 REMOVE THE FLEXIBLE BOOT FROM THE FAN BYPASS CONNECTOR DUCT.			1.0
						1C 2 REPLACE THE DIFFUSER HOUSING.			10.0
						1C 3 INSTALL THE FLEXIBLE BOOT ONTO THE FAN BYPASS CONNECTOR DUCT.			1.0
						1C 4 DO THE DIFFUSER HOUSING INSTALLATION TEST.			1.0
								-	13.0
XJL4290	100	NRR	AE	2152	777-53-830-00-02	FUS-RH PACK RAM AIR INLET DUCT AFT SLEEVE CONNECTOR FOUND TORN.	L429	COMP	10/05/2023
	FUS								2.0
								-	2.0
XJL4308	100	NRR	AE	2152	777-53-830-00-02	FUS-RH PACK LWR FCV BONDING BROKEN.	L430	WIP	10/05/2023
	FUS								0.0
						1C 1 REPLACE THE BONDING.			1.0
						1C 2 DO THE BONDING TEST.			0.5
								-	1.5
XJL4316	300	NRR	SM	5500	777-55-861-00-01	RIGHT SIDE HORIZONTAL STABILIZER T/E ACCESS PANEL 345GXB 3 EA ANCHOR NUT BROKEN	L431	COMP	10/04/2023
	EMP								3.0
								-	
									3.0
XJL4324	100	NRR	ΑE	2152	777-53-830-00-02	FUS-RH PACK THE CONDITIONING LOW LIMIT VALVES 2EA BONDINGS BROKEN.	L432	WIP	10/05/2023
	FUS								0.0
						1C 1 REPLACE THE BONDING.			1.0
						1C 2 DO THE BONDING TEST.			0.5
								-	1.5
XJL4332	100	NRR	AE	2152	777-53-830-00-02	FUS-RH PACK THE CONDITIONING ECONOMY VALVE BONDING BROKEN.	L433	WIP	10/05/2023
	FUS								0.0
						1C 1 REPLACE THE BONDING.			1.0
						1C 2 DO THE BONDING TEST.			0.5
						TO 2 DO THE DONDING IEST.		_	0.5
									1.5

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR (By JSN)

RUN DATE: 10/6/2023

RUN TIME: 14:22

62 OF 89

1.5

PAGE:

REFERENCE NO: PROJECT: XJ

REQUESTED BY:

CUSTOMER: CX

ALL

A/C TYPE: 777

A/C REGN: B-KPV

CHECK TYPE: 2C

ESTIMATED MHR: ALL

JSN RANGE SELECTED: ALL ORIGINATING CUST REF NO:

STATUS: ALL

ATA NO: ALL

PERIOD: ALL ZONE: ALL

DISPOSITION CODE: ALL

DEFECT TYPE: ALL

CTRL CODE:

515653

BMS571R1-2

TRADE: ALL

TYPE CODE:

CUST ENDORSE: ALL

ORIG-STAGE: ALL

ORIGINATOR: ALL

AREA: ALL

STAGE: ALL

LIPDATED DATE STATUS

	ZONE	STG						STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL4340	100	NRR	AE	2152	777-53-830-00-02	FUS-RH PACK RAM AIR INLET DUCT MIDDLE BONDING BROKEN.	L434	WIP	10/04/2023
	FUS								0.0
						1C 1 REPLACE THE BONDING.			1.0
						1C 2 DO THE BONDING TEST.			0.5
								-	1.5
XJL4357	500	NRR	SS	5700	777-12-008-00-02	RHW L/E ACCESS PANEL611CB EXTERNAL SURFACE FOUND DELAMINATION	L435	WIP	09/25/2023
	WNG								0.0
						1C 1 DO AN INSPECTION TO FIND THE DAMAGE DIMENSION			1.0
						1C 2 DO THE REPAIR TO DAMAGED AREA			12.0
						1C 3 DO THE POST REPAIR INSPECTION			1.0
						1C 4 APPLY RESIN AND SMOOTH OUT			2.0
						2C 5 FILL IN THE SDR FORM			0.0
						2C 6 APPLY CONDUCTIVE COATING			1.0
						2C 7 MEASURE THE RESISTIVITY OF CONDUCTIVE COATING			0.5
						2C 8 RESTORE SURFACE FINISH			0.0
								-	17.5
XJL4365	200	NRP	AV	3351	777-33-060-01-CX-01	EMERGENCY LIGHT TEST FOUND 1D.2D AISLE EMERGENCY LIGHT COVER MISSING	L436	OPEN	09/24/2023
	CAB								2.0
								-	2.0
XJL4373	200	NRP	AV	3351	777-33-060-01-CX-01	REMOVE THE CEILING PANEL FOUND 67HK. 65HK CONNECTOR CRACK	L437	WIP	10/03/2023
	CAB								2.0
								-	2.0
XJL4381	100	NRR	AE	2100	777-53-830-00-01	LEFT AIR CONDITIONING SYSTEM RAM AIR INLET DUCT OUTBOARD SUPPORT ROD FOUND ROD END BEARING	L438	COMP	10/04/2023
	FUS					WORN			2.0
								-	2.0
XJL4399	300	NRR	AE	5500	777-55-824-00-01	VERTICAL STABILIZER FORWARD TIP FAIRING 327 1 EA BONDING JUMPER FOUND WIRE BROKEN	L439	COMP	10/02/2023
	EMP								0.0
						1C 1 REPLACE THE BONDING.			1.0
						1C 2 DO THE BONDING TEST.			0.5
						TO E SO THE SONDING FEOT.		_	0.5
								-	

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 63 OF 89 RUN DATE: 10/6/2023

RUN TIME : 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL

PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO:

ALL

ATA NO: ALL

ZONE: ALL

DISPOSITION CODE: ALL

STAGE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL

CTRL CODE

TYPE CODE ODICINATOD.

CTRL CODE:					TYPE CODE:	ORIGINATO)R: ALL				
	ZONE	STG								STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO		DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL4407	300	NRR	AE	5500	777-55-824-00-01	VERTICAL STABILIZER TIP FAIR	ING 327 FOUND BULB	SEAL TORN	L440	COMP	09/27/2023
	EMP										2.0
										-	2.0
XJL4415	200	NRM	CL	2500	AEO-29097-01	CABIN FLASH LIGHT BASE FOUL	ND DIRTY		L441	COMP	10/05/2023
	CAB										5.0
										-	5.0
XJL4423	200	NRM	Al	2560	AEO-29097-01	CABIN EMERGENCY EQUIPMEN	IT SECURITY SEAL FC	UND DAMAGE	L442	WIP	09/28/2023
	CAB										1.0
										-	1.0
XJL4431	200	NRR	SS	25	777-C252430-01-03-	PEY PAX SEAT LEGREST SUPP	ORT BRACKET SCREV	V FOUND LOOSEN AT:32A 30E F 31E 32D 33F G 34D EF G 34K 33	H L443	COMP	10/03/2023
	CAB				01	K 32H 31D 30D 31A 34C 33C TOT	AL:20EA		2110	COM	10.0
										-	10.0
XJL4449	200	NRR	SS	25	777-C252430-01-06-	PEY PAY SEAT RACK REST HYD) FWD COVER &SCRE	W FOUND MISSING AT:33A 34A TOTAL:2EA	L444	WIP	10/04/2023
7021110	CAB			20	01	TETTINGENT BROKNEST TIL	TWD GOVER GOORE	W FOORD WILDOWS AT TOTAL ZEIN	L 444	VVIE	1.0
										-	
XJL4456	200	NRR	SS	25	777-C252430-01-04-	PEY PAX SEAT CONSOLE FWD	COVER FOLIND CRAC	VED AT 24AC 24FC TOTAL 2FA			1.0
AJL4450	CAB	NKK	33	25	01	PET PAX SEAT CONSOLE FWD	SOVER FOUND CRAC	NED AT 34AC STEG TOTAL ZEA	L445	WIP	10/04/2023
										-	2.0
											2.0
XJL4464	200 CAB	NRR	SS	25	777-C252430-01-03- 01	PEY PAX SEAT LEGREST HYD S	CREW FOUND LOOSE	EN AT:33A C 34A C 30E 32H 32E 33D TOTAL:8EA	L446	COMP	10/03/2023
	CAD										4.0
										-	4.0
XJL4472	200	NRR	SS	25	777-C252430-01-03- 01	PEY PAX SEAT LEGREST BUTTO	ON CABLE OPERATION	N FOUND TIGHTEN AT:33A H TOTAL:2EA	L447	COMP	10/03/2023
	CAB				01						1.0
										-	1.0
XJL4480	200	NRR	SS	25	777-C252430-01-06-	PEY PAX SEAT BACK REST HYD	FWD COVER SCREW	FOUND MISSING AT:33C	L448	WIP	10/04/2023
	CAB				01						0.5
										-	0.5

515653

REQUESTED BY:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

64 OF 89 PAGE:

RUN DATE: 10/6/2023

REFERENCE NO: BMS571R1-2 (By JSN) RUN TIME : 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

TINE CODE .					TIFE CODE.	ONGINATOR: F	ALL		STATUS	UPDATED DATE
JOB NO	ZONE AREA	STG	TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
		NRR			777-C252430-01-03-					
(JL4498	200 CAB	NKK	SS	25	777-0252430-01-03- 01	PEY PAX SEAT BUTTOM PAN STRUCTURI	FOUND CRACKED AT:33A 30D E F 32G TOTAL:5EA	L449	WIP	10/05/2023
	0/15								_	5.0
										5.0
(JL4506	200	NRR	SS	25	777-C252430-01-05- 01	PEY PAX SEAT ARM REST LOWER PLUG I	FOUND MISSING AT:33A 33F 34G (2EA) 33H TOTAL:5EA	L450	COMP	10/05/2023
	CAB									2.5
									-	2.5
JL4514	200	NRR	SS	25	777-C252430-01-05- 01	PEY PAX SEAT ARM REST AFT PLUG FOU	ND MISSING AT:33A 34A 32K 34K 32A K TOTAL:6EA	L451	COMP	10/04/2023
	CAB				U I					3.0
									-	3.0
(JL4522	200	NRR	SS	25	777-C252430-01-03-	PEY PAX SEAT AFT FOOTREST WASHER	FOUND MISSING AT:32A C 30E(2EA) 31D F G 32D 33E(3EA) TOTAL:11EA	L452	WIP	10/05/2023
	CAB				01					11.0
									-	11.0
JL4530	200	NRR	SS	25	777-C252430-01-03-	PEY PAX SEAT LEGREST OPERATION FO	JND NOISE AT:34A 31E 34D TOTAL:3EA	L453	COMP	10/03/2023
	CAB				01					1.5
									-	1.5
JL4548	200	NRR	SS	25	777-C252430-01-05-	PEY PAX SEAT ARM REST TIRM CAP FOU	ND LOOSEN AT:32A 32G 34H TOTAL:3EA	L454	COMP	10/03/2023
	CAB				01			2101	001111	1.5
									-	1.5
JL4555	200	NRR	SS	25	777-C252430-01-03-	PEY PAX SEAT BOTTOM PAN FWD PLUG	SCREW FOUND LOOSEN AT 32C 33C	L455	COMP	
024000	CAB	TVICE	00	20	01	TETT/WOLKT BOTTOMT/MYT WBT EGG	JONEW FOOTING EGGENTH. 1920 000	L455	COMP	10/03/2023
									-	
4500	000	NDD	00	0.5	777 0050400 04 00	DEV DAY OF AT DAOK DEGT LIVE OIDE DAY	(00DEW FOUND 000EN AT 200 040			1.0
JL4563	200 CAB	NRR	SS	25	777-C252430-01-06- 01	PEY PAX SEAT BACK REST HYD SIDE BAY	SCREW FOUND LOOSEN AT:32C 34C	L456	COMP	10/03/2023
	0/15								_	1.0
										1.0
JL4571	200	NRR	SS	25	777-C252430-01-03- 01	PEY PAX SEAT AFT FOOTREST BUSHING	FOUND MISSING AT:31A 33E 33F G TOTAL:3EA	L457	WIP	10/05/2023
	CAB									3.0
									-	3.0

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 65 OF 89

ESTIMATED MHR: ALL

RUN DATE: 10/6/2023

RUN TIME: 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL

ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

CINE CODE.	ZONE	CTC			TIFE CODE.	ONGINATOR:	ALL		STATUS	UPDATED DATE
JOB NO	AREA	316	TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL4589	200	NRR	SS	25	777-C252430-01-03-		CKET PIN AND WASHER&CLIP AND BUSHING FOUND MISSING AT:34A	L458	WIP	10/05/2023
	CAB				01					1.0
									-	1.0
XJL4597	200	NRR	SS	25	777-C252430-01-06-	PEY PAX SEAT BACK REST ATT HEADRE	ST SLIDE TRACK FOUND LOOSEN AT:31C	L459	COMP	10/03/2023
	CAB				01			L400	COIVII	0.5
									-	0.5
XJL4605	200	NRR	SS	25	777-C252430-01-04-	PEY PAX SEAT CONSOLE TOP CAP FOUR	ID CBACKED AT:3//AC	L460	COMP	
7.02-4000	CAB	TVICE	00	20	01	TETTAX GEAT CONGOLE TO CALL TOO	D GINGINED AT. STAG	L400	COMP	10/04/2023
									-	
V II 4642	200	NRR	SS	25	777-C252430-01-06-	DEV DAY CEAT DAOY DEGT CODEW COLL	ID LOODEN ATTAC 22A O 24E 20E O D 20E E O 22E 24D E O 20ILIX 22ILIX 24ILIX			1.0
XJL4613	CAB	INIXIX	33	25	01	TOTAL:20EA	ND LOOSEN AT31C 33A C 31E 30F G D 32E F G 33E 34D E G 32H K 33H K 34H K	L461	COMP	10/03/2023
									-	10.0
V.II. 4004	000	NDD		0.5	777 0050400 04 00					10.0
XJL4621	200 CAB	NRR	SS	25	777-C252430-01-03- 01	PEY PAX SEAT FOOTREST ATT SCREW F	OUND LOOSEN AT:31A C 30D E F G 32H K TOTAL:8EA	L462	COMP	10/03/2023
	O/ ND								_	4.0
										4.0
XJL4639	200 CAB	NRR	SS	25	777-C252430-01-06- 01	PEY PAX SEAT CONSOLE FWD TOP CAP	SCREW FOUND MISSING AT:31C 33F 34K TOTAL:3EA	L463	WIP	10/05/2023
	CAB									1.5
									-	1.5
XJL4647	200	NRR	SS	25	777-C252440-04-04- 01	EY FIRST SEAT INNER SHOUD FOUND LO	OOSEN AT 40HJK 39DEFG 39AC40C 59ABC 60DEFG 59HJK TTL 20EA	L464	WIP	10/05/2023
	CAB				01					5.0
									-	5.0
XJL4654	200	NRR	SS	25	777-C252430-01-05- 01	PEY PAX SEAT CONSOLE ARM CAP SCR	EW FOUND MISSING AT:31C 30G TOTAL:2EA	L465	WIP	10/05/2023
	CAB				UI					1.0
									-	1.0
XJL4662	200	NRR	SS	25	777-C252430-01-05-	PEY PAX SEAT ARM REST SHROUD FOU	ND CRACKED AT:30D	L466	WIP	10/05/2023
	CAB				01					1.0
									-	1.0

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 66 OF 89 RUN DATE: 10/6/2023

RUN TIME :

14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL

PERIOD: ALL

ZONE: ALL

ESTIMATED MHR: ALL DISPOSITION CODE: ALL

ORIGINATING CUST REF NO:

ALL

ATA NO: ALL TRADE: ALL CUST ENDORSE: ALL

AREA: ALL STAGE: ALL

DEFECT TYPE: ALL

CTRL CODE :					TYPE CODE:	ORIGINATOR: ALL	ANLA. ALL	STAGE . ALL		
JOB NO	ZONE AREA	STG	TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS STATUS	UPDATED DAT EST Mhr
KJL4670	200	NRP	SS	25	777-25-050-08-CX-R-		RATION FOUND MALFUNCTION AT:30D E F G 31A C 32H K			
3L4070	CAB	IVIXI	00	20	01	TOTAL:8EA	WHICH TOURD WALL ONCHON AT SUD ET G STA C SZITK	L467	COMP	10/04/2023
									-	
JL4688	200	NRR	SS	25	777-C252440-04-04-	EV FIRST OF ATOINE DUMBER DAME FOUND REQUES	AT 000			8.0
JL4000	CAB	INKK	33	25	01	EY FIRST SEATSIDE BUMPER PANL FOUND BROKEN	AT 60G	L468	OPEN	09/25/2023
									-	1.0
										1.0
JL4696	200 CAB	NRR	SS	25	777-C252430-01-01- 01	PEY PAX SEAT BELT FOUND FRAY AT:31A 33A 30G T	DTAL:3EA	L469	COMP	10/04/2023
	OND								_	1.5
										1.5
JL4704	200 CAB	NRR	SS	25	777-C252430-01-05- 01	PEY PAX SEAT ARM REST OPERATION FOUND NOISE	E AT:31C	L470	COMP	10/03/2023
	CAB									0.5
									-	0.5
JL4712	200	NRR	SS	25	777-C252430-01-05- 01	PEY PAX SEAT ARM REST STRUCTURE FOUND LOOS	SEN AT:30D 31D G 34G 33H TOTAL: 5EA	L471	WIP	09/28/2023
	CAB				01					5.0
									-	5.0
JL4720	200	NRR	SS	25	777-C252440-04-04- 01	EY FIRST SEAT SIDE FAIRING SCREW FOUND LOOSE	N AT 39G	L472	WIP	10/05/2023
	CAB				UI					0.5
									-	0.5
JL4738	200	NRP	SS	25	777-25-050-08-CX-R-	PEY PAX SEAT CONSOLE PTV ARM PLUG FOUND MIS	SSING AT:30D	L473	COMP	10/04/2023
	CAB				01					0.5
									-	0.5
JL4746	200	NRR	SS	25	777-C252430-01-03-	PEY PAX SEAT LEGREST BUTTON CABLE FOUND BR	OKEN AT:30E	L474	WIP	10/04/2023
	CAB				01					1.0
									-	1.0
JL4753	200	NRR	Al	2502	777-C252420-01-05-	CAB-FB2 SEAT BACKSHELL ROLLER BLIND BLACK FA	STENER FOUND MISSING	L475	OPEN	09/25/2023
	CAB			1 2502	01					5.0
									-	5.0

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 67 OF 89

RUN DATE: 10/6/2023

RUN TIME: 14:22

ESTIMATED MHR: ALL

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL

ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

	ZONE	STG			THE GODE.	ONO WITCH			STATUS	UPDATED DATI
JOB NO	AREA	0.0	TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
JL4761	200	NRR	AV	3326	777-C330000-01-03-	TOILET LIGHT INSPECTION FOUND CE	LING LIGHT COVER CRACK AT LAV D	L476	COMP	10/05/2023
	CAB				01					1.0
									-	1.0
L4779	200	NRR	AV	3326	777-C330000-01-03-	TOILET LIGHT INSPECTION FOUND LAV	CALL LIGHT LENS CRACK AT LAV C,E,H,K,L	L477	COMP	10/05/2023
	CAB				01					2.5
									-	2.5
L4787	200	NRR	Al	2502	777-C252420-01-05-	CAB-FB2 SEAT BACKSHELL ROLLER BI	IND FOUND DAMAGE AT 19K 20K 21A 18A 15A	L478	COMP	10/02/2023
	CAB				01					5.0
									-	5.0
L4795	200	NRR	SS	2511	777-25-020-02-01	PILOT SEAT VELCRO TAPE FND LOOSE	E	L479	WIP	10/05/2023
	CAB									1.0
									-	1.0
L4803	200	NRR	SS	2511	777-25-020-02-01	PILOT SEAT HEADREST FND NOISE		L480	OPEN	09/25/2023
	CAB									1.0
									-	1.0
L4811	200	NRR	SS	2511	777-25-020-02-01	PILOT SEAT BOTTOM COVER FND WOR	RN	L481	WIP	09/26/2023
	CAB									1.0
									-	1.0
L4829	200	NRR	SS	2511	777-25-020-02-01	PILOT SEAT BOTTOM CUSHION		L482	WIP	10/03/2023
	CAB									1.0
									-	1.0
L4837	200	NRR	SS	2511	777-25-020-02-01	1ST OBS SEAT RECLINE SIDE SCREW	FND LOOSE	L483	OPEN	09/25/2023
	CAB									1.0
								-	1.0	

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 68 OF 89 RUN DATE: 10/6/2023

RUN TIME: 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE : ALL TRADE : ALL CUST ENDORSE : ALL AREA : ALL STAGE : ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

CTRL CODE					TYPE CODE:			ORIGINATOR: ALL			
	ZONE	STG								STATUS	UPDATED DAT
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTR	L SH NC	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
JL4845	600	NRR	ΑE	2800	777-28-015-00-01	RHV	W F/T VEN	T SCOOP DOOR 644BB FOUND ONE PUNCH HOLE	L484	OPEN	09/25/2023
	F/T										0.0
						1C	1	REMOVE VENT SCOOP ASSEMBLY TO THE ACCESS DOOR			3.0
						1C	2	REINSTALL VENT SCOOP ASSEMBLY TO THE NEW ACCESS DOOR			3.0
						1C	3	CARRY OUT BONDING RESISTANCE TEST BETWEEN THE UPPER DUCT ON THE VENT SCOOP ASSEMBLY AND THE ACCESS DOOR			0.5
						1C	4	APPLY THE SEALANT ALONG THE TOP OF THE SCREWS			1.0
						2C	5	REINSTALL VENT SCOOP ACCESS DOOR			0.0
						2C	6	CARRY OUT BONDING RESISTANCE TEST BETWEEN THE ACCESS DOOR AND THE LOWER WING SKIN			0.5
						2C	7	DO A VISUAL CHECK TO MAKE SURE THAT ACCESS DOOR INSTALLATION IS FLUID TIGHT			0.5
										-	8.5
L4852	100 FUS	NRP	SM	5000	777-53-545-01-01	LEF	T FORWA	RD BSTA1035+20 INCH LOWER WING TO BODY FAIRING SUPPORT ANGLE CRACKED	L485	WIP	10/02/2023
	FUS										0.0
						1C	1	REMOVE SUPPORT FTG ATT SCREW			4.0
						1C	2	REMOVE CRACK SUPPORT FTG			4.0
						1C	3	TRANSFER HOLES TO NEW FTG			4.0
						1C	4	INSTALL NEW FTG			4.0
						2C	5	INSTALL SUPPORT FTG ATT SCREW			4.0
						2C	6	CARRY OUT FASTENERS SEAL APPLICATION			2.0
						2C	7	PERFORM THE FUEL TANK LEAKAGE CHECK			2.0
						2C	8	TOUCH UP PAINT			1.0
						3C	9	REMOVE LEFT WING FUEL TANK ACCESS DOOR 531AB			1.0
						3C	10	INSTALL LEFT WING FUEL TANK ACCESS DOOR 531AB			1.0
						3C	11	MAKE SURE NO FUEL LEAKAGE AT THE APPLICEABLE TANK ACCESS DOOR			0.5
						4C	12	MEASURE RESISTANCE BETWEEN BRACKET AND PANEL			0.5
										-	28.0
L4860	100	NRR	AE	2152	777-53-830-00-01	FUS	S-LH PACK	HEAT EXCHANGER FOUND CRACKED.	L486	WIP	10/03/2023
	FUS										0.0
						1C	1	REMOVE THE FAN BYPASS CHECK VALVE.			1.0
						1C	2	REMOVE THE DUAL HEAT EXCHANGER.			10.0
						1C	3	REINSTALL THE DUAL HEAT EXCHANGER.			12.0
						1C	4	INSTALL THE FAN BYPASS CHECK VALVE.			2.0
						2C	5	DO THE DUAL HEAT EXCHANGER INSTALLATION TEST.			1.0
										-	26.0

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 69 OF 89 RUN DATE: 10/6/2023

RUN TIME :

ESTIMATED MHR: ALL

14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL JSN RANGE SELECTED: ALL

> ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE : TYPE CODE: ORIGINATOR ·

CTRL CODE :					TYPE CODE:			ORIGINATOR: ALL			
	ZONE	STG								STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTR	L SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL4878	100	NRR	AE	2152	777-53-830-00-01	FUS	S-RH PACK	UPR FCV BONDING BROKEN.	L487	WIP	10/05/2023
	FUS										0.0
						1C	1	REPLACE THE BONDING.			1.0
						1C	2	DO THE BONDING TEST.			0.5
											1.5
XJL4886	100	NRR	AE	2152	777-53-830-00-01	FUS	S-LH PACK	RAM AIR INLET DUCT AFT BONDING BROKEN.	L488	WIP	10/03/2023
	FUS										0.0
						1C	1	REPLACE THE BONDING.			1.0
						1C	2	DO THE BONDING TEST.			0.5
											1.5
XJL4894	300	NRR	PT	5500	777-55-000-06-CX-01	VER	RTICAL ST	ABILIZER LEADING EDGE 321E FOUND COATING DETERIORATION	L489	WIP	09/27/2023
	EMP										0.0
						1C	1	DISCONNECT HF ANTENNA FEEDLINE			2.0
						1C	2	REMOVE PNL 321E			0.0
						1C	3	APPLY ANTI-STATIC COATING TO SURFACE			30.0
						1C	4	C/O RESISTANCE CHECK			2.0
						2C	5	RESTORE THE ORIGINAL FINISH COATING			10.0
						2C	6	RECONNECT THE HF ANTENNA FEEDLINE CONNECTOR			2.0
						2C	7	RE-INSTALL THE 321E			0.0
						2C	8	C/O HF SYSTEM TEST			1.0
						3C	9	DISCONNECT HF ANTENNA FEEDLINE			0.0
										•	47.0
XJL4902	100	NRR	AE	2152	777-53-830-00-01	FUS	S-LH PACK	TRIM AIR VALVE BONDING BROKEN.	L490	WIP	10/05/2023
	FUS										0.0
						1C	1	REPLACE THE BONDING.			1.0
						1C	2	DO THE BONDING TEST.			0.5
							_	DO THE BOTOM TEON			1.5
XJL4910	100	NRR	AE	2152	777-53-830-00-01	EHG	STH DVCK	THE CONDITIONING O/B LOW LIMIT VALVES BONDINGS BROKEN.	L491	WIP	10/05/2023
7.02 10 10	FUS	11111	,	2102	777 00 000 00 01	100	LITTAON	THE GOLD HOURING OID CON CHINIT VALVEO BONDINGO BROKEN.	L491	VVIF	
						10	4	DEDLAGE THE DONONIO			0.0
						1C	1	REPLACE THE BONDING.			1.0
						1C	2	DO THE BONDING TEST.			0.5
										•	1.5

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

70 OF 89 PAGE:

RUN TIME :

RUN DATE: 10/6/2023

14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

ZONE STG

515653

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL

CUST ENDORSE: ALL

PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO:

ALL

ATA NO: ALL

ZONE: ALL AREA: ALL

DISPOSITION CODE: ALL

DEFECT TYPE : ALL

CTRL CODE:

TRADE: ALL TYPE CODE:

ORIGINATOR: ALL

STAGE: ALL

STATUS	UPDATED DATE
STATUS	EST Mhr

JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL4928	200	NRR	SS	25	777-C252420-01-02- 02	FB2 SEAT BACK REST SIDE B	AY GEAR INNER STOP SCREW&BUSHING FOUND MISSING AT:17G	L492	WIP	10/05/2023
	CAB				02					1.0
									-	1.0
XJL4936	200	NRR	SS	25	777-C252420-01-02- 01	FB2 SEAT BOTTOM PAN FWD	BUTTON CAP FOUND BROKEN AT:17K	L493	WIP	10/04/2023
	CAB				01					2.0
									-	2.0
XJL4944	200	NRR	SS	25	777-C252440-04-04- 01	EY F/R SEAT CENTER CONSC TTL:6EA	DLE CONNECT STRUCTURE ATT CLAMP FND BROKEN AT:40HJ 39G 39D 39C 59A 60E	L494	OPEN	09/25/2023
	CAB				01	TIL.OEA				12.0
									-	12.0
XJL4951	200	NRR	SS	25	777-C252420-01-02- 01	FB2 SEAT BOTTOM PAN LOW	ER BRACKET FWD SCREW FOUND LOOSEN AT:12D 16D 19A 11K TOTAL:4EA	L495	COMP	10/04/2023
	CAB				01					2.0
									-	2.0
XJL4969	200	NRR	SS	25	777-C252420-01-02- 01	FB2 SEAT BOTTOM PAN SIDE	BAY BRACKET SCREW FOUND LOOSEN AT:21K	L496	COMP	10/04/2023
	CAB				01					0.5
									-	0.5
XJL4977	200	NRR	SS	25	777-C252420-01-02- 01	FB2SEAT TRACKING BUTTON	SCREW FOUND LOOSEN AT:25K 22K 20G 19G TOTAL:4EA	L497	COMP	10/04/2023
	CAB				01					2.0
									-	2.0
XJL4985	200	NRR	SS	25	777-C252420-01-02- 01	FB2 SEAT BACK REST ATT SO	CREW FOUND LOOSEN AT:17K 26K 16G 23A 21A 17A 16A 25K 21G TOTAL:9EA	L498	COMP	10/04/2023
	CAB				01					4.5
									-	4.5
XJL4993	200	NRR	SS	25	777-C252420-01-02- 02	FB2 SEAT BACK REST SCREV	V FOUND MISSING AT:20D	L499	WIP	10/04/2023
	CAB				02					0.5
									-	0.5
XJL5008	200	NRR	SS	25	777-C252420-01-02- 02	FB2SEAT BELT AIR BAG FOU	ND TORN AT:19D 22D 21K 19G 17G TOTAL:5EA	L500	WIP	10/01/2023
	CAB				UZ					7.5
									-	7.5

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

71 OF 89 PAGE: RUN DATE: 10/6/2023

RUN TIME : 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL

PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO:

ALL

ATA NO: ALL

ZONE: ALL

DISPOSITION CODE: ALL

DEFECT TYPE : ALL

TRADE: ALL

CUST ENDORSE: ALL

AREA: ALL STAGE: ALL

CTRL CODE :	TYPE CODE:	ORIGINATOR:	ALL

TRL CODE :					TYPE CODE:	URIGINATUR:	ALL			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
KJL5016	200 CAB	NRR	SS	25	777-C252420-01-02- 01	FB2 SEAT BACK REST SIDE BAY GEAR A 12K G 11G TOTAL:14EA	TT SCREW FOUND LOOSEN AT:17A 22D 25D A 25K 23G 22K 20K 17G 16K G	L501	WIP	10/03/2023 7.0
									-	7.0
JL5024	200	NRR	SS	25	777-C252420-01-02- 02	FB2 SEAT BACK REST HEADREST STRU 18G 16K TOTAL:12EA	CTURE SCREW FOUND LOOSEN AT:17A 18A D 19D 22A 23A 25G 24K G 23G	L502	COMP	10/04/2023
	CAB				02	TOG TON TOTAL TZEA			_	6.0
										6.0
(JL5032	200 CAB	NRR	SS	25	777-C252420-01-02- 01	FB2 SEAT RECLINE MOTOR GEAR ATT P	IN FOUND BROKEN AT:17D 19A 20A 24A 16G TOTAL:5EA	L503	WIP	10/06/2023
									_	5.0
										5.0
JL5040	200	NRR	SS	25	777-C252420-01-02- 01	FB2 SEAT LEGREST BUTTON SCREW FC	DUND LOOSEN AT:17A 16A 17D 18D 23D 24A 26K 24K 23K 20K 16K TOTAL:11EA	L504	COMP	10/04/2023
	CAB									5.5
									-	5.5
JL5057	200	NRR	SS	25	777-C252420-01-02- 02	FB2 SEAT BACK REST HEADREST SLIDE	TRACK FOUND BROKEN AT:15A 17D 19D 20D 21G TOTAL:5EA	L505	WIP	10/04/2023
	CAB				02					2.5
									-	2.5
JL5065	200	NRR	SS	25	777-C252420-01-02- 02	FB2 SEAT BOTTOM PAN LOWER BRACK	ET FWD SCREW&NUT FOUND MISSING AT:11D	L506	WIP	10/05/2023
	CAB				02					1.0
									-	1.0
JL5073	200	NRR	SS	25	777-C252420-01-02- 02	FB2 SEAT LEGREST MOTOR ATT SCREV	/ FOUND LOOSEN AT:11D 16D 23D 23A 20K 12G TOTAL:6EA	L507	COMP	10/04/2023
	CAB				02					3.0
									-	3.0
JL5081	200	NRR	SS	25	777-C252420-01-02-	FB2SEAT RECLINE BUTTON SCREW FOL	JND LOOSEN AT:11D 23D 26D TOTAL3EA	L508	COMP	10/04/2023
	CAB				02					1.5
									-	1.5
JL5099	200	NRR	SS	25	777-C252420-01-02-	FB2SEAT BELT BUCKLE FOUND FRAY A	T:11D 20D 22A 23A 25D 25G 23G 22G 16G TOTAL:9EA	L509	COMP	10/04/2023
	CAB				02				4.5	
									-	4.5

REQUESTED BY:

REFERENCE NO:

DEFECT TYPE: ALL

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: RUN DATE: 10/6/2023

RUN TIME :

72 OF 89

14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL

PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO:

ALL

ATA NO: ALL TRADE: ALL

ZONE: ALL

DISPOSITION CODE: ALL STAGE: ALL

CTRL CODE:

TYPE CODE:

ORIGINATOR: ALL

CUST ENDORSE: ALL

AREA: ALL

CTATHE	

	ZONE	STG						STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
(JL5107	200	NRR	SS	25	777-C252420-01-02- 01	FB2 SEAT BELT BUCKLE FOUND FRAY AT:18A 19A 26K 25K 18K 16K TOTAL:6EA	L510	COMP	10/04/2023
	CAB				01				9.0
								-	9.0
JL5115	200	NRR	SS	25	777-C252430-01-06- 01	PEY PAX SEAT BACK REST TV SHROUD LOWER COVER FOUND LOOSEN AT:33F	L511	COMP	10/03/2023
	CAB				01				0.5
								-	0.5
JL5123	200	NRR	SS	25	777-C252430-01-03- 01	PEY PAX SEAT BACK REST TV SHROUD PLACARD FOUND TORN AT:33D 32A 33K TOTAL:3EA	L512	COMP	10/04/2023
	CAB				U I				1.0
								-	1.0
JL5131	200	NRR	SS	25	777-C252430-01-06-	PEY PAX SEAT BACK REST TV SHROUD LOWER COVER SCREW FOUND LOOSEN AT:33D	L513	COMP	10/03/2023
	CAB				01				0.5
								-	0.5
JL5149	200	NRR	SS	25	777-C252430-01-04-	PEY PAX SEAT CONSOLE ARM CAP SCREW FOUND LOOSEN AT:33G	L514	COMP	10/03/2023
	CAB				01				0.5
								-	0.5
JL5156	200	NRR	SS	25	777-C252430-01-01-	PEY PAX SEAT LEGREST DRESS COVER FOUND NO MATCH AT:33G	L515	WIP	10/03/2023
	CAB				01				0.5
								-	0.5
JL5164	200	NRR	SS	25	777-C252430-01-06-	PEY PAX SEAT BACK REST BRACKET SCREW FOUND LOOSEN AT:33G 34F E G D TOTAL:5EA	L516	COMP	10/03/2023
	CAB				01				2.5
								-	2.5
JL5172	200	NRR	SS	25	777-C252430-01-02-	PEY PAX SEAT SIDE FAIRING FOUND LOOSEN AT:32D	L517	COMP	10/03/2023
	CAB				01				0.5
								-	0.5
JL5180	200	NRR	SS	25	777-C252430-01-03-	PEY PAX SEAT LEGREST LIFE JACKET BOX VELCRO TAPE FOUND LOOSENAT:32D F G 31E F 33F E G 34D G 32H 34K	L518	COMP	10/04/2023
	CAB				01	33H 32C 33A TOTAL:15EA			7.5
							-	7.5	

REQUESTED BY:

REFERENCE NO:

DEFECT TYPE: ALL

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 73 OF 89

RUN DATE: 10/6/2023

0.5

RUN TIME : 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL

PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO:

ALL

ATA NO: ALL TRADE: ALL

ZONE: ALL

DISPOSITION CODE: ALL

CTRL CODE:

TYPE CODE:

CUST ENDORSE: ALL ORIGINATOR: ALL

AREA: ALL	STAGE:	ALL
-----------	--------	-----

CTRL CODE :					TYPE CODE:	ORIGINATOR	: ALL			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL5198	200	NRR	SS	25	777-C252430-01-03- 01	PEY PAX SEAT LEGREST LIFE JAC	KET BOX FOUND BROKEN AT:32E 34C 33E 31D TOTAL:4EA	L519	WIP	10/04/2023
	CAB				01					4.0
									-	4.0
XJL5206	200	NRR	SS	25	777-C252430-01-02- 01	PEY PAX SEAT SIDE BAY REAR CO	OVER SCREW FOUND LOOSEN AT:31E	L520	COMP	10/03/2023
	CAB				O1					0.5
									-	0.5
XJL5214	200	NRR	SS	25	777-C252430-01-03-	PEY PAX SEAT LEGREST SUPPOR	T ATT SCREW&NUT INSTALL FOUND WRONG AT:32E	L521	WIP	10/05/2023
	CAB				01					0.5
									-	0.5
XJL5222	200	NRR	SS	25	777-C252430-01-04-	PEY PAX SEAT CONSOLE IN ARM	TABLE SLIDE TRACK SCREW FOUND MISSING AT:32F	L522	WIP	10/05/2023
	CAB				01					0.5
									-	0.5
XJL5230	200	NRR	SS	25	777-C252430-01-03-	PEY PAX SEAT AFT FOOTREST BU	SHING FOUND MISSING AT:31E F G TOTAL3EA	L523	OPEN	09/25/2023
	CAB				01					1.5
									-	1.5
XJL5248	200	NRR	SS	25	777-C252430-01-03-	PEY PAX SEAT LEGREST SUPPOR	T BRACKET AND SCREW&NUT AND WASHER FOUND MISSING AT:31D	L524	OPEN	09/25/2023
	CAB				01					1.0
									-	1.0
XJL5255	200	NRR	SS	25	777-C252430-01-05-	PEY PAX SEAT ARM REST CAP FO	UND TORN AT:31D 33D TOTAL:2EA	L525	WIP	10/04/2023
	CAB				01					1.0
									-	1.0
XJL5263	200	NRR	SS	25	777-C252430-01-03-	PEY PAX SEAT AFT FOOTREST SC	REW FOUND LOOSEN AT:30G	L526	COMP	10/03/2023
	CAB				01					0.5
									-	0.5
XJL5271	200	NRR	SS	25	777-C252430-01-03-	PEY PAX SEAT BOTTOM PAN PLUC	S SCREW FOUND MISSING AT:30G	L527	COMP	10/04/2023
	CAB				01					0.5
									-	

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

74 OF 89 PAGE:

RUN DATE: 10/6/2023

5.0

RUN TIME : 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL

PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO:

ALL

ATA NO: ALL

ZONE: ALL AREA: ALL

DISPOSITION CODE: ALL

DEFECT TYPE: ALL

TRADE: ALL

CUST ENDORSE: ALL

DEFECTION		-			IIVADE : ALI			ANLA. ALL	OTAGE. ALL			
CTRL CODE		0.7.0			TYPE CODE:	ORIGINATOR :	ALL				STATUS	UPDATED DATE
JOB NO	ZONE AREA	SIG	TD	ATA	ORIG CUST REF NO.	CTRL SH NO	С	EFECT DESCRIPTION		JSN	STATUS	EST Mhr
XJL5289	200	NRR	SS	25	777-C252430-01-03-	PEY PAX SEAT CONSOLE SIDE BAY FAIL	RING FOUND CRACKED /	T:30F 32G TOTAL:2EA		L528	COMP	10/04/2023
	CAB				01							2.0
											-	2.0
XJL5297	200	NRR	SS	25	777-C252430-01-04-		E STOWAGE SHROUD FO	UND BROKEN AT:30F G 31G 32G E 33D H 34H		L529	WIP	10/04/2023
	CAB				01	TOTAL:8EA						8.0
											-	8.0
XJL5305	200	NRR	SS	25	777-C252430-01-05-	PEY PAX SEAT ARM REST OPERATION	FOUND LOOSEN AT:30E			L530	COMP	10/03/2023
	CAB				01							0.5
											-	0.5
XJL5313	300	NRR	AE	2700	777-55-822-00-01	RUDDER TAB LOWER LEFT AND RIGHT	SIDE BULB SEALS TORN			L531	COMP	10/05/2023
	EMP											3.0
											-	3.0
XJL5321	100	NRR	Al	5600	777-53-904-00-01	CABIN A ZONE LH SIDEWALL WINDOW [OUST COVER INSIDE FOL	ND DUSTY		L532	OPEN	09/25/2023
	CAB											8.0
											-	8.0
XJL5339	100	NRR	Al	5600	777-53-904-00-01	CABIN A ZONE RH SIDEWALL WINDOW	DUST COVER INSIDE FOL	IND DUSTY		L533	OPEN	09/25/2023
	CAB											8.0
											-	8.0
XJL5347	100	NRR	Al	5600	777-53-908-00-01	CABIN B ZONE RH SIDEWALL WINDOW	DUST COVER INSIDE FOL	IND DUSTY		L534	OPEN	09/25/2023
	CAB											16.0
											-	16.0
XJL5354	100	NRR	Al	5600	777-53-908-00-01	CABIN B ZONE LH SIDEWALL WINDOW [OUST COVER INSIDE FOU	ND DUSTY		L535	OPEN	09/25/2023
	CAB											16.0
											-	16.0
XJL5362	100	NRR	Al	2500	777-53-904-00-01	CABIN A RH WINDOW SHADE FOUND ST	IFF TO OPERATE			L536	OPEN	09/25/2023
	CAB											5.0
											-	

ORIGINATING CUST REF NO:

515653

ALL

REQUESTED BY:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

PAGE: 75 OF 89 RUN DATE: 10/6/2023

REFERENCE NO: BMS571R1-2 (By JSN) RUN TIME : 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

> ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

CUST ENDORSE: ALL DEFECT TYPE: ALL TRADE: ALL AREA: ALL STAGE: ALL

CTRL CODE : TYPE CODE: ORIGINATOR ·

CTRL CODE :					TYPE CODE:	ORIGINATOR	: ALL		STATUS	UPDATED DAT
JOB NO	ZONE AREA	STG	TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
JL5370	100	NRR	Al	2500	777-53-904-00-01	CABIN A LH WINDOW SHADE FOUN		L537	OPEN	09/25/2023
	CAB							2007	OI LIV	5.0
									-	5.0
L5388	100	NRR	Al	2500	777-53-908-00-01	CABIN B ZONE LH WINDOW SHADE	FOUND STIFF TO OPERATE	L538	OPEN	09/25/2023
	CAB							2000	OI EN	8.0
									-	8.0
L5396	100	NRR	AI	2500	777-53-908-00-01	CABIN B ZONE RH WINDOW SHADE	FOUND STIFF TO OPERATE	L539	OPEN	09/25/2023
	CAB					5. B 5 20.12 1.1. 1.1. 1.5 0.1 0.1. 2.1		2009	OI LIV	8.0
									-	8.0
L5404	200	NRR	SS	25	777-C252440-04-04-	CAB E ZONE EY SEAT TRIMCAP FO	NIND CRACKED AT:46EG	L540	OPEN	09/25/2023
	CAB				01	OND E ZONE ET OEM TRIMOTIT TO	one of violes million	L340	OPLIN	0.5
									-	0.5
_5412	200	NRR	SS	25	777-C252440-04-04-	CAR E ZONE EY SEAT ARMREST O	PERATION FOUND LOOSE AT:43FG 42H 44H 45HJ 72C 72D 63HJ TTL:7EA	L541	WIP	10/05/2023
20112	CAB			20	01	OND E ZONE ET OEKT ANNIKEOT O	ENVITORY SOLD ESSEE AT 1-91 S 421 1-41 1-45 16 125 125 30 16 11 E.F.E.A.	L34 I	VVIF	2.5
									-	2.5
L5420	200	NRR	SS	25	777-C252440-04-04-	CAB E ZONE EY SEAT ARMREST O	PERATION FOUND TIGHTEN AT:41JK 42JK 63BC 69BC 66FG 61HJ 61JK TTL:7EA	L542	WIP	10/05/2023
20120	CAB	14141		20	01	STEE ESTEET SERTIFICATION	ELVITORI GOLD HOLLEN HOLLEN CODE COLIC COLIC COLIC COLIC	L342	VVIF	2.5
									-	2.5
_5438	200	NRR	AV	3326	777-C330000-01-03-	LAV D CEILING LIGHT MALFUNCTION	NO.	L543	OPEN	09/25/2023
20100	CAB	14141	,	0020	01	EW B GEIENG EIGHT WILL GROW	···	L043	OPEN	2.0
									-	2.0
L5446	200	NRR	SS	25	777-C252440-04-04-	CAR E ZONE EY SEAT ARMREST FO	OUND MULFUNCTION AT:71D 66H 67H TTL:3EA	L544	OPEN	09/25/2023
20110	CAB	14141		20	01	STEE ESTEET SETTIMENTEST I	Solid Modern Marie Solid Milliand	L344	OPEN	6.0
									-	6.0
_5453	200	NRR	Al	25	777-53-904-00-01	CABIN G1 GALLERY TABLE SEALAI	NT CHIPPED	L545	OPEN	09/25/2023
_0-00	CAB	INIXIX	, NI	20	777-00-004-00-01	SABIR OF GALLERY TABLE SEALAR		L040	UPEN	09/25/2023
									-	
										2.0

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

CUST ENDORSE: ALL

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 76 OF 89

RUN DATE: 10/6/2023

RUN TIME : 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG

ORIG-STAGE: ALL PERIOD: ALL

ORIGINATING CUST REF NO: ALL ATA NO: ALL

TRADE: ALL

ZONE: ALL DISPOSITION CODE: ALL AREA: ALL STAGE: ALL

ESTIMATED MHR: ALL

DEFECT TYPE: ALL

TYPE CODE: ORIGINATOR: ALL

CTRL CODE:

TRL CODE :					TYPE CODE:	ORIGINATOR:	ALL			
	ZONE	STG							STATUS	UPDATED DATE
IOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
JL5461	200	NRR	SS	25	777-C252440-04-04-	CAB E ZONE FIRST ROW SEAT ARM	REST FOUND LOOSEN AT:59JK 59C 4H TTL:3EA	L546	WIP	10/05/2023
	CAB				01					1.5
									-	1.5
JL5479	200	NRR	ΑI	25	777-53-908-00-01	CABIN G2&G3 GALLERY TABLE SEA	LANT CHIPPED	L547	WIP	09/29/2023
	CAB									3.0
									-	3.0
JL5487	200	NRR	ΑI	5600	777-56-000-01-CX-01	COCKPIT L1&R1 WINDSHIELD MOIS	TURE SEAL FOUND WORN	L548	COMP	10/02/2023
	CAB									10.0
									-	10.0
JL5495	200	NRR	SS	25	777-C252000-01-07-	CAB B ZONE B/C SEAT BOTTOM CO	VER FOUND TORN TTL:1EA	L549	COMP	10/04/2023
	CAB				R-01					0.5
									-	0.5
(JL5503	100	NRW	AE	5336	SWC-28028-01-01	FUS-RAM AIR INLET ACTUATOR DO	OR PANEL 191LL 5EA STUDS HEAD WORN.	L550	WIP	10/05/2023
	FUS									3.0
									-	3.0
(JL5511	100	NRW	AE	5336	SWC-28028-01-01	FUS-RAM AIR INLET ACTUATOR DO	OR PANEL 191LR 4EA STUDS HEAD WORN.	L551	WIP	10/05/2023
	FUS									3.0
									-	3.0
JL5529	200	NRR	Al	25	777-53-920-00-01	M/D M LAV FAUCET FOUND WATER	LEAKING	L552	WIP	09/29/2023
	CAB									0.0
						1C 1 REPLACE LAV FAUC	ET			4.0
						1C 2 C/O LAV FAUCET W	ATER LEAK CHECK			0.5
									-	4.5
JL5537	200	NRP	AV	3351	777-33-115-00-02	FOUND L1,L4,R1,R2 DOOR EMERGE	NCY LIGHT LENS LOOSEN	L553	COMP	10/05/2023
	CAB									6.0
									-	6.0

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

CUST ENDORSE: ALL

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 77 OF 89

RUN DATE: 10/6/2023

40.0

RUN TIME : 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE:

ORIG-STAGE: ALL PERIOD: ALL

ORIGINATING CUST REF NO: ALL ATA NO: ALL

ZONE: ALL DISPOSITION CODE: ALL AREA: ALL STAGE: ALL

ESTIMATED MHR: ALL

CTRL CODE:

DEFECT TYPE: ALL

CAB

TYPE CODE: ORIGINATOR: ALL

TRADE: ALL

	ZONE	STG					· 		STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL5545	100 FUS	NRW	AE	5336	SWC-28028-01-01	FUS-RAM AIR INLET ACTUATOR DO	DR PANEL 191LR 2EA HINGE BONDINGS BROKEN.	L554	WIP	10/05/2023
	100					1C 1 REPLACE THE BOND	1110			0.0
						1C 1 REPLACE THE BOND 1C 2 DO THE BONDING TO				1.0 0.5
									-	1.5
JL5552	200	NRP	AV	3351	777-33-115-00-02	FOUND L3 DOOR NO 2 EMERGENCY	LIGHT DIM	L555	WIP	09/27/2023
	CAB									6.0
									-	6.0
JL5560	100	NRR	Al	5200	777-12-102-00-01	AFT CGO DOOR LINING SCREWS AN	ID SPACERS FOUND WORN	L556	OPEN	09/25/2023
	LWR									0.5
									-	0.5
JL5578	100	NRR	Al	3800	777-38-000-09-CX-01	BULK CGO AFT WASTE TANK RINSE	LINE WATER FILTER HOUSING FOUND BROKEN	L557	COMP	10/03/2023
	LWR									3.0
									-	3.0
L5586	200 CAB	NRR	Al	2500	777-53-912-00-01	CABIN DR3- DR4 LH PAX WINDOW D	UST COVER INTERIOR FND DIRTY	L558	COMP	10/02/2023
	CAB								_	34.0
									_	34.0
IL5594	200 CAB	NRR	Al	2500	777-53-912-00-01	CABIN DR3- DR4 RH PAX WINDOW D	UST COVER INTERIOR FND DIRTY	L559	COMP	10/02/2023
	CAD								_	34.0
										34.0
JL5602	200 CAB	NRR	Al	2500	777-53-916-00-01	CABIN DR4- DR5 LH PAX WINDOW D	UST COVER INTERIOR FND DIRTY	L560	COMP	10/02/2023
	O/ LD								_	40.0
										40.0
JL5610	200	NRR	ΑI	2500	777-53-916-00-01	CABIN DR4- DR5 RH PAX WINDOW D	UST COVER INTERIOR FND DIRTY	L561	COMP	10/02/2023

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 78 OF 89 RUN DATE: 10/6/2023

RUN TIME : 14:22

UPDATED DATE

REFERENCE NO: PROJECT: XJ

REQUESTED BY:

CUSTOMER: CX

A/C TYPE: 777

A/C REGN: B-KPV

CHECK TYPE: 2C

ESTIMATED MHR: ALL

JSN RANGE SELECTED: ALL ORIGINATING CUST REF NO: ALL

STATUS: ALL

ORIG-STAGE: ALL ATA NO: ALL

PERIOD: ALL ZONE: ALL

DISPOSITION CODE: ALL

DEFECT TYPE: ALL

ZONE STG

515653

BMS571R1-2

TRADE: ALL

CUST ENDORSE: ALL

AREA: ALL

STAGE: ALL

CTRL CODE:

TYPE CODE:

ORIGINATOR: ALL

STATUS

JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH	INO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL5628	200	NRR	Al	2500	777-53-916-00-01	CABIN DI	R4- DR5 L12, L17, L20, R9, PAX WIND	DOW DUST COVER FND SCRATCHED	L562	COMP	10/02/2023
	CAB										12.0
										-	12.0
(JL5636	100	NRR	SM	5200	777-52-190-00-01	FWD CG	O DOOR OPERATIONAL SWITCH AC	CESS DOOR SPRING FOUND BROKEN	L563	WIP	09/29/2023
	LWR										0.0
						1C 1	REMOVE BROKEN HINGE AT	T FASTENERS			4.0
						1C 2	REMOVE BROKEN HINGE AT	T SCREW			1.0
						1C 3	INSTALL NEW HINGE				8.0
						1C 4	TOUCH UP PAINT				0.5
						2C 5	REINSTALL NEW HINGE ATT	SCREW			1.0
										-	14.5
KJL5644	200	NRR	Al	2500	777-53-916-00-01	CABIN SI	DE BIN DR INTERIOR SURFACE AT 6	67A, 68H AND EXTERIOR SURFACE AT 67D, 68D FND DENT	L564	WIP	09/28/2023
	CAB										8.0
						1C 1	REPAIR SIDE BIN DOOR DEN	T AREA			8.0
						1C 2	PLEASE TOUCH UP PAINT				1.0
										-	17.0
KJL5651	100	NRR	SM	5200	777-52-195-00-01	AFT CGC	DOOR OPERATIONAL SWITCH ACC	ESS DOOR SPRING FOUND BROKEN	L565	WIP	09/29/2023
	LWR										0.0
						1C 1	REMOVE BROKEN HINGE AT	T FASTENERS			4.0
						1C 2	REMOVE BROKEN HINGE AT	T SCREW			1.0
						1C 3	INSTALL NEW HINGE				8.0
						1C 4	TOUCH UP PAINT				0.5
						2C 5	REINSTALL NEW HINGE ATT	SCREW			1.0
										-	14.5
(JL5669	200	NRR	Al	2500	777-53-912-00-01	CABIN A	FT ZONE O/H BIN SIDE TRIM FND CR	ACKED AT 40G FWD, 41G AFT, 41A FWD, 42D AFT AND 43D FWD & AFT.	L566	COMP	10/02/2023
	CAB										12.0
										-	12.0
(JL5677	200	NRR	SS	25	777-C252430-01-02-	D ZONE I	PEY SEAT PAN LOWER WIRE COVER	R FND MISSING AT:30F 33E	L567	OPEN	09/25/2023
	CAB				01						2.0
										-	2.0
											2.0

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 79 OF 89 RUN DATE: 10/6/2023

RUN TIME :

14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL

PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO:

ALL

ATA NO: ALL

ZONE: ALL AREA: ALL

DISPOSITION CODE: ALL

CTRL CODE:

DEFECT TYPE: ALL

TRADE: ALL TYPE CODE:

CUST ENDORSE: ALL ORIGINATOR: ALL

STAGE: ALL

STATUS UPDATED DATE

	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL5685	300 EMP	NRR	AV	5500	777-55-828-01-01	DISCONNECT AND CONNECT TH CAMERA	E ELECTRICAL CONNECTOR FROM LEFT AND RIGHT SIDE H/STABILIZER L/E TAXI	L568	WIP	09/26/2023
						1C 1 DISCONNECT TH	E CONNECTOR FROM THE LEFT AND RIGHT SIDE CAMERA			0.0
						1C 2 CONNECT THE C	ONNECTOR FROM THE LEFT AND RIGHT SIDE CAMERA			0.0
						2C 3 C/O MAIN GEAR	CAMERA INSTALLATION TEST			0.0
									-	2.0
XJL5693	100 FUS	NRR	AE	5346	777-53-844-00-01	FUS-KEEL BEAM PANEL149C 2E/	A BLOCKS MISSING.	L569	COMP	10/04/2023
	FU5									1.0
									-	1.0
XJL5701	100	NRR	SM	5300	777-53-818-00-01	FWD CGO R/H STA825 CEILING S	SUPPORT ANCHOR NUT FOUND DAMAGED	L570	COMP	10/03/2023
	LWR									1.0
									-	1.0
XJL5719	300	NRR	AE	5300	777-53-880-00-01	FORWARD WIN TO BODY FAIRIN	G 191GL 191JL 191KL 191PL 191RL TOTAL 200EA SCREWS HEAD WORN	L571	OPEN	09/26/2023
	EMP									0.5
									-	0.5
XJL5727	300	NRP	AV	2361	777-55-806-00-01	VERTICAL FIN TOP #2 STATIC DI	SCHARGER BROKEN.	L572	OPEN	09/26/2023
	EMP									1.0
									-	1.0
XJL5735	300	NRP	AV	2361	777-55-806-00-01	VERTICAL FIN AFT ALL 6 EA STA	TIC DISCHARGER BROKEN.	L573	OPEN	09/26/2023
	EMP									6.0
									-	6.0
XJL5743	200	NRR	SS	25	777-C252430-01-07-	PEY PAX SEAT BACK REST RECI	INE CABLE OPERATION FOUND TIGHTEN AT:33F 32G 31G 34H TOTAL:4EA	L574	COMP	10/04/2023
	CAB				01					2.0
									-	2.0
XJL5750	200	NRM	AV	3531	AEO-29573-01		TLE NEAR EXPIRY DATE AT LAV B, STOWAGE E3R LOWER, G4 DOGHOUSE UPPER,	L575	OPEN	09/26/2023
	CAB					G4 DOGHOUSE LOWER, 72G DOG	SHOUS MIDDLE, TOTAL 5EA			9.0
									-	9.0

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

DEFECT TYPE: ALL

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

AREA: ALL

PAGE: 80 OF 89

STAGE: ALL

RUN DATE: 10/6/2023

0.0

RUN TIME : 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

CUST ENDORSE: ALL

CTPL CODE : TYPE CODE : OPIGINATOR : ALL

TRADE: ALL

CTRL CODE:					TYPE CODE:	ORIGINATOR: ALL			
	ZONE	STG						STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL5768	200	NRR	Al	2560	777-53-904-00-01	CABIN R2 DOOR AREA BESIDE THE ATTENDANT SEAT FOUND FLASHLIGHT(UTILITY) FOUND DAMAGE	L576	COMP	10/04/2023
	CAB								1.0
								-	1.0
XJL5776	200	NRR	Al	2560	777-53-904-00-01	CABIN R5 DOOR AREA INSIDE THE ATTENDANT SEAT FOUND FLASHLIGHT(DME) FOUND LOW POWER	L577	COMP	09/28/2023
7.0207.70	CAB			2000	66 66 66 6	S. B. ITTO DOGITAL DE TILE TO LES TE TO LES TE TO LES TE TO TE CONTROLLE TO THE CONTROLLE T	LSTT	COME	1.0
								-	
									1.0
XJL5784	100	NRR	AE	5200	777-53-800-00-07	EXTERNAL ELECTRICAL POWER RECEPTACLE ACCESS DOOR MISS ALIGNMENT WITH FUSELAGE SKIN	L578	WIP	10/03/2023
	FUS								0.0
						1C 1 REMOVE EXTERNAL POWER DOOR			2.0
						1C 2 REMOVE EXTERNAL POWER DOOR HINGE H-LOCK			2.0
						1C 3 REPLACE EXTERNAL POWER DOOR HINGE			2.0
						1C 4 INSTALL EXTERNAL POWER DOOR HINGE H-LOCK			2.0
						2C 5 INSTALL EXTERNAL POWER DOOR			2.0
						2C 6 PERFORM EXTERNAL POWER SUPPLY DOOR INSTALLATION TEST			1.0
								-	11.0
XJL5792	100	NRR	AE	5200	777-53-800-00-07	EXTERNAL ELECTRICAL POWER RECEPTACLE ACCESS DOOR 1EA BONDING JUMPER WIRES FOUND BROKEN	L579	WIP	10/03/2023
	FUS								0.0
						1C 1 REPLACE THE BONDING.			1.0
						1C 2 DO THE BONDING TEST.			0.5
								-	4.5
									1.5
XJL5800	100 FUS	NRR	AE	2900	777-53-844-00-01	AFT KEEL BEAM ACCESS PANEL 149CL INNER CAVITY FOUND CENTER HYD RESERVOIR DRAIN HOSE TORN	L580	COMP	10/04/2023
	FUS								1.0
								-	1.0
XJL5818	200	NRR	CL	5300	777-53-546-01-01	BOTH LEFT AND RIGHT SIDE OVERWING TO BODY FAIRING INNER CAVITY DIRTY	L581	WIP	09/29/2023
	FUS								10.0
								-	
									10.0
XJL5826	200	NRR	CL	2501	777-53-908-00-01	CAB-FB2 SEAT BACK SHELL BOTTLE CONSOLE RED FABRIC TRIM FOUND DIRTY 11A 12A 16A 17A 19A 20A 21A 23A 22A 26A 16D 17D 11D 12D 20D 21D 22D 24D 25D 26D 11G 16G 20G 23G 24G 25G 18K 20K 23K 25K 17K	L582	OPEN	09/26/2023
	CAB					22A 20A 10D 11D 12D 20D 21D 22D 24D 20D 21D 10D 10D 20D 20D 20D 20D 10N 20N 20N 11N			0.0
								-	

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 81 OF 89 RUN DATE: 10/6/2023

RUN TIME : 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

> ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL5834	200	NRR	ΑE	5300	777-53-546-01-01	APPLY CIC TO BOTH LEFT AND RIG	HT SIDE OVERWING TO BODY FAIRING INNER CAVITY AFTER CLEANING	L583	OPEN	09/26/2023
	FUS									3.0
									-	3.0
XJL5842	100	NRR	SM	5300	777-53-800-00-10	FWD CARGO BILGE AREA BSTA100	0 LEFT SIDE FRAME FOUND ELECTRICAL WIRE 1EA STANDOFF BROKEN	L584	COMP	10/03/2023
	LWR									1.0
									-	1.0
XJL5859	200	NRR	Al	25	777-53-920-00-01	M/D M LAV TOILET SHROUD COVER	R FOUND CRACKED	L585	COMP	10/02/2023
	CAB									2.0
									-	2.0
XJL5867	400	NRP	SM	5400	777-900001-01-1-01	#2 PYI ON AFT FAIRING I/B FWD & A	AFT ACC DOOR LOWER 2EA LATCHES SPRING BROKEN.	L586	WIP	10/04/2023
	ENG					#21 120111 117 m m m 0 #2 1 112 w /		2300	VVII	0.0
						1C 1 REMOVE BROKEN I	ATCH			4.0
						1C 2 INSTALL NEW LATO	H			4.0
						1C 3 TOUCH UP PAINT			_	1.0
										9.0
XJL5875	400 ENG	NRP	AE	7100	777-900001-01-1-01	#1 ENG FAN COWL 3EA HOIST PLU	GS FND BROKEN.	L587	OPEN	09/26/2023
	ENG									2.0
									-	2.0
XJL5883	400	NRP	AE	7100	777-900001-01-1-01	#2 ENG FAN COWL 2EA HOIST PLU	GS FND BROKEN.	L588	OPEN	09/26/2023
	ENG									1.0
									-	1.0
XJL5891	200	NRR	Al	2500	777-53-912-00-01	CABIN DOOR 3 FWD CENTER PART	ITION AFTER SIDE KICK STRIP FOUND DETACHED	L589	COMP	09/30/2023
	CAB									2.0
									-	2.0
XJL5909	400	NRP	ΑE	7500	777-900001-01-1-01	#2 ENG TURBINE COOLING DUCT 5	EA CLAMP RETAININGS FND WORN.	L590	OPEN	09/26/2023
	ENG									8.0
									-	8.0

REQUESTED BY:

PROJECT: XJ

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 82 OF 89 RUN DATE: 10/6/2023

RUN TIME : 14:22

REFERENCE NO: BMS571R1-2

515653

CUSTOMER: CX A/C TYPE: 777

STATUS: ALL

A/C REGN: B-KPV ORIG-STAGE: ALL

CHECK TYPE: 2C

ESTIMATED MHR: ALL

STAGE: ALL

JSN RANGE SELECTED: ALL ORIGINATING CUST REF NO: ALL

ATA NO: ALL

DISPOSITION CODE: ALL

DEFECT TYPE: ALL

TRADE: ALL

CUST ENDORSE: ALL AREA: ALL

PERIOD: ALL

ZONE: ALL

TRL CODE	ZONE AREA	STG	TD	ATA	TYPE CODE: ORIG CUST REF NO.	ORIGINATOR: ALL CTRL SH NO DEFECT DESCRIPTION	JSN	STATUS STATUS	UPDATED DATE
JL5917	400	NRP	AE	8000	777-900001-01-1-01	#1 ENG STARTER DUCT 6 O'CLOCK 1EA SUPPORT ROD FND WORN	L591	OPEN	09/26/2023
	ENG								2.0
								-	2.0
JL5925	300	NRR	CL	5300	777-55-800-00-01	HORIZONTAL STABILIZER JACKSCREW COMPARTMENT BSTA2174 TO BSTA2412 BILGE AREA DIRTY	L592	WIP	10/04/2023
	EMP						2002	****	15.0
								-	15.0
L5933	300	NRR	ΑE	5300	777-55-800-00-01	APPLY CIC TO HORIZONTAL STABILIZER JACKSCREW COMPARTMENT BSTA2174 TO BSTA2412 BILGE AREA	1.502	WID	
_0900	EMP	MIXIX	AL	3300	777-33-800-00-01	AFFLE DIG TO FIGNIZUNTAL STABILIZER JAGNOGNEW COMFANTIMENT BSTAZ174 TO BSTAZ41Z BILGE AREA	L593	WIP	10/05/2023
								-	3.0
									3.0
L5941	400 ENG	NRP	AE	7100	777-900001-01-1-01	#1 ENG RH FAN COWL ACTUATOR NIPPLE FND LEAKAGE.	L594	OPEN	09/26/2023
	LINO							_	3.0
									3.0
L5958	200	NRR	AV	2502	777-25-040-03-CX-01 -01	EMA TEST FOUND 19D EMA INTERFACE CABLE ASSEMBLY INOP	L595	WIP	10/02/2023
	CAB				-01				3.0
								-	3.0
L5966	200	NRR	Al	2500	777-53-916-00-01	CABIN SIDE BIN DR INTERIOR SURFACE AT 43H AND 44H FND DENT	L596	WIP	09/28/2023
	CAB								4.0
						1C 1 REPAIR SIDE BIN DOOR DENT AREA 1C 2 PLEASE TOUCH UP PAINT			4.0 1.0
						1C 2 PLEASE TOUCH UP PAINT		-	
1.5074	000	NDD	A) /	0500	777 OF 040 00 OV 04	NARPESTICAL FILL FOLLAR ALCOSES TEST BLANK BLAS MISSING			9.0
L5974	200 CAB	NRR	AV	2502	777-25-040-03-CX-01 -01	INSPECTION EMA FOUND 11G.25G TEST BLANK PLUG MISSING	L597	WIP	10/02/2023
	0,10							_	1.0
									1.0
_5982	200 CAB	NRP	AV	3531	777-35-160-01-CX-01	LAV B 2EA SPARE PORTABLE OXYGEN MASK NEAR EXPIRY DATE	L598	OPEN	09/26/2023
	CAB								2.0
								-	2.0

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 83 OF 89

RUN TIME :

RUN DATE: 10/6/2023

LIDDATED DATE

14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL

ATA NO: ALL

PERIOD: ALL

ESTIMATED MHR: ALL DISPOSITION CODE: ALL

ORIGINATING CUST REF NO:

ALL DEFECT TYPE: ALL

TRADE: ALL

CUST ENDORSE: ALL

ZONE: ALL AREA: ALL

STAGE: ALL

0747110

CTRL CODE:

TYPE CODE:

OPIGINATOR: ALL

ORIGINAL	UK.	ALL

	ZONE	STG						STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL5990	200	NRR	CL	2527		M/D #1DOOR TO #3DOOR REMOVED AISLE CARPETS AREA FLOOR PNL UPPER SURFACE FND DIRTY	L599	COMP	09/28/2023
	CAB								32.0
								-	32.0
XJL6006	300	NRR	SM	5300	777-53-924-00-01	TAIL CONE FUSELAGE EXTERNAL SKIN BSTA2390 TO BSTA2412 STR1L TO STR2L FOUND 1EA DENT MARK	L600	WIP	10/02/2023
	EMP								0.0
						1C 1 CARRY OUT CRACK FREE CHECK			1.0
						2C 2 PLS CARRY OUT REPAIR INSTRUCTION AS PER RS-34790 REV 00			0.0
								-	1.0
XJL6014	700	NRR	AE	3222	777-32-802-00-01	L/G-NLG RH AFT DOOR OPERATIONAL ROD GEAR SIDE ATTACHED BOLT 1EA GREASE NIPPLE MISSING.	L601	COMP	10/05/2023
	LDG								1.0
								-	1.0
XJL6022	300 EMD	NRR	SM	5300	777-53-924-00-01	TAIL CONE FUSELAGE EXTERNAL SKIN BSTA2390 TO BSTA2412 STR2L TO STR3L FOUND 1EA SCRATCH MARK	L602	WIP	09/28/2023
	EMP								0.0
						1C 1 REMOVE THE SCRATCH DAMAGE			2.0
						1C 2 APPLY A CHEMICAL CONVERSION COATING			0.5
						1C 3 ASSESS THE REWORK AREA			1.0
						1C 4 APPLY 1 LAY OF BMS 10-79, TYPE III PRIMER TO THE SURFACE 2C 5 CARRY OUT THICKNESS CHECK			1.0 1.0
						2C 6 CARRY OUT CRACK FREE CHECK			1.0
						3C 7 PLS CARRY OUT REPAIR INSTRUCTION AS PER RS-34790 REV 00			0.0
						T LEG START GOT RELYMENTAGE ENTRO GAT 30 NEV 00		-	6.5
XJL6030	700	NRR	ΑE	3245	777-53-810-00-01	L/G-NLG LH SPIN BRAKE METAL PLATE CRACKED.	L603	COMP	10/05/2023
7.02000	LDG		712	0210	777 00 010 00 01	BO NEO EITO IN DIVINE METAET BYTE ON WINED.	L003	COIVIE	4.0
								-	
XJL6048	300	NRR	SM	5500	777-55-820-00-01	VERTICAL STABILIZER T/E ACCESS PANEL 324DXL FOUND 5EA ANCHOR NUTS BROKEN	L604	COMP	4.0 10/04/2023
700000	EMP	MAC	OW	0000	777-30-020-01	VERTICAL GRADIEIZER TIZ ACCESST ANEL 3245/LT CONS SEA ANGITOR NOTS BROKEN	L004	COMP	2.0
								-	2.0
XJL6055	300	NRR	ΑE	5500	777-55-820-00-01	VERTICAL STABILIZER T/E ACCESS PANEL 324DXL 324AL AND 324GK TOTAL 200EA SCREW HEAD WORN	L605	OPEN	09/26/2023
	EMP	11111	,	0000	00 020 00 01	VERTICAL OF BELLET THE ACCESS FAMILE OF BALL OF THE OFFICE TO THE FOUND TO THE TOTAL OF THE TOTAL OF THE OFFICE OFFICE OF THE OFFICE OFFICE OFFICE OFFICE OFFICE OFFICE OFFICE OFFICE OF	LUUS	OFEN	
								_	0.0
									0.0

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

DEFECT TYPE: ALL

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

AREA: ALL

84 OF 89 PAGE:

STAGE: ALL

RUN DATE: 10/6/2023

5.0

RUN TIME : 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL ALL CUST ENDORSE: ALL

TRADE: ALL CTRL CODE: TYPE CODE: ORIGINATOR: ALL

TRL CODE :					TYPE CODE:	ORIGINATOR	: ALL			
IOD NO	ZONE	STG	TD	ATA	ODIC CUCT DEE NO	CTRL SH NO	DEFECT DESCRIPTION	ICNI	STATUS	UPDATED DATE
JL6063	AREA	NRR	Al	ATA	ORIG CUST REF NO.		DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
JL6063	200 CAB	NKK	AI	1100	777-11-000-01-CX-R- 01	CABIN LAV WATER HEATER ACC P	NL INSIDE FND PLACARDS MISSING AT LAV A(1EA) AND LAV B(2EA)	L606	OPEN	09/26/2023
									_	3.0
										3.0
L6071	300 EMP	NRR	CL	5300	777-53-880-00-01	PLEASE CLEAN BODY FAIRING BAG	CK SIDE SURFACE	L607	WIP	10/04/2023
	LIVII								_	10.0
										10.0
_6089	100 LWR	NRR	SS	2500	777-53-862-00-01	AFT CARGO BILGE AREA INSULATI	ON BLANKET FOUND BROKEN AT STA 1434+21 TO STA 1434+42 R/H	L608	WIP	10/06/2023
	LVVIX								_	5.0
									_	5.0
.6097	100 LWR	NRR	SS	2500	777-53-862-00-01	AFT CARGO BILGE AREA INSULATI	ON BLANKET FOUND BROKEN AT STA 1434+42 TO STA 1434+63 R/H	L609	WIP	10/06/2023
	LVVK									5.0
									-	5.0
.6105	100	NRR	SS	2500	777-53-862-00-01	AFT CARGO BILGE AREA INSULATI	ON BLANKET FOUND BROKEN AT STA 1434+84 TO STA 1434+105 R/H	L610	WIP	10/05/2023
	LWR									5.0
									-	5.0
6113	100	NRR	SS	2500	777-53-862-00-01	AFT CARGO BILGE AREA INSULATI	ON BLANKET FOUND BROKEN AT STA 1434+168 TO STA 14+189 R/H	L611	WIP	10/04/2023
	LWR									5.0
									-	5.0
6121	100	NRR	SS	2500	777-53-862-00-01	AFT CARGO BILGE AREA CENTER A	AND L/H INSULATION BLANKET FOUND BROKEN AT STA 1643 TO STA 1664.TOTAL	L612	OPEN	09/26/2023
	LWR					ZEA				10.0
									-	10.0
6139	100	NRR	SS	2500	777-53-862-00-01	AFT CARGO BILGE AREA R/H AND	JH INSULATION BLANKET FOUND BROKEN AT STA 1685 TO STA 1706.TOTAL 2EA	L613	OPEN	09/26/2023
	LWR									10.0
									-	10.0
6147	100	NRR	SS	2500	777-53-862-00-01	AFT CARGO BILGE AREA INSULATI	ON BLANKET FOUND BROKEN AT STA 1748 TO STA 1769 R/H	L614	WIP	10/03/2023
	LWR									5.0
									-	

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

AREA: ALL

STAGE: ALL

PAGE: 85 OF 89

RUN DATE: 10/6/2023

RUN TIME : 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL CTRL CODE: ORIGINATOR: ALL

CTRL CODE.	ZONE	STG			TIFE CODE.	ONGINATOR: A	-L		STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL6154	100	NRR	SS	2500	777-53-862-00-01	AFT CARGO BILGE AREA INSULATION BLA	NKET FOUND BROKEN AT STA 1853 TO STA 1874 R/H	L615	WIP	10/04/2023
	LWR									5.0
									-	5.0
XJL6162	700	NRR	AE	3245	777-32-810-02-01	L/G-RH MLG NO.8 FOUND DEEP CUT.		L616	OPEN	09/27/2023
	LDG									0.0
									-	0.0
XJL6170	400	NRP	AE	2911	777-29-000-02-CX-01	LH HYD COMPARTMENT 5EA DIFFERENT F	RESSURE INDICATOR COVERS AGED.	L617	COMP	10/03/2023
	FUS									3.0
									-	3.0
XJL6188	400	NRP	ΑE	2911	777-29-000-02-CX-01	RH HYD COMPARTMENT 5EA DIFFERENT F	PRESSURE INDICATOR COVERS AGED.	L618	COMP	10/03/2023
	FUS									3.0
									-	3.0
XJL6196	400	NRP	AE	2911	777-29-000-02-CX-01	CTR HYD SYS 10EA DIFFERENT PRESSUR	E INDICATOR COVERS AGED.	L619	COMP	10/03/2023
	FUS									4.0
									-	4.0
XJL6204	700	NRR	ΑE	3211	777-32-300-00-01	L/G-LH MLG DRAG BRACE LOCK LINK ASS	TOGGLE 3EA GREASE NIPPLES MISSING.	L620	COMP	10/05/2023
	LDG									3.0
									-	3.0
XJL6212	500	NRP	ΑE	5700	777-900001-01-1-01	L & R WING UPPER PANEL (#6~9 SPOILER	FWD) SEALANT FOUND MISSING & POOR CONDITION	L621	COMP	09/28/2023
	WNG									3.0
									-	3.0
XJL6220	100	NRR	ΑE	5300	777-53-804-00-01	NOSE RADOME PRESSURE BULKHEAD LE	T SIDE BULB SEAL TORN	L622	COMP	10/05/2023
	FUS									2.0
									-	2.0
XJL6238	400	NRP	AE	7800	777-24-030-00-01	#2 ENG LH TR COWL 9 O'CLOCK FWD SEA	ASSY FND CRACKED.	L623	OPEN	09/27/2023
	ENG									4.0
									-	4.0
										0

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 86 OF 89

RUN DATE: 10/6/2023

0.0

RUN TIME : 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL

PERIOD: ALL

AREA: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL

ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL CTRL CODE :

TRADE: ALL

CUST ENDORSE: ALL

STAGE: ALL

52. 20	,	_				7.1.2.1.7.2.2									
CTRL CODE	:				TYPE CODE:	ORIGINATOR: ALL									
	ZONE	STG						STATUS	UPDATED DATE						
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION	JSN	STATUS	EST Mhr						
XJL6246	400	NRP	AE	5400	777-24-030-00-01	#1 PYLON AFT CAVITY WATER LEVELING COMPOUND FND LOOSEN.	L624	WIP	10/06/2023						
	ENG								4.0						
								-							
									4.0						
XJL6253	400	NRP	AE	5400	777-24-030-00-01	#2 PYLON AFT CAVITY WATER LEVELING COMPOUND FND LOOSEN.	L625	WIP	10/06/2023						
	ENG								4.0						
								-	4.0						
XJL6261	100	CUS	AV	25		AS PER MST FINDING REPORT (2023/9/29) ITEM 1: BOTH FWD & AFT CARGO HANDLEING CONTROL PANEL CONTROL	L626	OPEN	09/29/2023						
7020201	LWR	000	, Av	23	20	5	20	20	20			SWITCHS JAM NUT FOUND WHITE POWDER DOPOSITE, PLEASE CLEAN UP AND RECTIFY IF NECESSARY!	L020	OPEN	
													0.0		
								-	0.0						
XJL6279	800	CUS	AV	52		AS PER MST FINDING REPORT (2023/9/29) ITEM 2: BOTH FWD & AFT CARGO DOOR CONTROL PANEL CONTROL	L627	OPEN	09/29/2023						
	LWR					SWITCH & INDICATOR LIGHT HOUSING FOUND WHITE POWDER DEPOSITE, PLEASE CLEAN IT AND RECTIFY IF			0.0						
						NECESSARY!									
									0.0						
XJL6287	100	CUS	Al	52		AS PER MST FINDING REPORT (2023/9/29) ITEM 3: AFT LAVATORY SERVICE PANEL FOUND MINOR CORROSION	L628	WIP	10/01/2023						
	LWR					UNDER THE HINHE AREA, PLEASE CLEAN UP AND RECTIFY!			9.5						
						1C 1 REMOVE THE CORROSION			2.0						
						1C 2 APPLY A CHEMICAL CONVERSION COATING			0.5						
						1C 3 CARRY OUT THICKNESS CHECK			1.0						
						1C 4 CARRY OUT CRACK FREE CHECK			1.0						
						2C 5 REMOVE THE PANEL 2C 6 INSTALL THE PANEL			2.0 2.0						
						2C 0 INSTALL THE PAINEL		_							
									18.0						
XJL6295	100	CUS	AE	36		AS PER MST FINDING REPORT (2023/9/29) ITEM 4: AFT ADP BLEED AIR DUCT FIT THROUGHT FROM AFT CARGO	L629	OPEN	09/29/2023						
	FUS					COMPARTMENT FOUND LEAKAGE EVIDENCE MARKS (DARK DEPOSITE), PLEASE INVESTIGATION AND CONDITION CHECK!			0.0						
						OTEON:		-							
									0.0						
XJL6303	800	CUS	JS PT	PT 36		AS PER MST FINDING REPORT (2023/9/29) ITEM 5: ALL MED DOOR HANDLE STOWAGE CAVITIES FOUND PAINT	L630	OPEN	09/29/2023						
	LWR						CHIPPED DUE PAINT STRIPPING PROCESSES, PLEASE CLEAN UP THAN TOUCH UP BEFORE FLIGHT!			0.0					
								_							

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 87 OF 89

RUN DATE : 10/6/2023 RUN TIME : 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE:

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL

ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

2C

ESTIMATED MHR: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

TRL CODE :					TYPE CODE:	ORIGINATOR:	ALL		CTATUC	LIDDATED DATE		
		STG							STATUS	UPDATED DATE		
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr		
JL6311	400 ENG	CUS	AE	29			9/29) ITEM 6: #1 ENGINE HYRDAULIC LINES FROM PYLON TO ENGINE SLEEVE EASE CLEAN IT THAN LEAK CHECK ALL RELATED LINES CONNECTION!	L631	L631 OPEN	09/29/2023		
						1C 1 CLEAN THE SUBJECT	AREA			3.0		
						1C 2 C/O LEAK CHK				1.0		
									-	4.0		
JL6329	700	CUS	PT	29		•	(9/29) ITEM 8: NLG LOWER CYLINDER FRONT FACE WARNING STENCIL FOUND	L632	OPEN	09/29/2023		
	LDG					FADED, PLEASE RE-APPLY STENCIL I	AVV AMM!			0.0		
									-	0.0		
IL6337	700	CUS	ΑE	12		•	9/29) ITEM 9: BOTH LH AND RH MLG WHEEL WELL FWD ZONE FOUND BOTH	L633	OPEN	09/29/2023		
	LDG								AR & SPOLIER CONTROL CABLES CONTAMATED WITH YELLOW DUST DUE LONG TERM PARKING, AN IT THAN SERVICING THOSE RELATED CABLES!			0.0
						TELNOL OLLAWTI TIINWOLIWOT	HOOL NEETHED OF BEEC.		-	0.0		
JL6345	500	CUS	ΑE	27		AS PER MST FINDING REPORT (2023)	9/29) ITEM 10: LH WING O/B FLAP I/B ATTACH FITTING FOUND SHIM PLATE	L634	OPEN	0.0		
	WNG						S AREA, PLEASE INVESTIGATION AND RECTIFY IAW AMM!	2004	OI LIV	0.0		
									-	0.0		
JL6352	600	NRR	GW	57	777-28-031-40-02	RHW UPPER ACCESS PANEL661JT S	CDEIMO FOLIND CEIZED	1.005	00110			
JL0332	WNG	INIXIX	GW	31	777-20-031-40-02	KNW UPPER ACCESS PANEL001J1 SI	CKEWS FOUND SEIZED	L635	COMP	10/04/2023		
	******									1.0		
									-	1.0		
JL6360	600	NRR	SM	57	777-28-031-40-02	RHW UPPER ACCESS PANEL661JT AI	NCHOR NUT FOUND WORN	L636	WIP	10/04/2023		
	WNG									1.0		
									-	1.0		
JL6378	200	LOG	Al	52		PLEASE RESTORATION-PAX ENTRY [DOORS ESCAPE SLIDE/RAFTS MISSING.	L637	COMP	10/04/2023		
	CAB									0.0		
						1C 1 REMOVE THE COVER	FROM THE FLOOR PROXIMITY ESCAPE PATH MARKING SYS LIGHTS			2.0		
						1C 2 REMOVE THE COVER	FROM THE EMERGENCY EXIT SIGN			2.0		
						1C 3 REMOVE THE INOPER	RATION PLACARDS FROM DOORS			1.0		
									-	5.0		
IL6386	200	NRR	SS	25	777-C252000-01-06-	A ZONE FIRST CLASS PAX SEAT BAC	KREST COVER FND DIRTY TTL:1EA	L638	OPEN	10/03/2023		
	CAB				R-02					1.0		
									-	1.0		

DISTRIBUTION: 0PPC REQUESTED BY: 515653

ALL

BMS571R1-2

REFERENCE NO:

ORIGINATING CUST REF NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 88 OF 89 RUN DATE: 10/6/2023

RUN TIME : 14:22

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL

> ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

CHECK TYPE:

2C

ESTIMATED MHR: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE : TYPE CODE: ORIGINATOR ·

CIRL CODE:					TYPE CODE:	ORIGINATOR:	ALL			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL6394	200	NRP	Al	25	777-900003-01-1-01	M/D L/R 3 DOOR LOWER LINING 6EA A	TTACH STUD FOUND DETACHED	L639	WIP	10/05/2023
	CAB									3.0
									-	3.0
XJL6402	200	NRP	AV	3351	777-33-060-01-CX-01	RESTORE THE EMERGENCY LIGHT AT	G3 GALLERY FOUND 2EA PROXIMITY FLOOR PATH LIGHT CRACK	L640	WIP	10/05/2023
	CAB									2.0
									-	2.0
XJL6410	500	NRR	ΑE	2800	TA28000101	PERFORM BOTH FUEL TANK ACCESS	DOORS LEAK CHECK	L641	OPEN	10/05/2023
	F/T									4.0
									-	4.0
XJL6428	200	NRR	AV	3327	777-C330000-01-02-	RESTORE THE GALLERY LIGHT LEN FO	OUND 4EA RINGS&STUDS ARE MISSING AT FWD GALLERY	L642	OPEN	10/05/2023
	CAB				01					2.0
									-	2.0
XJL6436	200	NRP	ΑI	2531	777-900003-01-1-01	CABIN G7 GALLERY COFFEE MAKER 9	INSTALLATION LOCK FASTENER HOLE FOUND DAMAGE	L643	OPEN	10/06/2023
	CAB									2.0
									-	2.0

DISTRIBUTION: 0PPC TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD. PAGE: 89 OF 89 REQUESTED BY: 515653 NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

RUN DATE: 10/6/2023 RUN TIME: 14:22

5,318.2

Total Mhr:

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

> ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

TYPE CODE: CTRL CODE: ORIGINATOR: ALL

STATUS UPDATED DATE ZONE STG

JOB NO AREA TD ATA ORIG CUST REF NO. CTRL SH NO DEFECT DESCRIPTION JSN **STATUS** EST Mhr

TOTAL NO OF NRC PRINTED: 643

Jobs OPEN: 131 Jobs READY: 0 232 Jobs WIP: Jobs HOLD: 0 Jobs CANC: 0 Jobs DEFER: 0

280

Jobs COMP:

REFERENCE NO:

ORIGINATING CUST REF NO:

BMS571R1-2

ALL

I CERTIFY THAT I HAVE CHECKED THAT ALL THE ABOVE REFERENCED CARDS HAVE BEEN CERTIFIED AS HAVING BEEN COMPLETED.

PLANNING ENGINEER _____ DATE ____

CERTIFYING STAFF _____ DATE _____

STAMP AND SIGNATURE