

# DWM3001CDK SDK 0.1.1 Release Notes

## **Change Log**

Initial release

#### **Main Features**

Target supported: DWM3001CDK

• Content of the DWM3001C module: Nordic® nRF52833 BLE SoC + Qorvo® DW3110 UWB transceiver

UWB Stack Version: R11.9.2

• Driver version: 6.0.14

• FiRa Ranging (TWR and 2D AoA)

#### **Known issues**

- 1. FiRa CLI & UCI builds: Default radiation power value on Ch5 exceeds FCC limits.
- 2. FiRa CLI build: Starting and stoping FiRa ranging application will crash after a number of cycles.

If a user sends command INITF, STOP, INITF, STOP,... more than 100 times, the device will crash. The issue is identified and will be fixed in a future release.

3. FiRa - CLI build: Starting a FiRa session with invalid parameters leads to a software hang.

Starting a FiRa session using INITF/RESPF with invalid parameters will make the software irresponsive and the target needs to be reset. The issue will be fixed in a future release.

4. FiRa - CLI build : LFoM is not implemented.

Reporting LFoM (estimation of local AoA reliability) is not yet supported. It will be implemented in a future release.

- 5. FiRa CLI build: Using STAT or DECA\$ commands during a ranging session as an initiator interrupts the ranging.
- 6. FiRa UCI build: RSSI is not implemented.

Reporting RSSI (received signal strength indicator) is not yet supported. It will be implemented in a future release.

© 2022 Qorvo US, Inc. Qorvo® Proprietary Information



7. FiRa - UCI build: Calibration not implemented. It will be implemented in a future release.

### Release folder structure

- Binaries - DWM3001CDK-DW3_QM33_SDK_CLI-FreeRTOS_0_1_1.hex - DWM3001CDK-DW3_QM33_SDK_UCI-FreeRTOS_0_1_1.hex	
├─ Doc	
<ul> <li>DWM3001CDK_SDK_Developer_Guide_0.1.1.pdf</li> <li>DWM3001CDK_SDK_Release_Notes_0.1.1.pdf</li> <li>DW3xxx_Driver_API_Guide_6.0.14.pdf</li> <li>uwb-stack-R11.9.2.pdf</li> </ul>	
└─ Sources	
UMM3001CDK-FreeRTOS_DW3_QM33_SDK_0_1_1.zip	

© 2022 Qorvo US, Inc. Qorvo® Proprietary Information