

Accident Report

SEN/2017/S115-001

Form: S115

Version # : V001

Vessel Name: MT STRATEGIC ENTITY Exported By/ On:

Name Of Port: Barranquilla Position: (Lat) 11 02 N (Long) 074 49 W

Report Date: 09-Sep-2017 Date & Time of Incident (LT): 30-Aug-2017 9:00 pm

Section 1 : Severity & Classification

Severity of Accident Major

Classification of Accident Damage to Property

Section 2 : Event Description

DURING THE BERTHING MANEUVER AT MONOEMRES BERTH BY STARBOARD SIDE ASSISTED BY PILOT ALEJANDRO HENAO AND TUGS CAUCA AND ODIN IT WAS FOUND THAT THE VESSEL STERN AND PARALLEL BODY NOT COMING ALONGSIDE.THEN VESSEL MADE FAST WITH MOORING ROPES AND WITHOUT FURTHER FORCE VESSEL WAS ABOUT 1.3 TO 2.5 MTRS AWAY FROM JETTY TO VESSEL PARALLEL BODY. SOUNDINGS WERE TAKEN TO CONFIRM VESSEL TOUCHING BOTTOM AND WAS FOUND THAT THE DEPTHS ALONGSIDE STARBOARD SIDE WERE LESS THAN THE DRAFTS.VESSEL DRAFT WERE 6.80 M/7.10 M.MINIMUM DEPTH ALONGSIDE WAS FOUND 4.40M.TIDAL RANGE 0.1 M TO 0.40 M.TIDAL HEIGHT AT THE TIME OF INCIDENT 0.20 M.

Section 3: General Information

A. Alcohol & Drug testing carried out post incident?	Yes
B. Vessel Activity at time of accident ?	In Port
C. Was the Vessel Delayed ?	Manoeuvring Yes
D. Bad Weather ?	No
E. Restricted Visibility ?	No
F. Has there been a breach of Company's Policy and Regulations?	No

Section 4: Injury to personnel

	Name C	rew#	Rank	SignOn Dt. / Hrs	OCIMF Reporting
1	Medical Treatment Case (MTC)=FAC + LV	VC + RWC	:	0	
- 1	Lost Time Injury (LTI) =Fatalities + PTD +	PPD + LW	:	0	
-	Total Recordable Cases (TRC) =LTI + RW	C + MTC	:	0	

Section 5 : Cargo Cargo Contamination / Damage ? A. Name of Charterer B. Type of Cargo C. Tank / Hold Number(s) D. Tank Coating E. Load Port(s) F. Discharge Port(s) I. Cargo Quantity J. Tanks / holds inspected prior loading K. Wall wash test done?

Section 6 : Navigation

Section 7 : Environmental Pollution				
Is there loss to environment ?				
Incident First Observerd :				
Ceased Operations :				
Reported to any authority :				
Date & Time :				
Authority Name :				

Section 8: Mooring

Section 9 : Equipment Failure

Is critical equipment affected?

Is the damage to a third party ?	
Is the damage to own vessel or equipment?	
Section 11 : Fire	
Was there an explosion?	
Section 12 : Security	
Section 13 : Causes of Accident	
Section 13 : Causes of Accident	
Immediate Cause ?	
Immediate Cause ? (Human actions)	
(Human actions) Other (Specify): GROUNDING A RESULT	
Immediate Cause ? (Human actions) Other (Specify): GROUNDING A RESULT (Conditions)	
Immediate Cause ? (Human actions) Other (Specify): GROUNDING A RESULT	
Immediate Cause ? (Human actions) Other (Specify): GROUNDING A RESULT (Conditions) Third Party / External , Unsafe Port / Berth	
Immediate Cause ? (Human actions) Other (Specify): GROUNDING A RESULT (Conditions) Third Party / External , Unsafe Port / Berth Root Cause ?	
Immediate Cause ? (Human actions) Other (Specify): GROUNDING A RESULT (Conditions) Third Party / External , Unsafe Port / Berth Root Cause ? (Human factors)	
Immediate Cause ? (Human actions) Other (Specify): GROUNDING A RESULT (Conditions) Third Party / External , Unsafe Port / Berth Root Cause ?	
Immediate Cause ? (Human actions) Other (Specify): GROUNDING A RESULT (Conditions) Third Party / External , Unsafe Port / Berth Root Cause ? (Human factors)	
Immediate Cause ? (Human actions) Other (Specify): GROUNDING A RESULT (Conditions) Third Party / External , Unsafe Port / Berth Root Cause ? (Human factors) Incorrect Information	

Was immediate corrective action taken?

Yes

VESSEL COMMENCED DISCHARGE OPERATIONS TO RE-FLOAT THE VESSEL. VESSEL WAS RE-FLOATED AT 2315 LT ON 03RD SEPT AT 4.8 MTRS DRAFT AFT.

Is further action recommended to prevent recurrence?

No

Confirmation of follow up On Board Immediate trainining given ? No	
Immediate trainining given 2	- 1
ininediate training given:	
Further trainining required ?	
Safety meeting convened ? Yes	
Date of Meeting: 9-Oct-2017	
Supplementary Information	
Have you submitted supplementary information related to this accident ?	
INFORMATION EXCHANGE WITH AGENTS REGARDING DEPTHS ALONGSIDE WAS DONE.AS PER AGENTS DEPTH ALONGSIDE WAS 8.0 MTRS.OWN VESSEL MAX DRAFT 7.10 MTRS. DREDGING OPERATIONS SCHEDULED AT MONOMERES BERTH PRIOR OWN VESSEL BERTHING. HOWEVER VESSEL BERTHING PLAN PREPONED. THE BATHYMETRY CHART SHOWN BY PILOT WAS DTD 16TH AUGUST SHOWING DEPTHS OF M.CHARTERERS CANPOTEX FAILED TO PROVIDE VESSEL WITH SAFE BERTH AS PER C/P RESULTING IN BRIOF C/P.LOP WAS ISSUED FOR UNSAFE BERTH.	8.2
Section 15 : Office Comments	!
Was any investigation done by office OR external party ?	
Investigation Date :	
Name of Person / Organization :	
Was the vessel delayed ?	
Days: Hours:	
Potential for Recurrence	
Causes of Accident (As assessed by office)	1
Immediate Cause ?	
(Human actions)	
Other (Specify):	
(Conditions)	
(Conditions)	
Other (Specify):	1
Other (Specify):	
Other (Specify): Root Cause ?	
Other (Specify): Root Cause ? (Human factors)	
Other (Specify): Root Cause ? (Human factors) Other (Specify):	
Other (Specify): Root Cause? (Human factors) Other (Specify): (Job factors)	

Remarks:

Remarks :	
Section 16 : Closure	
Closed By:	Closed On:

Suggestions for improvement?

it is an electronic report, signature not required