

CUMMINS MARINE

Technical Service Bulletin

Bulletin #	TSB-247B
Date Issued	12 June 2014
Date Superseded	(none, current)
Severity	Advisory
Distribution	Authorized service centers, end customers

SUBJECT

False high-temperature readings on cooling sensor, 2006–2009 6BTA marine block series.

AFFECTED PRODUCTS

6BTA marine series, block serial range **1700001 through 1899999**. Production years 2006 through 2009 inclusive.

SYMPTOM

Intermittent high-temperature indication on instrument panel or multifunction display. Indication may show 10–15 degrees above nominal cruise temperature. Actual coolant temperature, when verified with an independent IR or contact thermometer at the thermostat housing, is within nominal range. Symptom often appears under steady-state cruise conditions and resolves when RPM drops or engine cycles off.

ROOT CAUSE

Cooling sensor P/N 3-928-489 (original production) exhibits a known drift in its resistance characteristic over time, leading to systematic over-reporting of coolant temperature to the instrumentation circuit. Failure is gradual, not sudden.

REMEDY

Replace cooling sensor with revised part P/N 3-928-489-A1. Installation labor: 0.5 hours. Current Cummins list price is on file with the parts catalog; authorized dealers (Hamilton Marine, Defender Marine) typically carry the revised sensor at dealer pricing below Cummins list.

NOTES

This is an instrumentation-only issue. Actual engine cooling performance is not affected. Owners may choose to defer replacement at next scheduled service if the false reading is intermittent and does not interfere with operation. If the false reading is causing the operator to throttle back or divert routes unnecessarily, replacement is recommended.

DOCUMENT CONTROL

TSB-247

first issued 02 March 2012

TSB-247A	revised 18 November 2013
TSB-247B	revised 12 June 2014 (current)

© Cummins Inc. — Service Information. For authorized service centers and end customers. Reproduction permitted for service purposes.