

# **Technical Service Information**

### FORD AXOD/AXOD-E

## NEW DESIGN SOLENOID PACK FOR 1995 VEHICLE HARNESS WILL NOT CONNECT TO A NEW SOLENOID PACK

**CHANGE:** Beginning at the start of production for 1995, all models of the E40D transmission were

produced with a new design solenoid pack, that will not interchange with the previous models.

**REASON:** New design vehicle harness connector with grommet installed, to eliminate contamination

from water and road debris, that may cause corrosion.

#### PARTS AFFECTED:

SOLENOID PACK - New design solenoid assembly case connector to accommodate the new design vehicle harness connector. Refer to Figure 1 for identification of the previous design and the new design solenoid assemblies.

NOTE: The plastic sleeve incorporated in the previous design solenoid pack has been eliminated on the new design solenoid pack (See Figures 1 and 2). This plastic sleeve will sometimes remain on the vehicle harness connector when it is disconnected. If a new solenoid pack is installed (which includes sleeve), it will be impossible to reconnect the vehicle harness to the solenoid pack until the old sleeve is removed (See Figure 2).

#### **INTERCHANGEABILITY:**

The previous design solenoid assembly will fit only 1989-1994 model vehicles, and the new design solenoid assembly will fit only 1995-UP models. They will not interchange!

#### **SERVICE INFORMATION:**

Solenoid Assembly, 1989- 1994 Models Only	E9TZ-7G391-A
Solenoid Assembly, 1995- Up Models Only	F5TZ-7G39 1-A



# **Technical Service Information**

# **EPC SOLENOID DIFFERENCES PREVIOUS DESIGN NEW DESIGN** 1989 - 1994 1995 - UP VIEW LOOKING INTO THE CASE CONNECTOR Copyright © 1999 ATSG

Figure 1
AUTOMATIC TRANSMISSION SERVICE GROUP



## **Technical Service Information**

