

Technical Service Information

FORD AX4N NEW PUMP SPACER PLATE TO VALVE BODY GASKET

CHANGE: A new design pump spacer plate to valve body gasket was implemented during the 1998 model

year for all models of the AX4N transaxle.

REASON: To eliminate the possibility of unsupported gasket material breaking off and sticking valves in the

valve body. The valve most commonly stuck has been the by-pass clutch control valve causing

no converter clutch engagement.

PARTS AFFECTED:

(1) A large portion of the previous design gasket has been removed to prevent unsupported gasket material from breaking off and entering the valve body, as shown in Figures 1 and 2.

SERVICE INFORMATION:

Pump Spacer Plate To Valve Body Gasket (New Design) F8DZ-7A136-AB

Copyright © 2000 ATSG

00-08 Page 1 of 3



Technical Service Information




Figure 1

00-08 Page 2 of 3

Copyright © 2000 ATSG



Technical Service Information




Figure 2

00-08 Page 3 of 3