

Technical Service Information

KM 175 BINDING UP

COMPLAINT: Bind up in D: second, third, or overdrive. And the low reverse clutches are burned.

CAUSE: Broken square cut waved spacer found underneath the diaphragm return spring in the low

reverse clutch housing, and will not allow the clutch to release (see figure 1).

CORRECTION: Replace the wave spacer.




Figure 1

Copyright © 2000 ATSG