

Technical Service Information

HONDA/ACURA MGHA FAMILY WRONG GEAR STARTS, SETS VARIOUS SOLENOID DTC'S

COMPLAINT: After overhaul, a Honda vehicle equipped with a MGHA Family transmission exhibits a

complaint of wrong gear starts. When checking for codes with a scanner, various solenoid

DTC's may be stored.

CAUSE: One cause may be solenoid connectors cross connected. Cross connecting the brown or

black connectors between Shift Solenoid A, B, C or the TCC Solenoid may cause wrong gear starts, but would not set DTC's. Cross connecting Shift Solenoid A, B, C or TCC Solenoid black or brown connectors with CPC Solenoids A, B, or C may also cause wrong

gear starts and will most likely store a DTC for the affected solenoids.

CORRECTION: Use the diagram in Figure 1 to identify the proper solenoid locations. There are a few

different brown and black connectors. Use the chart in Figure 2 to identify the correct solenoid connector color as well as corresponding wire color to assist the technician in

correct assembly.

Note: Wire colors provided are based on 2001 model Acura MDX vehicle. Use care when connecting the solenoids. Wire colors may vary between models, however connector

colors remain the same.



Technical Service Information

MGHA FAMILY SOLENOID AND PRESSURE SWITCH LOCATIONS




Figure 1



Technical Service Information

MGHA FAMILY SOLENOID AND PRESSURE SWITCH CONNECTOR AND WIRE COLORS

SOLENOID/ PRESSURE SWITCH	CONNECTOR COLOR	WIRE COLOR
Shift Solenoid A	Black	Blue/Yellow Black
Shift Solenoid B	Brown	Lt Green/White Black
Shift Solenoid C	Brown	Lt Green Black
Torque Converter Clutch Solenoid	Black	Yellow Black
Clutch Pressure Control Solenoid A	Black	White Red
Clutch Pressure Control Solenoid B	Brown	Lt. Green Brown/White
Clutch Pressure Control Solenoid C	Black	Red/Blue Lt Green/Red
3RD Clutch Pressure Switch	Grey	Blue/White
4TH Clutch Pressure Switch	Beige/Natural	Blue/Yellow

Copyright © 2009 ATSG

Figure 2