

Technical Service Information

THM 440-T4 TCC APPLY ON 1-2 SHIFT

COMPLAINT:

The converter clutch applies immediately after the transaxle has shifted to 2nd gear, and cannot be released with the brake pedal. The converter clutch will apply on the 1-2 shift even with the wire harness disconnected from the transaxle.

CAUSE:

The cause may be one of the following:

- (1) The TCC screen and orifice assembly missing from its location in the spacer plate (See Figure 1).
- (2) The TCC screen and orifice assembly "Melted" and usually found in the TCC solenoid, blocking the exhaust passage. Usually an aftermarket product, not OEM.
- (3) The TCC solenoid blocked with foreign material.
- (4) TCC solenoid for Canadian application, which is self grounded, installed on a computer controlled transaxle (See Figure 2). NOTE: Will not lock-up with wire harness disconnected.

- **CORRECTION:** (1) Install the TCC screen and orifice assembly, with the "0" ring, in its proper location in spacer plate (See Figure 1). OEM part numbers are found below.
 - (2) Replace TCC screen and orifice assembly with OEM PART NUMBER 8658060, and replace TCC solenoid assembly with the proper part number.
 - (3) Replace the TCC solenoid assembly with the proper part number. (4) Install the PROPER TCC solenoid assembly. If your valve body is equipped with the TCC Throttle Valve line-up, it requires the self grounded solenoid, I.D. stamped 732 (See Figure 2). If your valve body is not equipped with the TCC Throttle Valve line-up, it requires the computer controlled solenoid, I.D. stamped 419 (See Figure 2).

SERVICE INFORMATION:

"Early" Model TCC Screen	
"Late" Model TCC Screen and Orifice Assembly	
ECM Controlled TCC Solenoid Assembly	
NON-ECM TCC Solenoid Assembly (Canadian)	



Technical Service Information




Figure 1



Technical Service Information




Figure 2
AUTOMATIC TRANSMISSION SERVICE GROUP