

Technical Service Information

MITSUBISHI F4A40/50 SERIES ERRATIC SHIFTS AND OR GEAR RATIO ERROR CODES

COMPLAINT: Mitsubishi vehicles equipped with the F4A40/50 series transaxle, may exhibit erratic shifts

or Diagnostic Trouble Codes related to gear ratio errors, such as P0732, 2nd gear ratio error

P0733 3rd gear ratio error, P0734 4th gear ratio error, after transaxle replacement.

CAUSE: The cause may be, a wrong transaxle, or gear train parts, were installed into the vehicle that

contained incorrect ratios that are incompatible with the vehicles computer.

CORRECTION: Refer to Figure 1 to see the location and legend of the Identification stamp that is

located on the top of the transaxle case, to verify the correct ratios. Refer to Figure 2 for an application chart matching Identification number to vehicle model and year, to ensure the

correct ratios are installed into the vehicle.



Technical Service Information





Figure 1



Technical Service Information



YEAR	MODEL	ENGINE	TRANSMISSION	SPRAG
1997	Diamante	3.5L SOHC	F4A51-2-D5A	No
1998-01	Diamante	3.5L SOHC	F4A51-2-D5B	Yes
2000-01	Eclipse	2.4L SOHC	F4A42-2-M6B	Yes
2000	Eclipse	3.0L SOHC	F4A51-2-E6B	Yes
2001	Eclipse	3.0L SOHC	F4A51-2-E5B	Yes
1999-01	Galant	2.4L SOHC	F4A42-2-M6B	Yes
1999	Galant	3.0L SOHC	F4A51-2-D6B	Yes
2000	Galant	3.0L SOHC	F4A51-2-E6B	Yes
1997-99	Mirage	<i>1.5L SOHC</i>	F4A41-1-M8A	No
1997-98	Mirage	1.8L SOHC	F4A42-1-M8A	No
2000	Mirage	1.5L SOHC	F4A41-2-M8B	Yes
1999-01	Mirage	1.8L SOHC	F4A42-2-M8B	Yes

Copyright © 2005 ATSG