

Technical Service Information

THM 4L80-E NEW SHIFT SOLENOIDS

CHANGE: Beginning in the middle of 1996 model year, as a running change, all THM 4L80-E/4L80-

EHD transmissions were built with revised shift solenoids once again.

REASON: Revised internal seal material and coil windings for increased durability.

PARTS AFFECTED:

(1) SHIFT SOLENOID "A" - Revised internal seal material, and is now TAN in color, instead of the previous Purple (See Figure 1).


(2) SHIFT SOLENOID "B" - Reveised internal seal material, and is now BLACK in color, instead of the previous Tan (See Figure 1).

INTERCHANGEABILITY:


The new design Shift Solenoids will retro-fit back on *all* previous models.

SERVICE INFORMATION:

Shift Solenoid "A"	'(TAN)	10478125
Shift Solenoid "B"	(BLACK)	10478126







BLACK

Copyright © 2001 ATSG