

Technical Service Information

THM 3L80 (400) CHECKBALL ADDED TO CASE

CHANGE: Check ball added to case on 1987-1988 vehicles, and ONLY on vehicles with GVW of


under 10,000lbs.

REASON: Softens the apply feel when the selector is moved from Park/Neutral to reverse.

PARTS AFFECTED:

- (1) **Transmission Case** Seventh check ball added to the case, and orificed cup plug added in the reverse servo feed bore. See Figure 1 for locations of both items.
- (2) Spacer Plate Spacer plate is revised for the additional check ball (See Figure 2).
- (3) Valve Body Gaskets Both gaskets are also revised for the additional check ball.

SERVICE INFORMATION:










Figure 1
AUTOMATIC TRANSMISSION SERVICE GROUP