

Technical Service Information

THM 200C ENGINE STALLS IN REVERSE

COMPLAINT: Engine stalls when the transmission selector is placed in reverse, but okay in drive.

CAUSE: One possible cause can br a cross leak in the pump, or cross leak between the pump

gears (excessive side clearance)

CORRECTION: An in car repair can be made by removing the pressure regulator valve and

grinding flats on the lands as shown in Figure 1. Or the valve can be replaced with

part number 8638950

