

Technical Service Information

THM 4T60-E OIL PUMP PIVOT PIN CHANGE

CHANGE: Beginning at Start Of Production for 1993 THM 4T60 and THM 4T60-E transaxles, all

models were produced with a revised oil pump pivot pin and pump casting.

REASON: Cost savings to produce.

PARTS AFFECTED:

- (1) OIL PUMP PIVOT PIN Now has a groove machined around the diameter of the pivot pin to establish the air bleed in the decrease oil circuit, as shown in Figure 1.
- (2) PUMP CASTING The threaded brass air bleed plug that screwed into the pump casting has been eliminated, as shown in Figure 1. This hole is now cast shut.

INTERCHANGEABILITY:

- (1) When servicing models WITH the brass air bleed plug, the SOLID pivot pin MUST be used.
- (2) When servicing models WITHOUT the brass air bleed plug, the GROOVED pivot pin MUST be used, (See Figure 1).

SERVICE INFORMATION:




Figure 1