

# **Technical Service Information**

# THM 200-4R "CHATTERS" IN REVERSE, ALL FORWARD GEARS OK

**COMPLAINT:** The vehicle may display a "Chatter" and/or a slipping condition when the selector

lever is placed in the Reverse position. All forward gears are OK.

CAUSE: The cause may be, leaking of reverse feed oil, created by a bent or warped spacer

plate, a bent or distorted 1-2 accumulator tension plate, or the checkball that is retained by a sleeve in the 1-2 accumulator housing not sealing because of debris and/or damage to the checkball seat in the housing. Refer to Figures 1 and 2.

**CORRECTION:** Replace the defective parts as necessary using the OEM part numbers listed below.

#### **SERVICE INFORMATION:**

1-2 Accumulator Housing With/Ball	. 8678913
1-2 Accumulator Tension Plate	. 8634924
Spacer Plate Gasket Package	. 8634969
Spacer Plate (I.D. "CD"), For Models: 7CRF, 7CTF, 8CRF, 8CTF	8669050
Spacer Plate (I.D. "CH"), For Models: 7KCF, 7KJF, 7KTF,	
8KTF, 9KJF, 9KTF, OKDF, OKJF, OKTF	. 8669060
Spacer Plate (I.D. YE"), For Models: 7CCF, 8CCF	8669051
Spacer Plate (I.D. "CC"), For Models: 7CHF, 8CHF	. 8669049
Spacer Plate (I.D. "CF"), For Models: 7CYF, 8CYF	8669052
Spacer Plate (I.D. "CA"), For Models: 7CZF, 8CZF	. 8669047
Spacer Plate For Models: 9CTF, 9CUF, 0CTF, 0CUF	. 8669056



### **Technical Service Information**




Figure 1
AUTOMATIC TRANSMISSION SERVICE GROUP



## **Technical Service Information**




Figure 2