

# **Technical Service Information**

# THM 4L60 (700-R4)

## CONVERTER CLUTCH THROTTLE VALVE BORE ELIMINATED

**CHANGE:** Converter clutch throttle valve bore in valve body casting eliminated starting with the

production of 1989 model THM 700-R4 (4L60).

**REASON:** No current production models using the converter clutch throttle valve, so the TCC bore is

not needed.

### PARTS AFFECTED:

Valve Body Casting - The new valve body casting will no longer have the TCC bore, and now contains a "Notch" in the worm track area allowing 2nd clutch oil into the XC Signal circuit (See Figure 1).

### INTERCHANGEABILITY:

Not interchangeable with 1987 or earlier model transmissions, is compatible with 1988 models only.

