

2000 ISUZU TROOPER & BMW 4L30-E D.T.C. P1870 OR TCC SHUDDER

COMPLAINT: 2000 and up Isuzu Trooper and BMW models with the 4L30-E transmission may exhibit a

Diagnostic Trouble Code P1870 Torque Converter Slip or a shudder on Torque Converter

Clutch application.

CAUSE: The Cause may be, a worn Torque Converter Regulator Valve and Sleeve, creating

insufficient converter apply pressure to hold the clutch on. See Figure 1.

2000 and up model Trooper and BMW applications have a Pulse Width Modulated Converter application. This TCC application strategy change, required a new TCC PWM

solenoid and numerous casting changes to the pump and it's related parts.

See Figure 3 for the ON-OFF two valve pump that is still used on 2000 and up Cadillac

Catera, Rodeo and Passport models.

See Figure 2 for the PWM pump with the identification of the new valves and their

locations.

See Figure 4 for the differences in the worm track configuration of the ON-OFF pump

casting and the PWM pump casting.

See Figure 5 for the differences in the hole configuration between the pump plates. See Figure 6 for the differences in the worm track configuration of the Bell Housings.

See Figure 7 for a partial hydraulic schematic of the PWM Torque Convertor Clutch apply

circuit.


CORRECTION: Replace the Torque Converter Regulator Valve and Sleeve.


SERVICE INFORMATION:

TORQUE CONVERTER REGULATOR VALVE (Isuzu)......8-96018-518-0 TORQUE CONVERTER REGULATOR VALVE SLEEVE (Isuzu)......8-96018-472-0

TORQUE CONVERTER REGULATOR VALVE AND SLEEVE


Special thanks to: Ted's Transmission Alex Biliski at Santilli's Transmission Glenside Pa. Dynamic Dino John Forrester





Copyright © 2005 ATSG





Some manuals list all of the TCC related valves the same name.

Copyright © 2005 ATSG

Figure 2






Figure 3






Figure 4




Figure 5
AUTOMATIC TRANSMISSION SERVICE GROUP

05-08 Page 4 of 6







Figure 6








Figure 7
AUTOMATIC TRANSMISSION SERVICE GROUP

05-08 Page 6 of 6