

Technical Service Information

THM 4L80-E NEW SHIFT SOLENOIDS

CHANGE:

Beginning on November 11, 1993 (Julian Date 315) all THM 4L80-E/4L80-EHD

transmissions were built with revised shift solenoid assemblies.

REASON:

Revised internal seal material for increased durability.

PARTS AFFECTED:

- (1) SHIFT SOLENOID "A" Revised internal seal material, and is now PURPLE in color, instead of the previous Gray (See Figure 1).
- (2) SHIFT SOLENOID "B" Revised internal seal material, and is now TAN in color, instead of the previous Green (See Figure 1).


INTERCHANGEABILITY:


The new Shift Solenoids will retro-fit back on ALL previous models of the THM 4L80-E/4L80-EHD transmissions.

SERVICE INFORMATION:

Shift Solenoid "A"	(PURPI	LE)	 		 24201004
Shift Solenoid "B" ((TAN).		 	. .	 24201005

SHIFT SOLENOID "A" SHIFT SOLENOID "B" 24201004 24201005





Copyright © 2001 ATSG