

Technical Service Information

THM 440-T4 HARSH 3-2 DOWNSHIFT

COMPLAINT: Harsh 3-2 part throttle, and/or full throttle downshift.

CAUSE Improper timing for release of the third clutch and re-application of the 1-2 band.

CORRECTION: Install a new 3-2 Control Valve Spring, now available in a service package from OEM.

See "Service Information" in this bulletin for proper part numbers, and refer to Figure 1

for proper installation.




Figure 1



Technical Service Information

SERVICE INFORMATION HIGH ALTITUDE ONLY	
	•
	864697
	· · · · · · · · · · · · · · · · · · ·
5CN, 5CN	
6AAH, 6AMH, 6AFH	I, 6APH, 6ASH,
бачн, бввн, бвнн	I, 6FBH 864698
·	864698
6BAH	864698
6BCH, 6BDH, 6BMH	H, 6BZH, 6FCH, 6FZH
6BLH, 6BTH, 6BYH	I 8646993
6CMH, 6CNH, 6CFH	I
6FTH, 6FYH	864699
***********	***************************************
	8646982
7FCH, 7FZH	8646979
7FJH, 7FNH, 7FRH	I, 7FTH 8646993
	I, 8BYH, 8FJH 8646993
8BKH, 8FBH	8646982
*********	***************************************
	, 9ANH, 9ATH, 9AJH 8646953
YACH, YADH, YAHH	8675936
	I, 9BWH 8646982
9BFH, 9BMH	8646993
	, 9WCH 8646981
9BPH, 9WRH	
	, 9CYH, 9CZH 8646994
9PBH, 9WLH, 9WKH	6662932
9WUH, 9WZH, 9VYH	8646993
9ҮАН, 9ҮВН, 9ҮЈН	, 9YCH, 9YFH 8646982
	, OANH, OATH 8646980
OLMH, OLNH	
OBAH, OBDH, OBWH	, OBJH
OYKH, OYLH	



Technical Service Information

ERVICE INFORMATION: (Cont'd)	
LOW ALTITUDE ONLY:	
6FCH, 6FZH	0662022
6FBH	
6CFH, 6CMH, 6CNH	
6ВНН	
6BBH	
6BCH, 6BDH, 6BMH, 6BZH	
6BAH, 6BLH, 6BTH, 6BYH, 6FTH, 6FYH	
ODAN, ODAN, ODIN, ODIN, OFIN	
7FCH, 7FZH	
7FBH, 7FKH	
7FJH, 7FNH, 7FRH, 7FTH	
8FCH	
8BRH	
8FBH, 8BKH	
8BJH, 8BTH, 8BYH, 8FJH	
9AAH, 9ABH, 9AFH, 9AJH, 9ANH, 9ATH	8646953
9YBH, 9YJH, 9YFH, 9YCH	8646981
9BCH, 9BHH, 9WBH, 9PAH	
9BFH, 9BMH, 9WUH, 9WZH, 9VYH	8646980
9BPH, 9WRH	8662932
9WTH	8646953
OAAH, OABH, OAFH, OANH, OATH	
OAJH	
OLMH, OLNH	
OBFH	8646979
OBAH, OBDH, OBJH, OBWH	
ОВНН	
OBPH	
OPAH	8662907
OYKH, OYLHOCHH, OCJH	