

## **Technical Service Information**

## CHRYSLER A604 TAPERED SNAP RING BROKEN IN INPUT DRUM

COMPLAINT: The color coded tapered snap ring that goes on top of the

Underdrive/ Overdrive reaction plate, in the input housing, is

found broken and usually in many pieces (See Figure 1).

CAUSE: Snap ring is not thick enough.

CORRECTION: Install "Updated" (Thicker) tapered snap ring, and the "Updated"

Underdrive/Overdrive reaction plate. THESE TWO PIECES MUST BE INSTALLED TOGETHER. Neither part is compatable with the previous parts. These parts will retro fit back on previous model vehicles

WITH THE 4 OVERDRIVE PACK ONLY.

#### SERVICE INFORMATION:

Updated Tapered Snap Ring (Black .075" Thick) ...... 4567602

Underdrive/Overdrive Reaction Plate (Updated Selective)

.273"-.277" Thickness ...... 4567640

NOTE: This change was implemented at start of production for all 1993 model A604 transaxles.

FOR IDENTIFICATION OF THE INDIVIDUAL PARTS THAT YOU MAY HAVE ON YOUR SHELF, SEE FIGURE 2.




Figure 1

Copyright © 2000 ATSG



### **Technical Service Information**


### UNDERDRIVE/OVERDRIVE TAPERED SNAP RING IDENTIFICATION

THICKNESS	COLOR CODE	APPLICATION	PART NO.
.070"	BLUE	3 O.D. PLATE ONLY	4377189
.060"	GREEN/WHITE	4 O.D. PLATE ONLY	4531411
.075"	BLACK	4 O.D. PLATE ONLY	4567602


MEASURE SNAP RING ACROSS THE THICKEST DIMENSION AS SHOWN AT RIGHT.



# UNDERDRIVE/OVERDRIVE REACTION PLATE MEASURE THICKNESS OF LONGEST TANGS FOR IDENTIFICATION




THIS PLATE REQUIRES .070" BLUE TAPERED SNAP RING, AND IS INSTALLED WITH STEP FACING DOWN.



THIS PLATE REQUIRES .060" GREEN/WHITE TAPERED SNAP RING, AND IS INSTALLED WITH STEP FACING DOWN.

RADIUSED UNDERCUT TO MAKE ROOM FOR THICKER SNAP RING



THIS PLATE <u>REQUIRES</u> .075" BLACK TAPERED SNAP RING, AND IS INSTALLED WITH <u>SQUARE</u> STEP FACING DOWN.

THE "UPDATED" BLACK SNAP RING AND THE "UPDATED" UNDERCUT REACTION PLATE WILL RETRO FIT BACK ON 4 O.D. PLATE ONLY.