

Technical Service Information

FORD 4EAT PROBE

DISPLAYS 4-2 3-1 SHIFT PATTERN (AFTER REBUILD)

COMPLAINT: After you have finished the rebuild and installed the transaxle back into the vehicle, it

starts off in 4th gear, followed by a shift into 2nd gear, followed by a shift into 3rd gear, and then shifts into 1st gear. The last shift is sometimes described as a shift into neutral,

because of vehicle speed at the time of the shift.

The vehicle will also display a 1-2-Neutral shift when manual shifting through the shift

pattern, and a slipping condition on heavy acceleration.

CAUSE: The cause may be the 1-2 shift solenoid and the 2-3 shift solenoid reversed in their

locations in the valve body (See Figure 1).

CORRECTION: Install the shift solenoids in their proper locations, as shown in Figures 1 and 2.

Use Figure 1 for the 1-2 and 2-3 shift solenoids, and Figure 2 for the 3-4 and lock-up

solenoids.



Technical Service Information




Figure 1



Technical Service Information




Figure 2