

THM 440-T4 3RD CLUTCH LINING CHANGE

CHANGE: Because of a change in the 3rd clutch fiber material, all 1989 THM 440-T4 models built after

March 17, 1989 (Julian Date 076), have new calibrations, and new two letter model codes

(See Figure 1).

REASON: Different supplier for 3rd clutch plates.

PARTS AFFECTED:

(1) 3RD CLUTCH PLATES - The new 3rd clutch plates have a different fiber material and can be identified by black stripes, or notches, as shown in Figure 3.

(2) CALIBRATION - THM 440-T4 models built after March 17, 1989 (Julian Date 076) will contain the following calibration changes:

(A) - New Spacer Plate (See Figure 2).

(B) - New 3-2 Control Valve Spring.

(C) - New 2-3 Accumulator Valve Spring.

(D) - New 1-2 Servo Cushion Spring (Except AAH, ABH, AFH).

The recalibrated valve body assembly will have an update level "Laser Etched" into the casting by the servo pipes. See Figure 2, for valve body I.D. and new spacer plate information.

INTERCHANGEABILITY:

- (1) Harsh shifts or a possible tie-up condition may occur on 2-3 and 3-2 shifts if the previous 3rd clutch plates (No Stripe) are installed into a trans-axle built after March 17, 1989 (Julian Date 076), with the new model codes.
- (2) A slide-bump condition on 2-3 and 3-2 shifts may occur, if the new 3rd clutch plates (Black Stripe) are installed into a transaxle built prior to March 17, 1989 (Julian Date 076), with the old model codes.
- (3) When the supply of the previous 3rd clutch plates (No Stripe) are depleted, the new 3rd clutch plates (Black Stripe) will be available with an instruction sheet showing which calibration update kit to order for each model built prior to March 17, 1989 (Julian Date 076). See "Service Information" in this bulletin for part numbers.



SERVICE INFORMATION:

3rd Clutch Plate Package (Previous - No Stripe)	8662954
3rd Clutch Plate Package (New - Black Stripe)	
Calibration Update Kit (9AAH, 9ABH, 9AFH)	8675936
Calibration Update Kit (9BAH, 9BDH)	8675937
Calibration Update Kit (9BFW, 9BMH)	8675938
Calibration Update Kit (9BHH)	
Calibration Update Kit (9BJH)	
Calibration Update Kit (9BPH)	
Calibration Update Kit (9BWH, 9VXH)	
Calibration Update Kit (9CDH, 9CLH, 9czH)	
Calibration Update Kit (9CYH)	
Calibration Update Kit (9PAH)	
Calibration Update Kit (9CPH)	
Calibration Update Kit (9CHH)	
Calibration Update Kit (9CJH)	

NOTE: Calibration Update Kits include the following:

- (A) New Spacer Plate.(B) New 3-2 Control Valve Spring.(C) New 2-3 Accumulator Valve Spring.
- (D) New 1-2 Servo Cushion Spring (Except AAH, ABH, AFR)
- (E) Instruction Sheet.



OLD MODEL	NEW MODEL	CODES	CODE INFORMATION
AAH	ACH		
ABH	ADH		
AFH	АНН		(*) . NO CHANGES (NO NEW 3RD CLUTCH PLATES)
(AJH)	(AJH)	(*)	10)
(ANH)	(ANH)	(*)	(O) = EARLY 1990 MODEL
(ATH)	(HTA)	(*)	
(OLAH)	(OLAH)	(*) (0)	
(OLCH)	(OLCH)	(*)	
PAH	PSH		NOTE: IF THE MODEL CODES CHANGED THEN THE
VXH	VYH		3RD CLUTCH PLATE ASSEMBLY AND CALIBRATIONS
BAH	WBH		DID ALSO.
BDH	WCH		
BFH	WLH		
ВМН	WKH		
ВНН	WRH		
BJH	WZH		
врн	WTH		
BWH	WUH		
CDH	YAH		
CLH	УВН		
СРН	YCH		
CYH	YFH		
CZH	HLY		
оснн	ОҮКН	(0)	
осин	OYLH	(O)	

Figure 1

MODELS	VALVE BODY I.D.	MODELS	SPACER PLATE LAST FOUR NUMBERS
AJH	BS-1	HLA	8394
ACH, ADH, AHH	9A-3	ACH, ADH, AHH	5213
ANH, ATH	98-2	ANH, ATH	8415
WBH, WCH	90-2	WBH, WCH	5103
WLH, WKH	9E-3	WLH, WKH	5091
WRH	9G-3	WRH	5091
WZH, WUH	9H-3	WZH	5099
		WUH	5097
W TH	9J-3	WTH	5091
YAH, YBH, YJH	9M-2	YAH, YBH, YJH	5089
YCH	9P-2	YCH	5093
PBH	9U-2	PBH	5101
OYKH	04-1	OYKH	5201
OYLH	0W-1	OYLH	5203
OLAH	02-1	OLAH	8874
YFH	90-0	YFH	8273

Figure 2






Figure 3
AUTOMATIC TRANSMISSION SERVICE GROUP