



SKILL FORGE
WHERE STUDENTS BECOME TEACH

SOP-300 — Complete Tint Installation Workflow

Section 4: Window Tint

SOP · Version 1.0

Organization: _____

Document ID: sop-300-complete-tint-installation-
workflow

Effective Date: _____

Approved By: _____

SOP-300 — Complete Tint Installation Workflow

Forge Standard Operating Procedures v1.0

Section 4: Window Tint

Purpose

End-to-end procedure for professional window tint installation from bay setup through QC.

Scope

All automotive window tint services. Follow Window Tint Master Install Manual for film-specific detail.

Procedure

Pre-install

1. Verify legal VLT limits for customer state and window location.
2. Complete SOP-200 through SOP-204.
3. Protect interior: seat covers, dash mat, door panel tape on switches.

Glass preparation

1. Clean exterior glass for patterning reference if needed.
2. Interior glass: scrub with dedicated glass cleaner, scrape embedded particles with razor (45° angle, wet), final IPA wipe.
3. Roll down windows 1" to clean top edge channel.

Film application

1. Cut pattern (plotter or hand) with 1/16" shrink allowance.
2. Shrink on outside or heat-form per film type; never overheat ceramic.
3. Apply slip solution; position film; squeegee center-out; tack edges last.
4. Heat post-form edges; wipe solution from film and glass.

QC & cure instructions

1. Inspect for contamination, fingers, and light gaps.
2. Complete SOP-205 and SOP-206.
3. Instruct customer: 3–5 day window cure, no rolling down until verified.

Quality standards

- ☐ Zero dust particles visible at 18" in final QC light
- ☐ Edges uniformly tucked — no gap at defroster lines

Related documents

Document	ID
Window Tint Master Install Manual	window-tint-master-install
Window Tint Workbook	window-tint-workbook
Tint Pricing Guide	tint-pricing-guide

Revision history

Version	Date	Author	Changes
1.0	2026-07-23	Forge Operations	Initial release

Confidential — Skill Forge training operations.