FRANMARINE UNDERWATER SERVICES PTY LTD

LOSS OF STEERING

Emergency Procedure

MV ROHANI | UVI: 457394

Marine Order 504 (2024) — Schedule 1 Compliance

Document Number:	FUS-SMS-ROH-06E
Revision:	01
Date:	7 July 2026
Author:	Matthew Hilder
Reviewed By:	Belinda Brooks
Approved By:	Kirby Hamilton
Vessel:	MV Rohani (UVI 457394)

DOCUMENT CONTROL

Revision History

Rev	Date	Author	Description	Approved
01	7 July 2026	M. Hilder	Initial issue	K. Hamilton

Approval

Role	Name	Date
Author	Matthew Hilder	7 July 2026
Reviewed	Belinda Brooks	7 July 2026
Approved	Kirby Hamilton	7 July 2026

Review Frequency

This document shall be reviewed at least every 12 months, or sooner following a significant incident, change of operations, vessel modification, or change in applicable legislation.

Controlled Distribution

This document is a controlled distribution issued from the Franmarine document management system (DMS), which holds the master record, revision history, and approval log. The controlled digital copy is located in the vessel's SharePoint folder. Printed or downloaded copies are uncontrolled; refer to the SMS Document Register for the current revision status.

TABLE OF CONTENTS

1. PURPOSE

This procedure establishes the actions to be taken in the event of a loss of steering on MV Rohani.

1.1 Regulatory Reference

Marine Order 504 (2024), Schedule 1, Clause 12.

1.2 Vessel Configuration

MV Rohani is fitted with twin Detroit Diesel 6V-92T diesel inboard engines driving twin screws with rudder steering. In the event of a steering system failure, the twin-screw configuration allows the vessel to be steered using differential thrust — that is, by applying more throttle to one engine than the other to turn the vessel. This is the primary emergency steering method for this vessel.

2. IMMEDIATE ACTIONS

- Reduce speed to idle immediately.
- Alert all crew to the loss of steering.
- Attempt differential thrust steering: increase throttle on the port engine to turn to starboard, or increase throttle on the starboard engine to turn to port. Start with small throttle adjustments to gauge the vessel's response.
- Assess for collision risk. If in a busy waterway or unable to maintain safe directional control, issue a SÉCURITÉ or PAN PAN call on VHF Ch 16 advising of the loss of steering and the vessel's position. Advise the relevant port authority (refer FUS-SMS-ROH-05J for VHF channels).

3. TROUBLESHOOTING

Common causes of steering failure on this vessel:

- Low hydraulic steering fluid — check the reservoir level and top up if possible.
- Hydraulic line failure — inspect visible hose runs for leaks or burst hoses.
- Steering linkage or hydraulic failure — inspect the helm, the steering lines or linkages, and the rudder stock connections.
- Obstruction at the rudders or propellers — check for rope, debris, or marine growth fouling the rudders or screws.
- Rudder tie-bar or linkage failure — inspect the connection between the rudders (if fitted) for damage or disconnection.

If the fault can be identified and rectified safely, do so. If not, proceed with differential thrust steering to a safe location.

4. EMERGENCY NAVIGATION USING DIFFERENTIAL THRUST

With twin screws, MV Rohani can be navigated effectively using differential thrust alone:

- To turn to starboard: increase port engine throttle while reducing or idling the starboard engine.
- To turn to port: increase starboard engine throttle while reducing or idling the port engine.
- To maintain a straight course: match both engine RPMs. Small adjustments will be needed as wind and current act on the vessel.
- Navigate at reduced speed. Differential thrust steering is less precise than hydraulic steering and the vessel will respond more slowly, especially at low speeds.
- Navigate to the nearest safe port, berth, or anchorage.
- If unable to maintain any directional control (e.g. the rudders are jammed hard over), deploy the anchor to arrest drift and prevent grounding or collision. Request a tow if necessary.

5. POST-INCIDENT

- Do not continue normal operations until steering is fully restored and tested.
- Report to the East Coast Operations Superintendent.
- Record all details in the vessel logbook.
- Arrange for repair by a qualified marine mechanic before the vessel returns to service.

6. REFERENCES

- FUS-SMS-ROH-06 Emergency Plan
- FUS-SMS-ROH-07 Maintenance
- Marine Order 504 (2024), Schedule 1, Clause 12