

Maintenance sheet version 10 for accumulation area (single mast, two levels)

Station name	CP1
People present	HETJA, APA, BAV, ABV + Johann & Greta (NOR)
Purpose	(Maintenance) / installation / take-down / quick visit / emergency
Date	9 MAY 2025

Notes:
 iPhone 3D scan lidar with Scaniverse App attempt planned → option used: objects
 → processing: area ("lidar")

AWS to do list		Check after maintenance			
Part	Shipped? (Y/N)	Replaced? (Y/N)	Number shipped/arrival	Number departure	
Radiometer	Y	Y	SN:213256 Calib: 20/01/2025	213256	Clean? ☒ Y / N
Iridium modem IMEI number	N	N	300534062024	750	
Inclinometer/compass	N	N	Attached to the radiometer? ☒ Y / N internal		
Satellite antenna	N	N			
Wind sensor upper	Y	Y	Black box pointing toward the radiometer (i.e., along the boom)? ☒ Y / N SN 144398		
Wind sensor lower	Y	Y	Black box pointing same direction as the radiometer? Y / N 202383		
Temperature / humidity assembly upper	Y (Lufft)	Y	Fan spins? Y / N Sounds, OK? Y / N SN: 389.0223.1714 246		
Temperature / humidity assembly lower	Y (Lufft)	Y	Fan spins? Y / N Sounds, OK? Y / N SN: 390.0223.1714.246		
Sonic ranger upper	Y	Y	Old sensor with new membrane? Y / N SN 19392		
Sonic ranger lower	Y	Y	Old sensor with new membrane? Y / N SN 12652		
Thermistor string	PVC tube Ext. cable	cable replaced pvc extended			
Solar panel	N	N	Clean? ☒ Y / N NB: is not effective when partially covered		
GPS antenna	N	N	At top of logger enclosure? Y / N		
Logger box ID	N		CR1000 or CR1000X? ID number:		
Logger enclosure	N	N	Replaced (including everything inside)? Y ☒ N New desiccant bags? Y / N		
Battery box	N	N	New box? Y ☒ N New desiccant bags? Y ☒ N Battery box not found		
Mast extension inserted?	Y	Y	How many inserted? How long? 1 standard Notes:		
Mast	N	N	New mast? Y ☒ N New sensor boom? Y ☒ N		

GNNs dist on mast to connector from lower
 GNNs rod point 40° down from south "beds"

Station name	CP1
Date	9 MAY 2025 HETJA, APA, BAV, AEU

Metadata maintenance

	Arrival	Departure
Time difference between logger clock and UTC ($\pm$ mm:ss)	- 00:13	
Download data to PC and/or change SD card (wait for green light)	(Y) N	N/A Y/N
Name of logger program	GCNet V2-6	same
Screen dump of values in fast scan mode	(Y) N	PC battery dead Y (N)
Photos of mast, sensors, logger box wiring etc. (more is better)	(Y) N	Y/N
Upper boom direction with radiometer relative to north CNR pointing south	0 true/magn.	0 true/magn.
Lower boom perpendicular to upper boom. If not, measure.	(Y) N	(Y) N
Box on upper wind sensor exactly same direction as radiometer? If not, measure.	(Y) N	(Y) N
Box on lower wind sensor exactly same direction as radiometer? If not, measure.	clockwise as seen from below Y (N) 3°	as before Y (N) 3°
Upper temperature / humidity height (bottom of casing – surface)	384 cm	cm
Lower temperature / humidity height (bottom of casing – surface)	258 cm	405 cm
Upper sonic ranger height (bottom of casing – surface)	356 cm	cm
Lower sonic ranger height (bottom of casing – surface)	219 cm	370 cm
Length of thermistor string on surface from surface marking	N/A cm	N/A cm
Apparent damage to sensors? If yes, which?	Y (N)	Y (N)

Notes:

Snowboard depth: 129 cm $\pm$ 0.5 (3 pokes)
 Snowboard stake height: 40 cm
 Thermistor PVC tube height: 53 cm (top of lid)

Mast tilt: CNR 4° down towards snow
 N-S
 W-E : 0°

→ 171 cm } departure
 → PVC 253 cm }

SD-card was ejected, data copied and wiped clean before re-installation

Must-do at next visit:

maybe values from SW in and out have been swapped? (HETJA in place with most bits → BAV comment)

HETJA: New power extension

→ Cord for logger/battery box

- Plastic mounting on new lower Lufft broke during installation

APA NOTE: Battery box not found and thus left deep in the snow. Existing power cable was long (rolled up coil) and used to extend the power along extended mast. Whether or not to bring a new battery box should be considered - the alternative is to extend the power cable
 → if so: bring power extension cable