

Maintenance sheet version 10 for ablation area (tripod, one level)

Station name	KAN_T
People present	KKK + 33
Purpose	Maintenance / installation / take-down / quick visit / emergency
Date	15/5-2025

Notes: Install GNSS gadget
Ret tripod op I lodret
Only need 2 have maintenance

AWS to do list		Check after maintenance			
Part	Shipped (Y/N)	Replaced? (Y/N)	Number shipped/arrival	Number departure	
Radiometer	N	N			Clean? Y / N
Ablation hose assembly	N	N			No air in hose and bladder half full? Y / N
Iridium modem IMEI number	N	N			
Inclinometer/compass	N	N	Attached to the radiometer? Y / N		
Satellite antenna	N	N			
Wind sensor	Y	Y	Black box pointing toward the radiometer (i.e., along the boom)? Y / N		
Temperature / humidity assembly	N	N	Fan spins? Y / N Sounds, OK? Y / N		
HygroClip T/hum assembly	N	N	NB: Rotronics (Y / N) could have a 40 °C offset. New or old type? NB: Lufft sensor (Y / N)		
Sonic ranger on AWS	N	N	Old sensor with new membrane? Y / N		
Sonic ranger on stake	N	Y	Old sensor with new membrane? Y / N NB: make sure not being buried next winter		
Thermistor string	Y	Y			
Solar panel	N	N	Clean? Y / N NB: is not effective when partially covered		
GPS antenna	Y Abracon	(N)	At top of logger enclosure? Y / N		
Logger box ID	N	N	CR1000 or CR1000X? ID number:		
Logger enclosure	N	N	Replaced (including everything inside)? Y / N New desiccant bags? Y / N		
Battery box	N	N	New box? Y / N New desiccant bags? Y / N		
Stakes	N	Y	New one(s) drilled in? Y / N Length of new stake(s) 8 m? Y / N		
Tripod	N	N	New tripod? Y / N New sensor boom? Y / N		

visit 20250522: fixed GNSS mount - issue
installed GNSS, the remaining part

Station name	KAN_T
Date	15/5-25

Metadata maintenance

	Arrival	Departure
Time difference between logger clock and UTC ($\pm$ mm:ss)	-00:06.5	-00:06.5
Download data and/or change CF/SD Card (wait for green light)	☒ Y / ☐ N	☐ Y / ☐ N
Name of logger program	received 1-5	fine
Screen dump of values in fast scan mode	☒ Y / ☐ N	☒ Y / ☐ N
Photos of tripod, sensors, logger box wiring etc. (more is better)	NE ☒ Y / ☐ N	☒ Y / ☐ N
Boom direction relative to north boom bended horizontally	$\frac{1}{2}$ 48° true/magn.	48° true/magn.
Box on wind sensor exactly towards mast? If not, measure.	☒ Y / ☐ N	☒ Y / ☐ N
Radiometer exactly aligned with inclinometer? If not, measure.	☒ Y / ☐ N	☒ Y / ☐ N
Temperature / humidity height (bottom of casing - surface)	cm	cm
Stake assembly standing?	☒ Y / ☒ sort of	☒ Y / ☐ N / sort of
Free length of stake broken	120 cm	48 cm
Height of ablation bladder fluid level above the ice surface	1/2 cm	1/2 cm
Vertical difference in surface height (at station - at hose) (approx.)	1/2 cm	1/2 cm
Length of thermistor string on surface from surface marking	1/2 cm	1/2 cm
Apparent damage to sensors? If yes, which?	☒ Y / ☐ N	☒ Y / ☐ N

Notes:

* stake broken at 2m assembly

wind anemometer blown off, could not find it

iridium antenna not vertical

small tube in bladder bended, probably no flow from bladder

~~Must do at next visit:~~

DTA seemed filled up

"Maybe" the tripod had tilted completely over $\rightarrow$ someone else raised it again

not stake done;

could not redrill stake $\rightarrow$ cable frozen in

boom mount adjusted 3 cm down

could not correct tripod tilt

redrilled stakes and new SRSO

5mm drill

GPS status: takachi box installed, y-splitter wiring, need mount, antenna, cable y-splitter, power cable