

Maintenance sheet version 10 for accumulation area (single mast, two levels)

Station name	KAN_U
People present	HETJA, APA, BAV, ARU, FALO - JOHANN + GRETA
Purpose	Maintenance / installation / take-down / quick visit / emergency
Date	MAY 16, 2025

Notes: ENVIRONMENT: ~ 12 m/s wind, -7°C

Storm moving in afternoon

GNSS from JG installed, antenna connector broke on antenna, tried to fix it with tape as photo documented

AWS to do list		Check after maintenance			
Part	Shipped? (Y/N)	Replaced? (Y/N)	Number shipped/ as last	Number departure	
Radiometer	Y Y	Y	SN: 202703 Calib: 20/01/2025	↔	Clean? Y/N
Iridium modem IMEI number	N	N			
Inclinometer/compass	N	Y	Attached to the radiometer? Y/N		
Satellite antenna	Y Y	Y			
Wind sensor upper	N	N	Black box pointing toward the radiometer (i.e., along the boom)? Y/N		
Wind sensor lower	N	N	Black box pointing same direction as the radiometer? Y/N		
Temperature / humidity assembly upper	Y (Lufft)	Y	Fan spins? Y / N Sounds, OK? Y / N		
Temperature / humidity assembly lower	Y (Lufft)	Y	Fan spins? Y / N Sounds, OK? Y / N		
Sonic ranger upper	Y	Y	Old sensor with new membrane? Y / N		
Sonic ranger lower	N	Y	Old sensor with new membrane? Y / N		
Thermistor string	PVC tube Ext. cable	Extended w. red cable	Extended, new cable connected		
Solar panel	N	N	Clean? Y/N NB: is not effective when partially covered		
GPS antenna	N	N	At top of logger enclosure? Y/N		
Logger box ID	N	N	CR1000 or CR1000X? ID number:		
Logger enclosure	N	N	Replaced (including everything inside)? Y/N New desiccant bags? Y/N		
Battery box	N	N	New box? Y/N New desiccant bags? Y/N		
Mast extension inserted?	Y	N	How many inserted? How long? Notes:		
Mast	N	N	New mast? Y/N New sensor boom? Y/N		

more notes:

Malå GPR did not work, possibly due to blowing snow?

Must consider how this GPR can become more reliable...

Page 1 of 2

Battery box found under lower Lufft, but retrieval was not easy because of ice layers at depth. This required a lot of digging also towards mast to untie the cable.

nextyl:

Avoid ziptying power cable low on mast!

None inserted, mast high enough for 2 yrs

Station name	KAN_U	NETJA, APA, BAV, ARV, FALO
Date	16 MAY, 2025	Johann + Gert +1h5 ahead of UTC

Metadata maintenance

	Arrival	Departure
Time difference between logger clock and UTC ($\pm$ mm:ss)	+00:08	00:00
Download data to PC and/or change SD card (wait for green light)	Y/N	Y/N
Name of logger program	WVetv2-6	-11-
Screen dump of values in fast scan mode	Y/N	Y/N
Photos of mast, sensors, logger box wiring etc. (more is better)	Y/N	Y/N
Upper boom direction with radiometer relative to north	$^{\circ}$ true/magn.	$^{\circ}$ true/magn.
Lower boom perpendicular to upper boom. If not, measure.	Y/N	Y/N
Box on upper wind sensor exactly same direction as radiometer? If not, measure.	See photo for Y/N errata.	Y/N
Box on lower wind sensor exactly same direction as radiometer? If not, measure.	Varies Y/N loose!	Y/N
Upper temperature / humidity height (bottom of casing – surface)	418 cm	cm
Lower temperature / humidity height (bottom of casing – surface)	292 cm	cm
Upper sonic ranger height (bottom of casing – surface)	367 cm	cm
Lower sonic ranger height (bottom of casing – surface)	263 cm	cm
Length of thermistor string on surface from surface marking	N/A cm	cm
Apparent damage to sensors? If yes, which?	Y/N	Y/N

Notes:

Height of snowboard stake: 65 cm
 Depth to snowboard : 110 cm
 Height of thermistor PVC tube : 118 cm
 Depth to battery box : 116 cm

Departure : snowb. stake : 158 cm
 therm. PVC : 316 cm

GNSS AWS dist to mast
 → 0 cm

measurement done while there was a lot of activity over and around the antenna but we had no choice ...

- GNSS from JJ installed, Antenna connector at antenna broke during installation

Must-do at next visit:

Young Wind lower taped and loose - turning a bit in wind
 Young + upper box is not pointing south (azim. photo taken for a ref)
 Invisu antenna taped to logger box (plus)

Arrival notes

→ - New Antenna and ~~wire~~ for GNSS Setup
 Antenna cable

- Must bring new Young Wind sensor for lower - it was & is broken, but fixed with tape

- Mast tilting $\sim 5^{\circ}$: maybe consider erecting new mast in 2026