SPN	FMI	DTC	SYMPTOM/CAUSE	RECOVERY FROM ERROR
3242	0	Emergency exhaust gas temperature sensor 1: High	DPF inlet temperature higher than 1319° F (715° C). Engine stops. Inhibit starter relay activation until exhaust temperatures reduces down to 572° F (300° C).	Under 572° F (300° C) and key switch turn OFF.
3242	3	Exhaust gas temperature sensor 1: High	Open circuit or +B short circuit of sensor/harness. DPF inlet temperature sensor voltage 4.92V or more.	Key switch turn OFF.
3242	4	Exhaust gas temperature sensor 1: Low	Ground short circuit of sensor/ harness. DPF inlet temperature sensor voltage 0.08V or less.	Key switch turn OFF.
3246	0	Emergency exhaust gas temperature sensor 2: High	DPF outlet temperature 1508° F (820° C) or more.	Under 572° F (300° C) and key switch turn OFF. Inhibit starter relay activation until exhaust temperature reduces down to 572° F (300° C).
3246	3	Exhaust gas temperature sensor 2: High	Open circuit or +B short circuit of sensor/harness. DPF outlet temperature sensor voltage 4.92V or more.	Key switch turn OFF.
3246	4	Exhaust gas temperature sensor 2: Low	Ground short circuit of sensor/ harness. DPF outlet temperature sensor voltage 0.08V or less.	Key switch turn OFF.
3251	3	Differential pressure sensor 1: High	Open circuit or +B short circuit of sensor/harness. DPF differential pressure sensor voltage 4.7V or more.	Key switch turn OFF.
3251	4	Differential pressure sensor 1: Low	Ground short circuit of sensor/ harness. DPF differential pressure sensor voltage 0.21V or less.	Key switch turn OFF.
3252	0	Emission deterioration.	DOC is heated due to unburned fuel. Output and accelerator limitation 50%. EGR stops.	Key switch turn OFF to minimize emission to DPF.
3509	3	Sensor supply voltage 1: High	Voltage to sensor is above 5.625V. EGR stops. Faulty starting. Engine may stop. Emission related.	Key switch turn OFF.
3509	4	Sensor supply voltage 1: Low	Voltage to sensor is below 4.375V. EGR stops. Faulty starting. Engine may stop. Emission related.	Key switch turn OFF.
3510	3	Sensor supply voltage 2: High	Voltage to sensor is above 5.625V. Faulty starting. Emission related.	Key switch turn OFF.
3510	4	Sensor supply voltage 2: Low	Voltage to sensor is below 4.375V. Faulty starting. Emission related.	Key switch turn OFF.
3511	3	Sensor supply voltage 3: High	Voltage to sensor is above 5.25V. Faulty starting.	Key switch turn OFF.
3511	4	Sensor supply voltage 3: Low	Voltage to sensor is below 4.75V. Faulty starting.	Key switch turn OFF.

SPN	FMI	DTC	SYMPTOM/CAUSE	RECOVERY FROM ERROR
3701	0	Excessive PM 5.	PM accumulation more than trigger level. Regeneration Level = 5.	Key switch turn OFF. **Engine not forcibly stopped by ECU. STRONGLY recommend operator to stop engine promptly.** Must be reset by Kubota service tool.
3701	15	Excessive PM 3.	PM accumulation more than trigger level. Regeneration Level = 3.	Diagnostic counter = 0
3701	16	Excessive PM 4.	PM accumulation more than trigger level. Regeneration Level = 4.	Diagnostic counter = 0
4765	0	Emergency exhaust gas temperature sensor 0: High	DOC inlet temperature 1292° F (700° C) or more. Engine stops.	Key switch turn OFF. Inhibit starter relay activation until exhaust temperature reduces down to 527° F (300° C).
4765	3	Exhaust gas temperature sensor 0: High	Open circuit or +B short circuit of sensor/harness. DOC inlet temperature sensor voltage 4.92V or more.	Key switch turn OFF.
4765	4	Exhaust gas temperature sensor 0: Low	Open circuit or +B short circuit of sensor/harness. DOC inlet temperature sensor voltage 0.08V or less.	Key switch turn OFF.
523523	2	Injector drive circuit open in Nos. 1 & 4 cylinder simultaneously.	Wiring harness open circuit. Injectors that have no DTC are operated. Engine vibration increases and may stop.	Key switch turn OFF.
523523	3	Nos. 1 & 4 cylinder injector short to +B at power supply side, or all cylinder injectors short to +B.	Wiring harness short to +B. Injectors that have no DTC are operated. Engine vibration increases and may stop.	Key switch turn OFF.
523523	4	Nos. 1 & 4 cylinder injector short to ground at power supply side, or all cylinder injectors short to ground.	Wiring harness short to ground. Injectors that have no DTC are operated. Engine vibration increases and may stop.	Key switch turn OFF.
523524	2	Injector drive circuit open in Nos. 2 & 3 cylinder simultaneously.	Wiring harness open circuit. Injectors that have no DTC are operated. Engine vibration increases and may stop.	Key switch turn OFF.
523524	3	Nos. 2 & 3 cylinder injector short to +B at power supply side, or all cylinder injectors short to +B.	Wiring harness short to +B. Injectors that have no DTC are operated. Engine vibration increases and may stop.	Key switch turn OFF.
523524	4	Nos. 2 & 3 cylinder injector short to ground at power supply side, or all cylinder injectors short to ground.	Wiring harness short to ground. Injectors that have no DTC are operated. Engine vibration increases and may stop.	Key switch turn OFF.
523525	1	Injector charge voltage low.	Injector charge voltage low. Failure of charge circuit of ECU. Engine may stop.	Key switch turn OFF.

SPN	FMI	DTC	SYMPTOM/CAUSE	RECOVERY FROM ERROR
523527	2	ECU monitoring error.	Failure of monitoring IC of CPU. Engine stops.	Key switch turn OFF.
523535	0	Injector charge voltage: High	EGR stops. Engine forcibly stops 60 seconds later.	Key switch turn OFF.
523536	2	EGR feedback error.	DC motor feedback control error. During wrong duty feedback, activation of restoration will repeat 30 times. If the restoration was not successfully completed, it will be judged as a feedback error. EGR stops.	Diagnostic counter = zero
523537	2	EGR DC motor temperature error.	Estimated temperature is 113° F (45° C) or above. EGR stops.	Diagnostic counter = zero
523538	2	QR data error.	QR data read error from EEPROM. Nozzle correction is not executed.	Key switch turn OFF.
523539	2	Pump seizing 1.	Rail pressure of 230 MPa (33400 psi or 2350 kgf/cm^2) or more continues one second under the condition of above 800 min-1 (rpm). Under 800 min-1 (rpm) condition, rail pressure of 220 MPa (31900 psi or 2250 kgf/cm^2) or more continues one second under the condition of below 800 min-1 (rpm). [Threshold changes depending upon the engine speed. 700 min-1 (rpm) should be used as a reference.	Key switch turn OFF to minimize PM emission to DPF and avoid extremely high pressure in injection system.
523540	2	Pump seizing 2.	Rail pressure of 197MPa (28600 psi or 2010 kgf/cm^2) or more continues one second under the condition of above 800 min-1 (rpm). Under 800 min-1 (rpm) condition, rail pressure of 220 MPa (31900 psi or 2250 kgf/cm^2) or more continues one second under the condition of below 800 min-1 (rpm). [Threshold changes depending upon the engine speed. 700 min-1 (rpm) should be used as a reference.	Key switch turn OFF.
523541	3	EGR lift sensor: High	+B short circuit of sensor/harness. Failure of sensor. Voltage of ECR lift sensor is 4.5V or above. EGR stops.	Key switch turn OFF.
523541	4	EGR lift sensor: Low	Open circuit or short circuit of sensor/ harness. Failure of sensor. Voltage of ECR lift sensor is 0.3V or less. EGR stops.	Key switch turn OFF.
523543	2	Accelerator position sensor error (CAN).	Accelerator position sensor signal error (sensor/harness open circuit, ground short circuit, etc.).	Diagnostic counter = zero. CAN signal recovers.
523544	3	+B short of air heater relay driving circuit.	+B short circuit of harness. Faulty starting. White smoke increases.	Key switch turn OFF.

SPN	FMI	DTC	SYMPTOM/CAUSE	RECOVERY FROM ERROR
523544	4	Ground short of air heater relay driving circuit.	Ground short or open circuit of harness.	Key switch turn OFF.
523547	2	CAN2 bus off.	CAN2 bus off.	Key switch turn OFF.
523548	2	CAN-KBT frame error.	CAN-KBT frame open circuit error.	Key switch turn OFF.
523572	4	EGR position sensor failure.	EGR position sensor error signal received via CAN. EGR stops.	Key switch turn OFF.
523574	3	EGR actuator open circuit.	EGR actuator open error signal received via CAN. EGR stops.	Key switch turn OFF.
523575	7	EGR actuator valve stuck.	EGR actuator valve stuck error received via CAN. EGR stops.	Key switch turn OFF.
523576	2	EGR (DC motor) overheat.	EGR (DC motor) temperature error signal received via CAN (exceeds 257° F or 125° C). EGR stops.	Key switch turn OFF.
523577	2	EGR (DC motor) temperature sensor failure.	EGR (DC motor) temperature sensor error signal received via CAN. EGR stops.	Key switch turn OFF.
523578	2	No communication with EGR.	Interruption of CAN. EGR stops.	Key switch turn OFF.
523580	2	Intake throttle feedback error.	Deviation of throttle position is not corrected in 20 times of duty error recovery action.	Key switch turn OFF.
523582	3	Intake throttle lift sensor: High	Intake throttle lift sensor voltage 4.89V or more.	Key switch turn OFF.
523582	4	Intake throttle lift sensor: Low	Intake throttle lift sensor voltage 0.1V or less.	Key switch turn OFF.
523589	17	Low coolant temperature in parked regeneration.	During regeneration mode, engine warm-up condition is not satisfied because coolant temperature is too low (below 149° F or 65° C).	Diagnostic counter = zero Leaving from Parked active regeneration status.
523590	16	Parked regeneration timed out.	Regeneration incomplete due to low temperature of DPF.	Diagnostic counter = zero Leaving from Parked active regeneration status.
523591	2	CAN CCVS (parking and vehicle speed) frame error.	CAN CCVS frame time-out error. Parking SW = off. Vehicle speed = 0	Key switch turn OFF.
523592	2	CAN CM1 (Regen SW) frame error.	CAN CM1 frame time-out error. Regeneration inhibit = on. Parked regeneration SW = off.	Key switch turn OFF.
523593	2	CAN DDC1 (transmission) frame error.	CAN DDC1 frame time-out error.	Key switch turn OFF.
523594	2	CAN ETC2 (neutral SW) frame error.	CAN ETC2 frame time-out error	Key switch turn OFF.
523595	2	CAN ETC5 (neutral SW) frame error.	CAN ETC5 frame time-out error.	Key switch turn OFF.
523596	2	CAN TSC1 frame error.	No request to “TSC1 buffer” continues three times after over-ride control request (other than 0x00).	Diagnostic counter = zero

LEEBOY
FAYAT GROUP

500 Lincoln County Parkway Ext.
Lincolnton, North Carolina 28092
Phone: (704) 966-3300 - Fax Sales: (704) 483-5802

Scan QR Code to download and view this manual.

www.LeeBoy.com

Printed in the U.S.A.