

TECHNICAL SERVICE BULLETIN INFORMATION

Technical Service Bulletin No: TB – 0123-T89P-002		Release Date: 05 th Jan 2023
<u>Vehicle:</u>	BB	
<u>Applied Models:</u>	B20 – Elite 2019 – 2022 models	
<u>Region:</u>	INDIA	
<u>Variant:</u>	All variants & All editions including special edition	
<u>Affected - ECU/Functionality/Parts</u>	BCM ECU	
<u>Issue:</u>	Sunroof DTC's are raised B2340-11, B2340-12, B2340-13 in BCM ECU	
<u>Issue Description:</u>	DTC related to sunroof raised in BCM ECU which functionality is not applicable for the vehicle	
<u>Solution:</u>	If the DTC B2340-11, B2340-12 & B2340-13 is raised, Perform the below actions based on the DTC state. <u>DTC raised and its in memorized state:</u> Erase the faults and perform BCM ECU Re-flashing by following corresponding procedure. <u>DTC raised and its in present state:</u> Perform BCM ECU Re-flashing by following corresponding procedure.	