

SERVICE CIRCULAS No. 1, Sardar Patel Road, Guindy, Chennai - 600 032. Web : www.ashokleyland.com

> SRV: CIR: 34: 2016 05th Jul 2016


To

ALL VEHICLE DEALERS / ASCs


SUB: IMPROVED REAR SPRING MIDDLE BRACKET MOUNTING - CT25XX HAULAGE AND TIPPER, **CT31XX TWIN STEER HAULAGE MODELS**

As a durability improvement, rear spring middle bracket mounting has been improved with the following changes,

- > Rear spring middle bracket (RSMB) mounting bolts 6 nos. changed to M16 bolts and AMPT nuts in place of M14 bolts and clevloc nuts
- Rear spring middle cross member gusset thickness changed from 6.3mm to 8mm
- Consequentially FSM, internal flitch and external flitch (LH and RH) have been modified. Details given below.
 - In FSM (LH and RH), RSMB mounting holes dia. increased from 14.5mm to 16.5mm
 - In external and internal flitch (LH and RH), RSMB mounting hole dia. increased from 14.5mm to 16.5mm
 - o In external flitch (LH and RH), RSMB dowel pin mounting hole dia. 13.5mm added



Rear spring middle cross member



Parts Add / Delete List: Common for all models

Sl.no.	Part Description	Added Part No.	Deleted Part No.	Quantity
1	Rear spring middle cross member	-	B1088507	1
2	Rear spring middle cross member	FCF05313	-	1
3	Rear spring middle bracket	-	X0404522	2
4	Sub assy. of rear spring middle bracket	B5B27105	-	2
5	Special Flanged Bolt - Hex - M14 X 2 CP X 65mm LONG X GR 10.9	-	X3516910	12
6	Special Flanged Bolt - Hex - M16 X 2 CP X 75mm LONG X GR 10.9	FYJ00119	-	4
7	Special Flanged Bolt - Hex - M16 X 2 CP X 70.7mm LONG X GR 10.9	F1B00421	-	8
8	Special Nut - Clevloc - M14 X 2CP X 12mm LONG X GR 10	-	F3562810	12
9	Special Flanged Nut - HEX - M16 X 2 CP X 18.3mm LONG X GR 10	F7F00810	-	12

Note:

- There is no change in part no. of frame side member, internal flitch and external flitch (LH and RH).
- Modified rear spring middle bracket is not interchangeable with existing part.

Cut off details: CT25XX TIPPER

Ennore: Chassis no - MB1HTDFD2GEEU4856, Month Feb -16

Hosur-II: Chassis no - MB1HTDFD1GRFN4483, Month Jan -16

PNR: Chassis no - MB1HTDFD2GPES5647, Month Feb -16

Cut off details: CT25XX HAULAGE, CT31XX TWIN STEER HAULAGE

Hosur-II: Chassis no - MB1DTKYC4GRBP2231, Month May -16

After market preparedness:

THE THAT WE FOR CALLEDS					
Rear Spring middle cross member mounting	Tightening torque range remains same 80 - 100 Nm				
Rear Spring middle bracket mounting	Tightening torque range changed from 185 - 205 Nm to 285 - 315 Nm				

Please monitor the performance and provide feedback.

Thanking you,

Yours faithfully, For ASHOK LEYLAND LTD.

R.THANGARAJ

DEPUTY GENERAL MANAGER - SERVICE