

GET it digital

Modul 6: Magnetic quantities



Stand: 18. Februar 2026



Further use as OER is expressly permitted: This work and its contents are licensed under CC BY 4.0. Excluded from the license are the logos used as well as all elements marked otherwise. Attribution according to the TULLU rule should be given as follows: “GET it digital module 6: Magnetic quantities” by R. Wegener, G. Lisicki, J. Kirschner, License: CC BY 4.0.

The license agreement is available here:

<https://creativecommons.org/licenses/by/4.0/deed.de>

The work is available online at:


<https://getitdigital.uni-wuppertal.de/module/modul-6-magnetische-groessen>




Learning objectives: Magnetic quantities

The students


- ▶ know the basic magnetic quantities in the magnetic circuit.
- ▶ understand the physical principles behind the individual magnetic quantities.
- ▶ can describe the interactions between magnetic quantities.
- ▶ can calculate the individual quantities in the magnetic circuit.




Magnetismus




Magnetic field



Magnetic field




Magnetic field




- Magnetic field lines are always closed (source-free)..


Magnetic field





- ▶ Magnetic field lines are always closed (source-free)..
- ▶ Outside the magnet, they run from the north pole to the south pole.




- ▶ Magnetic field lines are always closed (source-free)..
- ▶ Outside the magnet, they run from the north pole to the south pole.
- ▶ They always exit or enter the magnetic surface perpendicularly.






Magnetic flux




Flux or magnetic tension Θ (Theta) =
Total current of a fluxed area


Electrical
flux
 $= N \cdot I$



Magnetic flux




Electrical
flux
 $= N \cdot I$




Flux or magnetic tension Θ (Theta) =
Total current of a fluxed area

$$\Theta = \sum_n I_n = N \cdot I \quad (\text{simplified})$$

Magnetic flux



Electrical
flux
 $= N \cdot I$




Flux or magnetic tension Θ (Theta) =
Total current of a fluxed area

$$\Theta = \sum_n I_n = N \cdot I \quad (\text{simplified})$$

$$\Theta = \iint_A \vec{J} \cdot d\vec{A} \quad (\text{generally})$$

Magnetic flux



Electrical
flux
 $= N \cdot I$

Flux or magnetic tension Θ (Theta) =
Total current of a fluxed area


$$\Theta = \sum_n I_n = N \cdot I \quad (\text{simplified})$$

$$\Theta = \iint_A \vec{J} \cdot d\vec{A} \quad (\text{generally})$$

$$\Theta = \oint_s \vec{H} \cdot d\vec{s} \quad [\text{A}]$$

H is the magnetic field strength
 s is the edge of the area A

Magnetic field strength



If $\vec{H}$ is constant over the integration path $d\vec{s}$:

$$\oint_s \vec{H} \cdot d\vec{s} = |\vec{H}| \cdot \ell_m$$

$$|\vec{H}| = \frac{\Theta}{\ell_m} \quad \left[\frac{\text{A}}{\text{m}} \right]$$

Example: Magnetic field strength

A toroidal coil with 1000 turns and an average field line length of 50 cm is traversed by a current of 100 mA. How strong is the magnetic field?

Example: Magnetic field strength

A toroidal coil with 1000 turns and an average field line length of 50 cm is traversed by a current of 100 mA. How strong is the magnetic field?

$$\Theta = H \cdot \ell_{\text{m}} = N \cdot I$$

Example: Magnetic field strength

A toroidal coil with 1000 turns and an average field line length of 50 cm is traversed by a current of 100 mA. How strong is the magnetic field?

$$\Theta = H \cdot \ell_{\text{m}} = N \cdot I$$

$$H = \frac{N \cdot I}{\ell_{\text{m}}}$$

Example: Magnetic field strength

A toroidal coil with 1000 turns and an average field line length of 50 cm is traversed by a current of 100 mA. How strong is the magnetic field?

$$\Theta = H \cdot \ell_m = N \cdot I$$
$$H = \frac{N \cdot I}{\ell_m} = \frac{1000 \cdot 0,1 \text{ A}}{0,5 \text{ m}} = 200 \frac{\text{A}}{\text{m}}$$

Example: Magnetic field strength

A toroidal coil with 1000 turns and an average field line length of 50 cm is traversed by a current of 100 mA. How strong is the magnetic field?

$$\Theta = H \cdot \ell_m = N \cdot I$$
$$H = \frac{N \cdot I}{\ell_m} = \frac{1000 \cdot 0,1 \text{ A}}{0,5 \text{ m}} = 200 \frac{\text{A}}{\text{m}}$$

A direct current of $I = 50 \text{ A}$ flows through a straight conductor. How strong is the magnetic field at a distance of $r = 20 \text{ cm}$?

Example: Magnetic field strength

A toroidal coil with 1000 turns and an average field line length of 50 cm is traversed by a current of 100 mA. How strong is the magnetic field?

$$\Theta = H \cdot \ell_m = N \cdot I$$
$$H = \frac{N \cdot I}{\ell_m} = \frac{1000 \cdot 0,1 \text{ A}}{0,5 \text{ m}} = 200 \frac{\text{A}}{\text{m}}$$

A direct current of $I = 50 \text{ A}$ flows through a straight conductor. How strong is the magnetic field at a distance of $r = 20 \text{ cm}$?

$$H = \frac{N \cdot I}{\ell_m}$$

Example: Magnetic field strength


A toroidal coil with 1000 turns and an average field line length of 50 cm is traversed by a current of 100 mA. How strong is the magnetic field?

$$\Theta = H \cdot \ell_m = N \cdot I$$
$$H = \frac{N \cdot I}{\ell_m} = \frac{1000 \cdot 0,1 \text{ A}}{0,5 \text{ m}} = 200 \frac{\text{A}}{\text{m}}$$

A direct current of $I = 50 \text{ A}$ flows through a straight conductor. How strong is the magnetic field at a distance of $r = 20 \text{ cm}$?

$$H = \frac{N \cdot I}{\ell_m} = \frac{1 \cdot 50 \text{ A}}{2\pi \cdot 0,2 \text{ m}} = 39,79 \frac{\text{A}}{\text{m}}$$

Magnetic flux and flux density



Magnetic flux density:


$$\vec{B} \quad [\text{T}]$$

Permeability:

$$\mu \quad [1]$$

$$\vec{B} = \mu_0 \cdot \mu_r \cdot \vec{H}$$

Magnetic flux and flux density



Magnetic flux density:

$$\vec{B} \quad [\text{T}]$$

Permeability:

$$\mu \quad [1]$$

$$\vec{B} = \mu_0 \cdot \mu_r \cdot \vec{H}$$


Magnetic flux:

$$\Phi \quad [\text{Wb}]$$

$$\Phi = \iint_A \vec{B} \cdot d\vec{A}$$

$$\vec{B} = \frac{\Phi}{\vec{A}}$$

Magnetic flux and flux density



Hard magnetic:

$$H_c > 10 \cdot 10^3 \frac{\text{A}}{\text{m}}$$


e.g. permanent magnets

Soft magnetic:

$$H_c < 500 \frac{\text{A}}{\text{m}}$$

e.g. actuators

Magnetic flux and flux density



Hard magnetic:

$$H_c > 10 \cdot 10^3 \frac{\text{A}}{\text{m}}$$

e.g. permanent magnets

Soft magnetic:


$$H_c < 500 \frac{\text{A}}{\text{m}}$$

e.g. actuators

Remanence flux density

$$B_r$$

Magnetic flux and flux density



Hard magnetic:

$$H_c > 10 \cdot 10^3 \frac{\text{A}}{\text{m}}$$

e.g. permanent magnets

Soft magnetic:


$$H_c < 500 \frac{\text{A}}{\text{m}}$$

e.g. actuators

Remanence flux density

$$B_r$$

Magnetic flux and flux density



Hard magnetic:

$$H_c > 10 \cdot 10^3 \frac{\text{A}}{\text{m}}$$

e.g. permanent magnets

Soft magnetic:

$$H_c < 500 \frac{\text{A}}{\text{m}}$$

e.g. actuators

Remanence flux density

$$B_r$$

Coercive field strength H_c

Example: Magnetic flux density

Inside a tightly wound toroidal coil, a magnetic field strength of $H = 100 \frac{\text{A}}{\text{m}}$ is to be generated. The coil has a mean radius of 5 cm.

1. Calculate the required current I if the coil has $N = 200$ windings.

Example: Magnetic flux density

Inside a tightly wound toroidal coil, a magnetic field strength of $H = 100 \frac{\text{A}}{\text{m}}$ is to be generated. The coil has a mean radius of 5 cm.

1. Calculate the required current I if the coil has $N = 200$ windings.

$$\Theta = H \cdot \ell_{\text{m}} = N \cdot I$$

$$I = \frac{H \cdot \ell_{\text{m}}}{N} = \frac{100 \frac{\text{A}}{\text{m}} \cdot 2 \cdot \pi \cdot 5 \cdot 10^{-2} \text{ m}}{200} = 157,08 \text{ mA}$$

Example: Magnetic flux density

Inside a tightly wound toroidal coil, a magnetic field strength of $H = 100 \frac{\text{A}}{\text{m}}$ is to be generated. The coil has a mean radius of 5 cm.

1. Calculate the required current I if the coil has $N = 200$ windings.

$$\Theta = H \cdot \ell_m = N \cdot I$$

$$I = \frac{H \cdot \ell_m}{N} = \frac{100 \frac{\text{A}}{\text{m}} \cdot 2 \cdot \pi \cdot 5 \cdot 10^{-2} \text{ m}}{200} = 157,08 \text{ mA}$$

2. How large will the flux density B be in the case of an air coil ($\mu_r = 1$) or an iron-filled coil ($\mu_r = 2000$ at the operating point)?

Example: Magnetic flux density

Inside a tightly wound toroidal coil, a magnetic field strength of $H = 100 \frac{\text{A}}{\text{m}}$ is to be generated. The coil has a mean radius of 5 cm.

1. Calculate the required current I if the coil has $N = 200$ windings.

$$\Theta = H \cdot \ell_m = N \cdot I$$


$$I = \frac{H \cdot \ell_m}{N} = \frac{100 \frac{\text{A}}{\text{m}} \cdot 2 \cdot \pi \cdot 5 \cdot 10^{-2} \text{ m}}{200} = 157,08 \text{ mA}$$

2. How large will the flux density B be in the case of an air coil ($\mu_r = 1$) or an iron-filled coil ($\mu_r = 2000$ at the operating point)?

$$B_{\text{Luft}} = \mu_0 \cdot \mu_r \cdot H = 1,256 \cdot 10^{-6} \frac{\text{Vs}}{\text{Am}} \cdot 100 \frac{\text{A}}{\text{m}} = 125,6 \mu\text{T}$$

$$B_{\text{Eisen}} = 2000 \cdot B_{\text{Luft}} = 251,2 \text{ mT}$$

Magnetic flux and flux density



Magnetische Flussdichte:


$$\vec{B} \quad [\text{T}]$$

Permeabilität:

$$\mu \quad [1]$$

$$\vec{B} = \mu_0 \cdot \mu_r \cdot \vec{H}$$

Magnetic flux and flux density



Magnetische Flussdichte:

$$\vec{B} \quad [\text{T}]$$

Permeabilität:

$$\mu \quad [1]$$

$$\vec{B} = \mu_0 \cdot \mu_r \cdot \vec{H}$$


Magnetic flux:

$$\Phi \quad [\text{Wb}]$$

$$\Phi = \iint_A \vec{B} \cdot d\vec{A}$$

$$\vec{B} = \frac{\Phi}{\vec{A}}$$

Magnetic flux and flux density



Hard magnetic:

$$H_c > 10 \cdot 10^3 \frac{\text{A}}{\text{m}}$$


e.g. permanent magnets

Soft magnetic:

$$H_c < 500 \frac{\text{A}}{\text{m}}$$

e.g. actuators

Magnetic flux and flux density



Hard magnetic:

$$H_c > 10 \cdot 10^3 \frac{\text{A}}{\text{m}}$$

e.g. permanent magnets

Soft magnetic:


$$H_c < 500 \frac{\text{A}}{\text{m}}$$

e.g. actuators

Remanence flux density

$$B_r$$

Magnetic flux and flux density



Hard magnetic:

$$H_c > 10 \cdot 10^3 \frac{\text{A}}{\text{m}}$$

e.g. permanent magnets

Soft magnetic:


$$H_c < 500 \frac{\text{A}}{\text{m}}$$

e.g. actuators

Remanence flux density

$$B_r$$

Magnetic flux and flux density



Hard magnetic:

$$H_c > 10 \cdot 10^3 \frac{\text{A}}{\text{m}}$$

e.g. permanent magnets

Soft magnetic:

$$H_c < 500 \frac{\text{A}}{\text{m}}$$

e.g. actuators

Remanence flux density

$$B_r$$

Coercive field strength H_c

Example: Magnetic flux density

Inside a tightly wound toroidal coil, a magnetic field strength of $H = 100 \frac{\text{A}}{\text{m}}$ is to be generated. The coil has an average radius of 5 cm.

1. Calculate the required current I if the coil has $N = 200$ windings.

Example: Magnetic flux density

Inside a tightly wound toroidal coil, a magnetic field strength of $H = 100 \frac{\text{A}}{\text{m}}$ is to be generated. The coil has an average radius of 5 cm.

1. Calculate the required current I if the coil has $N = 200$ windings.

$$\Theta = H \cdot \ell_{\text{m}} = N \cdot I$$

$$I = \frac{H \cdot \ell_{\text{m}}}{N} = \frac{100 \frac{\text{A}}{\text{m}} \cdot 2 \cdot \pi \cdot 5 \cdot 10^{-2} \text{ m}}{200} = 157,08 \text{ mA}$$

Example: Magnetic flux density

Inside a tightly wound toroidal coil, a magnetic field strength of $H = 100 \frac{\text{A}}{\text{m}}$ is to be generated. The coil has an average radius of 5 cm.

1. Calculate the required current I if the coil has $N = 200$ windings.

$$\Theta = H \cdot \ell_{\text{m}} = N \cdot I$$

$$I = \frac{H \cdot \ell_{\text{m}}}{N} = \frac{100 \frac{\text{A}}{\text{m}} \cdot 2 \cdot \pi \cdot 5 \cdot 10^{-2} \text{ m}}{200} = 157,08 \text{ mA}$$

2. How large will the flux density B be in the case of an air coil ($\mu_{\text{r}} = 1$) or an iron-filled coil ($\mu_{\text{r}} = 2000$ at the operating point)?

Example: Magnetic flux density

Inside a tightly wound toroidal coil, a magnetic field strength of $H = 100 \frac{\text{A}}{\text{m}}$ is to be generated. The coil has an average radius of 5 cm.

1. Calculate the required current I if the coil has $N = 200$ windings.

$$\Theta = H \cdot \ell_{\text{m}} = N \cdot I$$



$$I = \frac{H \cdot \ell_{\text{m}}}{N} = \frac{100 \frac{\text{A}}{\text{m}} \cdot 2 \cdot \pi \cdot 5 \cdot 10^{-2} \text{ m}}{200} = 157,08 \text{ mA}$$

2. How large will the flux density B be in the case of an air coil ($\mu_{\text{r}} = 1$) or an iron-filled coil ($\mu_{\text{r}} = 2000$ at the operating point)?



$$B_{\text{Luft}} = \mu_0 \cdot \mu_{\text{r}} \cdot H = 1,256 \cdot 10^{-6} \frac{\text{Vs}}{\text{Am}} \cdot 100 \frac{\text{A}}{\text{m}} = 125,6 \mu\text{T}$$

$$B_{\text{Eisen}} = 2000 \cdot B_{\text{Luft}} = 251,2 \text{ mT}$$

Magnetic resistance



Magnetic resistance





$$R_m = \frac{\ell_m}{\mu_r \cdot \mu_0 \cdot A} \quad \left[\frac{\text{A}}{\text{V} \cdot \text{s}} \right]$$

Analogous to Ohm's law for electricity, the following applies to magnetic circuits:


$$\Theta = R_m \cdot \Phi$$

Lorentz force







Lorentz force



Lorentz force




Lorentz force




A force acts on a unit charge q moving at velocity $\vec{v}$ in a magnetic field $\vec{B}$:


$$\vec{F} = q \cdot (\vec{v} \cdot \vec{B})$$





$$F = q \cdot v \cdot B \cdot \sin \alpha$$

$$F = I \cdot \ell \cdot N \cdot B \cdot \sin \alpha$$









Example: Lorentz force

A direct current motor has a magnetic flux density of $B = 0.8 \text{ T}$ in the air gap. There are a total of $N = 400$ windings under the poles, through which a current of $I = 10 \text{ A}$ flows. The effective conductor length is $\ell = 150 \text{ mm}$.

Calculate the force F at the circumference of the anchor.


A direct current motor has a magnetic flux density of $B = 0.8 \text{ T}$ in the air gap. There are a total of $N = 400$ windings under the poles, through which a current of $I = 10 \text{ A}$ flows. The effective conductor length is $\ell = 150 \text{ mm}$.


Calculate the force F at the circumference of the anchor.


$$\begin{aligned} F &= B \cdot I \cdot \ell \cdot N \\ &= 0,8 \frac{\text{Vs}}{\text{m}^2} \cdot 10 \text{ A} \cdot 0,15 \text{ m} \cdot 400 \\ &= 480 \frac{\text{kg} \cdot \text{m}^2 \cdot \text{s} \cdot \text{A} \cdot \text{m}}{\text{s}^3 \cdot \text{A} \cdot \text{m}^2} = 480 \text{ N} \end{aligned}$$

Force between two straight, parallel, thin and infinitely long conductors:

$$F_{12} = \frac{\ell \cdot \mu_0 \cdot I_1 \cdot I_2}{2 \cdot \pi \cdot r}$$







$$u_i = B \cdot \ell \cdot v \cdot N$$

The magnitude of the induced voltage depends on:

- ▶ the magnetic flux density B
- ▶ the length of the conductor in the magnetic field ℓ
- ▶ the speed of movement or change in flow v
- ▶ the number of conductors in the magnetic field N

General law of induction:

$$u_i = -N \cdot \frac{d\Phi}{dt}$$

General law of induction:

$$u_i = -N \cdot \frac{d\Phi}{dt}$$

Lenz's law:

Cause and effect are always opposite.



$$L = \frac{N \cdot \Phi}{I} \quad [\text{H}]$$





$$L = \frac{N \cdot \Phi}{I} \quad [\text{H}]$$


$$u = -L \cdot \frac{di}{dt}$$



$$L = \frac{N \cdot \Phi}{I} \quad [\text{H}]$$

$$u = -L \cdot \frac{di}{dt}$$





For simple geometric structures, the inductance can be determined via the magnetic resistance:

$$L = \frac{N^2}{R_m}$$

Method 1 using field sizes:

1. Assumption of a current $I \rightarrow$ flow

$$\Theta = N \cdot I$$

2. Calculate field strength

$$H = \frac{\Theta}{\ell_m}$$

3. Calculate flux density

$$B = \mu_r \cdot \mu_0 \cdot H$$

4. Determine magnetic flux

$$\Phi = \iint_A \vec{B} \cdot d\vec{A}$$

5. Inductance

$$L = \frac{N \cdot \Phi}{I}$$

Method 1 using field sizes:


1. Assumption of a current $I \rightarrow$ flow
 $\Theta = N \cdot I$
2. Calculate field strength
 $H = \frac{\Theta}{\ell_m}$
3. Calculate flux density
 $B = \mu_r \cdot \mu_0 \cdot H$
4. Determine magnetic flux
 $\Phi = \iint_A \vec{B} \cdot d\vec{A}$
5. Inductance
 $L = \frac{N \cdot \Phi}{I}$

Method 2 via magnetic resistance:

1. Divide the magnetic circuit into sections and magnetic resistance R_m calculate
 $R_m = \frac{\ell_m}{\mu_r \cdot \mu_0 \cdot A}$
2. Calculate total resistance (for series structure)
 $R_{m,ges} = \sum R_m$
3. Inductance
 $L = \frac{N^2}{R_{m,ges}}$

Example: Inductance

For a coil with an iron core and air gap, the influence of the air gap d on the inductance L is to be investigated. The coil has $N = 100$ turns. The relative permeability is $\mu_r = 2000$. The average iron core length is $\ell_m = 5$ cm. The cross-sectional area is $A = 1$ cm².



- ▶ The air gap does not exist for the time being: $d = 0$. How large is the inductance L ?

- The air gap does not exist for the time being: $d = 0$. How large is the inductance L ?

$$R_m = \frac{\ell_m}{\mu_r \cdot \mu_0 \cdot A}$$
$$L = \frac{N^2}{R_m}$$

- The air gap does not exist for the time being: $d = 0$. How large is the inductance L ?

$$R_m = \frac{\ell_m}{\mu_r \cdot \mu_0 \cdot A}$$

$$L = \frac{N^2}{R_m}$$

$$L = \frac{100^2 \cdot 2000 \cdot 1,256 \cdot 10^{-6} \frac{\text{Vs}}{\text{Am}} \cdot 1 \cdot 10^{-4} \text{ m}^2}{0,05 \text{ m}}$$

- The air gap does not exist for the time being: $d = 0$. How large is the inductance L ?

$$R_m = \frac{\ell_m}{\mu_r \cdot \mu_0 \cdot A}$$

$$L = \frac{N^2}{R_m}$$

$$L = \frac{100^2 \cdot 2000 \cdot 1,256 \cdot 10^{-6} \frac{\text{Vs}}{\text{Am}} \cdot 1 \cdot 10^{-4} \text{ m}^2}{0,05 \text{ m}}$$

$$L = 0,05 \frac{\text{Vs}}{\text{A}} = 50 \text{ mH}$$

- ▶ The air gap is now $d = 1 \text{ mm}$. How large is the inductance?

- The air gap is now $d = 1 \text{ mm}$. How large is the inductance?

$$\begin{aligned} R_m &= R_{m,\text{Fe}} + R_{m,\text{L}} \\ &= \frac{\ell_m - d}{\mu_r \cdot \mu_0 \cdot A} + \frac{d}{\mu_0 \cdot A} \end{aligned}$$


- The air gap is now $d = 1 \text{ mm}$. How large is the inductance?

$$\begin{aligned} R_m &= R_{m,\text{Fe}} + R_{m,\text{L}} \\ &= \frac{\ell_m - d}{\mu_r \cdot \mu_0 \cdot A} + \frac{d}{\mu_0 \cdot A} \\ &= \frac{0,05 \text{ m} - 0,001 \text{ m}}{2000 \cdot 1,256 \cdot 10^{-6} \frac{\text{Vs}}{\text{Am}} \cdot 1 \cdot 10^{-4} \text{ m}^2} + \frac{0,001 \text{ m}}{1,256 \cdot 10^{-6} \frac{\text{Vs}}{\text{Am}} \cdot 1 \cdot 10^{-4} \text{ m}^2} \end{aligned}$$


- The air gap is now $d = 1 \text{ mm}$. How large is the inductance?

$$\begin{aligned} R_m &= R_{m,\text{Fe}} + R_{m,\text{L}} \\ &= \frac{\ell_m - d}{\mu_r \cdot \mu_0 \cdot A} + \frac{d}{\mu_0 \cdot A} \\ &= \frac{0,05 \text{ m} - 0,001 \text{ m}}{2000 \cdot 1,256 \cdot 10^{-6} \frac{\text{Vs}}{\text{Am}} \cdot 1 \cdot 10^{-4} \text{ m}^2} + \frac{0,001 \text{ m}}{1,256 \cdot 10^{-6} \frac{\text{Vs}}{\text{Am}} \cdot 1 \cdot 10^{-4} \text{ m}^2} \\ L &= 1,226 \text{ mH} \end{aligned}$$

Energy in the magnetic field




$$p = \frac{dW}{dt} = u \cdot i \quad u = L \cdot \frac{di}{dt}$$



$$p = \frac{dW}{dt} = u \cdot i \quad u = L \cdot \frac{di}{dt}$$

$$dW_m = u_L \cdot i_L \cdot dt = L \cdot \frac{di}{dt} \cdot i_L \cdot dt = L \cdot i_L \cdot di_L$$



$$p = \frac{dW}{dt} = u \cdot i \quad u = L \cdot \frac{di}{dt}$$

$$dW_m = u_L \cdot i_L \cdot dt = L \cdot \frac{di}{dt} \cdot i_L \cdot dt = L \cdot i_L \cdot di_L$$

$$\begin{aligned} W_m &= L \cdot \int_0^I i_L \cdot di_L = \frac{1}{2} \cdot L \cdot I^2 \\ &= \frac{1}{2} \cdot N \cdot \Phi \cdot I \end{aligned}$$


Calculation based on field sizes:

$$\begin{aligned} W_m &= \ell_m \cdot A \cdot \int_0^{B_L} H dB \\ &= \ell_m \cdot A \cdot \frac{B_L^2}{2 \cdot \mu_r \cdot \mu_0} \end{aligned} \quad (1)$$


Calculation based on field sizes:

$$\begin{aligned} W_m &= \ell_m \cdot A \cdot \int_0^{B_L} H dB \\ &= \ell_m \cdot A \cdot \frac{B_L^2}{2 \cdot \mu_r \cdot \mu_0} \end{aligned} \quad (1)$$

$$\frac{W_m}{V} = \frac{B_L^2}{2 \cdot \mu_0} = \frac{F}{A}$$




Alternating current only utilises the surface of a conductor.



Alternating current only utilises the surface of a conductor.

$$\delta = \sqrt{\frac{\rho_R}{\pi \cdot \mu \cdot f}}$$



Alternating current only utilises the surface of a conductor.

$$\delta = \sqrt{\frac{\rho_R}{\pi \cdot \mu \cdot f}}$$

Frequency	Skin-Depth δ_{Cu}
5 Hz	29,7 mm
50 Hz	9,38 mm
500 Hz	2,97 mm
500 kHz	93,8 μ m

Example: Skin-depth

A copper conductor is traversed by a current with a frequency of $f = 50 \text{ Hz}$. The following values are given for the conductor:

- ▶ Absolute magnetic permeability: $\mu = 4\pi \cdot 10^{-7} \frac{\text{Vs}}{\text{Am}}$
- ▶ Specific resistance: $\rho_R = 0,01721 \frac{\Omega \cdot \text{mm}^2}{\text{m}}$

Calculate the skin depth δ of the conductor.

Example: Skin-depth

A copper conductor is traversed by a current with a frequency of $f = 50 \text{ Hz}$. The following values are given for the conductor:

- ▶ Absolute magnetic permeability: $\mu = 4\pi \cdot 10^{-7} \frac{\text{Vs}}{\text{Am}}$
- ▶ Specific resistance: $\rho_R = 0,01721 \frac{\Omega \cdot \text{mm}^2}{\text{m}}$

Calculate the skin depth δ of the conductor.

$$\delta = \sqrt{\frac{\rho_R}{\pi \cdot \mu \cdot f}}$$

Example: Skin-depth

A copper conductor is traversed by a current with a frequency of $f = 50 \text{ Hz}$. The following values are given for the conductor:

- ▶ Absolute magnetic permeability: $\mu = 4\pi \cdot 10^{-7} \frac{\text{Vs}}{\text{Am}}$
- ▶ Specific resistance: $\rho_R = 0,01721 \frac{\Omega \cdot \text{mm}^2}{\text{m}}$

Calculate the skin depth δ of the conductor.

$$\delta = \sqrt{\frac{\rho_R}{\pi \cdot \mu \cdot f}}$$
$$\delta = \sqrt{\frac{0,01721 \frac{\Omega \cdot \text{mm}^2}{\text{m}}}{\pi \cdot 4\pi \cdot 10^{-7} \frac{\text{Vs}}{\text{Am}} \cdot 50 \text{ Hz}}}$$

Example: Skin-depth


A copper conductor is traversed by a current with a frequency of $f = 50 \text{ Hz}$. The following values are given for the conductor:


- ▶ Absolute magnetic permeability: $\mu = 4\pi \cdot 10^{-7} \frac{\text{Vs}}{\text{Am}}$
- ▶ Specific resistance: $\rho_R = 0,01721 \frac{\Omega \cdot \text{mm}^2}{\text{m}}$

Calculate the skin depth δ of the conductor.


$$\begin{aligned}\delta &= \sqrt{\frac{\rho_R}{\pi \cdot \mu \cdot f}} \\ \delta &= \sqrt{\frac{0,01721 \frac{\Omega \cdot \text{mm}^2}{\text{m}}}{\pi \cdot 4\pi \cdot 10^{-7} \frac{\text{Vs}}{\text{Am}} \cdot 50 \text{ Hz}}} \\ \delta &\approx 9,34 \text{ mm}\end{aligned}$$

- ▶ A current I flows through a conductor plate.






- ▶ A current I flows through a conductor plate.
- ▶ The Lorentz force deflects the moving charge carriers to the edge.



- ▶ A current I flows through a conductor plate.
- ▶ The Lorentz force deflects the moving charge carriers to the edge.
- ▶ The charge displacement generates an electric field.



- ▶ A current I flows through a conductor plate.
- ▶ The Lorentz force deflects the moving charge carriers to the edge.
- ▶ The charge displacement generates an electric field.
- ▶ This is measured as the Hall voltage U_H .

$$U_H = A_H \cdot \frac{I \cdot B}{d}$$

Example: Hall voltage

A metal plate with a thickness of $d = 1 \text{ cm}$ and a current of $I = 2 \text{ A}$ is located in a magnetic field with a flux density of $B = 0.5 \text{ T}$. The Hall constant of the material is $A_H = 3.2 \cdot 10^{-3} \frac{\text{m}^3}{\text{C}}$. Calculate the Hall voltage.

Example: Hall voltage

A metal plate with a thickness of $d = 1 \text{ cm}$ and a current of $I = 2 \text{ A}$ is located in a magnetic field with a flux density of $B = 0.5 \text{ T}$. The Hall constant of the material is $A_H = 3.2 \cdot 10^{-3} \frac{\text{m}^3}{\text{C}}$. Calculate the Hall voltage.

$$U_H = A_H \cdot \frac{I \cdot B}{d}$$

Example: Hall voltage

A metal plate with a thickness of $d = 1 \text{ cm}$ and a current of $I = 2 \text{ A}$ is located in a magnetic field with a flux density of $B = 0.5 \text{ T}$. The Hall constant of the material is $A_H = 3.2 \cdot 10^{-3} \frac{\text{m}^3}{\text{C}}$. Calculate the Hall voltage.

$$U_H = A_H \cdot \frac{I \cdot B}{d}$$

$$U_H = 3,2 \cdot 10^{-3} \frac{\text{m}^3}{\text{C}} \cdot \frac{2 \text{ A} \cdot 0,5 \text{ T}}{0,01 \text{ m}}$$

Example: Hall voltage

A metal plate with a thickness of $d = 1 \text{ cm}$ and a current of $I = 2 \text{ A}$ is located in a magnetic field with a flux density of $B = 0.5 \text{ T}$. The Hall constant of the material is $A_H = 3.2 \cdot 10^{-3} \frac{\text{m}^3}{\text{C}}$. Calculate the Hall voltage.

$$U_H = A_H \cdot \frac{I \cdot B}{d}$$

$$U_H = 3,2 \cdot 10^{-3} \frac{\text{m}^3}{\text{C}} \cdot \frac{2 \text{ A} \cdot 0,5 \text{ T}}{0,01 \text{ m}}$$

$$U_H = 0,32 \text{ V}$$