



AUSTIN AUTOMOTIVE

2625 EAST MAIN STREET
CANON CITY CO, 81212

Phone: 719-275-5055

VISIT US AT WWW.AUSTINAUTOMOTIVE.COM
MON - THURS 7:30AM - 5:30PM / FRI 7:30AM - 4:30PM

05/19/2025 1:42:48 PM

Repair Order #

43650

COUNTRY SIDE HEATING AND SOLAR

MATT/KALEA BAYER

1722 EDELWEISS DR

WESTCLIFFE CO, 81252

Matt Cell (719) 306-9606 ; Jason Cell (719) 371-5757

2008 Dodge Ram 2500HD 3/4 Ton - Pickup

Odometer In: 172788

Odometer Out: 172778

License: BYN-073 CO

VIN: 3D7KS28A38G180521

Eng: 6.7 L 408 CID L6 Cummins

Repair Order

Vehicle Time In: 4/21/2025 12:05:02PM

Vehicle Time Out: 5/19/2025 1:25:46PM

CONCERN AND CAUSE

CUSTOMER STATES :

Matt Bayer Dodge 2500 diesel

- Full bumper to bumper check, check all fluids, change top off as necessary
- Service, air filter, CABIN AIR FILTER replacement
- Tires rotation
- Blend doors check - very little on feet/always on defrost
- Front end check - shake down, it's a rough ride
- Shocks/struts? It's a rough ride now (hasn't been done since I owned it @ 110k miles)
- ****Smell coolant/oil burning (slight variation in engine when driving 160-210, it normally holds steady at 190)****
- Driver front window regulator, this works now, but does not when cold. Please replace.



INSPECTION RESULTS:

Front tires are choppy and wearing

Steering gear is seeping

The steering dampener is leaking

Front brakes are close to metal to metal 10%

The transfer case, front differential, and rear differential need services.

The front axel U-joints have rust rings

Front and rear shocks are worn out and should be replaced

There is a oil leak at the valve cover and the lower rocker housing

The vehicle needs a factory thermostat, Dodges are very particular about the thermostats - we have seen a lot of issues with all after market thermostats being faulty especially with Chrysler.

To repair the HVAC system the vehicle will need the lower part of the heater box replace due to the housing for the door being broken.

Replaced the heater hoses and the heater core as well. The evaporator core was in good shape and did not need to be replaced.

Labor: \$154.00

Parts: \$0.00

Sublet: \$0.00

Job Total: \$154.00

LUBE, OIL AND FILTER CHANGE CUMMINS 5.9 & 6.7

DRAIN AND REFILL CRANKCASE WITH PREMIUM DIESEL RATED MOTOR OIL, REPLACE OIL FILTER. LUBRICATE CHASSIS WHERE APPLICABLE. INSPECT AIR AND CABIN FILTER, TOP OFF ALL FLUID LEVELS AND APPLY REMINDER STICKER

Labor: \$30.00

Parts: \$0.00

Sublet: \$0.00

Job Total: \$30.00

Multi Point LOF Inspection

PERFORM Multi Point LOF Inspection

Description

15W/40 Synthetic Blend Oil

ENGINE OIL FILTER

Quantity

12.00

1.00

Sale

\$4.99

\$25.00

Extended

\$59.88

\$25.00

Labor: \$0.00

Parts: \$84.88

Sublet: \$0.00

Job Total: \$84.88

ROTATE TIRES

Labor: \$0.00

Parts: \$0.00

Sublet: \$0.00

Job Total: \$0.00



live

AUSTIN AUTOMOTIVE

2625 EAST MAIN STREET
CANON CITY CO, 81212
Phone: 719-275-5055

VISIT US AT WWW.AUSTINAUTOMOTIVE.COM
MON - THURS 7:30AM - 5:30PM / FRI 7:30AM - 4:30PM

05/19/2025 1:42:48 PM

Repair Order #
43650

FRONT SIDE HEATING AND SOLAR

T/KALEA BAYER

22 EDELWEISS DR
WESTCLIFFE CO, 81252

Matt Cell (719) 306-9606 ; Jason Cell (719) 371-5757

2008 Dodge Ram 2500HD 3/4 Ton - Pickup

Odometer In: 172788

Odometer Out: 172778

License: BYN-073 CO

VIN: 3D7KS28A38G180521

Eng: 6.7 L 408 CID L6 Cum

Repair Order

Continued From Previous Page

FRONT DIFFERENTIAL HOUSING COVER Remove & Replace

Labor: \$154.00 Parts: \$0.00 Sublet: \$0.00

Job Total: \$154.00

DIFFERENTIAL FLUID Drain & Refill

Description

Valvoline Synpower 75W90 Gear Oil - 1 qt

Quantity

2.35

Sale

\$21.99

Extended

\$51.68

Labor: \$0.00 Parts: \$51.68 Sublet: \$0.00

Job Total: \$51.68

REAR DIFFERENTIAL HOUSING COVER Remove & Replace

Labor: \$154.00 Parts: \$0.00 Sublet: \$0.00

Job Total: \$154.00

DIFFERENTIAL FLUID Drain & Refill

Description

Valvoline Synpower 75W90 Gear Oil - 1 qt

Quantity

3.80

Sale

\$21.99

Extended

\$83.56

Labor: \$0.00 Parts: \$83.56 Sublet: \$0.00

Job Total: \$83.56

TRANSFERCASE FLUID Drain & Refill

Description

Synthetic Universal ATF

Quantity

4.00

Sale

\$5.99

Extended

\$23.96

Labor: \$77.00 Parts: \$23.96 Sublet: \$0.00

Job Total: \$100.96

SHOCK ASSEMBLY Remove & Replace

DOES NOT include alignment.

Description

Shock - MonoMax - Front

Quantity

2.00

Sale

\$170.62

Extended

\$341.24

Labor: \$308.00 Parts: \$341.24 Sublet: \$0.00

Job Total: \$649.24

REAR SHOCK ASSEMBLY Remove & Replace

DOES NOT include disassemble or alignment (where applicable).

Description

Shock - MonoMax - Rear

Quantity

2.00

Sale

\$170.70

Extended

\$341.40

Labor: \$154.00 Parts: \$341.40 Sublet: \$0.00

Job Total: \$495.40

AXLE SHAFT U-JOINT Remove & Replace

Description

SKF Universal Joint

Quantity

2.00

Sale

\$94.85

Extended

\$189.70

Labor: \$616.00 Parts: \$189.70 Sublet: \$0.00

Job Total: \$805.70

STEERING GEAR ASSEMBLY Remove & Replace

Includes: Adjust toe-in on Rack and Pinion type Steering Gears. NOTE: Deduct .4 if alignment is also performed.





AUSTIN AUTOMOTIVE

2625 EAST MAIN STREET
CANON CITY CO, 81212

Phone: 719-275-5055

VISIT US AT WWW.AUSTINAUTOMOTIVE.COM

MON - THURS 7:30AM - 5:30PM / FRI 7:30AM - 4:30PM

05/19/2025 1:42:48 PM

Repair Order #

43650

IDE HEATING AND SOLAR

EA BAYER

WEISS DR

UFFE CO, 81252

ell (719) 306-9606 ; Jason Cell (719) 371-5757

pair Order

2008 Dodge Ram 2500HD 3/4 Ton - Pickup

Odometer In: 172788

Odometer Out: 172778

License: BYN-073 CO

VIN: 3D7KS28A38G180521

Eng: 6.7 L 408 CID L6 Cumm

Continued From Previous Page

Description	Quantity	Sale	Extended
Power Steering Gear Box - Remfd	1.00	\$507.25	\$507.25
Synthetic Universal ATF	1.00	\$5.99	\$5.99
Labor: \$385.00			
Parts: \$513.24			
Sublet: \$0.00			
Job Total: \$898.24			

STEERING DAMPENER Remove & Replace

Description	Quantity	Sale	Extended
Steering Damper	1.00	\$128.61	\$128.61
Labor: \$0.00			
Parts: \$128.61			
Sublet: \$0.00			
Job Total: \$128.61			

WINDOW REGULATOR Remove & Replace

Description	Quantity	Sale	Extended
Window Motor and Regulator Assembly	1.00	\$105.83	\$105.83
Dexcool Coolant (Orange)	2.00	\$14.99	\$29.98
Labor: \$154.00			
Parts: \$135.81			
Sublet: \$0.00			
Job Total: \$289.81			

FRONT DISC ROTOR Remove & Replace

Includes: Repack Wheel Bearings (where applicable) and replace Pads (if necessary).
DOES NOT include refinishing.

Description	Quantity	Sale	Extended
Front Disc Brake Rotor	2.00	\$189.22	\$378.44
Front Brake Pads	1.00	\$71.10	\$71.10
Labor: \$0.00			
Parts: \$449.54			
Sublet: \$0.00			
Job Total: \$449.54			

VALVE COVER GASKET Remove & Replace

Description	Quantity	Sale	Extended
GASKET, Rocker Arm Housing	1.00	\$77.95	\$77.95
Valve Cover Gasket	1.00	\$281.63	\$281.63
Labor: \$385.00			
Parts: \$359.58			
Sublet: \$0.00			
Job Total: \$744.58			

THERMOSTAT &/OR GASKET Remove & Replace

Description	Quantity	Sale	Extended
THERMOSTAT	1.00	\$244.00	\$244.00
SEAL, THERMOSTAT	1.00	\$20.95	\$20.95
Labor: \$261.80			
Parts: \$264.95			
Sublet: \$0.00			
Job Total: \$526.75			

HVAC DOOR ACTUATOR Remove & Replace

Includes: R&I Instrument Panel.

Description	Quantity	Sale	Extended
SEAL KIT, A/C And Heater Unit	1.00	\$53.35	\$53.35
HVAC Heater Core	1.00	\$128.70	\$128.70





AUSTIN AUTOMOTIVE

2625 EAST MAIN STREET
CANON CITY CO, 81212

Phone: 719-275-5055

VISIT US AT WWW.AUSTINAUTOMOTIVE.COM
MON - THURS 7:30AM - 5:30PM / FRI 7:30AM - 4:30PM

05/19/2025 1:42:48 PM

Repair Order #
43650

COUNTRY SIDE HEATING AND SOLAR

MATT/KALEA BAYER

1722 EDELWEISS DR
WESTCLIFFE CO, 81252

Matt Cell (719) 306-9606 ; Jason Cell (719) 371-5757

2008 Dodge Ram 2500HD 3/4 Ton - Pickup

Odometer In: 172788

Odometer Out: 172778

License: BYN-073 CO

VIN: 3D7KS28A38G180521

Eng: 6.7 L 408 CID L6 Cum

Repair Order

Continued From Previous Page

Small Heater Hose
HOSE, Heater
Heater Box Half with Door

1.00	\$22.36	\$22.36
1.00	\$50.25	\$50.25
1.00	\$395.00	\$395.00

Labor: \$770.00

Parts: \$649.66

Sublet: \$0.00

Job Total: \$1,419.66

AIR CONDITIONING SYSTEM CHARGE

Includes Evacuating, Vacuum, And Recharge System With Freon And Add Leak Detector Oil/Dye. Inspect All Connections And Seals, Check For Leaks With Ultraviolet Light And Freon Detector. Does Not Include System Repairs.

Description

BG Air Conditioning Oil With Dye
R134A Refrigerant

Quantity	Sale	Extended
1.00	\$6.95	\$6.95
1.00	\$28.99	\$28.99

Labor: \$84.99

Parts: \$35.94

Sublet: \$0.00

Job Total: \$120.93

Customer Authorization

4/25/25 9:21

Written by: CB **Initiated By:** Customer Phone 719-306-9606

5/1/25 14:20

Written by: CB **Initiated By:** Customer Phone 719-306-9606

Authorized By

COUNTRY SIDE
HEATING AND SOLAR

Previous Est.

\$ 5,125.83

Add'l Cost

\$ 5,125.83

Revised Est.

\$10,251.66

Authorized By

COUNTRY SIDE
HEATING AND SOLAR

\$ 7,301.57

\$ 7,301.57

\$14,603.14

Service Advisor: Cory B

Technician(s): Jason C #46, ; Matt W #50,

I consent to receiving text messages regarding your services, via automated technology, to the cell phone number you have on file. I acknowledge that I do not have to provide this consent to receive your services. Message and data rates may apply. Respond STOP to any message to cancel.

12 month, 12,000 mile warranty, whichever occurs first, is provided on all parts and labor unless otherwise specified. All warranty repairs must be performed at this facility. For warranty service outside a 25 mile radius from your original repairing location, contact the NAPA Auto Care Warranty Administrator at 800-452-NAPA (6272). For warranty service inside a 25 mile radius from your original repairing location, please contact your original location for service.

Labor Total: \$3,687.79

Parts Total: \$3,653.75

Shop Supplies: \$25.00

HazMat: \$2.95

Sub Total: \$7,369.49

Tax Total: \$320.06

Grand Total: \$7,689.55

Balance Due: \$7,689.55



SIGNATURE..... DATE.....

