3.12.9.11 MUPS-011 Pass number is out of sequence

Cause: Pass number is not in sequence

Remedy: Use correct pass number

3.12.9.12 MUPS-012 Last pass was incomplete

Cause: Last pass was not welded to completion

Remedy: Use correct pass number

3.12.9.13 MUPS-013 Invalid Leader OFFSET MODE

Cause: Leader Offset requires CD Move

Remedy: Add CD Move.

3.13 N

3.13.1 NCBN Alarm Code

3.13.1.1 NCBN-001 NC Command too long %s

Cause: NC command length too long

Remedy: Correct the command syntax and load the program again

3.13.1.2 NCBN-002 Syntax Error %s%s LN#%d

Cause: NC command syntax error

Remedy: Correct the command syntax and load the program again

3.13.1.3 NCBN-003 Unknown command

Cause: Invalid or undefined command was used

Remedy: Correct the command syntax and load the program again

3.13.1.4 NCBN-004 Multiple N-code LN#%d

Cause: Multiple N-code in one line

Remedy: Correct the command syntax and load the program again

3.13.1.5 NCBN-005 N-code missing LN#%d

Cause: A line must start with N-code

Remedy: Correct the command syntax and load the program again

3.13.1.6 NCBN-006 Config data expected LN#%d

Cause: Config command should be followed by config string data expressed as comment string

Remedy: Correct the command syntax and load the program again

3.13.1.7 NCBN-007 O-Code missing LN#%d

Cause: A program should begin with O-code i.e. program name

Remedy: Correct the command syntax and load the program again

3.13.1.8 NCBN-008 Word too long

Cause: Specified Program name too long

Remedy: Correct the command syntax and load the program again

3.13.1.9 NCBN-009 NO M-code allowed here

Cause: M-code is not allowed in this context

Remedy: Correct the command syntax and load the program again

3.13.1.10 NCBN-010 Unexpected code (%s%s) LN#%d

Cause: Commands are not placed in right order

Remedy: Correct the command syntax and load the program again

3.13.1.11 NCBN-011 Only one M-code allowed each line

Cause: Only one M-code per line is allowed

Remedy: Correct the command syntax and load the program again

3.13.1.12 NCBN-012 T-code expected

Cause: A T-code is expected for this M-code

Remedy: Correct the command syntax and load the program again

3.13.1.13 NCBN-013 NC conversion feature NOT loaded

Cause: NC conversion software is required to process this file type

Remedy: Please purchase proper software option

3.13.1.14 NCBN-014 NC prog (%s) NOT loaded

Cause: Specified program was not loaded due to error this file type

Remedy: Look at the cause code on the 2nd line of the screen, and fix the error