
Modelling of Machines

Section 6

Rotational and transformer voltages

Consider the simplified representation of a machine



L₁ and L₂ are constant and the mutual inductance between coils varies as:

$$M = M_d \cos \theta$$

The terminal voltages when the rotor are rotating is given by:

$$V_1 = i_1 R_1 + \frac{d \psi_1}{dt} = i_1 R_1 + L_1 \frac{d i_1}{dt} + M_d \cos \theta \quad \frac{d i_2}{dt} - M_d i_2 \sin \theta \quad \frac{d \theta}{dt}$$
 and

$$V_2 = i_2 R_2 + \frac{d\psi_2}{dt} = i_2 R_2 + L_2 \frac{di_2}{dt} + M_d \cos\theta \frac{di_1}{dt} - M_d i_1 \sin\theta \frac{d\theta}{dt}$$

This can be expressed in matrix form as:


$$\begin{bmatrix} V_1 \\ V_2 \end{bmatrix} = \begin{bmatrix} R_1 & 0 \\ 0 & R_2 \end{bmatrix} + \begin{bmatrix} L_1 & M_d \cos \theta \\ M_d \cos \theta & L_2 \end{bmatrix} \frac{d}{dt} + \begin{bmatrix} 0 & -M_d \sin \theta \\ -M_d \sin \theta & 0 \end{bmatrix} \frac{d\theta}{dt} \begin{bmatrix} i_1 \\ i_2 \end{bmatrix}$$

or
$$[V] = |R| + [L] \frac{d}{dt} + [G] \omega | [i]$$
 Resistive Transformer Rotational terms terms

Analysis of Kron primitive machine


Assumptions and conventions

- 1) Flux is directly proportional to current (i.e. magnetic saturation)
- 2) Commutation is ideal (no voltage drop)
- 3) All types of winding can be represented by concentrated coils (i.e. coils along one axis)
- 4) Two axes represent axes of symmetry
- 5) Dot-blank notation relates current polarity to direction of flux



Primitive coil current always flows into dot end Current in at dot end gives flux in same direction Mutual inductance between coils on same axis is positive Positive voltage at dot end Power into coil from source given by positive current Coils are arranged with dot end nearest centre


Applying the conventions and assumptions yields the generalised unconnected form of the Kron primitive



Interactions between stator and rotor coils


Coils on same axis





Transformer voltage even when ω=0

Coils on orthogonal axes



Rotational voltage even when i≠f(t)

Consider coil d₁ in the unconnected Kron primitive

$$V_{d1} = i_{d1} R_{d1} + \frac{d \psi_{d1}}{dt}$$

$$\psi_{d1} = L_{d1}i_{d1} + M_{d1d2}i_{d2} + M_{d1q1}i_{q1} + M_{d1q2}i_{q2}$$

$$\frac{d\psi_{d1}}{dt} = L_{d1} \frac{di_{d1}}{dt} + M_{d1d2} \frac{di_{d2}}{dt} + G_{d1q1} \omega i_{q1} + G_{d1q2} \omega i_{q2}$$


Where G are rotational voltage terms

Use p to denote d/dt (note: this is simply a shorthand notation and NOT a mathematical transformation)

The voltage equations for d₁ coil can be expressed as:

$$[V] = [Z][I]$$
 where $[Z] = [R] + [L]p + [G]\omega$

Note convention on subscripts



i.e refers to voltage in d1 due to flux in d2

The same voltage equations can be derived for the remaining coils – putting these into matrix for yields the **generalised form of the voltage matrix equations**:

V _{d1}		$R_{d1} + L_{d1}p$	$G_{d1q1}\omega_{r}$	$M_{d1d2}p$	$G_{d1q2}\omega$	$\left i_{d1} \right $
V _{q1}		$G_{q1d1}\omega_{r}$	$R_{q1}+L_{q1}p$	$G_{q1d2}\omega_{r}$	$M_{q1q2}p$	$\left i_{\mathrm{q}1} \right $
V _{d2}		$M_{d2d1}p$	0	$R_{d2}+L_{d2}p$	0	i_{d2}
V _{q2}		0	$M_{q2q1}p$	0	$R_{q2}+L_{q2}p$	$\left i_{ m q2} ight $


Points to note:

- Leading diagonal contains self impedance terms
- No rotational voltage induced in stator coils (d2 and q2) hence presence of zero terms in matrix

The general form of the matrix equations can be simplified by noting the following:

$$M_{d1d2} = M_{d2d1} = M_d$$
 and $M_{q1q2} = M_{q2q1} = M_q$

The G coefficients can be expressed in terms on inductances noting polarity - Consider G_{q1d2}



Sign of angle determined by angle of voltage axis relative to flux axis in direction of rotation – in this case voltage axis lags flux axis in direction of rotation – hence -90°

Consider the G term which relates the rotational voltage induced in a rotor coil by flux in a stator coil on an orthogonal axis

$$G_{q1d2} = -M_d \sin \theta$$


But $\theta = -90^{\circ}$ and since $\sin(-90) = -1$ then:

$$G_{q1d2} = M_d$$

By a similar analysis $G_{d1q2} = -M_q$

This can consolidated into rule that the G coefficient is positive when the FLUX AXIS LEADS VOLTAGE AXIS IN DIRECTION OF ROTATION

Consider the G term which relates the rotational voltage induced in a rotor coil by flux in a <u>rotor</u> coil on an orthogonal axis



$$G_{d1q1} = -M_{q1q1} \sin (90)$$

= - L_{q1}

By a similar process:

$$G_{q1d1} = + L_{d1}$$

This leads to a simplified matrix of equations:

v_{d1}		$R_{d1}+L_{d1}p$	$-L_{q1}\omega_r$	$M_d p$	$-M_q\omega$	i _{d1}
V _{q1}		$L_{d1}\omega_{r}$	$R_{q1}+L_{q1}p$	$M_d\omega_r$	$M_q p$	i_{q1}
V _{d2}		M_dp	0	$R_{d2} + L_{d2}p$	0	i_{d2}
V _{q2}		0	$M_q p$	0	$R_{q2}+L_{q2}p$	i_{q2}

Notes:

The rotational terms comprise L terms when the coils are both on the rotor The rotational terms comprise M terms when a stator coil is involed

No rotational voltages are induced in stator coils